

ASS. REC. BY:

REF: CS/C12 19019348 / Ks f3

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)From (Person): Glenn Cheung of C12 Date/Time: 1.11.19 15:47pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLP 8833J Insured: SMG 80513at Workshop m/s Ah Lim motor Tel: 64831248of 10 AMC Industrial Park 2A #01-09Policy No: DMPGSA 360 91119000 Claim No: SVM191205130C02

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 24.10.19
(Client's Record)CA / REV / REP. / REV 24 HRS mp 4.11.2019 H.O.D. Endorsement: _____Date/Time: 1.11.19 4:20 p.m Person Contacted: Glenn Vehicle: IN / OUT

Date/Time	Action/Instruction (☒) Estimate
	<u>SLP 8833J - X</u>
	<u>SMG 80513 -</u>
<u>31/12</u>	<u>\$3138.12 Confirm</u>
	<u>(\$1,467.40 Red - 32%)</u>

REF: CTT

ASS. REC. BY:

ASSIGNMENT

From: Date: 4.11.2019

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLP 8833J

at Workshop m/s Ah Lim Motor

of 10 Amk Industrial Park 2A 701-09

Insured:

Policy No:

Claims No:


Sum Insured: Excess:

(Client's Record)

Make of Veh: 12.00pm On way

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Turn Sum: 1-B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLP 8833J Yr Regis: 06 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel C.C. 1496

Colour: M.P. White A/C: Insured / Std / NI / NA

Sp. Reading: 5219 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: RU 3 1248203

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / Std A/Rim or

Tyre Size: F: 225/50R17

R:

BS / DUN / EXNOVA / GY / PS / LIZA / MIC / OHTSU PIR / SUMI /

TOYO / YOKO or

Front R/Bal. 8 mm

Rear R/Bal. 8 mm

L/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 28/11/19

D.O.A. 4/11/19

Survey held at

Des. of Damages: Frt / Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 1 DEC 2019

Date/Time, File Pass to?

1) 5/12/19

Date/Time, File Return to?

2)

Rep. Format:

Lump Sum / P/L: 3,138.12 p/l

☐ : Prel. Report☒ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 Oct 2019		01 Nov 2019 15:47 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:									
Main Claimant: ER KAH LANG , ID: S1478833F									
Vehicle Reg. No.: SLP8833J		Date of Loss:	28/10/2019 13:00 - :59						
Claim Type: TP / SNM19D205130C02		Policy/Cover Note No.:	DMPCSN30091119000						
Vehicle Reg. No. (Insured): SMG8051J		Policy No. (Claimant):	GA230918						
		Excess:	S\$750.00						
Repairer: Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6483 1244									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]									
Claimant's Insurer: AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 12/11/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 833F

Vehicle Details

Vehicle No.: SLP8833J
Vehicle to be Exported: Yes
Intended Deregistration Date: 29 Oct 2019
Vehicle Make: HONDA
Vehicle Model: VEZEL HYBRID 1.5X CVT
Primary Colour: White
Manufacturing Year: 2017
Engine No.: LEB5949220
Chassis No.: RU31249203
Maximum Power Output: 112.0 kW (150 bhp)
Open Market Value: \$25,596.00
Original Registration Date: 23 Jun 2017
First Registration Date: 23 Jun 2017
Transfer Count: 0
Actual ARF Paid: \$5,000.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 22 Jun 2027
PARF Rebate Amount: \$3,750.00

Intended COE Rebate Details

COE Expiry Date: 22 Jun 2027
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$55,414.00
COE Rebate Amount: \$42,390.00
Total Rebate Amount: \$46,140.00

The information contained herein is correct as at 29 Oct 2019

OK

7P/Ching
 4/10/19 11:30 am
PANY
 Singapore 568047

SURVEYOR COPY

Estimate No: MC1900796
Date: 30 Oct 2019
Policy No: GA230918
Veh Reg No: SLP8833J
Make/Model: HONDA VEZEL
 HYBRID 1.5X CVT

ATTN:

Your Ref No: -
Claim Type: Third Party
Accident Date: 28/10/2019
TP Veh Reg No: SMG8051J

Not Withstand
Resolving By Pain 4 days

4 days

Description	Quantity	List Price	Amount
		SS	SS
SPARE PARTS			
1 REAR WINDSCREEN MOULDING	1 PC	120.00	✓
2 TAILGATE	1 PC	1,050.00	✓
3 TAILGATE EMBLEM	1 PC	15.70	x
4 TAILGATE VEZEL LOGO	1 PC	43.00	✓
5 TAILGATE HYBRID LOGO	1 PC	75.50	✓
6 TAILGATE INNER LOCK	1 PC	157.10	x
7 TAILGATE RUBBER	1 PC	92.30	x
8 REAR BUMPER	1 PC	777.90	✓
9 REAR BUMPER SIDE RETAINERS LH & RH	2 PC	35.00	x
10 REAR BUMPER CLIPS	15 PC	52.50	✓
11 REAR BUMPER REFLECTOR LH	1 PC	141.00	x
12 END PANEL	1 PC	411.90	x
13 Rear Bumper Buzzer Assy (Supp)	Gr	\$85/-	
		2,971.90	
	Less 20%	594.38	2,377.52
Special Nett			
13 REAR BUMPER LOWER SPOILER -CHECK PRICE	1 PC	0.00	x
14 INNER SEAL	1 PC	20.00	✓
15 SEALANT	1 PC	40.00	✓
16 REVERSE SENSOR	2 PC	200.00	x
		260.00	260.00
LABOUR			
17 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	15/-
18 TO REMOVE & REFIT REAR WINDSCREEN	1 EA	120.00	✓
19 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	80.00	50/-
20 TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	30/-
21 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD END PANEL TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK.	1 PC	800.00	500/-
22 TO SPRAY TAILGATE, REAR BUMPER, END PANEL	1 PC	800.00	600/-
		1,900.00	1,900.00

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : ER KAH LANG
BLK 838 HOUGANG CENTRAL #02-509

SINGAPORE 530838

ATTN:

Estimate No: MC1900796
Date: 30 Oct 2019
Policy No: GA230918
Veh Reg No: SLP8833J
Make/Model: HONDA VEZEL
HYBRID 1.5X CVT

Your Ref No: -
Claim Type: Third Party
Accident Date: 28/10/2019
TP Veh Reg No: SMG8051J

Estimate Repair Cost to Vehicle No :SLP8833J

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
		Total	S\$ 4,537.52
		Add GST @ 7%	317.63
		Total Amount Payable	S\$ 4,855.15

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND EIGHT HUNDRED FIFTY FIVE AND CENTS FIFTEEN ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

4605.52

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

COPY

M/S : ER KAH LANG
BLK 838 HOUGANG CENTRAL #02-509
SINGAPORE 530838

Claim No: MC1900796
No: MF1900809
Date: 24 Dec 2019
Policy No: GA230918
Veh Reg No: SLP8833J
Make/Model: HONDA VEZEL
HYBRID 1.5X CVT
Chassis No: RU31249203
TP Ins Co: CHINA

ATTN:

Your Ref No: -
Claim Type: Third Party
Accident Date: 28/10/2019
TP Veh Reg No: SMG8051J

Repair Cost to Vehicle No (For Finalization):SLP8833J

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
SPARE PARTS			
1 REAR WINDSCREEN MOULDING	1 PC	120.00	
2 TAILGATE	1 PC	1,050.00	
3 TAILGATE VEZEL LOGO	1 PC	43.00	
4 TAILGATE HYBRID LOGO	1 PC	75.50	
5 REAR BUMPER	1 PC	777.90	
6 REAR BUMPER CLIPS	15 PC	52.50	
7 REAR BUMPER BUZZER ASSY	1 PC	85.00	
		2,203.90	
	Less 20%	440.78	1,763.12
Special Nett			
8 INNER SEAL	1 PC	20.00	
9 SEALANT	1 PC	40.00	
		60.00	60.00
LABOUR			
10 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	15.00	
11 TO REMOVE & REFIT REAR WINDSCREEN	1 EA	120.00	
12 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	50.00	
13 TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	30.00	
14 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD END PANEL TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK.	1 PC	500.00	
15 TO SPRAY TAILGATE, REAR BUMPER, END PANEL	1 PC	600.00	
		1,315.00	1,315.00

AH LIM MOTOR COMPANY
10 Ang Mo Kio Industrial Park 2A
AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : ER KAH LANG
BLK 838 HOUGANG CENTRAL #02-509
SINGAPORE 530838

Claim No: MC1900796
No: MF1900809
Date: 24 Dec 2019
Policy No: GA230918
Veh Reg No: SLP8833J
Make/Model: HONDA VEZEL
HYBRID 1.5X CVT
Chassis No: RU31249203
TP Ins Co: CHINA

ATTN:

Your Ref No: -
Claim Type: Third Party
Accident Date: 28/10/2019
TP Veh Reg No: SMG8051J

Repair Cost to Vehicle No (For Finalization):SLP8833J

Description	Quantity	List Price S\$	Amount S\$
		Total	S\$ 3,138.12
		Add GST @ 7%	219.67
		Total Amount Payable	S\$ 3,357.79

TOTAL: SINGAPORE DOLLAR THREE THOUSAND THREE HUNDRED FIFTY SEVEN AND CENTS SEVENTY NINE ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 04/11/2019

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 FAX: 6483 6170
AUTHORISED SIGNATURE

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119019348/KSF3N2
Date: 07/01/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30091119000
Claimant Vehicle No :	SLP8833J	Insured Vehicle No :	SMG8051J
Date of Loss:	28/10/2019	Nature of Claim:	TP
		Claim No:	SNM19D205130C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP8833J	Engine No:	LEB5949220
Make & Model:	HONDA VEZEL, 1.5 X HYBRID CVT (A)	Chassis No:	RU31249203
Reg. Date:	23/06/2017 (Man. Year: 2017)	Odometer:	52191 km
Colour:	Metallic Pearl White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50R17	Rear Tyre Size:	225/50R17
Front Left Side:	Pirelli 8 mm	Rear Left Side:	Pirelli 8 mm
Front Right Side:	Pirelli 8 mm	Rear Right Side:	Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,705.52	1,823.12	882.40	32.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,900.00	1,315.00	585.00	30.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,605.52	3,138.12	1,467.40	31.86
+ GST 7.00/7.00% (S\$)	322.39	219.67	102.72	31.86
Nett Amount (S\$)	4,927.91	3,357.79	1,570.12	31.86

INSPECTION

Date of Assignment:	01/11/2019	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint Singapore 568047
Date Inspected:	04/11/2019 Inspected At:	
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Jan 2020)

Parts: M1-SUV HONDA VEZEL 1.5 X HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLP8833J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	120.00 FL	*120.00 FL
2	1		*TAILGATE	Bent	1,050.00 FL	*1,050.00 FL
3	1		*TAILGATE EMBLEM	Not Necessary	15.70 FL	*- FL
4	1		*TAILGATE VEZEL LOGO	Necessary	43.00 FL	*43.00 FL
5	1		*TAILGATE HYBRID LOGO	Necessary	75.50 FL	*75.50 FL
6	1		*TAILGATE INNER LOCK	Repair	157.10 FL	*- FL
7	1		*TAILGATE RUBBER	Serviceable	92.30 FL	*- FL
8	1		*REAR BUMPER	Buckled	777.90 FL	*777.90 FL
9	2		*REAR BUMPER SIDE RETAINERS LH & RH	Serviceable	35.00 FL	*- FL
10	15		*REAR BUMPER CLIPS	Necessary	52.50 FL	*52.50 FL
11	1		*REAR BUMPER REFLECTOR LH	Serviceable	141.00 FL	*- FL
12	1		*END PANEL	Repair	411.90 FL	*- FL
13	1		*REAR BUMPER BUZZER ASSY	Cracked	85.00 FL	*85.00 FL
14	1		*REAR BUMPER LOWER SPOILER (NPA)	Serviceable	0.00 FS	*- FS
15	1		*INNER SEAL	Necessary	20.00 FS	*20.00 FS
16	1		*SEALANT	Necessary	40.00 FS	*40.00 FS
17	2		*REVERSE SENSOR	Serviceable	200.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc,

Sub Total (S\$)	3,316.90	2,263.90
- List Item Discount on L Items 20.00/20.00% (S\$)	611.38	440.78
Total Parts (S\$)	2,705.52	1,823.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING,WIRE SOCKETS AND ETC.TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	15.00
2	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	120.00
3	TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS	New	80.00	50.00
4	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	60.00	30.00
5	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD END PANEL.TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS.TO REFIT LISTED PARTS BACK	New	800.00	500.00
6	TO SPRAY TAILGATE,REAR BUMPER,END PANEL	New	800.00	600.00
Gross Labour Cost (S\$)			1,900.00	1,315.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >