

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

COPY

M/S : ER KAH LANG
BLK 838 HOUGANG CENTRAL #02-509
SINGAPORE 530838

Claim No: MC1900796
No: MF1900809
Date: 24 Dec 2019
Policy No: GA230918
Veh Reg No: SLP8833J
Make/Model: HONDA VEZEL
HYBRID 1.5X CVT
Chassis No: RU31249203
TP Ins Co: CHINA

ATTN:

Your Ref No: -
Claim Type: Third Party
Accident Date: 28/10/2019
TP Veh Reg No: SMG8051J

Repair Cost to Vehicle No (For Finalization):SLP8833J

Description	Quantity	List Price	Amount
		SS	SS
SPARE PARTS			
1 REAR WINDSCREEN MOULDING	1 PC	120.00	
2 TAILGATE	1 PC	1,050.00	
3 TAILGATE VEZEL LOGO	1 PC	43.00	
4 TAILGATE HYBRID LOGO	1 PC	75.50	
5 REAR BUMPER	1 PC	777.90	
6 REAR BUMPER CLIPS	15 PC	52.50	
7 REAR BUMPER BUZZER ASSY	1 PC	85.00	
		2,203.90	
	Less 20%	440.78	1,763.12
Special Nett			
8 INNER SEAL	1 PC	20.00	
9 SEALANT	1 PC	40.00	
		60.00	60.00
LABOUR			
10 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	15.00	
11 TO REMOVE & REFIT REAR WINDSCREEN	1 EA	120.00	
12 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	50.00	
13 TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	30.00	
14 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD END PANEL. TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK.	1 PC	500.00	
15 TO SPRAY TAILGATE, REAR BUMPER, END PANEL	1 PC	600.00	
		1,315.00	1,315.00

AH LIM MOTOR COMPANY
10 Ang Mo Kio Industrial Park 2A
AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170