



Automotive Repair Centre Pte Ltd

CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST1910-130
DATE : 30-Oct-2019
POLICY NO. : A80467989MCX
VEHICLE REG. NO. : SLX5574J
VEHICLE MAKE : HONDA SHUTTLE-1.5 G CVT (A)

TO Motor Claim Department
India International Insurance Pte Ltd
64 Cecil Street, #04-#05 IOB Building, Singapore 049711
Tel: 6347 6100
Fax: 6224 4174 / 6225 7743

FOR SURVEYOR

ESTIMATE REPAIR COST

| NO. | DESCRIPTION | QUANTITY | UNIT COST | TOTAL COST |
|---------------------------|--|----------|-------------|-------------|
| SPARE PARTS | | | | |
| 1 | Rear Bumper / DD | 1 | \$ 1,180.00 | \$ 1,180.00 |
| 2 | Rear Bumper Clip / MC | 10 | \$ 4.00 | \$ 40.00 |
| 3 | Rear Bumper Retainer RH / DR | 1 | \$ 30.00 | \$ 30.00 |
| 4 | Rear Bumper Grille RH / CH | 1 | \$ 50.00 | \$ 50.00 |
| 5 | Rear Bumper Grille Inner Sponge Bracket RH X | 1 | \$ 60.00 | \$ 60.00 |
| 6 | Rear Bumper Grille Reflector RH ? | 1 | \$ 50.00 | \$ 50.00 |
| 7 | Rear Bumper Finisher Cover No. 6 X | 1 | \$ 30.00 | \$ 30.00 |
| 8 | Rear Bumper Tow Eye Cover / DR | 1 | \$ 20.00 | \$ 20.00 |
| 9 | Rear Bumper Protector No. 8 X | 1 | \$ 40.00 | \$ 40.00 |
| 10 | Rear Tailgate / DD | 1 | \$ 1,200.00 | \$ 1,200.00 |
| 11 | Rear Tailgate Chrome Garnish X | 1 | \$ 400.00 | \$ 400.00 |
| 12 | Rear Tailgate Shuttle Emblem / MC | 1 | \$ 60.00 | \$ 60.00 |
| 13 | Rear Tailgate Honda Emblem X | 1 | \$ 40.00 | \$ 40.00 |
| 14 | Rear Tailgate Lock / DD | 1 | \$ 100.00 | \$ 100.00 |
| 15 | Rear Tailgate Rubber Seal / CR4 | 1 | \$ 180.00 | \$ 180.00 |
| 16 | Rear Tailgate Inner Trim X CR4 | 1 | \$ 320.00 | \$ 320.00 |
| 17 | Rear / End Panel Garnish No. 10 / CR4 | 1 | \$ 160.00 | \$ 160.00 |
| 18 | Rear / End Panel Garnish Cover No. 7 X | 1 | \$ 90.00 | \$ 90.00 |
| 19 | End Panel ? | 1 | \$ 600.00 | \$ 600.00 |
| 20 | Rear Windscreen Molding / MC | 1 | \$ 80.00 | \$ 80.00 |
| Total Spare Parts | | | | \$ 4,730.00 |
| SPECIAL NETT | | | | |
| 21 | Reverse Sensor / SHM | 1 | \$ 200.00 | \$ 200.00 |
| 22 | Rear Windscreen Sealant / MC | 1 | \$ 40.00 | \$ 40.00 |
| Total Special Nett | | | | \$ 240.00 |
| LABOUR | | | | |
| 23 | Spray Painting Rear Bumper, Tailgate and Inner Panel | 1 | \$ 800.00 | \$ 800.00 |
| 24 | Remove, Replace and Repair Accident Affected Area | 1 | \$ 800.00 | \$ 800.00 |
| 25 | Remove and Refit Rear Bumper Reverse Sensor | 1 | \$ 100.00 | \$ 100.00 |
| 26 | Transfer Door Fitting and Window Mechanism to New Door | 1 | \$ 80.00 | \$ 80.00 |
| 27 | Remove and Refit Rear Windscreen | 1 | \$ 120.00 | \$ 120.00 |
| 28 | Apply Rust Proofing on Replaced/Repaired Panel | 1 | \$ 100.00 | \$ 100.00 |
| 29 | Check and Rectify Electrical wiring | 1 | \$ 30.00 | \$ 30.00 |

700
600
20
30
30



Automotive Repair Centre Pte Ltd

CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

Estimate

ESTIMATE NO. : EST1910-130
DATE : 30-Oct-2019
POLICY NO. : A80467989MCX
VEHICLE REG. NO. : SLX5574J
VEHICLE MAKE : HONDA SHUTTLE-1.5 G CVT (A)

TO Motor Claim Department
India International Insurance Pte Ltd
64 Cecil Street, #04-#05 IOB Building, Singapore 049711
Tel: 6347 6100
Fax: 6224 4174 / 6225 7743

FOR SURVEYOR

ESTIMATE REPAIR COST

| NO. | DESCRIPTION | QUANTITY | UNIT COST | TOTAL COST |
|-----|-------------|----------|-----------------------------|--------------------|
| | | | Total Labour | \$ 2,030.00 |
| | | | Amount Before Excess | \$ 7,000.00 |
| | | | Add GST @ 7% | 490.00 |
| | | | Total Amount Payable | \$ 7,490.00 |

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Steve (LKK) w/L Mr/L 4/11/19, 11am
8322 8813
5 days
L/S
Ry AC SPJ

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: