

**Automotive Repair Centre Pte Ltd**CO. Reg. No. : 201312913C  
GST Reg. No. : 201312913C**Estimate**38 Woodlands Industrial Park E1  
#05-18, Singapore 757700  
Tel: 64688834 Fax: 64622278  
E-mail: info@automotiverepaircentre.com.sgESTIMATE NO. : EST1910-130  
DATE : 30-Oct-2019  
POLICY NO. : A80467989MCX  
VEHICLE REG. NO. : SLX5574J  
VEHICLE MAKE : HONDA SHUTTLE-1.5 G CVT (A)TO Motor Claim Department  
India International Insurance Pte Ltd  
64 Cecil Street, #04-#05 IOB Building, Singapore 049711  
Tel: 6347 6100  
Fax: 6224 4174 / 6225 7743

FOR SURVEYOR

--

**ESTIMATE REPAIR COST**

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<b><u>SPARE PARTS</u></b>			
1	Rear Bumper	1	\$ 1,180.00	\$ 1,180.00
2	Rear Bumper Clip	10	\$ 4.00	\$ 40.00
3	Rear Bumper Retainer RH	1	\$ 30.00	\$ 30.00
4	Rear Bumper Grille RH	1	\$ 50.00	\$ 50.00
5	Rear Bumper Grille Inner Sponge Bracket RH	1	\$ 60.00	\$ 60.00
6	Rear Bumper Grille Reflector RH	1	\$ 50.00	\$ 50.00
7	Rear Bumper Finisher Cover No. 6	1	\$ 30.00	\$ 30.00
8	Rear Bumper Tow Eye Cover	1	\$ 20.00	\$ 20.00
9	Rear Bumper Protector No. 8	1	\$ 40.00	\$ 40.00
10	Rear Tailgate	1	\$ 1,200.00	\$ 1,200.00
11	Rear Tailgate Chrome Garnish	1	\$ 400.00	\$ 400.00
12	Rear Tailgate Shuttle Emblem	1	\$ 60.00	\$ 60.00
13	Rear Tailgate Honda Emblem	1	\$ 40.00	\$ 40.00
14	Rear Tailgate Lock	1	\$ 100.00	\$ 100.00
15	Rear Tailgate Rubber Seal	1	\$ 180.00	\$ 180.00
16	Rear Tailgate Inner Trim	1	\$ 320.00	\$ 320.00
17	Rear / End Panel Garnish No. 10	1	\$ 160.00	\$ 160.00
18	Rear / End Panel Garnish Cover No. 7	1	\$ 90.00	\$ 90.00
19	End Panel	1	\$ 600.00	\$ 600.00
20	Rear Windscreen Molding	1	\$ 80.00	\$ 80.00
	<b>Total Spare Parts</b>			\$ 4,730.00
	<b><u>SPECIAL NETT</u></b>			
21	Reverse Sensor	1	\$ 200.00	\$ 200.00
22	Rear Windscreen Sealant	1	\$ 40.00	\$ 40.00
	<b>Total Special Nett</b>			\$ 240.00
	<b><u>LABOUR</u></b>			
23	Spray Painting Rear Bumper, Tailgate and Inner Panel	1	\$ 800.00	\$ 800.00
24	Remove, Replace and Repair Accident Affected Area	1	\$ 800.00	\$ 800.00
25	Remove and Refit Rear Bumper Reverse Sensor	1	\$ 100.00	\$ 100.00
26	Transfer Door Fitting and Window Mechanism to New Door	1	\$ 80.00	\$ 80.00
27	Remove and Refit Rear Windscreen	1	\$ 120.00	\$ 120.00
28	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
29	Check and Rectify Electrical wiring	1	\$ 30.00	\$ 30.00



# Automotive Repair Centre Pte Ltd

CO. Reg. No. : 201312913C  
GST Reg. No. : 201312913C

# Estimate

38 Woodlands Industrial Park E1  
#05-18, Singapore 757700  
Tel: 64688834 Fax: 64622278  
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST1910-130  
DATE : 30-Oct-2019  
POLICY NO. : A80467989MCX  
VEHICLE REG. NO. : SLX5574J  
VEHICLE MAKE : HONDA SHUTTLE-1.5 G CVT (A)

TO Motor Claim Department  
India International Insurance Pte Ltd  
64 Cecil Street, #04-#05 IOB Building, Singapore 049711  
Tel: 6347 6100  
Fax: 6224 4174 / 6225 7743

FOR SURVEYOR

### ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
Estimate prepared by: Raymond Tan			Total Labour	\$ 2,030.00
The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.			Amount Before Excess	\$ 7,000.00
			Add GST @ 7%	490.00
			<b>Total Amount Payable</b>	<b>\$ 7,490.00</b>