

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19019372/EPA3Q2

Date: 23/06/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SMH2346T	Insured Vehicle No :	SHA2131S
Date of Loss: 26/10/2019	Nature of Claim: TP	Claim No: MCT19100682

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH2346T		
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Engine No:	3A92UHL8369
Reg. Date:	16/01/2019 (Man. Year: 2018)	Chassis No:	MMBSTA13AKH000487
Colour:	Red	Odometer:	25771 km
Engine Capacity:	1193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Tourador 5 mm	Rear Left Side:	Tourador 5 mm
Front Right Side:	Tourador 5 mm	Rear Right Side:	Tourador 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,647.00	1,828.00	819.00	30.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,380.00	2,350.00	2,030.00	46.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,027.00	4,178.00	2,849.00	40.54
+ GST 7.00/7.00% (S\$)	491.89	292.46	199.43	40.54
Nett Amount (S\$)	7,518.89	4,470.46	3,048.43	40.54
+ Car Rental (4.0 x S\$100.00/day + 7.00% GST) (S\$)		428.00		
Nett Liability (S\$)		4,898.46		

INSPECTION

Date of Assignment:	31/10/2019	
Date Inspected:	03/12/2019 Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 08 Jan 2020)	
Parts:	N/A	mitsubishi attrage 1.2 CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMH2346T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FR BUMPER BODY KIT SEALANT	Necessary	80.00 FS	*20.00 FS
2	1		*SUNDRIES	Necessary	50.00 FS	*50.00 FS
3	1		*FENDER ,FR RH	Dented	497.00 FS	*497.00 FS
4	1		*SHIELD ,FR WHEELHOUSE ,RH	Crushed	98.00 FS	*98.00 FS
5	6		*CLIP ,INNERSHIELD	Necessary	24.00 FS	*24.00 FS
6	1		*HEADLAMP ASSY ,RH	Not Necessary	660.00 FS	*- FS
7	1		*WHEEL ,DISC RHF	Cut	687.00 FS	*687.00 FS
8	1		*GARNISH ,FR FENDER RH	Not Necessary	65.00 FS	*- FS
9	1		*EMBLEM ECO	Not Necessary	34.00 FS	*- FS
10	1		*STRUT ,FR SUSPENSION	Bent	452.00 FS	*452.00 FS
					Total Parts (\$\$)	2,647.00 1,828.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RENEW RHF FENDER REPAIR RHF DOOR ,FR BUMPER & FR BUMPER BODY KIT	New	2,200.00	1,100.00
2	RESPRAY FR BUMPER ,FR BUMPER BODY KIT ,RHF FENDER & RHF DOOR	New	1,680.00	840.00
3	RENEW RHF SPORT RIM & TRANSFER TYRE	New	50.00	50.00
4	CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM	New	50.00	0.00
5	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	200.00	200.00
6	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
7	APPLY ANTI CORROSION ON AFFECTED AREAS	New	80.00	40.00
Gross Labour Cost (\$\$)			4,380.00	2,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >