



ACE AUTOLUTION PTE LTD
13 Kaki Bukit Road 4 Bartley Biz Centre #03-29
Singapore 417807
Tel:6702 4282 Fax:6702 4202

TPALH.
Khandhna.

DA17V251883

Page No. 1

Vehicle No. GBG5666K SUZUKI EVERY

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR ADJUSTMENT
	PARTS (LIST ITEMS)			
1	REAR TAILGATE <i>Dented.</i>		1375.00	899.60 899.60
1	REAR TAILGATE LOCK <i>Damaged.</i>		279.00	145. 145.00
1	REAR TAILGATE CENTRE LOGO <i>Neu</i>		65.00	45 45.00
1	REAR TAILGATE ABSORBER LH & RH @\$300.00 <i>Not Neu</i>		600.00	X
1	REAR TAILGATE INNER BOARD <i>Neu</i>		418.00	X
1	REAR TAILGATE RUBBER <i>Neu</i>		235.00	X
1	REAR TAILGATE OUTER HANDLE <i>Not Neu</i>		101.00	X
1	REAR BUMPER <i>Deformed.</i>		511.00	✓
2	REAR BUMPER SIDE RETAINER LH & RH @\$80.50 <i>Neu NEC</i>		161.00	✓
1	REAR BUMPER SIDE LOWER GARNISH <i>Not Neu</i>		250.20	X
1	REAR END PANEL <i>Dented.</i>		543.50	✓
1	REAR END PANEL AIR VENT <i>Neu</i>		95.00	X
1	REAR FLOOR PANEL <i>Neu</i>		1120.00	X
1	REAR FLOOR PANEL TOP MAT <i>Not Neu</i>		695.00	X
2	REAR TAILLAMP LH & RH @\$345.60 <i>in c. d. LH CRACKED</i>		691.20	175 175.20
1	REAR EXHAUST SILENCER <i>Not Neu</i>	NN	785.00	X
1	REAR EXHAUST SILENCER RUBBER <i>Not Neu</i>	NN	98.00	X
1	REAR FENDER INNER SHIELD LH <i>Not Neu</i>	NN	103.00	X
			8188.90	
		less	10%	10%
			818.89	
			7367.31	
	SPECIAL NETT ITEMS			
1 SET	REAR BUMPER CLIPS <i>plus</i>		100.00	30.00
1	REAR WINDSCREEN SEALANT <i>plus</i>		100.00	60.00
1	REAR TAILGATE INNER BOARD CLIPS <i>NN</i>		100.00	X
1	STICKER "70 KM/H" <i>plus</i>		70.00	15.00
1	STICKER "EVERY" <i>plus</i>		70.00	35.00
1	REAR BUMPER STICKER <i>plus</i>		180.00	150.00
1	REAR TAILGATE STICKER <i>plus</i>		250.00	200.00
			8227.31	



ACE AUTOLUTION PTE LTD
13 Kaki Bukit Road 4 Bartley Biz Centre #03-29
Singapore 417807
Tel:6702 4282 Fax:6702 4202

Page No. 2

Vehicle No. GBG5666K SUZUKI EVERY

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	LABOUR		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	1600.00	800
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1200.00	800
3	To remove , fefix wiring system at accident damage areas and check for proper function	150.00	30
4	To perform anti-rust treatment on affected areas	210.00	60
5	Cavity treatment on New parts	120.00	X
6	To remove and refix rear bootlid mechanism	150.00	80
7	To conduct water seepage test	120.00	X
8	To remove and refix rear windscreen	120.00	✓
Labour Total :		3670.00	
TOTAL (PARTS & LABOUR):		11907.31	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 4488.25

L/S: 3.61K ✓

06 days.