

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG19019374/ARA3Q2  
**Date:** 17/05/2021REFERENCE

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  |              |
| <b>Claimant Vehicle No :</b> | GBG4808A                             | <b>Insured Vehicle No :</b> | SMG2454U     |
| Date of Loss:                | 19/10/2019                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 1359916756SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                               |             |                   |
|-----------------------------|-----------------------------------------------|-------------|-------------------|
| Reg No:                     | <b>GBG4808A</b>                               | Engine No:  | K9KC400D057140    |
| Make & Model:               | NISSAN NV200, 1.5 D MT ABS AIRBAG 2WD 6DR (A) | Chassis No: | VSKYBAM20Z0145575 |
| Reg. Date:                  | 21/08/2017 (Man. Year: 2017)                  | Odometer:   | 66446 km          |
| Colour:                     | White                                         |             |                   |
| Engine Capacity:            | 1461 cc                                       |             |                   |
| Market Value/New Car Price: | N/A                                           |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b>             |             |                   |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |     |                         |     |                          |     |
|--------------------------|-----|-------------------------|-----|--------------------------|-----|
| General Condition:       |     | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification:    | No  | Pre-accident Condition:  |     |

CONDITION OF TYRES

|                   |              |                  |              |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size:  | 175/70 R14   | Rear Tyre Size:  | 175/70 R14   |
| Front Left Side:  | Maxtrex 6 mm | Rear Left Side:  | Maxtrex 6 mm |
| Front Right Side: | Maxtrex 6 mm | Rear Right Side: | Maxtrex 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 6,068.00          | 3,925.50          | 2,142.50          | 35.31         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 2,290.00          | 1,720.00          | 570.00            | 24.89         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>8,358.00</b>   | <b>5,645.50</b>   | <b>2,712.50</b>   | <b>32.45</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>4,500.00</b>   |                   |               |

|                                                 |                 |                 |                 |              |
|-------------------------------------------------|-----------------|-----------------|-----------------|--------------|
| <b>Nett Amount (S\$)</b>                        | <b>8,358.00</b> | <b>4,500.00</b> | <b>3,858.00</b> | <b>46.16</b> |
| <b>+ Loss of Use (6.0 x S\$60.00/day) (S\$)</b> |                 | 360.00          |                 |              |
| <b>+ Doc/Search Fee (S\$)</b>                   |                 | 7.45            |                 |              |
| <b>Nett Liability (S\$)</b>                     |                 | <b>4,867.45</b> |                 |              |

INSPECTION

Date of Assignment: 25/10/2019

Date Inspected: 31/10/2019

Estimated Period of Repair: 6.0 days

Inspected At:

Our Bro's Workshop (s) Pte Ltd (HQ)  
 10 Kaki Bukit Road 2, #03-37/38 First East Centre  
 Singapore 417868

**Adjuster:** ADRIAN LING**Manager:** Jaslin Kok Chin Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                           | Condition     | Repairer's | Amount       |
|-----|-----|----------|---------------------------------------|---------------|------------|--------------|
| 1   | 1   |          | *RR BUMPER ASSY                       | Deformed      | 490.00 F   | *490.00 FN   |
| 2   | 1   |          | *RR LH DOOR ASSY                      | Distorted     | 1,150.00 F | *1,150.00 FN |
| 3   | 1   |          | *RR RH DOOR ASSY                      | Dented        | 1,450.00 F | *1,450.00 FN |
| 4   | 1   |          | *RR LH TOP DOOR LOCK ASSY             | Not Necessary | 110.00 F   | *- FN        |
| 5   | 1   |          | *RR LH BOTTOM DOOR LOCK ASSY          | Damaged       | 110.00 F   | *110.00 FN   |
| 6   | 1   |          | *RR RH TOP DOOR LOCK ASSY             | Not Necessary | 110.00 F   | *- FN        |
| 7   | 1   |          | *RR RH BOTTOM DOOR LOCK ASSY          | Damaged       | 110.00 F   | *110.00 FN   |
| 8   | 1   |          | *RR DOORS OPENING PANEL WEATHERSTRIP  | Cut           | 120.00 F   | *120.00 FN   |
| 9   | 1   |          | *REVERSE SENSOR                       | Damaged       | 160.00 F   | *160.00 FN   |
| 10  | 2   |          | *RR DOOR LOCK CHECK LINK BOTTOM       | Not Necessary | 76.00 F    | *- FN        |
| 11  | 2   |          | *RR DOOR LOCK CHECK TOP               | Not Necessary | 76.00 F    | *- FN        |
| 12  | 1   |          | *RR END PANEL ASSY                    | Distorted     | 1,390.00 F | *485.00 FN   |
| 13  | 2   |          | *RR LH DOOR HINGE                     | Not Necessary | 220.00 F   | *- FN        |
| 14  | 2   |          | *RR RH DOOR HINGE                     | Not Necessary | 216.00 F   | *- FN        |
| 15  | 1   |          | *COMPANY STICKER FOR THE RR BOTH DOOR | Necessary     | 200.00 F   | *200.00 FN   |
| 16  | 1   |          | *6 PAX STICKER                        | Necessary     | 10.00 F    | *10.00 FN    |
| 17  | 1   |          | *70KM/H STICKER                       | Necessary     | 10.00 F    | *10.00 FN    |
| 18  | 1   |          | *SILLICONE FOR GLASS                  | Necessary     | 60.00 FS   | *60.00 FS    |

F=Franchise part. S=SpcNett. N=NettItemDisc.

|                                                           |                 |                 |
|-----------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                   | <b>6,068.00</b> | <b>4,355.00</b> |
| <b>- Nett Item Discount on N Items 0.00/10.00% (\$\$)</b> | 0.00            | 429.50          |
| <b>Total Parts (\$\$)</b>                                 | <b>6,068.00</b> | <b>3,925.50</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                     | Lab.Type | Repairer's      | Amount          |
|---------------------------------|-----------------------------------------------------------------|----------|-----------------|-----------------|
| <u>Labour Items</u>             |                                                                 |          |                 |                 |
| 1                               | TO REMOVE BOTH DOOR GLASS AND REFIX                             | New      | 240.00          | 120.00          |
| 2                               | SPRAY PAINT ON INNER PANEL AND AFFECTED AREA WORKS              | New      | 850.00          | 750.00          |
| 3                               | LABOUR CHARGE TO PANEL BEAT ,TRANSFER PARTS ,ADJUST AND REPLACE | New      | 1,200.00        | 850.00          |
| <b>Gross Labour Cost (\$\$)</b> |                                                                 |          | <b>2,290.00</b> | <b>1,720.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >