

COY/ALG19019314/Adas

GBG4808A
NISSAN NV200
ESTIMATE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: *[Signature]*
Date: *[Date]*

TPAIG.
Jia le.

VSKYBAM2020145575

NO

- 1 RR BUMPER ASSY *Deformed*
- 2 RR LH DOOR ASSY *Distorted*
- 3 RR RH DOOR ASSY *Deformed*
- 4 RR LH TOP DOOR LOCK ASSY *New*
- 5 RR LH BOTTOM DOOR LOCK ASSY *Damaged*
- 6 RR RH TOP DOOR LOCK ASSY *New*
- 7 RR RH BOTTOM DOOR LOCK ASSY *Damaged*
- 8 RR DOORS OPENING PANEL WEATHER STRIP *ut*
- 9 REVERSE SENSOR *Damaged*
- 10 TO REMOVE BOTH DOOR GLASS AND REFIX (Labour)
- 11 RR DOOR LOCK CHECK LINK BOTTOM X 2 *2 New*
- 12 RR DOOR LOCK CHECK TOP X 2 *2 New*
- 13 RR END PANEL ASSY *Distorted*
- 14 RR LH DOOR HINGE X 2 *2 New*
- 15 RR RH DOOR HINGE X 2 *2 New*
- 16 COMPANY STICKER FOR THE RR BOTH DOOR *New*
- 17 6 PAX STICKER *2 New*
- 18 70KM/H STICKER *2 New*
- 19 SPRAY PAINT ON INNER PANEL AND AFFECTED AREA WORKS
- 20 LABOUR CHARGE TO PANEL BEAT, TRANSFER PARTS, ADJUST AND REPLACE
- 21 SILICONE FOR GLASS *New*

QUANTITY	PRICE	TOTAL
1	490	✓ 490 NETT
1	1150	✓ 1150 NETT
1	1450	✓ 1450 NETT
1	110	X 110 NETT
1	110	✓ 110 NETT
1	110	X 110 NETT
1	110	✓ 110 NETT
1	120	✓ 120 NETT
1	160	✓ 160 NETT
1	240	120 240 NETT
2	38	X 76 NETT
2	38	X 76 NETT
1	1390	✓ 1390 NETT 485
2	110	X 220 NETT
2	108	X 216 NETT
1	200	✓ 200 NETT
1	10	✓ 10 NETT
1	10	✓ 10 NETT
1	850	750 850 NETT
1	1200	850 1200 NETT
1	60	✓ 60 NETT S/Nett
TOTAL		8358

Items: 4295
Len 10%: 386550
S.N: 60

Labour: 1720
total: 564550
1/8 4.5K
06 Days

4.5K