

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL: 6441 5655 FAX: 6441 5355/6243 8121
R.O.C No: 200104141D GST Reg. No. 20-0104141-D

TO : SXXX8190H
GUNASILAN RACHAEL VANITHA
NO

SINGAPORE
TEL : FAX :
PH : 91082084
ATIN :

ESTIMATE BILL

Number : EB00005320
Date : 01/11/2019
Case No : AD00010764
Vehicle No : SLU9218C
Chassis : RN61062520
Year of Mfr 2008
Policy No
Model : HONDA STREAM

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	TAILGATE	1.0	903.20	20	722.56
2	TAILGATE EMBLEM	1.0	35.00	20	28.00
3	TAILGATE LOGO - STREAM	1.0	24.70	20	19.76
4	TAILGATE INNER LOCK	1.0	181.50	20	145.20
5	TAILGATE DAMPER LH	1.0	118.60	20	94.88
6	TAILGATE DAMPER RH	1.0	118.60	20	94.88
7	REAR FENDER LAMP RH	1.0	352.80	20	282.24
8	END PANEL	1.0	306.70	20	245.36
9	REAR BUMPER	1.0	588.60	20	470.88
10	REAR BUMPER RETAINER RH	1.0	19.40	20	15.52
11	REAR BUMPER RETAINER LH	1.0	19.40	20	15.52
12	TAIL LAMP PANEL RH	1.0	145.90	20	116.72
13	REAR EXHAUST PIPE	1.0	514.20	20	411.36
14	REAR BUMPER BRACKET RH	1.0	20.90	20	16.72
15	REAR BUMPER BRACKET LH	1.0	20.90	20	16.72
16	TAILGATE WINDSCREEN MOULDING	1.0	65.00	20	52.00
List Price - Parts Sub Total					2,748.32
17	WINDSCREEN SEALANT	2.0	24.00	0	48.00
18	REVERSE SENSOR	1.0	280.00	0	280.00
19	REVERSE CAMERA	1.0	580.00	0	580.00
20	REAR FENDER RH - REPAIR	1.0			
21	REAR FLOOR PANEL - REPAIR	1.0			
Special Nett Price - Parts Sub Total					908.00
Parts Total					3,656.32
22	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	1,000.00	0	1,000.00
23	SPRAY PAINT ON THE AFFECTED AREAS	1.0	900.00	0	900.00
24	ANTI-RUST COATING	1.0	300.00	0	300.00
25	TO REMOVE & REFIT WINDSCREEN	1.0	180.00	0	180.00
26	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0	150.00
Labour 1 Sub Total					2,530.00

E. & O. E.

CUSTOMER SIGNATURE

Authorised by Repairer

Signature

Page 1 of 2

* N = Item not subjected to GST

HOCK WAH MOTOR WORKSHOP PTE LTD

AUTHORISED SIGNATURE

Issued by : Anysia