



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

TAN TIEN POH

30/10/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP111

vic

WSP2221622A274498

Accident date: 30/10/2019

Estimated repair cost for vehicle no: SKB1012T MERCEDES S320L 3.0 A '16

CHASSIS: WDD2221622A274498

S/n	Qty	Items	U/price	Amount
1	1	Rear R/H Door <i>Dented</i>		\$3,950.00 3280
2	2	Rear R/H Door Hinge <i>Not Nec</i>	\$245.00	\$490.00 X
3	1	Rear R/H Door Glass Top Chrome <i>Not Nec</i>		\$316.00 X
4	1	Rear R/H Door Glass Lower Chrome <i>Not Nec</i>		\$420.00 X
5	1	Rear R/H Door Lower Moulding <i>Not Nec</i>		\$205.00 X
6	1	Rear R/H Door Lower Chrome <i>Not</i>		\$320.00 ✓
7	1	Rear R/H Door Weatherstrip <i>Nec</i>		\$330.00 ✓
8	2	Rear R/H Door Frame Sticker <i>Nec</i>	\$95.00	\$190.00 ✓
9	1	Rear R/H Door Inner Lock <i>Damaged</i>		\$855.00 ✓
10	1	Rear R/H Door Inner Trim Board <i>Not Nec</i>		\$3,570.00 X
11	10	Rear R/H Door Inner Trim Board Clip <i>Not Nec</i>	\$8.00	\$80.00 X
12	1	Rear R/H Door Window Regular & Motor Assy <i>Damaged</i>		\$1,925.00 995
13	1	Rear R/H Door Window Sunshade Motor Assy <i>Not Nec</i>		\$2,380.00 X
14	1	Rear R/H Door Pillar <i>Repair</i>		\$3,890.00 X
15	1	Rear R/H Door Frame Panel <i>Repair</i>		\$4,810.00 X
16	1	Rear R/H Fender <i>Welded</i>		\$6,340.00 5488
17	1	Rear R/H Tyre <i>Punctured</i>		\$680.00 380(SW)
18	1	Rear R/H Rim <i>Not</i>		\$2,550.00 150(SW) X
19	1	Rear R/H Wheel Hub Cover <i>Not Nec</i>		\$155.00 X
20	1	Rear R/H Lower Arm		\$580.00 ✓
21	1	Rear R/H Upper Arm <i>But</i>		\$685.00 ✓
22	1	Rear R/H Control Arm		\$695.00 ✓
23	1	Rear R/H Knuckle Arm & Bearing Assy <i>Damaged</i>		\$2,270.00 1940
24	1	Rear R/H Shock Absorber <i>Damaged</i>		\$4,855.00 X 4570
25	1	Rear R/H Drive Shaft <i>Not Nec</i>		\$3,510.00 X
26	1	Rear Bumper <i>Repair</i>		\$2,265.00 X
27	10	Rear Bumper Clip <i>Not Nec</i>	\$8.00	\$80.00 X

28	1	R/H Rocker Panel Skirt	<i>Deland</i>	\$1,290.00	866
29	10	R/H Rocker Panel Skirt Clip	<i>nu</i>	\$10.00	\$100.00 30
				Subtotal:-	<u>\$49,786.00</u>

20824
18741.60 SN: 1880

Labour charges

To remove & refit rear R/H door, glass, lock, rubber, frame sticker, trim board, regulator motor & sunshade motor		\$480.00	150
To remove & refit rear windscreen		\$160.00	120
Gum		\$80.00	✓
To remove & refit rear R/H fuel tank		\$380.00	120
To remove & refit rear drive shaft & undercarriage		\$680.00	350
To check wheel alignment		\$150.00	80
To check wiring		\$200.00	30
To reset computer		\$450.00	150
Towing fee		\$150.00	✓
Tuff kote	3730	\$200.00	100
Panel beating		\$2,400.00	1200
Spray painting		\$2,000.00	1200
		Subtotal:-	<u>\$7,330.00</u>

Total:- \$57,116.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 24371.60
h/s: 19.5K
~~10~~ Dup.
10

19.5K