

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9999D**

**AAD1910-231**

*Not Authorized*  
*L/Sing &*

Vehicle No.:  
Chassis No.:  
Vehicle Make:  
Vehicle Model: **31 OCT 2019**  
Date of Accident :  
Third Party Insurer :  
Date of Registration:

**SHB 9999D**  
VF1ABL15AUC275172  
RENAULT  
LATITUDE  
27.10.19  
**TOKIO MARINE**  
30/10/2013

PART		LIST	
1	1 BUMPER COVER REAR	\$ <i>Bt</i> 561.70	✓
2	1 BUMPER LOWER REAR	\$ <i>Bt 10.1</i> 411.90	✓
3	1 BUMPER BRACKET CTR REAR	\$ <i>CM</i> 98.10	✓
4	1 BUMPER BRACKET SIDE RH REAR	\$ <i>Sm</i> 82.10	X
5	1 BUMPER RETAINER RH REAR	\$ <i>Sm</i> 59.80	X
6	1 BUMPER REFLECTOR RH	\$ <i>CM</i> 16.60	✓
7	1 BUMPER BRACKET SIDE LH REAR	\$ <i>Sm</i> 80.80	X
8	1 BUMPER RETAINER LH REAR	\$ <i>Sm</i> 54.20	X
9	1 BUMPER REFLECTOR LH	\$ <i>CM</i> 16.60	✓
10	1 BUMPER BEAM REAR	\$ <i>Bt</i> 547.80	✓
11	1 BUMPER BEAM BRACKET LH REAR	\$ <i>D17</i> 114.50	✓
12	1 BUMPER BEAM BRACKET RH REAR	\$ <i>D17</i> 100.90	✓
13	1 BUMPER BLOCK LH REAR	\$ <i>Sm</i> 75.70	X
14	1 BUMPER BLOCK RH REAR	\$ <i>Sm</i> 76.50	X
15	1 BUMPER HARNESS REAR	\$ <i>Sm</i> 301.10	X
16	1 BOOT REAR	\$ <i>Bt</i> 1,677.20	✓
17	1 BOOT FINISHER	\$ <i>Way</i> 344.70	✓
18	1 BOOT WHEATERSTRIP	\$ <i>D17/11w</i> 178.20	<i>508sm</i>
19	1 BOOT REFLECTOR LAMP LH	\$ <i>CM</i> 277.70	✓
20	1 BOOT REFLECTOR LAMP RH	\$ <i>CM</i> 277.70	✓
21	1 BOOT BADGE 'RENAULT'	\$ <i>Mc</i> 82.40	✓
22	1 BOOT BADGE	\$ <i>Mc</i> 95.80	✓
23	1 BOOT STRUT LH	\$ <i>Sm</i> 145.10	X
24	1 BOOT STRUT RH	\$ <i>Sm</i> 145.10	X
25	1 BOOT HINGE LH	\$ <i>H</i> 254.20	X
26	1 BOOT HINGE RH	\$ <i>H</i> 253.80	X
27	1 BOOT INNER TRIM BOARD	\$ <i>Sm</i> 611.00	X

**Trans-cab Auto Services Pte Ltd**

**AAD1910-231**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9999D**

28	1	BOOT SWITCH	\$	S <sub>2</sub>	113.00	X
29	1	BOOT LOCK	\$	R <sub>2</sub>	246.60	✓
30	1	BOOT LOCK CATCH	\$	R	41.70	X
31	2	LICENCE PLATE LAMP	\$	S <sub>2</sub>	26.30	X
32	2	BOOT RUBBER PLUG	\$	S <sub>2</sub>	139.30	X
33	2	BOOT BUFFER	\$	S <sub>2</sub>	26.80	X
34	1	BOOT LOCK LINKAGE	\$	S <sub>2</sub>	20.60	X
35	1	BOOT LOCK LINKAGE HOLDER	\$	S <sub>2</sub>	99.50	X
36	1	BOOT TRIM BOARD	\$	Return	611.00	✓
37	1	FENDER PANEL INNER TRIM REAR LH	\$	S <sub>2</sub>	671.45	X
38	1	FENDER PANEL REAR LH	\$	R	1,933.20	X
39	1	WHEELARCH REAR LH	\$	S <sub>2</sub>	181.60	X
40	1	FENDER PANEL INNER TRIM REAR RH	\$	S <sub>2</sub>	671.45	X
41	1	FENDER PANEL REAR RH	\$	R	1,933.20	X
42	1	WHEELARCH REAR RH	\$	S <sub>2</sub>	275.40	X
43	1	AIR VENT LH	\$	S <sub>2</sub>	59.40	X
44	1	AIR VENT RH	\$	S <sub>2</sub>	59.40	X
45	1	TAILLAMP RH	\$	M <sub>3</sub> M	313.10	✓
43	1	TAILLAMP PANEL RH	\$	R <sub>2</sub>	401.40	✓
44	1	TAILLAMP LH	\$	M <sub>3</sub> M	401.40	✓
45	1	TAILLAMP PANEL LH	\$	R	401.40	X
46	1	OUTER PANEL REAR (End Panel)	\$	R <sub>2</sub>	745.80	✓
47	1	OUTER PANEL REAR (End Panel)TRIM	\$	D <sub>1</sub>	404.56	✓
48	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	1,229.40	X
49	1	SPARE WHEEL PANEL TRIM	\$	S <sub>2</sub>	612.21	X
50	1	SPARE TYRE BOARD	\$	S <sub>2</sub>	680.90	X
51	1	EXHAUST REAR	\$	R	5,263.60	X
52	1	EXHAUST CAP REAR	\$	R	125.40	X
<b>TOTAL</b>			<b>\$</b>		<b>24,630.27</b>	
<b>10%</b>			<b>\$</b>		<b>2,463.03</b>	
			<b>\$</b>		<b>22,167.24</b>	

**Special Nett**

1	1SET PARKING AID	\$	Shay	700.00	✓
2	1SET REAR BUMPER CLIP	\$	R <sub>2</sub>	66.00	✓
3	1SET BUMPER BRACKET CTR CLIP	\$	R <sub>2</sub>	33.00	✓

**Trans-cab Auto Services Pte Ltd**

**AAD1910-231**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9999D**

4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET BUMPER RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET BUMPER RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	na	16.00	X
11	1 EXHAUST BRACKET REAR	\$	na	24.80	X
12	1SET BOOT FINISHER CLIP	\$	na	24.20	✓
13	1 BOOT STICKER "Trans-cab"	\$	na	30.00	—
14	1 BOOT STICKER "6555-3333"	\$	na	30.00	—
15	1 BOOT INNER TRIM CLIP	\$	na	45.00	X
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	X
17	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	su	385.00	X
18	1 SPARE TYRE	\$	su	330.00	X
19	1 FENDER INNER TRIM CLIP LH	\$	na	28.00	X
20	1 TAILLAMP CLIP RH	\$	na	5.00	✓
21	2 REAR WINDSCREEN SEALANT	\$	na	80.00	} X
22	1 WINDSCREEN MOULDING	\$	na	100.00	
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
24	1 TAILLAMP CLIP LH	\$	na	5.00	
25	1 Rear Bumper Protector	\$	na	100.00	
26	1 REAR LEFT TYRE	\$	su	300.00	
27	1 REAR LEFT TYRE RIM	\$	su	380.00	
28	1 REAR RIGHT TYRE	\$	su	300.00	
29	1 REAR RIGHT TYRE RIM	\$	su	380.00	
30	1SET FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	
31	1 FENDER INNER TRIM CLIP RH	\$	na	28.00	
32	1SET Rear licence plate with holder	\$	na	80.00	45.00

**TOTAL \$ 3,788.00**

**TOTAL PARTS \$ 25,955.24**

**LABOUR**

Putty And Spray Painting Of The Affected Portion. \$ 9,000.00 *sd*

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9999D****AAD1910-231**

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	9,000.00	<i>Book</i>
To supply and re-do rear luggage floor panel insulation padding.	\$	<i>nn</i> 380.00	<i>X</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	<i>Book</i>
To drop rear exhaust box, renew the same, to repair	\$	170.00	<i>Book</i>
Towing Fees	\$	<i>nn</i> 170.00	<i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	} <i>Book</i>
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	<i>X</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00	<i>Book</i>
To repair and realign rear exhaust pipe.	\$	<i>5</i> 170.00	<i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>5</i> 170.00	<i>X</i>
To reinstall rear bumper parking sensor.	\$	<i>5</i> 170.00	<i>X</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>5</i> 380.00	<i>X</i>
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	<i>5</i> 170.00	<i>X</i>

**Trans-cab Auto Services Pte Ltd**

**AAD1910-231**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9999D**

To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>nn</i>	380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i>	380.00	X
To Check Electrical Lighting Concerned.	\$		170.00	<i>201</i>
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	<i>nn</i>	380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i>	380.00	X
<b>TOTAL</b>	<b>\$</b>		<b>22,370.00</b>	
<b>Over All Total</b>	<b>\$</b>		<b>48,325.24</b>	

**(LUMP SUM) Repair Days**      *30 DAYS*  
*6 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: