

ASS. REC. BY:

REF: TM1/CC3/TM190193921 kvf302


*Kenneth*

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD/TP/WS/TP RES/OD RES/EVA/INV/MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s Trans Cab  
 of \_\_\_\_\_  
 Insured: YN 6072H  
 Policy No. MT104898  
 Claims No. M1908654  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: £ 31,900  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: 20% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SHB 9999B Yr Regn: 10 13  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Traller or \_\_\_\_\_  
 Make: Renault Latitude c.c. 1995  
 Colour M. White / Red A/C: Insured / Std / NI / NA  
 Sp. Reading 683400 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: V11ABL15AUC 275172  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Mod: NI / S/Rim / STD A/Rim or  
 Tyre Size: F: Sailun 215/60R16  
 R: Giti  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_  
 Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 9 mm R/Bal. 8 mm  
 L/Bal. 9 mm L/Bal. 8 mm  
 D.O.A. 27/10/19 D.O.I. 31/10/19  
 Survey held at \_\_\_\_\_  
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>1</u>	<u>File pass to GIA not ready</u>
<u>SHB 9999B - X</u>	
<u>11/11/19</u>	<u>Email GIA &amp; preli revised to Tmz</u>
<u>23/12/19</u>	<u>L1 Top 8 7800 (Real 40,525.24, 8490 confirmed by email)</u>

RECEIVED 24 DEC 2019

Date/Time, File Pass to?  : Preli. Report  
 : Final Report

2) 23/12 - typist

Report Format: menmen  
 Lump Sum / I.B.I: (\$) 7800

Days Of Repair: 6  
 Resurvey No. of Trip: 1

Add Fee:  : Site Insp (\$) )  
 : Interview (\$) )  
 : Tech Invs (\$) )  
 : Weekend (\$) )

Survey Fee:

Transportation:	<u>250</u>
S - RS - SI	<u>11</u>
Fuel/ops	
Others	
TOTAL	<u>261</u>

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Nov 2019		05 Nov 2019 11:45 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b>			<b>[Created by insurer]</b>						
Insured:	RJ CONTRACT PTE LTD, Co. Reg. No.: 200916424N								
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K								
Vehicle Reg. No.:	SHB9999D	Date of Loss:	27/10/2019 02:00 - :59						
Claim Type:	TP / M1908654	Policy/Cover Note No.:	MT104898 (Comprehensive) Coverage: 07/08/2019 - 06/08/2020						
Vehicle Reg. No. (Insured):	YN6072H	Policy No. (Claimant):							
		Excess:	S\$5,000.00						
Repairer:	Trans-Cab Services Pte Ltd (HQ) 2 Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666								
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by <b>Dillen Senthilan so Selvarajoo</b> ]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... <b>[Final Rpt due 14/11/2019]</b>								
Driver/Custodian (Insured):	ALLIMUTHU AYYAPPAN (0), NRIC: G6533127L Email:								
<b>ASSOCIATED MAIL RECEIVED</b>			<a href="#">View All</a>	<a href="#">Compose Case Mail</a>					
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>			<a href="#">View All</a>	<a href="#">Search Tasks</a>					
			<a href="#">Create New Task</a>	<a href="#">Complete</a>					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**Veron Chen (LKKAuto)**

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Tuesday, 5 November 2019 8:42 AM  
**To:** 'motorclaims'; SUR  
**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP -TRANS-CAB AUTO SERVICES PTE LTD, DOA: 27/10/2019, SHB 9999B (TP VEHICLE), YN 6072H (OI VEHICLE)  
**Attachments:** EST.pdf; PRELI REVISED.pdf; POLICE REPORT.pdf; GIA.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHB 9999B at M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63 SINGAPORE 569111 on 31/10/2019

Enclosed herewith a copy of TP's GIA report and estimated cost of repair.

Kindly create claim in merimen for our necessary action.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**Veron Chen (LKKAuto)**

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Monday, 23 December 2019 8:53 AM  
**To:** Ng Wai Yin; SUR  
**Cc:** jasminetan@transcab.com.sg  
**Subject:** RE: PENDING DOCUMENTS -- AAD1910-231 SHB999B DOA: 27.10.19  
**Attachments:** MARK EST.pdf

Dear Wai Yin,

WITHOUT PREJUDICE

Lump Sum \$7800 before GST @ 6 working days.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Ng Wai Yin <waiyin.ng@transcab.com.sg>  
**Sent:** Friday, 20 December 2019 9:42 AM  
**To:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>  
**Subject:** RE: PENDING DOCUMENTS -- AAD1910-231 SHB999B DOA: 27.10.19

Hi Veron

1) SHB 9999B-DOA: 27/10/2019 – NBV \$ 31,911.75

Thank You

Best Regards,

**Ng Wai Yin**

Finance Department

TEL: 6603 1265 Ext.308

**\*\*\* Please be reminded that all claims correspondence to be send to [claims@transcab.com.sg](mailto:claims@transcab.com.sg)**

TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63

Singapore 569111

Tel: 6287 6666 Fax: 6287 7764

---

**From:** Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]  
**Sent:** Tuesday, 17 December, 2019 8:45 AM  
**To:** Ng Wai Yin <waiyin.ng@transcab.com.sg>  
**Subject:** PENDING DOCUMENTS

Dear Wai Yin,

Please forward documents, book value and resurvey photos.

- 1) SHD 5679T-DOA :9/112019
- 2) SHB 9999B-DOA: 27/10/2019

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

**Veron Chen (LKKAuto)**

---

**From:** Ng Wai Yin <waiyin.ng@transcab.com.sg>  
**Sent:** Monday, 23 December 2019 11:27 AM  
**To:** Veron Chen (LKKAuto)  
**Cc:** 'Jasmine Tan'; SUR  
**Subject:** FW: PENDING DOCUMENTS -- AAD1910-231 SHB999B DOA: 27.10.19  
**Attachments:** MARK EST.pdf

Without Prejudice

Dear Veron

Amount confirmed \$ 7,800 (before GST).

Thank You  
Best Regards,  
**Ng Wai Yin**  
Finance Department  
TEL: 6603 1265 Ext.308

**\*\*\* Please be reminded that all claims correspondence to be send to [claims@transcab.com.sg](mailto:claims@transcab.com.sg)**

TRANS-CAB SERVICES PTE LTD  
No. 2 Ang Mo Kio Street 63  
Singapore 569111  
Tel: 6287 6666 Fax: 6287 7764

---

**From:** Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]  
**Sent:** Monday, 23 December, 2019 8:53 AM  
**To:** Ng Wai Yin <waiyin.ng@transcab.com.sg>; SUR <sur@lkkauto.com>  
**Cc:** jasminetan@transcab.com.sg  
**Subject:** RE: PENDING DOCUMENTS -- AAD1910-231 SHB999B DOA: 27.10.19

Dear Wai Yin,

WITHOUT PREJUDICE

Lump Sum \$7800 before GST @ 6 working days.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Ng Wai Yin <waiyin.ng@transcab.com.sg>  
**Sent:** Friday, 20 December 2019 9:42 AM

**To:** Veron Chen (LKKAuto) <[veronchen@lkkauto.com](mailto:veronchen@lkkauto.com)>  
**Subject:** RE: PENDING DOCUMENTS -- AAD1910-231 SHB999B DOA: 27.10.19

Hi Veron

1) SHB 9999B-DOA: 27/10/2019 – NBV \$ 31,911.75

Thank You  
Best Regards,  
**Ng Wai Yin**  
Finance Department  
TEL: 6603 1265 Ext.308

**\*\*\* Please be reminded that all claims correspondence to be send to [claims@transcab.com.sg](mailto:claims@transcab.com.sg)**

TRANS-CAB SERVICES PTE LTD  
No. 2 Ang Mo Kio Street 63  
Singapore 569111  
Tel: 6287 6666 Fax: 6287 7764

---

**From:** Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]  
**Sent:** Tuesday, 17 December, 2019 8:45 AM  
**To:** Ng Wai Yin <[waiyin.ng@transcab.com.sg](mailto:waiyin.ng@transcab.com.sg)>  
**Subject:** PENDING DOCUMENTS

Dear Wai Yin,

Please forward documents, book value and resurvey photos.

- 1) SHD 5679T-DOA :9/112019
- 2) SHB 9999B-DOA: 27/10/2019

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :[sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

> [Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	878K
<b>Vehicle Details</b>	
Vehicle No.:	SHB9999D
Vehicle to be Exported:	Yes
Intended Deregistration Date:	04 Nov 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	M9R8839C000620
Chassis No.:	VF1ABL15AUC275172
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	30 Oct 2013
First Registration Date:	30 Oct 2013
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Oct 2021
PARF Rebate Amount:	\$8,123.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	29 Oct 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$61,324.00
COE Rebate Amount:	\$15,207.00
<b>Total Rebate Amount:</b>	<b>\$23,330.00</b>
<b>Message</b>	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 04 Nov 2019

OK

> [Back to OneMotoring](#)

### Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	878K
<b>Vehicle Details</b>	
Vehicle No.:	SHB9999D
Vehicle to be Exported:	Yes
Intended Deregistration Date:	30 Oct 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	M9R8839C000620
Chassis No.:	VF1ABL15AUC275172
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	30 Oct 2013
First Registration Date:	30 Oct 2013
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Oct 2021
PARF Rebate Amount:	\$8,123.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	29 Oct 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$61,324.00
COE Rebate Amount:	\$15,289.00
<b>Total Rebate Amount:</b>	<b>\$23,412.00</b>
<b>Message</b>	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 30 Oct 2019

OK

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report	30/10/2019 14:05
Date Of Accident	27/10/2019 02:20
Exact Location Of Accident	ORCHARD ROAD
Country/State of Loss	SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB9999D
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666

#### Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

#### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VFX/P1680520
Cover Note Number	

#### Driver

Name of Driver	TAN KOK CHENG
NRIC No	S2005832C
Date Of Birth	20/06/1952
Occupation	OUTDOOR
Date Of Driving Pass	05/01/1970
Driving Experience	49 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82691111
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	BLK 430B YISHUN AVE 11 #09-402
Postcode	762430
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : CHAMEERA MADHUSANKA GENDER: : MALE
Passenger 2	NAME: : CONGANIGE RUSITH DESHAN ANTHONY GENDER: : MALE
Passenger 3	NAME: : SENANAYAKE ARACHCHILAGE HASTHA LAKDINA GENDER: : MALE
Passenger 4	NAME: : CHATHURANGA DE COSTA GENDER: : MALE

### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	10 UBI AVENUE 3
Police Station Address	<b>ROAD:</b> 10 UBI AVENUE 3 , <b>POSTCODE:</b> 408865 , <b>COUNTRY:</b> SINGAPORE
Police Station Contact	<b>TEL NO:</b> - <b>FAX NO:</b>
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

### Circumstances of Accident

PLEASE SEE ATTACH POLICE REPORT : T/20191027/7001

### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN6072H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	ALLIMUTHU AYYAPPAN
NRIC/Passport Number	034678189
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF INJURED PERSON 1

Name	TAN KOK CHENG
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SHB9999D
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

#### DETAILS OF INJURED PERSON 2

Name	CHAMEERA MADHUSANKA
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SHB9999D
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

#### DETAILS OF INJURED PERSON 3

Name	CONGANIGE RUSITH DESHAN ANTHONY
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SHB9999D
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

#### DETAILS OF INJURED PERSON 4

Name	SENANAYAKE ARACHCHILAGE HASTHA LAKDINA
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SHB9999D
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	YES
Address	

Postcode

**DETAILS OF INJURED PERSON 5**

Name CHATHURANGA DE COSTA

Approximate Age

Injuries Sustain

Injured person in which vehicle? SHB9999D

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

plc see attach police report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

POLICE REPORT Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20191027/7001

1 of 3

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

Report No. T/20191027/7001

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 27/10/2019 04:53	Vide Report No.: E/20191027/0038	Station Diary No.:
--	-------------------------------------	--------------------

Informant's Particulars			
Name of Informant: TAN KOK CHENG		Address: APT BLK 430B YISHUN AVENUE 11 #09-402 SINGAPORE 762430	
ID Type / ID No.: NRIC NO / S2005832C		Contact No.: Home/Office:	Mobile: 82691111
Nationality: SINGAPORE CITIZEN		Email: kctan1u@gmail.com	
Sex: Male	Age: 67	Date of Birth: 20/06/1952	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation:		Driving Licence Information: Class:	Date of Expiry:

General Information of the Accident				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 27/10/2019 02:20	Type of Location: Straight Road
Location: ORCHARD ROAD				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Traffic Light - Working	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHB9999D	Car				Seriously Damaged	5
YN6072H	Lorry				Seriously Damaged	1

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**



T/20191027/7001

2 of 3

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

Report No. T/20191027/7001

## CONTINUATION OF REPORT

Driver			
Name	TAN KOK CHENG	ID No.	S2005832C
Related Vehicle	SHB9999D (Car)	Contact No.	82691111
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	07	Degree of Injury	Serious

Brief Details.

On 27 October 2019 at around 220AM, I was travel on Orchard Road toward Bras Basah Road. Suddenly I felt two high impact came from the rear. A lorry(YN6072H) rear end into my taxi(SHB9999D).

I will be traveling to Veitnam on 29the October 2019 to 3th October 2019 anything please contact me via WhatsApp(82691111) or gmail(kctan1u@gmail.com).



**SINGAPORE  
POLICE FORCE**



T/20191027/7001

3 of 3

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

Report No. T/20191027/7001

**CONTINUATION OF REPORT**

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:  
Not applicable

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / TPIB /  
NORAMEERA BINTE MOHAMED HUSSEIN  
Contact No.: 65476236

Authentication Stamp  
NP168

Signature Of Informant:  
The identity of the person making this report has  
been authenticated by SingPass. No signature is  
required.

Date/Time:  
27/10/2019 04:53

Classification Of Case:

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9999D**

**AAD1910-231**

*Not Authored*  
*1/1 Sep 8*

Vehicle No.:  
Chassis No.:  
Vehicle Make: **31 OCT 2019**  
Vehicle Model:  
Date of Accident :  
Third Party Insurer :  
Date of Registration:

**SHB 9999D**  
VF1ABL15AUC275172  
RENAULT  
LATITUDE  
27.10.19  
**TOKIO MARINE**  
30/10/2013

PART		LIST	
1	1 BUMPER COVER REAR	\$ <i>Bz</i> 561.70	✓
2	1 BUMPER LOWER REAR	\$ <i>B+ID,1</i> 411.90	✓
3	1 BUMPER BRACKET CTR REAR	\$ <i>CM</i> 98.10	✓
4	1 BUMPER BRACKET SIDE RH REAR	\$ <i>Sm</i> 82.10	X
5	1 BUMPER RETAINER RH REAR	\$ <i>Sm</i> 59.80	X
6	1 BUMPER REFLECTOR RH	\$ <i>CM</i> 16.60	✓
7	1 BUMPER BRACKET SIDE LH REAR	\$ <i>Sm</i> 80.80	X
8	1 BUMPER RETAINER LH REAR	\$ <i>Sm</i> 54.20	X
9	1 BUMPER REFLECTOR LH	\$ <i>CM</i> 16.60	✓
10	1 BUMPER BEAM REAR	\$ <i>Bz</i> 547.80	✓
11	1 BUMPER BEAM BRACKET LH REAR	\$ <i>Diz</i> 114.50	✓
12	1 BUMPER BEAM BRACKET RH REAR	\$ <i>Diz</i> 100.90	✓
13	1 BUMPER BLOCK LH REAR	\$ <i>Sm</i> 75.70	X
14	1 BUMPER BLOCK RH REAR	\$ <i>Sm</i> 76.50	X
15	1 BUMPER HARNESS REAR	\$ <i>Sm</i> 301.10	X
16	1 BOOT REAR	\$ <i>Bz</i> 1,677.20	✓
17	1 BOOT FINISHER	\$ <i>Way</i> 344.70	✓
18	1 BOOT WHEATERSTRIP	\$ <i>Diz/Ad</i> 178.20	<i>50% 89.10</i>
19	1 BOOT REFLECTOR LAMP LH	\$ <i>CM</i> 277.70	✓
20	1 BOOT REFLECTOR LAMP RH	\$ <i>CM</i> 277.70	✓
21	1 BOOT BADGE 'RENAULT'	\$ <i>Mc</i> 82.40	✓
22	1 BOOT BADGE	\$ <i>Mc</i> 95.80	✓
23	1 BOOT STRUT LH	\$ <i>Sm</i> 145.10	X
24	1 BOOT STRUT RH	\$ <i>Sm</i> 145.10	X
25	1 BOOT HINGE LH	\$ <i>H</i> 254.20	X
26	1 BOOT HINGE RH	\$ <i>H</i> 253.80	X
27	1 BOOT INNER TRIM BOARD	\$ <i>Sm</i> 611.00	X

**Trans-cab Auto Services Pte Ltd**

**AAD1910-231**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9999D**

28	1	BOOT SWITCH	\$	Sm	113.00	X
29	1	BOOT LOCK	\$	Na	246.60	✓
30	1	BOOT LOCK CATCH	\$	K	41.70	X
31	2	LICENCE PLATE LAMP	\$	Sm	26.30	X
32	2	BOOT RUBBER PLUG	\$	Sm	139.30	X
33	2	BOOT BUFFER	\$	Sm	26.80	X
34	1	BOOT LOCK LINKAGE	\$	Sm	20.60	X
35	1	BOOT LOCK LINKAGE HOLDER	\$	Sm	99.50	X
36	1	BOOT TRIM BOARD	\$	Return	611.00	✓
37	1	FENDER PANEL INNER TRIM REAR LH	\$	Sm	671.45	X
38	1	FENDER PANEL REAR LH	\$	K	1,933.20	X
39	1	WHEELARCH REAR LH	\$	Sm	181.60	X
40	1	FENDER PANEL INNER TRIM REAR RH	\$	Sm	671.45	X
41	1	FENDER PANEL REAR RH	\$	K	1,933.20	X
42	1	WHEELARCH REAR RH	\$	Sm	275.40	X
43	1	AIR VENT LH	\$	Sm	59.40	✓
44	1	AIR VENT RH	\$	Sm	59.40	X
45	1	TAILLAMP RH	\$	m3cm	313.10	✓
43	1	TAILLAMP PANEL RH	\$	B	401.40	✓
44	1	TAILLAMP LH	\$	m3cm	401.40	✓
45	1	TAILLAMP PANEL LH	\$	K	401.40	X
46	1	OUTER PANEL REAR (End Panel)	\$	B	745.80	✓
47	1	OUTER PANEL REAR (End Panel)TRIM	\$	Di	404.56	✓
48	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	K	1,229.40	X
49	1	SPARE WHEEL PANEL TRIM	\$	Sm	612.21	X
50	1	SPARE TYRE BOARD	\$	Sm	680.90	X
51	1	EXHAUST REAR	\$	K	5,263.60	X
52	1	EXHAUST CAP REAR	\$	K	125.40	X
<b>TOTAL</b>			<b>\$</b>		<b>24,630.27</b>	
<b>10%</b>			<b>\$</b>		<b>2,463.03</b>	
			<b>\$</b>		<b>22,167.24</b>	

**Special Nett**

1	1SET PARKING AID	\$	Shat	700.00	✓
2	1SET REAR BUMPER CLIP	\$	Na	66.00	✓
3	1SET BUMPER BRACKET CTR CLIP	\$	Na	33.00	✓

**Trans-cab Auto Services Pte Ltd**

**AAD1910-231**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9999D**

4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET BUMPER RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET BUMPER RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	na	16.00	X
11	1 EXHAUST BRACKET REAR	\$	na	24.80	X
12	1SET BOOT FINISHER CLIP	\$	na	24.20	✓
13	1 BOOT STICKER "Trans-cab"	\$	na	30.00	—
14	1 BOOT STICKER "6555-3333"	\$	na	30.00	—
15	1 BOOT INNER TRIM CLIP	\$	na	45.00	X
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	X
17	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	su	385.00	X
18	1 SPARE TYRE	\$	su	330.00	X
19	1 FENDER INNER TRIM CLIP LH	\$	na	28.00	X
20	1 TAILLAMP CLIP RH	\$	na	5.00	✓
21	2 REAR WINDSCREEN SEALANT	\$	na	80.00	} X
22	1 WINDSCREEN MOULDING	\$	na	100.00	
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
24	1 TAILLAMP CLIP LH	\$	na	5.00	
25	1 Rear Bumper Protector	\$	na	100.00	
26	1 REAR LEFT TYRE	\$	su	300.00	
27	1 REAR LEFT TYRE RIM	\$	su	380.00	
28	1 REAR RIGHT TYRE	\$	su	300.00	
29	1 REAR RIGHT TYRE RIM	\$	su	380.00	
30	1SET FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	
31	1 FENDER INNER TRIM CLIP RH	\$	na	28.00	
32	1SET Rear licence plate with holder	\$	na	80.00	455a

**TOTAL \$ 3,788.00**

**TOTAL PARTS \$ 25,955.24**

**LABOUR**

Putty And Spray Painting Of The Affected Portion. \$ 9,000.00 *Shol*

**Trans-cab Auto Services Pte Ltd**

AAD1910-231

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9999D

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	9,000.00	<i>book</i>
To supply and re-do rear luggage floor panel insulation padding.	\$	<i>rv</i> 380.00	<i>X</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	<i>book</i>
To drop rear exhaust box, renew the same, to repair	\$	170.00	<i>book</i>
Towing Fees	\$	<i>rv</i> 170.00	<i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	} <i>book</i>
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	
To check steering geometry and computer wheel alignment	\$	<i>rv</i> 220.00	<i>X</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00	<i>book</i>
To repair and realign rear exhaust pipe.	\$	<i>rv</i> 170.00	<i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>rv</i> 170.00	<i>X</i>
To reinstall rear bumper parking sensor.	\$	<i>rv</i> 170.00	<i>X</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>rv</i> 380.00	<i>X</i>
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	<i>rv</i> 170.00	<i>X</i>

**Trans-cab Auto Services Pte Ltd**

**AAD1910-231**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9999D**

To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00	X
To Check Electrical Lighting Concerned.	\$	170.00	<i>201</i>
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	<i>nn</i> 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00	X

**TOTAL** \$ 22,370.00

**Over All Total** \$ 48,325.24

**(LUMP SUM) Repair Days** ~~30 DAYS~~  
*6 days*

*LKK Auto Consultants* hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:



Wearnes Automotive Pte. Ltd.  
28 Leng Kee Road  
Singapore 159105

Telephone: +65 6471 3313  
Facsimile: +65 6471 3393  
Internet: www.renault.com.sg

RECEIVED 18 NOV 2013

GST Reg No. : M2-8920628X  
Tax Invoice No. : R 1014730 - 1014775  
Date : 30/10/2013  
ST: R

Invoice to:  
r05417  
TRANS-CAB SERVICES PTE LTD  
58 DEFU LANE 1  
DEFU INDUSTRIAL ESTATE  
SINGAPORE 539498

Deliver To:  
r05417  
TRANS-CAB SERVICES PTE LTD  
58 DEFU LANE 1  
DEFU INDUSTRIAL ESTATE  
SINGAPORE 539498

Model Latitude 2.0A Diesel	Colour NXD/ / ORIENTAL RED	VSB Refer to Attached	Order No r05417
Engine No Refer To Attached	Chassis No. Refer To Attached	Sales Consultant Jay Tan	Reg No. Refer To Attached

Description	Value/ Unit	Unit	GST (7%) @ 40 unit	Amount (S\$)
Vehicle Price	38,953.40	45	83,334.60	1,836,237.60
Road Tax	2,907.00	45	-	130,815.00
Registration Fee	140.00	45	-	6,300.00
COE Quota Premium	61,324.00	45	-	2,759,580.00
Custom Duty	3,999.60	45	12,598.65	192,580.65
Insurance	1,926.00	45	-	86,670.00
Equipment- Taximeter	600.00	45	1,890.00	28,890.00

Vehicle Total Price incl GST

	5,041,073.25
DOWNPAYMENT	4,536,965.70
Amount payable by Trans-Cab Services Pte Ltd	504,107.55

This is a computer-generated invoice. No signature is required.

E. & O. E.

	Supply	GST
TRANS-CAB SERVICES PTE		
DBS BANK LIMITED	1,397,475.00	97,823.25
Taxable	1,397,475.00	97,823.25
Non-taxable	3,545,775.00	-
	4,943,250.00	97,823.25

Please quote this invoice number when making payment.

Please remit payment to:  
Oversea-Chinese Banking Corporation Limited  
OCBC Centre Branch  
65 Chulia Street, Singapore 049513  
Bank Code: 7339

Branch Code: 501

Bank Account Name: Wearnes Automotive Pte Ltd

Bank Account: 296727-001

SWIFT CODE: OCBCSGSG

Cheques should be crossed and made payable to "Wearnes Automotive Pte Ltd".

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI19019392/KVF3N2  
Date: 27/12/2019

## REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MT104898
Claimant Vehicle No :	SHB9999D	Insured Vehicle No :	YN6072H
Date of Loss:	27/10/2019	Nature of Claim:	TP
		Claim No:	M1908654

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SHB9999D	Engine No:	M9R8839C000620
Make & Model:	RENAULT LATITUDE, 2.0 L (A)	Chassis No:	VF1ABL15AUC275172
Reg. Date:	30/10/2013 (Man. Year: 2013)	Odometer:	683400 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Sailun 9 mm	Rear Left Side:	Giti 8 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Giti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,955.24	7,761.01	18,194.23	70.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	22,370.00	1,960.00	20,410.00	91.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>48,325.24</b>	<b>9,721.01</b>	<b>38,604.23</b>	<b>79.88</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>7,800.00</b>		
<b>(S\$)</b>	48,325.24	7,800.00	40,525.24	83.86
<b>+ GST 7.00/7.00% (S\$)</b>	3,382.77	546.00	2,836.77	83.86
<b>Nett Amount (S\$)</b>	<b>51,708.01</b>	<b>8,346.00</b>	<b>43,362.01</b>	<b>83.86</b>

## INSPECTION

Date of Assignment:	05/11/2019	Inspected At:	Trans-Cab Services Pte Ltd (HQ) 2 Ang Mo Kio Street 63 Singapore 569111
Date Inspected:	31/10/2019		
Estimated Period of Repair:	6.0 days		

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

**REPAIR DETAILS****Reference**

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 27 Dec 2019)
<b>Parts:</b> 143	RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHB9999D)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*BUMPER COVER REAR	Bent	561.70 FL	-	*561.70 FL
2	1		*BUMPER LOWER REAR	Bent/Distorted	411.90 FL	-	*411.90 FL
3	1		*BUMPER BRACKET CTR REAR	Cracked	98.10 FL	-	*98.10 FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	82.10 FL	-	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	59.80 FL	-	*- FL
6	1		*BUMPER REFLECTOR RH	Cracked	16.60 FL	-	*16.60 FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	80.80 FL	-	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	54.20 FL	-	*- FL
9	1		*BUMPER REFLECTOR LH	Cracked	16.60 FL	-	*16.60 FL
10	1		*BUMPER BEAM REAR	Bent	547.80 FL	-	*547.80 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Distorted	114.50 FL	-	*114.50 FL
12	1		*BUMPER BEAM BRACKET RH REAR	Distorted	100.90 FL	-	*100.90 FL
13	1		*BUMPER BLOCK LH REAR	Serviceable	75.70 FL	-	*- FL
14	1		*BUMPER BLOCK RH REAR	Serviceable	76.50 FL	-	*- FL
15	1		*BUMPER HARNESS REAR	Serviceable	301.10 FL	-	*- FL
16	1		*BOOT REAR	Bent	1,677.20 FL	-	*1,677.20 FL
17	1		*BOOT FINISHER	Warped	344.70 FL	-	*344.70 FL
18	1		*BOOT REFLECTOR LAMP LH	Cracked	277.70 FL	-	*277.70 FL
19	1		*BOOT REFLECTOR LAMP RH	Cracked	277.70 FL	-	*277.70 FL
20	1		*BOOT BADGE RENAULT	Necessary	82.40 FL	-	*82.40 FL
21	1		*BOOT BADGE	Necessary	95.80 FL	-	*95.80 FL
22	1		*BOOT STRUT LH	Serviceable	145.10 FL	-	*- FL
23	1		*BOOT STRUT RH	Serviceable	145.10 FL	-	*- FL
24	1		*BOOT HINGE LH	Repair	254.20 FL	-	*- FL
25	1		*BOOT HINGE RH	Repair	253.80 FL	-	*- FL
26	1		*BOOT INNER TRIM BOARD	Serviceable	611.00 FL	-	*- FL
27	1		*BOOT SWITCH	Serviceable	113.00 FL	-	*- FL
28	1		*BOOT LOCK	Dented	246.60 FL	-	*246.60 FL
29	1		*BOOT LOCK CATCH	Repair	41.70 FL	-	*- FL
30	2		*LICENCE PLATE LAMP	Serviceable	26.30 FL	-	*- FL
31	2		*BOOT RUBBER PLUG	Serviceable	139.30 FL	-	*- FL
32	2		*BOOT BUFFER	Serviceable	26.80 FL	-	*- FL
33	1		*BOOT LOCK LINKAGE	Serviceable	20.60 FL	-	*- FL
34	1		*BOOT LOCK LINKAGE HOLDER	Serviceable	99.50 FL	-	*- FL
35	1		*BOOT TRIM BOARD	Deformed	611.00 FL	-	*611.00 FL
36	1		*FENDER PANEL INNER TRIM REAR LH	Serviceable	671.45 FL	-	*- FL
37	1		*FENDER PANEL REAR LH	Repair	1,933.20 FL	-	*- FL
38	1		*WHEELARCH REAR LH	Serviceable	181.60 FL	-	*- FL
39	1		*FENDER PANEL INNER TRIM REAR RH	Serviceable	671.45 FL	-	*- FL
40	1		*FENDER PANEL REAR RH	Repair	1,933.20 FL	-	*- FL
41	1		*WHEELARCH REAR RH	Serviceable	275.40 FL	-	*- FL
42	1		*AIR VENT LH	Serviceable	59.40 FL	-	*- FL
43	1		*AIR VENT RH	Serviceable	59.40 FL	-	*- FL
44	1		*TAILLAMP RH	Mtg Cracked	313.10 FL	-	*313.10 FL
45	1		*TAILLAMP PANEL RH	Bent	401.40 FL	-	*401.40 FL
46	1		*TAILLAMP LH	Mtg Cracked	401.40 FL	-	*401.40 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Reference	Amount
47	1	*TAILLAMP PANEL LH	Repair	401.40 FL	-	*- FL
48	1	*OUTER PANEL REAR (END PANEL)	Bent	745.80 FL	-	*745.80 FL
49	1	*OUTER PANEL REAR (END PANEL) TRIM	Distorted	404.56 FL	-	*404.56 FL
50	1	*SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	Repair	1,229.40 FL	-	*- FL
51	1	*SPARE WHEEL PANEL TRIM	Serviceable	612.21 FL	-	*- FL
52	1	*SPARE TYRE BOARD	Serviceable	680.90 FL	-	*- FL
53	1	*EXHAUST REAR	Repair	5,263.60 FL	-	*- FL
54	1	*EXHAUST CAP REAR	Repair	125.40 FL	-	*- FL
55	1	*BOOT WEATHERSTRIP (50%)	Distorted	178.20 FN	-	*89.10 F
56	1	*SET PARKING AID	Shorted	700.00 FS	-	*400.00 FS
57	1	*SET REAR BUMPER CLIP	Necessary	66.00 FS	-	*66.00 FS
58	1	*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	-	*33.00 FS
59	1	*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	-	*- FS
60	1	*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	-	*- FS
61	1	*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	-	*- FS
62	1	*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	-	*- FS
63	1	*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	-	*- FS
64	1	*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	-	*66.00 FS
65	1	*EXHAUST MOUNTING REAR	Not Necessary	16.00 FS	-	*- FS
66	1	*EXHAUST BRACKET REAR	Not Necessary	24.80 FS	-	*- FS
67	1	*SET BOOT FINISHER CLIP	Necessary	24.20 FS	-	*24.20 FS
68	1	*BOOT STICKER TRANS-CAB	Necessary	30.00 FS	-	*30.00 FS
69	1	*BOOT STICKER 6555-3333	Necessary	30.00 FS	-	*30.00 FS
70	1	*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	-	*- FS
71	1	*SET FENDER WHEELARCH REAR LH CLIP	Not Necessary	35.00 FS	-	*- FS
72	1	*SPARE TYRE RIM (ROUE 7J 16H 2547)	Serviceable	385.00 FS	-	*- FS
73	1	*SPARE TYRE	Serviceable	330.00 FS	-	*- FS
74	1	*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	-	*- FS
75	1	*TAILLAMP CLIP RH	Necessary	5.00 FS	-	*5.00 FS
76	2	*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	-	*- FS
77	1	*WINDSCREEN MOULDING	Not Necessary	100.00 FS	-	*- FS
78	1	*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	-	*- FS
79	1	*TAILLAMP CLIP LH	Not Necessary	5.00 FS	-	*- FS
80	1	*REAR BUMPER PROTECTOR	Not Necessary	100.00 FS	-	*- FS
81	1	*REAR LEFT TYRE	Serviceable	300.00 FS	-	*- FS
82	1	*REAR LEFT TYRE RIM	Serviceable	380.00 FS	-	*- FS
83	1	*REAR RIGHT TYRE	Serviceable	300.00 FS	-	*- FS
84	1	*REAR RIGHT TYRE RIM	Serviceable	380.00 FS	-	*- FS
85	1	*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	35.00 FS	-	*- FS
86	1	*FENDER INNER TRIM CLIP RH	Not Necessary	28.00 FS	-	*- FS
87	1	*SET REAR LICENCE PLATE WITH HOLDER	Dented	80.00 FS	-	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

<b>Sub Total (\$\$)</b>	<b>28,418.27</b>	<b>8,535.76</b>
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,445.21	774.75
- Nett Item Discount on N Items 10.00/0.00% (\$\$)	17.82	0.00

<b>Total Parts (\$\$)</b>	<b>25,955.24</b>	<b>7,761.01</b>
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	9,000.00	800.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	9,000.00	880.00
3	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING	New	380.00	0.00
4	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
5	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR	New	170.00	60.00
6	TOWING FEES	New	170.00	0.00
7	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST }	New	170.00	80.00
8	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST }	New	170.00	0.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
10	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	60.00
11	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
12	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	0.00
13	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
14	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
15	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	0.00
16	TO TRANSFER OF REAR BUMPER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
17	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
18	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
19	TO DROP DIESEL TANK,PIPES,HOSES TO FACILITATE BODYWORK REPAIR,FINAL CHECKING AND TESTING	New	380.00	0.00
20	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR	New	380.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>22,370.00</b>	<b>1,960.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >