

Tropical Tech Automobile Services

Blk 5030, Ang Mo Kio Avenue 3, #01-201, Industrial Park 2, Singapore 569535

Tel : 6481 7773 / 6481 1403 Fax : 6484 4978

E-mail : tasc303@singnet.com.sg

M / s : **China Taiping Insurance (Singapore) Pte. Ltd.**
3, Anson Road, #16-00,
Springleaf Tower,
Singapore 079909

Final bill : TT 73 / 19 / OD / WT

Registration No : SLP9188G

Attn : Motor Claims Department
Tel : 6389 6111
Fax : 6222 1033

Make model : BMW 530i

Mileage : Date : 31 / 12 / 2019

**OWN DAMAGE CLAIM VEHICLE BEARING REGISTRATION NO : SLP9188G ALONG JALAN PENDEKAR
18 ON 26 OCTOBER 2019 AT ABOUT 1110HRS.**

		Cost Price
1pc	Front bonnet	\$ 1,350.00
1pc	Front kidney grille (LH)	\$ 90.00
1pc	Front LH fender	\$ 580.00
1pc	Front LH fender 1st bracket	\$ 25.00
1pc	Front LED head-lamp (LH)	\$ 3,250.00
1pc	Front bumper	\$ 900.00
1pc	Front bumper lower side grille (LH)	\$ 70.00
1pc	Front bumper lower side grille chrome (LH)	\$ 50.00
1pc	Front bumper fog lamp (LH)	\$ 230.00
1pc	Front bumper side bracket (LH)	\$ 12.00
1pc	Front bumper frame (LH)	\$ 55.00
1pc	Front bumper reinforcement	\$ 440.00
Sub A total :		\$ 7,052.00
After GST 7% :		\$ 493.64
Mark up 15% :		\$ 1,057.80
A total :		\$ 8,603.44
Total amount of Page 1 :		\$ 8,603.44

Tropical Tech Automobile Services


(Authorised Signature)
William Tan



Tropical Tech Automobile Services

Blk 5030, Ang Mo Kio Avenue 3, #01-201, Industrial Park 2, Singapore 569535

Tel : 6481 7773 / 6481 1403 Fax : 6484 4978

E-mail : tasc303@singnet.com.sg

M / s : **China Taiping Insurance (Singapore) Pte. Ltd.**
3, Anson Road, #16-00,
Springleaf Tower,
Singapore 079909

Final bill : TT 73 / 19 / OD / WT

Registration No : SLP9188G

Attn : Motor Claims Department
Tel : 6389 6111
Fax : 6222 1033

Make model : BWM 530i

Mileage : Date : 31 / 12 / 2019

**OWN DAMAGE CLAIM VEHICLE BEARING REGISTRATION NO : SLP9188G ALONG JALAN PENDEKAR
18 ON 26 OCTOBER 2019 AT ABOUT 1110HRS.**

Supplemntnary spare part items :

		Cost Price
1pc	Front LH fender top covering (Inside)	\$ 25.00
2pcs	Front LH fender chrome moulding rivet (Each \$4.20)	\$ 8.40
1pc	Front LH head-lamp driving daylight LED ballast	\$ 150.00
1pc	Front bumper lower grille air duct (Centre)	\$ 40.00
Sub B total :		\$ 223.40
After GST 7% :		\$ 15.64
Mark up 15% :		\$ 33.51
B total :		\$ 272.55

Remove and transfer front bonnet necessary attachment spart part items.

Remove and transfer front bumper necessary attachment spart part items.

Remove and refit font bonnet, front kidney grille (LH), front LH fender 1st bracket , front LED head-lamp (LH), front bumper, front bumper lower side grille (LH), front bumper lower side grille chrome (LH), front bumper fog lamp (LH), front bumper side bracket (LH), front bumper frame (LH), front bumper reinforcement.

Heat /weld / beating / pull / straighten / align front chassis frame by Chassis
Aligment jack.

\$ 600.00

Total amount of Page 2 :

\$ 872.55

Tropical Tech Automobile Services

(Authorised Signature)
William Tan



Tropical Tech Automobile Services

Blk 5030, Ang Mo Kio Avenue 3, #01-201, Industrial Park 2, Singapore 569535

Tel : 6481 7773 / 6481 1403 Fax : 6484 4978

E-mail : tasc303@singnet.com.sg

M / s : **China Taiping Insurance (Singapore) Pte. Ltd.**
3, Anson Road, #16-00,
Springleaf Tower,
Singapore 079909

Final bill : TT 73 / 19 / OD / WT

Registration No : SLP9188G

Attn : Motor Claims Department
Tel : 6389 6111
Fax : 6222 1033

Make model : BMW 530i

Mileage : Date : 31 / 12 / 2019

**OWN DAMAGE CLAIM VEHICLE BEARING REGISTRATION NO : SLP9188G ALONG JALAN PENDEKAR
18 ON 26 OCTOBER 2019 AT ABOUT 1110HRS.**

Diagnostic and reset front parktronic sensor system by HHT	\$	60.00
Putty / primer application, spray painting on front bonnet, front LH fender, front bumper, front bumper parktronic sensor (Extreme, LH).	\$	750.00
Balance amount brought from Page 1 :	\$	8,603.44
Balance amount brought from Page 1 :	\$	872.55
Less own damaged insurance excess :	\$	(800.00)
Grand final amount :	\$	9,485.99

Tropical Tech Automobile Services

(Authorised Signature)
William Tan

