

Tropical Tech Automobile Services

31c 5030, Ang Mo Kio Avenue 3, #01-201, Industrial Park 2, Singapore 569535

Tel : 6481 7773 / 6481 1403 Fax : 6484 4978

E-mail : tase303@singnet.com.sg

M/s : China Taiping Insurance (Singapore) Pte. Ltd.
105 Cecil Street
#18-00 / #19-00 / #16-01/02
The Octagon Singapore 069534

Estimate bill : TT 73 / 19 / TP / WT

Registration No : SLP9188G

Attn : Attention : Motor Claims Department
Tel : Tel : 6389 6111
Fax : Fax : 6222 1033

Make model : BMW 530 i

Mileage :

Date : 01 / 11 / 2019

OWN DAMAGE CLAIM VEHICLE BEARING REGISTRATION NO : SLP9188G ALONG JALAN PENDEKAR 18 ON
26 OCTOBER 2019 AT ABOUT 1110 HRS.

1pc	Front bonnet	\$	3,281.00	✓
1pc	Front kidney grille (LH)	\$	232.00	✓
1pc	Front kidney grille air duct	\$	535.00	✓
1pc	Front LH fender	\$	1,509.00	✓
1pc	Front LH fender 1st bracket	\$	61.00	✓
1pc	Front LH fender cowl (Front)	\$	219.00	X
1pc	Front LED head-lamp (LH)	\$	5,850.00	✓
1pc	Front LED head-lamp panel (LH)	\$	268.00	X
1pc	Front bumper	\$	2,187.00	✓
1pc	Front bumper parktronic sensor (Extreme, LH)	\$	365.00	✓
1pc	Front bumper lower side grille (LH)	\$	171.00	✓
1pc	Front bumper lower side grille chrome (LH)	\$	122.00	✓
1pc	Front bumper fog lamp (LH)	\$	608.00	✓
1pc	Front bumper side bracket (LH)	\$	30.00	✓
1pc	Front bumper frame (LH)	\$	134.00	✓
1pc	Front bumper reinforcement	\$	1,240.00	✓
Sub A total :		\$	16,812.00	
Less 10% discount :		\$	1,681.20	
A total :		\$	15,130.80	
Total amount of Page 1 :		\$	15,130.80	

Tropical Tech Automobile Services

(Authorised Signature)

William Tan

Not Attached
Repair B4 paint
Ex 8800h
Fax 62564313
5 days

Tropical Tech Automobile Services

Blk 5030, Ang Mo Kio Avenue 3, #01-201, Industrial Park 2, Singapore 569535

Tel : 6481 7773 / 6481 1403 Fax : 6484 4578

E-mail : tase303@singnet.com.sg

M / s : **China Taiping Insurance (Singapore) Pte. Ltd.**
105 Cecil Street
#18-00 / #19-00 / #16-01/02
The Octagon Singapore 069534

Estimate bill : TT 73 / 19 / TP / WT

Registration No : SLP9188G

Attn : Attention : Motor Claims Department
Tel : 6389 6111
Fax : 6222 1033

Make model : BMW 530 i

Mileage :

Date : 01 / 11 / 2019

OWN DAMAGE CLAIM VEHICLE BEARING REGISTRATION NO : SLP9188G ALONG JALAN PENDEKAR 18 ON 26 OCTOBER 2019 AT ABOUT 1110 HRS.

Remove and transfer front bonnet necessary attachment spart part items.

Remove and transfer front bumper necessary attachment spart part items.

Remove and refit front bonnet, front kidney grille (LH), front kidney grille air duct, front LH fender, front LH fender 1st bracket, front LH fender cowling (Front), front LED head-lamp (LH), front LED head-lamp panel (LH), front bumper, front bumper parktronic sensor (Extreme, LH), front bumper lower side grille (LH), front bumper lower side grille chrome (LH), front bumper fog lamp (LH), front bumper side bracket (LH), front bumper frame (LH), front bumper reinforcement.

Heat / weld / beating / pull / straighten / align front chassis frame by Chassis Alignment jack.

Tuff kote front damaged portion.

Diagnostic and reset front parktronic sensor system by HHT

Putty / primer application, spray painting on front bonnet, front LH fender, front bumper, front bumper parktronic sensor (Extreme, LH).

Balance amount brought from Page 1 :

Grand final amount :

\$ 1,500.00

\$ 150.00 X

\$ 80.00

\$ 1,200.00

\$ 15,130.80

\$ 18,060.80

Tropical Tech Automobile Services

(Authorised Signature)
William Tan

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: