

SS REC BY

REF: CS/CTI 190 19400 / Lv f302

Special Instructions

Surveyor: AmunASSIGNMENT (Office)From (Person): Chung Bnn Snof CTIDate/Time: 4.11.19 9.37am

Estimated Cost: _____

Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLP 91886

Insured: _____

at Workshop n/a: Tropical SuraceTel: 64817773 | 81335187of Bit 5032 MK Ark 3 not 303Policy No: DMPKSN1734361902Claim No: SNM190205108101

Sum Insured: _____

Excess: \$800.00

Make of Veh: _____

D.O.A. 26.10.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 4.11.19 9.41am

Person Contacted: _____

Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLP 91886 - NA/CTI 190190205108101 24 D.O.A. 26/10/2019
4/11/19	@236pm Informed William Cost + .1590
5/11/19	Revert via merimen
5/11/19	Rare approved \$10,550.00 from Irene Tay by merimen
5/11/19	Informed Calvin c/A ex \$800 by email

ASSIGNMENT

From:

Date:

4.11.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLP 9188G

at Workshop m/s Tropical Success

ul BIC9032 AMT Ave 3 #01-303

Insured:

Policy No:

Claims No:

Sum Insured:

Excess: \$ 800.00

(Client's Record)

Make of Vehl:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value: \$178k

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repair: 05 days Res.: Yes or No

Lum Sum: 1.81% 3 Val.: Yes or No

CA / (REV) REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SLP 9188G

yr Regn:

04, 17

Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

BMW

2

530i

C.C.

1998

Colour:

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading:

49790

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WBAJA 52030G 885102

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orMod: ☐ Nil / ☐ S/Rim / ☒ STD A/Rim or

Tyre Size:

F:

245/40R19

R:

275/35R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

P

mm

R/Bal:

P

mm

L/Bal:

P

mm

L/Bal:

P

mm

D.O.A.

26/10/19

D.O.L.

4/11/19

Survey held at

☒Des. of Damages: ☐ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

FR MS

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: Action / Instruction

26/12 8 9588.80 encl

RECEIVED 10 FEB 2020

10/2/20 Final fig \$10,285.99. Confirmed by email (Recd 3173.51, 2490)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

10/2 - typist

Rep. of Fault:

Mechan

Lump Sum / TP:

10,285.99

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Work end (\$

Survey Fee:

770

Transportation:

: S + RS \$

: Photos

: S/W

TOTAL

770

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Nov 2019		04 Nov 2019 09:37 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	YANG YI ALBERT, ID: S15073341, Tel: +6581139939, Email: NOEMAIL								
Vehicle Reg. No.:	SLP9188G	Date of Loss:	26/10/2019 11:00 - :59						
Claim Type:	OD / SNM19D205108C01	Policy/Cover Note No.:	DMPCSN1734361902 (Comprehensive)						
		Excess:	S\$800.00						
Repairer:	Tropical Success Auto Care (HQ) BLK 5032 Ang Mo Kio Avenue 3, #01-303 Industrial Park 2, 569535 Ang Mo Kio - Tel: 6481 7773								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 13/11/2019]								
Driver/Custodian:	YANG YI ALBERT (58 / Male) , NRIC: S15073341, Tel: +6581139939 Email: NOEMAIL								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 5 November 2019 11:30 AM
To: Tropical Success; SUR
Subject: RE: REVISED ESTIMATE SLP9188G-DOA:26.10.2019

Dear Calvin,

As instructed by our client , please proceed to repair the **insured vehicle SLP 9188G on part by part (Cost plus 15%), (Excess S800/-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

NOTE: PLEASE PROVIDES PARTS INVOICE FOR FINALIZE.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tropical Success <tsac303@singnet.com.sg>
Sent: Tuesday, 5 November 2019 9:36 AM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: REVISED ESTIMATE SLP9188G

Regards
Calvin
Tropical Success Auto Care
Blk 5032 Ang Mo Kio Ind Pk2
#01-303 S(569535)
Tel: 64817773

View Received Message

This mail is associated with :

***SLP9188G (SNM19D205108C01)**

OD

Oct 26 2019 11:00AM

[YANG YI ALBERT]

Tropical Success Auto Care

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 05/11/2019 10:36 AM,

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$10552.40) - SLP9188G - Claim Handler: Chong Boon Sen

Approved: 10552.40.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199507198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 04 Nov 2019

Preliminary Advice

Vehicle No	: SLP9188G	Accident Date	: 26/10/2019
Make	: BMW 530i	Policy No.	: DMPCSN1734361902
Assignment Date	: 04/11/2019	Excess	: S\$800.00
Date of Inspection	: 4/11/2019	Est. Duration of Repair	: 5
Inspection At	: TROPICAL TECH AUTOMOBILE SERVICES		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,302.04
Revised Amount	:S\$	10,020.74
Check Items (Estimated)	:S\$	531.30
Total	:S\$	10,552.04

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	178,000.00
COE / PARF Rebate	:S\$	86,483.00
Salvage Value	:S\$	
Margin for Repair	:S\$	91,517.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	334I
Vehicle Details	
Vehicle No.:	SLP9188G
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Nov 2019
Vehicle Make:	B.M.W.
Vehicle Model:	530I LED NAV
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	14229889B48B20B
Chassis No.:	WBAJA52030G885102
Maximum Power Output:	185.0 kW (248 bhp)
Open Market Value:	\$49,363.00
Original Registration Date:	25 Apr 2017
First Registration Date:	25 Apr 2017
Transfer Count:	0
Actual ARF Paid:	\$61,109.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Apr 2027
PARF Rebate Amount:	\$45,831.00
Intended COE Rebate Details	
COE Expiry Date:	24 Apr 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$54,405.00
COE Rebate Amount:	\$40,652.00
Total Rebate Amount:	\$86,483.00

The information contained herein is correct as at 04 Nov 2019

OK

MOTOR PRIVATE CAR

CERTIFICATE OF INSURANCE

 Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
 Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960
 Road Transport Act, 1987 (Malaysia)
 Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

PLM 327843
ORIGINAL

Engine No : 14229889B48B20R

ChaNo: WRAJA52030G885102

CERTIFICATE No.

DMPCHN1734361902

1. Index Mark and Registration

SLP9188G

Number of Vehicle

2. Name of Policy Holder

YANG YI ALBERT

3. Effective date of the Commencement of Insurance for the purposes of the Regulations, Ordinance or Enactment

25 April 2019

Named Drivers Ex Sect. 1 S\$800.00

Additional Ex Other than Named Drivers:

Ex Sect. 1 - Age <= 25 S\$3,000.00

Ex Sect. 1 - Age >= 26 S\$500.00

* Age as at date of accident

EX ON WINDSCREEN S\$100.00

4. Date of Expiry of Insurance

24 April 2020

5. Persons or Classes of Persons entitled to drive*

(a) The Policyholder.

(b) Any other person who is driving on the Policyholder's order or with his permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover use for hire or reward tuition driving test racing pace-making, reliability trial, speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

Excess whichever is applicable for losses occurring outside Singapore (Constructive Total Loss/Theft) will be doubled.

One time Waiver of Excess for the first S\$1,000 will apply to the Insured and Named Drivers in the event of Own Damage Claim at our Authorized Workshops for each Policy Year.

HIRE PURCHASE CO. : DBS BANK LTD AS HP OWNER

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act 1987 (Malaysia), are not to be included under these headings.

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please see reverse

For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Issued By:

Authorised Officer

Authorised Signatory

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available if needed.

ACCIDENT STATEMENT

Date Of Report 29/10/2019 12:23
Date Of Accident 26/10/2019 11:10
Exact Location Of Accident JALAN PENDEKAR 18
Country/State of Loss MALAYSIA/JOHOR DARUL TAKZIM

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLP9188G
Insured/Policyholder
Name Of Registered Owner YANG YI ALBERT
NRIC No S1507334I
E-mail Address NOEMAIL
Mobile Phone No (LOCAL) +65-81139939
Alternative Phone No OFFICE-81139939

Vehicle Particulars

Manufacturer BMW
Model 530I LED NAV
Exact Purpose for which vehicle was being used at time of accident PRIVATE USE

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number DMPCSN1734361902
Cover Note Number

Driver

Name of Driver YANG YI ALBERT
NRIC No S1507334I
Date Of Birth 25/09/1961
Occupation INDOOR
Date Of Driving Pass 23/05/1979
Driving Experience 40 YEARS AND 5 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-81139939
Fax Number
Contact Number OFFICE-81139939
E-Mail Address NOEMAIL

Address 84 FLORA ROAD
#01-18
Postcode 507001

Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? YES
Foreign Vehicle Registration Number JET6896 (PRIVATE CAR)
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance?
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 4
Passenger 1
NAME: : -
GENDER: : FEMALE
Passenger 2
NAME: : -
GENDER: : MALE
Passenger 3
NAME: : -
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name TRAFFIC POLICE DIVISION HQ - SINGAPORE CITY
Police Station Address ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT - T/20191029/7007.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number JET6896

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the I&A Reports Management Centre established by the General Insurance Association of Singapore (GIA) for archiving, and that copies of this report will thereafter be made available upon application to interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police) for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms) which may be used outside of Singapore, for one or more of the above Purposes.
 - (d) My Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) The information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
(Date & Time)

Driver's Signature
(If Driver is not the policyholder)
(Date & Time)

Reporting Centre Person's Signature
Name
NRIC/FIN No.

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report 7/20/2024/2024

DECLARATION

I/We declare the foregoing particulars are true to every respect

Witness's Signature
(Date & Time)

Driver's Signature
(If driver is not the policy holder)
(Date & Time)

Reporting Centre Person's Signature
Name
NRIC/ID No.

Police Report



**SINGAPORE
POLICE FORCE**



T/20191029/1007

Police Station Of Origin
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No 65470000

Page 4

Report No: T/20191029-1007

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made
29/10/2019 11:49

Video Report No

Station Diary No

Informant's Particulars

Name of Informant YANG YI ALBERT			Address 84 FLORA ROAD #01-18 SINGAPORE 507001		
ID Type / ID No NRIC NO / S15073341			Contact No Home/Office Mobile 81139939		
Nationality SINGAPORE CITIZEN			Email YANGYI ALBERT@GMAIL.COM		
Sex Male	Age 58	Date of Birth 25/09/1961	Type of Informant Driver		
Race Chinese			Language: English Institution / School Name		
Occupation Technical/Engineering services manager (eg shipyard manager)			Driving Licence Information Class: 2,3,4 Date of Expiry		

General Information of the Accident

Type of Accident Non-Injury Foreign Vehicle	Drink Drive No	Date/Time of Accident 26/10/2019 11:10	Type of Location
Location Jalan Pendekar, Johor Bahru			
Weather Clear	Road Surface Dry	Road Speed Limit 40 Km/h	
Traffic Flow Two Way	Traffic Control Not Controlled	Traffic Volume Light	
Type of Collision Main Road	Anyone conveyed by ambulance No		

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLP9188G	Car	BMW	5 30i	Silver	Slightly Damaged	3

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLP9188G	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD	DMPCSN17346190-2	25/04/2019	24/04/2020

Police Report



SINGAPORE
POLICE FORCE

Police Station Of Origin
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408885
Tel No. 65470000



T/20191029/0007

Page 4

Report No. T/20191029/0007

CONTINUATION OF REPORT

Details of Person Involved

Any Pedestrian Involved No

No. of Pedestrians Injured NIL

Use of Pedestrian Crossing NA

Driver

Name YANG YI ALBERT

ID No

S15073341

Related Vehicle SLP9188G (Car)

Contact No

81139939

Hospital/Clinic NIL

Class of
Driving
Licence &
Expiry Date

Class 2,3,4

Date of Expiry NIL

Date Treatment NIL

Date Discharge

NIL

No. of Days granted Medical Leave NIL

Degree of Injury

NIL

Passenger

Name KHOO EE MOI

ID No

S2555755G

Related Vehicle SLP9188G (Car)

Contact No

90038585

Hospital/Clinic NIL

Class of
Driving
Licence &
Expiry Date

Class NIL

Date of Expiry NIL

Date Treatment NIL

Date Discharge

NIL

No. of Days granted Medical Leave NIL

Degree of Injury

NIL

Driver

Name YANG YI ALBERT

ID No

S15073341

Related Vehicle SLP9188G (Car)

Contact No

81139939

Hospital/Clinic NIL

Class of
Driving
Licence &
Expiry Date

Class NIL

Date of Expiry NIL

Date Treatment NIL

Date Discharge

NIL

No. of Days granted Medical Leave NIL

Degree of Injury

NIL

Police Report



**SINGAPORE
POLICE FORCE**

Police Station Of Origin
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No. 65470000



T-20151029-7007

3 of 4

Report No: T-20151029-7007

CONTINUATION OF REPORT

Passenger			
Name	ONG WAH KIAN	ID No	S1030078J
Related Vehicle	SLP9188G (Car)	Contact No	91063301
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class NIL Date of Expiry NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Passenger			
Name	NEO SIONG HOO	ID No	S1456342C
Related Vehicle	SLP9188G (Car)	Contact No	96662926
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class NIL Date of Expiry NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details

I am driving along the road, there is side parking along the two way traffic road. during my driving I was a car wish to make side parking stop on the road side. I over take his vehicle driving with in centre divide line. After passing by the white car in front suddenly see the black vehicle No JET6896 make his u-turn from the parking lot. I apply my emergency brake but still hit the car try to turning. My car had 3 passenger and JET6896 with 4 child behind site 2 audit include driver.

I already lodged a police report in Malaysia, report number R107013

Police Report



SINGAPORE
POLICE FORCE

Police Station Of Origin
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No. 65470000



T/20191029/007

4 of 4

Report No: T/20191029/007

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report
Not applicable

Signature Of Interpreter
Not applicable

Officer In Charge Of Case
TP / TPHQ /
YEO GEAK ENG CECILIA
Contact No. 65476404

Authentication Stamp
None

Signature Of Informant
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time
29/10/2019 11:49

Classification Of Case

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No. MNA119142623 Vehicle Registration No. SLP9188G
 Name (as shown on TNR): YANG YI ALBERT NRIC/FIN/Passport No. S15073341
 (~~Vehicle Owner~~ / Vehicle Owner) [*] Please delete as appropriate
 Address: 84 FLORA ROAD #01-18 Singapore (507001)
 Contact (Tel): _____ Mobile No. 81139939
 Email Address: _____
 Date of Accident: 26/10/2019 Time of Accident: 11:10
 Place of Accident: JALAN PENDEKAR 18
 Insurance Company: China Taiping Insurance (Singapore) Pte. Ltd.

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Amend from reporting only to an injury claim

Policyholder / Driver's Signature
 Date: _____

Reporting Centre Personnel's Signature
 Name: _____
 NRIC/FIN No.: _____
 Date: _____

Tropical Tech Automobile Services

Blk 5030, Ang Mo Kio Avenue 3, #01-201, Industrial Park 2, Singapore 569535

Tel : 6481 7773 / 6481 1403 Fax : 6484 4978

E-mail : tase303@singnet.com.sg

M/s : **China Taiping Insurance (Singapore) Pte. Ltd.**
105 Cecil Street
#18-00 / #19-00 / #16-01/02
The Octagon Singapore 069534

Estimate bill : TT 73 / 19 / TP / WT

Registration No : SLP9188G

Attn : Attention : Motor Claims Department
Tel : Tel : 6389 6111
Fax : Fax : 6222 1033

Make model : BMW 530 i

Mileage : Date : 01 / 11 / 2019

OWN DAMAGE CLAIM VEHICLE BEARING REGISTRATION NO : SLP9188G ALONG JALAN PENDEKAR 18 ON 26 OCTOBER 2019 AT ABOUT 1110 HRS.

1pc	Front bonnet	\$	By 3,281.00	✓
1pc	Front kidney grille (LH)	\$	cm 232.00	✓
1pc	Front kidney grille air duct	\$	cm 535.00	?
1pc	Front LH fender	\$	Bu 1,509.00	✓
1pc	Front LH fender 1st bracket	\$	61.00	?
1pc	Front LH fender cowling (Front)	\$	cm 219.00	X
1pc	Front LED head-lamp (LH)	\$	Bro 5,850.00	✓
1pc	Front LED head-lamp panel (LH)	\$	cm 268.00	X
1pc	Front bumper	\$	Bu 2,187.00	✓
1pc	Front bumper parktronic sensor (Extreme, LH)	\$	365.00	?
1pc	Front bumper lower side grille (LH)	\$	cm 171.00	✓
1pc	Front bumper lower side grille chrome (LH)	\$	cm 122.00	✓
1pc	Front bumper fog lamp (LH)	\$	mm 608.00	?
1pc	Front bumper side bracket (LH)	\$	30.00	?
1pc	Front bumper frame (LH)	\$	134.00	?
1pc	Front bumper reinforcement	\$	By 1,240.00	?
Sub A total :		\$	16,812.00	
Less 10% discount :		\$	1,681.20	
A total :		\$	15,130.80	
Total amount of Page 1 :		\$	15,130.80	

Tropical Tech Automobile Services

(Authorised Signature)
William Tan

NOT Withhold
Repair By paint
Ex 8800h

Fax 62564315

5 days

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Comp.

Acknowledged by Repairer

Signature: _____

Date: _____

Tropical Tech Automobile Services

Blk 5030, Ang Mo Kio Avenue 3, #01-201, Industrial Park 2, Singapore 569535

Tel : 6481 7773 / 6481 1403 Fax : 6484 4978

E-mail : tasc303@singnet.com.sg

M/s : **China Taiping Insurance (Singapore) Pte. Ltd.**
105 Cecil Street
#18-00 / #19-00 / #16-01/02
The Octagon Singapore 069534

Estimate billl : TT 73 / 19 / TP / WT

Registration No : SLP9188G

Attn : Attention : Motor Claims Department
Tel : Tel : 6389 6111
Fax : Fax : 6222 1033

Make model : BMW 530 i

Mileage : Date : 01 / 11 / 2019

OWN DAMAGE CLAIM VEHICLE BEARING REGISTRATION NO : SLP9188G ALONG JALAN PENDEKAR 18 ON 26 OCTOBER 2019 AT ABOUT 1110 HRS.

Remove and transfer front bonnet necessary attachment spart part items.

Remove and transfer front bumper necessary attachment spart part items.

Remove and refit front bonnet, front kidney grille (LH), front kidney grille air duct, front LH fender, front LH fender 1st bracket, front LH fender cowling (Front), front LED head-lamp (LH), front LED head-lamp panel (LH), front bumper, front bumper parktronic sensor (Extreme, LH), front bumper lower side grille (LH), front bumper lower side grille chrome (LH), front bumper fog lamp (LH), front bumper side bracket (LH), front bumper frame (LH), front bumper reinforcement.

Heat /weld / beating / pull / straighten / align front chassis frame by Chassis Alignment jack.

Tuff kote front damaged portion.

Diagnostic and reset front parktronic sensor system by HHT

Putty / primer application, spray painting on front bonnet, front LH fender, front bumper, front bumper parktronic sensor (Extreme, LH).

Balance amount brought from Page 1 :

Grand final amount :

\$ 600 1,500.00

\$ 150.00 X

\$ 80.00

\$ 750 1,200.00

\$ 15,130.80

\$ 18,060.80

Tropical Tech Automobile Services

(Authorised Signature)
William Tan

Tropical Tech Automobile Services

Blk 3030, Ang Mo Kio Avenue 3, #01-201, Industrial Park 2, Singapore 569535
Tel : 6481 7773 / 6481 1403 Fax : 6484 4978
E-mail : tase303@singnet.com.sg

M/s: China Taiping Insurance (Singapore) Pte. Ltd.
105 Cecil Street
#18-00 / #19-00 / #16-01/02
The Octagon Singapore 069534

Estimate bill: TT 73 / 19 / TP / WT

Attn: Attention: Motor Claims Department
Tel: Tel: 6389 6111
Fax: Fax: 6222 1033

Registration No: SLP9188G

Make model: BMW 530 i

Mileage:

Date: 05 / 11 / 2019

OWN DAMAGE CLAIM VEHICLE BEARING REGISTRATION NO : SLP9188G ALONG JALAN PENDEKAR 18 ON
26 OCTOBER 2019 AT ABOUT 1110 HRS.

1pc	Front bonnet	1350
1pc	Front kidney grille (LH)	90
1pc	Front kidney grille air duct	
1pc	Front LH fender	580
1pc	Front LH fender 1st bracket	25
1pc	Front LH fender cowl (Front)	
1pc	Front LED head-lamp (LH)	3250
1pc	Front LED head-lamp panel (LH)	
1pc	Front bumper	900
1pc	Front bumper parktronic sensor (Extreme, LH)	
1pc	Front bumper lower side grille (LH)	70
1pc	Front bumper lower side grille chrome (LH)	50
1pc	Front bumper fog lamp (LH)	230
1pc	Front bumper side bracket (LH)	12
1pc	Front bumper frame (LH)	55
1pc	Front bumper reinforcement	440
Sub A total:		
After GST 7%:		
Mark up 15%:		
A total:		

Cost Price	
S	BT 1,350.00
S	CRG 90.00
S	L 220.00
S	Buc 580.00
S	oil 25.00
S	svl 90.00
S	Bro 3,250.00
S	R 110.00
S	Buc 900.00
S	L 150.00
S	CRG 70.00
S	CRG 50.00
S	mtg CRG 230.00
S	oil 12.00
S	CRG 55.00
S	BT 150.00
S	7,632.00
S	534.24
S	1,144.80
S	9,311.04
S	9,311.04

Total amount of Page 1 :

Tropical Tech Automobile Services

(Authorised Signature)
William Tan

Tropical Tech Automobile Services

Blk 5030, Ang Mo Kio Avenue 3, #01-201, Industrial Park 2, Singapore 569535

Tel : 6481 7773 / 6481 1403 Fax : 6484 4978

E-mail : tase303@singnet.com.sg

M/s : China Taiping Insurance (Singapore) Pte. Ltd.
105 Cecil Street
#18-00 / #19-00 / #16-01/02
The Octagon Singapore 069534

Estimate bill : TT 73 / 19 / TP / WT

Registration No : SLP9188G

Attn : Attention : Motor Claims Department
Tel : 6389 6111
Fax : Fax : 6222 1033

Make model : BMW 530 i

Mileage : Date : 05 / 11 / 2019

OWN DAMAGE CLAIM VEHICLE BEARING REGISTRATION NO : SLP9188G ALONG JALAN PENDEKAR 18 ON
26 OCTOBER 2019 AT ABOUT 1110 HRS.

Remove and transfer front bonnet necessary attachment spart part items.

Remove and transfer front bumper necessary attachment spart part items.

Remove and refit front bonnet, front kidney grille (LH), front kidney grille air duct, front LH fender, front LH fender 1st bracket, front LH fender cowling (Front), front LED head-lamp (LH), front LED head-lamp panel (LH), front bumper, front bumper parktronic sensor (Extreme, LH), front bumper lower side grille (LH), front bumper lower side grille chrome (LH), front bumper fog lamp (LH), front bumper side bracket (LH), front bumper frame (LH), front bumper reinforcement.

\$ 1,500.00 600

Heat /weld / beating / pull / straighten / align front chassis frame by Chassis Alignment jack.

Tuff kote front damaged portion.

\$ HI 150.00 X

Diagnostic and reset front parktronic sensor system by HHT

\$ 60 80.00

Putty / primer application, spray painting on front bonnet, front LH fender, front bumper, front bumper parktronic sensor (Extreme, LH).

\$ 750 1,200.00

Balance amount brought from Page 1 :

\$ 9,311.04

Grand final amount :

\$ 12,241.04

13,459.50

Tropical Tech Automobile Services

12901.35

(Authorised Signature)
William Tan

Tropical Tech Automobile Services

Blk 5030, Ang Mo Kio Avenue 3, #01-201, Industrial Park 2, Singapore 569535

Tel : 6481 7773 / 6481 1403 Fax : 6484 4978

E-mail : tasc303@singnet.com.sg

M : **China Taiping Insurance (Singapore) Pte. Ltd.**
105 Cecil Street
#18-00 / #19-00 / #16-01/02
The Octagon Singapore 069534

Supplementary bill : TT 73 / 19 / TP W

Registration No : SLP9188G

Attn : Attention : Motor Claims Department
Tel : Tel : 6389 6111
Fax : Fax : 6222 1033

Make model : BMW 530i

Mileage : Date : 05 / 11 / 2019

DOWN DAMAGE CLAIM VEHICLE BEARING REGISTRATION NO : SLP9188G ALONG JALAN PENDEKAR 18 ON 26 OCTOBER 2019 AT ABOUT 1110 HRS.

Supplementary front part part items :

		Cost Price	
1pc	Front LH fender top covering (Inside) 25	\$ CM	75.00
1pc	Front LH fender chrome moulding rivet 4/20 x 2pc = 8/40 (Each \$5.00)	\$ m	1000.00
1pc	Front LH head-lamp driving daylight LED ballast 150	\$ CM	120.00
1pc	Front bumper under side dust covering (LH)	\$	28.00
1pc	Front bumper lower grille air duct (Centre) 40	\$ nd	30.00
1pc	Front bumper sponge	\$	60.00
	Sub A total :	\$	743.00
	After GST 7% :	\$ 24.01	71.00
	Mark up 15% :	\$	81.00
	A total :	\$ 418.46	118.00

Special net items :

Programming front head-lamp driving daylight ballast
B total :

NU \$ **BTH** 600.00 X
\$ 600.00

Putty / primer application, spray painting on front LH door.

NN \$ 700.00 X

Grand final amount :

\$ **1,218.46**

Tropical Tech Automobile Services

Sup total **223/40**
GST : **15.64**
Mark up 15% : **33.51**
272.55

(Authorised Signature)
William Tan

Tropical Tech Automobile Services

Blk 5030, Ang Mo Kio Avenue 3, #01-201, Industrial Park 2, Singapore 569535

Tel : 6481 7773 / 6481 1403 Fax : 6484 4978

E-mail : tase303@singnet.com.sg

M / s : **China Taiping Insurance (Singapore) Pte. Ltd.**
105 Cecil Street
#18-00 / #19-00 / #16-01/02
The Octagon Singapore 069534

Attn : Attention : Motor Claims Department
Tel : Tel : 6389 6111
Fax : Fax : 6222 1033

Supplementary bill : TT 73 / 19 / TP / WT

Registration No : SLP9188G

Make model : BMW 530 i

Mileage : Date : 05 / 11 / 2019

OWN DAMAGE CLAIM VEHICLE BEARING REGISTRATION NO : SLP9188G ALONG JALAN PENDEKAR 18 ON
26 OCTOBER 2019 AT ABOUT 1110 HRS.

Supplementary front part items :		Cost Price	
Ipc	Front bumper sponge <i>SVC</i>	\$	<i>CM</i> 50.00 ✓
	Sub A total :	\$	50.00
	After GST 7% :	\$	3.50
	Mark up 15% :	\$	7.50
	A total :	\$	61.00
Grand final amount :		\$	61.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tropical Tech Automobile Services



(Authorised Signature)
William Tan

Tropical Tech Automobile Services

Blk 3030, Ang Mo Kio Avenue 3, #01-201, Industrial Park 2, Singapore 569535
Tel : 6481 7773 / 6481 1403 Fax : 6484 4978
E-mail : tase303@singnet.com.sg

M s: China Taiping Insurance (Singapore) Pte. Ltd.
105 Cecil Street
#18-00 / #19-00 / #16-01/02
The Octagon Singapore 069534

Estimate bill: TT 73 / 19 / TP / WT

Registration No: SLP9188G

Attn: Attention: Motor Claims Department
Tel: Tel: 6389 6111
Fax: Fax: 6222 1033

Make model: BMW 530i

Mileage:

Date: 05 / 11 / 2019

OWN DAMAGE CLAIM VEHICLE BEARING REGISTRATION NO: SLP9188G ALONG JALAN PENDEKAR 18 ON
26 OCTOBER 2019 AT ABOUT 1110 HRS.

		Cost Price	
1pc	Front bonnet 1250	S BT 1,350.00	-
1pc	Front kidney grille (L.H) 90	S CRA 90.00	-
1pc	Front kidney grille air duct	S R 220.00	X
1pc	Front L.H fender 580	S BUC 580.00	-
1pc	Front L.H fender 1st bracket 25	S D.I 75.00	-
1pc	Front L.H fender cowling (Front)	S SVC 90.00	X
1pc	Front LED head-lamp (L.H) 2250	S Bro 3,250.00	-
1pc	Front LED head-lamp panel (L.H)	S R 110.00	X
1pc	Front bumper 900	S BUC 900.00	-
1pc	Front bumper parktronic sensor (Extreme, L.H)	S R 150.00	X
1pc	Front bumper lower side grille (L.H) 70	S CRA 70.00	-
1pc	Front bumper lower side grille chrome (L.H) 50	S CRA 50.00	-
1pc	Front bumper fog lamp (L.H) 220	S mtg CRA 230.00	-
1pc	Front bumper side bracket (L.H) 12	S D.I 17.00	-
1pc	Front bumper frame (L.H) 55	S CRA 55.00	-
1pc	Front bumper reinforcement 440	S BT 450.00	-
	Sub A total:	S 7,652.00	
	After GST 7%:	S 5,542.4	
	Mark up 15%:	S 1,114.80	
	A total:	S 9,311.01	

Total amount of Page 1:

Tropical Tech Automobile Services

(Authorised Signature)
William Tan

7052
GST : 493.64
Mark up 15% : 1057.80
8,603.44

Tropical Tech Automobile Services

Blk 5030, Ang Mo Kio Avenue 3, #01-201, Industrial Park 2, Singapore 569535
Tel : 6481 7773 / 6481 1403 Fax : 6484 4978
E-mail : tasc303@singnet.com.sg

M : S : China Taiping Insurance (Singapore) Pte. Ltd.
105 Cecil Street
#18-00 / #19-00 / #16-01/02
The Octagon Singapore 069534

Estimate bill : TT 73 / 19 / TP / WT

Registration No : SLP9188G

Attn : Attention : Motor Claims Department
Tel : Tel : 6389 6111
Fax : Fax : 6222 1033

Make model : BMW 530i

Mileage :

Date : 05 / 11 / 2019

OWN DAMAGE CLAIM VEHICLE BEARING REGISTRATION NO : SLP9188G ALONG JALAN PENDEKAR 18 ON 26 OCTOBER 2019 AT ABOUT 1110 HRS.

Remove and transfer front bonnet necessary attachment spart part items.

Remove and transfer front bumper necessary attachment spart part items.

Remove and refit front bonnet, front kidney grille (L.H), front kidney grille air duct, front L.H fender, front L.H fender 1st bracket, front L.H fender cowl (Front), front L.H head-lamp (L.H), front L.H head-lamp panel (L.H), front bumper, front bumper parktronic sensor (Extreme, L.H), front bumper lower side grille (L.H), front bumper lower side grille chrome (L.H), front bumper fog lamp (L.H), front bumper side bracket (L.H), front bumper frame (L.H), front bumper reinforcement.

S 1,500.00 600

Heat / weld / beating / pull / straighten / align front chassis frame by Chassis Alignment jack.

Tuff kote front damaged portion.

S NI 150.00 X

Diagnostic and reset front parktronic sensor system by HHT

S 60 80.00

Putty / primer application, spray painting on front bonnet, front L.H fender, front bumper, front bumper parktronic sensor (Extreme, L.H).

S 750 1,200.00

Balance amount brought from Page 1 :

S 9,311.04

Grand final amount :

S 12,241.04

Tropical Tech Automobile Services

Labour: 1,410

(Authorised Signature)
William Tan

Total : 8,603.44 +
272.55 +
1,410 +

10,285.99



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 7454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

TROPICAL SUCCESS AUTO CARE
BLK 5032 #01-303
ANG MO KIO IND PARK 2

TEL : 64812898 FAX : 64811403
ATTN :

TODAY

Arrange By
Driver *TAN*
Dept Direct: 6417 9791 / 6746 3009



Dept Direct: 6305 9010

Dept Direct: 6305 9011

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9797

Wiper blade: NWB (Nippon Wiper blade), Silver (Made in Korea)

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201911-01608
DATE : 04/11/2019
CUSTOMER ID : 1R0001
VEH REG. NO. : SL19188
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 2
CURR. : SGD

✓ SQ STOCK ID	DESCRIPTION	SIK TAG	QTY	U/PRICE	AMOUNT
1. 41007440427 G30	ALUMINIUM BONNET	CC CC2-G-010	1	1350.00	1,350.00
2. 51137390865 G30	GRILLE, FRT LH (LUXURY)	CC CC2-D-02C	1	90.00	90.00
3. 51137497281 G30 530I	AIR FLAPS, TOP	CC CC2-F-02AA	1	220.00	220.00
4. 41007443687 G30	SIDE PANEL, ALUMINIUM, FRT LH	CC CC2-H-05D	1	580.00	580.00
5. 63117214963 G30	ILLUM LAMP LED AIL LH (ICON LIGHT)	CC CC2-K-06B	1	3250.00	3,250.00
6. 51117427441 G30 530I	FRT BUMPER (LINE)	CC CC3-C-04A	1	900.00	900.00
7. 51117385277 G30 530I	GRILLE, AIR INLET, OPEN, LH	CC CC2-G-02AA	1	70.00	70.00

CONTINUE NEXT PAGE

[P] 04/11/2019 16:17:23

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

ORIGINAL

[E] 04/11/2019 4:09:03PM



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO. M2-0119201-3 CO. REG. NO. 199307741M

TROPICAL SUCCESS AUTO CARE

BLK 5032 #01-303

ANG MO KIO IND PARK 2

TEL : 64812898 FAX : 64811403

ATTN :

WIPER BLADE
Dept Direct: 6417 9791 / 6745 9028



Dept Direct: 6417 9324

Dept Direct: 6417 9796

Dept Direct: 6417 9796

Dept Direct: 6417 9796

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea)

Forch (Made in Germany)

Spark plug: Hirschman (Hirschman) (Made in Japan)

TAX INVOICE : AR201911-01608

DATE : 04/11/2019

CUSTOMER ID : IRO001

VEH REG. NO. : SLI9188

TERMS : 30 days

PO NO. :

PAGE NO. : Page 2 of 2

CURR. : SGD

SQ	STOCKID	DESCRIPTION	Skf Loc	QTY	U/PRICE	AMOUNT
8.	51117385283	FRT BUMPER GRILLE FINISHER	CC	1	50.00	50.00
	G30 530I	RED LH fog lamp lower side grill chain	CC2-M-07D			
9.	51117385347	GUIDE TOP LH	CC	1	25.00	25.00
	G30	Front wheel hub bracket	CC2-H-07AD			
10.	51117385345	SUPPORT FOOT LAMP LH	CC	1	55.00	55.00
	G30 530I	Front bumper frame	CC2-C-02S			

SUB-TOTAL : 6,590.00
ADDD (GST 7.00 %) 461.30

E. & O.E TOTAL AMOUNT SGD: 7,051.30

[P] 04/11/2019 16:17:24

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 04/11/2019 4:09:03PM

JAE Auto Pte. Ltd.

Sales Executive: QIANG



* AR201911-01608 *

This is computer generated document.

No signature is required.

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

60 JALAN LAM HUAT #B1-05/06 CARROS CENTRE
SINGAPORE 737869 TEL: 63625226 FAX: 63626977

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

TROPICAL SUCCESS AUTO CARE

BLK 5032 #01-303

ANG MO KIO IND PARK 2

TEL : 64812898 FAX : 64811403

ATTN :

Arrange By
Driver



Dept Direct: 6417 9791 / 6745 9838



Dept Direct: 6417 9794



Dept Direct: 6300 9610



Dept Direct: 6417 9795



Dept Direct: 6300 9611



Dept Direct: 6417 9796



Dept Direct: 6300 9611



Dept Direct: 6417 9796



Dept Direct: 6417 9792



Dept Direct: 6417 9796



Dept Direct: 6417 9795



Dept Direct: 6417 9795

Wiper blade: NWB (Nippon Wiper blades), Siiper (Made in Korea)
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201911-02264
DATE : 05/11/2019
CUSTOMER ID : TRO001
VEH REG. NO. : SLP9188
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. 51647383857 G30	H/LIGHT PANEL LH <i>Penit with head lamp panel</i>	U2 SUPPLIER	1	110.00	110.00
2. 51137416456 G30	ADJUSTMENT ELEMENT ✓	U2 BM-A15-H3	2	5.00	10.00

SUB-TOTAL : 120.00
ADD GST 7.00 % 8.40

E. & O.E TOTAL AMOUNT SGD : 128.40

[E] 05/11/2019 3:26:13PM

[P] 05/11/2019 3:33:08PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : QIANG



AR201911-02264

This is computer generated document.
No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

60 JALAN LAM HUAT #B1-05/06 CARROS CENTRE
SINGAPORE 737869 TEL: 63625226 FAX: 63626977

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WIPER BLADES
Dept Direct: 6417 9791 / 6745 9909



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Silver (Made in Korea),

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TROPICAL SUCCESS AUTO CARE

BLK 5032 #01-303

ANG MO KIO IND PARK 2

TEL : 64812898 FAX : 64811403

ATIN :

TAX INVOICE : AR201911-04481
DATE : 09/11/2019
CUSTOMER ID : TRO001
VEH REG. NO. : SLP9188
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1	51117385263 G30 530I	COVER, GRILLE, LH ✓	U2 BM-A106-L	1	45.00	45.00

SUB-TOTAL : 45.00
ADD GST 7.00 % 3.15

E & OE TOTAL AMOUNT SGD : 48.15

[P] 09/11/2019 9:24:31AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 09/11/2019 9:20:30AM

Goods Received in Good Order

JAE Auto Pte. Ltd.

Sales Executive : QIANG



* AR201911-04481 *

This is computer generated document.

No signature is required.

ORIGINAL

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSHIELD GLASS
Dept Direct: 6417 8791 / 6745 8828



Dept Direct: 6305 9810

Dept Direct: 6305 9811

Dept Direct: 6417 8792



Dept Direct: 6417 8794

Dept Direct: 6417 8795

Dept Direct: 6417 8796

Dept Direct: 6417 8797

Wiper blade: NWB (Nippon Wiper blade), Super (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

TROPICAL SUCCESS AUTO CARE
BLK 5032 #01-303
ANG MO KIO IND PARK 2

TEL : 64812898 FAX : 64811403
ATTN :

TAX INVOICE : AR201911-02251
DATE : 05/11/2019
CUSTOMER ID : 1RO001
VEH REG. NO. : SL19188
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ STOCKID	DESCRIPTION	SK1 and	QTY	UPPRICE	AMOUNT
1. 51767349605 G30	SIDE PANEL SEALING LH Front LH Panel top covering (inside)	CC CC2-D-02AA	1	25.00	25.00

SUB-TOTAL : 25.00
ADD GST 7.00 % 1.75

E & O E

TOTAL AMOUNT SGD : 26.75

[P] 05/11/2019 15:14:59

[E] 05/11/2019 3:14:27PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: QIANG

This is computer generated document.

No signature is required.



* AR201911-02251 *

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Bik 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

60 JALAN LAM HUAT #B1-05/06 CARROS CENTRE

SINGAPORE 737869 TEL: 63625226 FAX: 63626977

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

Arrange By *Gron*
Driver
Dept Direct: 6417 9791 / 6745 9939



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9797

Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea),

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201911-02476
DATE : 06/11/2019
CUSTOMER ID : TRO001
VEH REG. NO. : SLP9188
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

ROPICAL SUCCESS AUTO CARE

LK 5032 #01-303

NG MO KIO IND PARK 2

EL : 64812898 FAX : 64811403

ITN :

STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. 07149807127 R60 R61	EXPANDING RIVET (L=11MM) Front LH fender chrome moulding	U2 BM-A15-D8	4	1.00	4.00
2. 07147378241 F32 G12	RIVET Front LH fender chrome moulding	U2 SUPPLIER	9	3.20	28.80

SUB-TOTAL : 32.80
ADD GST 7.00 % 2.30

E & O E

TOTAL AMOUNT SGD : 35.10

06/11/2019 10:08:46AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 06/11/2019 9:29:34AM

Goods Received in Good Order

JAE Auto Pte. Ltd.

Sales Executive : QIANG



This is computer generated document.

No signature is required.

ORIGINAL

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSHIELD GLASS
Dept Direct: 6417 8101 / 6745 9628



Dept Direct: 6205 9610

Dept Direct: 6205 9611

Dept Direct: 6417 8782



Dept Direct: 6417 8784

Dept Direct: 6417 8785

Dept Direct: 6417 8786

Dept Direct: 6417 8787

Wiper blade: NWS (Nippon Wiper blade), Silver (Made in Korea),
Foch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

TROPICAL SUCCESS AUTO CARE
BLK 5032 #01-303
ANG MO KIO IND PARK 2

TEL : 64812898 FAX : 64811403
ATTN :

TAX INVOICE : AR201911-02259
DATE : 05/11/2019
CUSTOMER ID : TRO001
VEH REG. NO. : SL19188
TERMS : 30 days
PO NO.
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ	STOCKID	DESCRIPTION	SKT	QTY	U/PRICE	AMOUNT
1.	51717340785 G30	FRONT FENDER INNER SHIELD LH <i>coming</i>	CC CC2-B-03S	1	90.00	90.00
2.	51137359838 G30	AIR DUCT BOTTOM Front bumper lower grill (center) ✓	CC CC2-G-05AA	1	40.00	40.00
3.	63117214939 G30	DRIVING DAYLIGHT LED MODULE LH From LH LED driving daylight ballast ✓	CC CC2-J-08AA	1	150.00	150.00

SUB-TOTAL : 280.00
ADD GST 7.00 % 19.60

E & OE

TOTAL AMOUNT SGD : 299.60

[P] 05/11/2019 15:35:18

[E] 05/11/2019 3:23:14PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: QIANG

This is computer generated document.

No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

60 JALAN LAM HUAT #B1-05/06 CARROS CENTRE

SINGAPORE 737869 TEL: 63625226 FAX: 63626977

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

TROPICAL SUCCESS AUTO CARE

BLK 5032 #01-303

ANG MO KIO IND PARK 2

TEL: 64812898 FAX: 64811403

ATTN:

Depot Direct: 8417 9791 / 8745 9009



Wiper blade: NWS (Nippon Wiper blade), Silper (Made in Korea).

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201911-01629
DATE : 04/11/2019
CUSTOMER ID : TRO001
VEH REG. NO. : SLP9188
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. 51117385349 G30	GUIDE BUMPER, LH <i>Front bumper side bracket</i>	U2 BM-A15-C9	1	12.00	12.00
2. 51117385285 G30	FRT BUMPER SPONGE	U2 SUPPLIER	1	60.00	60.00
3. 51117385288 G30	FRT BUMPER REINFORCEMENT	U2 SUPPLIER	1	440.00	440.00

SUB-TOTAL : 512.00
ADD GST 7.00 % 35.84

E & O.E TOTAL AMOUNT SGD : 547.84

04/11/2019 5:21:15PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 04/11/2019 4:21:34PM

AE Auto Pte. Ltd.

Sales Executive: QIANG

This is computer generated document.

No signature is required.



* AR 201911-01629 *

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

TROPICAL SUCCESS AUTO CARE

BLK 5032 #01-303

ANG MO KIO IND PARK 2

TEL : 64812898 FAX : 64811403

ATTN :

WINDSHIELD GLASS
Dept Direct: 6417 9791 / 6745 9030



Dept Direct: 6305 9612

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9790

Dept Direct: 6417 9796

Dept Direct: 6417 9799

Wiper blade: NIPPON (Nippon Wiper blade), Siliper (Made in Korea)

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201911-01753

DATE : 05/11/2019

CUSTOMER ID : 1RO001

VEH REG. NO. : SLI9188

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR. : SGD

SQ STOCKID	DESCRIPTION	SK1.00	QTY	U/PRICE	AMOUNT
1. 63177349131 G30	FOG LAMP LH Front bumper	CC CC2-M-02C	1	230.00	230.00

SUB-TOTAL : 230.00
ADD GST 7.00 % 16.10

E & O E TOTAL AMOUNT SGD : 246.10

[P] 05/11/2019 09:18:14

[E] 05/11/2019 9:16:43AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: QIANG



* 4 8 2 0 1 9 1 1 - 0 1 7 5 3 *

This is computer generated document.

No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date

Tropical Tech Automobile Services

Bik 5030, Ang Mo Kio Avenue 3, #01-201, Industrial Park 2, Singapore 569535

Tel : 6481 7773 / 6481 1403 Fax : 6484 4978

E-mail : tase303@singnet.com.sg

M/s : China Taiping Insurance (Singapore) Pte. Ltd.
3, Anson Road, #16-00,
Springleaf Tower,
Singapore 079909

Final bill : TT 73 / 19 / OD / WT

Registration No : SLP9188G

Attn : Motor Claims Department
Tel : 6389 6111
Fax : 6222 1033

Make model : BMW 530i

Mileage : Date : 31 / 12 / 2019

OWN DAMAGE CLAIM VEHICLE BEARING REGISTRATION NO : SLP9188G ALONG JALAN PENDEKAR
18 ON 26 OCTOBER 2019 AT ABOUT 1110HRS.

	Cost Price
1pc Front bonnet	\$ 1,350.00
1pc Front kidney grille (LH)	\$ 90.00
1pc Front LH fender	\$ 580.00
1pc Front LH fender 1st bracket	\$ 25.00
1pc Front LED head-lamp (LH)	\$ 3,250.00
1pc Front bumper	\$ 900.00
1pc Front bumper lower side grille (LH)	\$ 70.00
1pc Front bumper lower side grille chrome (LH)	\$ 50.00
1pc Front bumper fog lamp (LH)	\$ 230.00
1pc Front bumper side bracket (LH)	\$ 12.00
1pc Front bumper frame (LH)	\$ 55.00
1pc Front bumper reinforcement	\$ 440.00
Sub A total :	\$ 7,052.00
After GST 7% :	\$ 493.64
Mark up 15% :	\$ 1,057.80
A total :	\$ 8,603.44
Total amount of Page 1 :	\$ 8,603.44

Tropical Tech Automobile Services


(Authorised Signature)
William Tan



Tropical Tech Automobile Services

Blk 5030, Ang Mo Kio Avenue 3, #01-201, Industrial Park 2, Singapore 569535

Tel : 6481 7773 / 6481 1403 Fax : 6484 4978

E-mail : tase303@singnet.com.sg

M / s : China Taiping Insurance (Singapore) Pte. Ltd.
3, Anson Road, #16-00,
Springleaf Tower,
Singapore 079909

Final bill : TT 73 / 19 / OD / WT

Registration No : SLP9188G

Attn : Motor Claims Department
Tel : 6389 6111
Fax : 6222 1033

Make model : BMW 530i

Mileage : Date : 31 / 12 / 2019

OWN DAMAGE CLAIM VEHICLE BEARING REGISTRATION NO : SLP9188G ALONG JALAN PENDEKAR
18 ON 26 OCTOBER 2019 AT ABOUT 1110HRS.

Supplemntnary spare part items :

		Cost Price
1pc	Front LH fender top covering (Inside)	\$ 25.00
2pcs	Front LH fender chrome moulding rivet (Each \$4.20)	\$ 8.40
1pc	Front LH head-lamp driving daylight LED ballast	\$ 150.00
1pc	Front bumper lower grille air duct (Centre)	\$ 40.00
	Sub B total :	\$ 223.40
	After GST 7% :	\$ 15.64
	Mark up 15% :	\$ 33.51
	B total :	\$ 272.55

Remove and transfer front bonnet necessary attachment spart part items.

Remove and transfer front bumper necessary attachment spart part items.

Remove and refit font bonnet, front kidney grille (LH), front LH fender 1st bracket , front LED head-lamp (LH), front bumper, front bumper lower side grille (LH), front bumper lower side grille chrome (LH), front bumper fog lamp (LH), front bumper side bracket (LH), front bumper frame (LH), front bumper reinforcement.

Heat /weld / beating / pull / straighten / align front chassis frame by Chassis Alignment jack.

\$ 600.00

Total amount of Page 2 :

\$ 872.55

Tropical Tech Automobile Services

(Authorised Signature)
William Tan



Tropical Tech Automobile Services

Blk 5030, Ang Mo Kio Avenue 3, #01-201, Industrial Park 2, Singapore 569535

Tel : 6481 7773 / 6481 1403 Fax : 6484 4978

E-mail : tasc303@singnet.com.sg

M / s : **China Taiping Insurance (Singapore) Pte. Ltd.**
3, Anson Road, #16-00,
Springleaf Tower,
Singapore 079909

Final bill : TT 73 / 19 / OD / WT

Registration No : SLP9188G

Attn : Motor Claims Department
Tel : 6389 6111
Fax : 6222 1033

Make model : BWM 530i

Mileage : Date : 31 / 12 / 2019

**OWN DAMAGE CLAIM VEHICLE BEARING REGISTRATION NO : SLP9188G ALONG JALAN PENDEKAR
18 ON 26 OCTOBER 2019 AT ABOUT 1110HRS.**

Diagnostic and reset front parktronic sensor system by HHT	S	60.00
Putty / primer application, spray painting on front bonnet, front LH fender, front bumper, front bumper parktronic sensor (Extreme, LH).	S	750.00
Balance amount brought from Page 1 :	S	8,603.44
Balance amount brought from Page 1 :	S	872.55
Less own damaged insurance excess :	S	(800.00)
Grand final amount :	S	9,485.99

Tropical Tech Automobile Services


(Authorised Signature)
William Tan



Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 10 February 2020 10:32 AM
To: William Tan; Kenneth Kong (LKKAUTO); SUR
Subject: RE: SLP9188G, Accident dated 26 October 2019

Dear William

Confirmed amount \$10,285.99 before excess \$800 @ 5 working days.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: William Tan <tanlihao74@gmail.com>
Sent: Saturday, 8 February 2020 6:19 PM
To: Kenneth Kong (LKKAUTO) <KennethKong@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; William Tan <tanlihao74@gmail.com>
Subject: Fwd: SLP9188G, Accident dated 26 October 2019

Dear Sir / Madam,

Please refer to attach documents.

This is how I work up the amount for this vehicle.

Please advised ?

Your message is ready to be sent with the following file or link attachments:

IMG_20200208_0001

Note: To protect against computer viruses, e-mail programs may prevent sending or receiving certain types of file attachments. Check your e-mail security settings to determine how attachments are handled.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Nov 2019		04 Nov 2019 09:37 Edit Adj Rpt	S\$10,285.99 Edit Estimates	S\$10,285.99 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	YANG YI ALBERT, ID: S1507334I, Tel: +6581139939, Email: NOEMAIL								
Vehicle Reg. No.:	SLP9188G	Date of Loss:	26/10/2019 11:00 - :59 [30 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / SNM19D205108C01	Policy/Cover Note No.:	DMPCSN1734361902 (Comprehensive)						
		Excess:	S\$800.00						
Repairer:	Tropical Success Auto Care (HQ) BLK 5032 Ang Mo Kio Avenue 3, #01-303 Industrial Park 2, 569535 Ang Mo Kio - Tel: 6481 7773								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 13/11/2019]								
Driver/Custodian:	YANG YI ALBERT (58 / Male), NRIC: S1507334I, Tel: +6581139939 Email: NOEMAIL								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
CHINA_TAIPIING (05/11/2019): Alert - Adj Mandate Approved (S\$10552.40) - SLP9188G - Claim Handler: Chong Boon...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLP9188G (SNM19D205108C01)

OD

Oct 26 2019 11:00AM

[YANG YI ALBERT]

Tropical Success Auto Care

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Video			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	29/10/19 12:42	Video - Accident [Linked Accident Report Documents]	Load AVI	
Assessment Reports			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	31/10/19 11:02	Addendum Sheet	Load JPG	☒
2	31/10/19 12:31	Addendum Sheet	Load JPG	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/11/19 10:17	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	29/10/19 12:41	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
2	29/10/19 12:41	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
3	29/10/19 12:41	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
4	29/10/19 12:41	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
5	29/10/19 12:41	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
6	29/10/19 12:41	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
7	29/10/19 12:41	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
8	29/10/19 12:41	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
9	29/10/19 12:41	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
10	29/10/19 12:41	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
11	29/10/19 12:41	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
12	29/10/19 12:41	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
13	29/10/19 12:41	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
14	29/10/19 12:41	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/11/19 10:18	General View	Load PDF	
2	10/02/20 10:29	Reinspection Photo	Load PDF	
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	04/11/19 09:37	od estimate	Load PDF	
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	29/10/19 12:42	Accident Sketch Plan [Linked Accident Report Documents]	Load JPG	☒
2	29/10/19 12:42	Accident Sketch Plan [Linked Accident Report Documents]	Load JPG	☒
3	29/10/19 12:42	Police Report	Load JPG	

Video			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
		[Linked Accident Report Documents]		☒
4	29/10/19 12:42	Police Report [Linked Accident Report Documents]	Load JPG	☒
5	29/10/19 12:42	Police Report [Linked Accident Report Documents]	Load JPG	☒
6	29/10/19 12:42	Police Report [Linked Accident Report Documents]	Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/11/19 15:54	MARK ESTIMATE (LIST)	Load PDF	
2	05/11/19 10:19	MARK ESTIMATE (COST PRICE)	Load PDF	
3	12/02/20 17:18	Parts Invoice	Load PDF	
4	13/02/20 08:29	Supplementary	Load PDF	

Linked Accident Report Documents

Video			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	29/10/19 12:42	Video - Accident	Load AVI	
Assessment Reports			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	31/10/19 11:02	Addendum Sheet	Load JPG	☒
2	31/10/19 12:31	Addendum Sheet	Load JPG	☒
3	06/12/19 19:06	Accident Statement	Load HTM	
4	06/12/19 19:06	Accident Statement	Load HTM	
5	06/12/19 19:09	Accident Statement	Load HTM	
6	06/12/19 19:09	Accident Statement	Load HTM	
7	06/12/19 19:12	Accident Statement	Load HTM	
8	06/12/19 19:13	Accident Statement	Load HTM	
9	06/12/19 19:14	Accident Statement	Load HTM	
10	06/12/19 19:15	Accident Statement	Load HTM	
11	06/12/19 19:15	Accident Statement	Load HTM	
12	06/12/19 19:17	Accident Statement	Load HTM	
13	06/12/19 19:17	Accident Statement	Load HTM	
14	06/12/19 19:17	Accident Statement	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	29/10/19 12:41	Accident Photo	Load JPG	☒
2	29/10/19 12:41	Accident Photo	Load JPG	☒
3	29/10/19 12:41	Accident Photo	Load JPG	☒
4	29/10/19 12:41	Accident Photo	Load JPG	☒
5	29/10/19 12:41	Accident Photo	Load JPG	☒
6	29/10/19 12:41	Accident Photo	Load JPG	☒
7	29/10/19 12:41	Accident Photo	Load JPG	☒
8	29/10/19 12:41	Accident Photo	Load JPG	☒
9	29/10/19 12:41	Accident Photo	Load JPG	☒
10	29/10/19 12:41	Accident Photo	Load JPG	☒
11	29/10/19 12:41	Accident Photo	Load JPG	☒
12	29/10/19 12:41	Accident Photo	Load JPG	☒
13	29/10/19 12:41	Accident Photo	Load JPG	☒
14	29/10/19 12:41	Accident Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	29/10/19 12:42	Accident Sketch Plan	Load JPG	

Video			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubl)	Thumbnail	Print
				☒
2	29/10/19 12:42	Accident Sketch Plan	 Load JPG	☒
3	29/10/19 12:42	Police Report	 Load JPG	☒
4	29/10/19 12:42	Police Report	 Load JPG	☒
5	29/10/19 12:42	Police Report	 Load JPG	☒
6	29/10/19 12:42	Police Report	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT119019400/KVF3E2

Date: 13/02/2020

REFERENCE

Insured/Claimant: YANG YI ALBERT Policy No: DMPCSN1734361902
Date of Loss: 26/10/2019 Nature of Claim: OD Claim No: SNM19D205108C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLP9188G**
Make & Model: BMW 530i, 2.0 LED NAV (A) Engine No: 14229889B48B20B
Reg. Date: 25/04/2017 (Man. Year: 2017) Chassis No: WBAJA52030G885102
Colour: Metallic Silver Odometer: 49790 km
Engine Capacity: 1998 cc
Market Value/New Car Price: S\$178,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R19 Rear Tyre Size: 275/35 R19
Front Left Side: Michelin 8 mm Rear Left Side: Michelin 8 mm
Front Right Side: Michelin 8 mm Rear Right Side: Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,171.25	8,875.99	295.26	3.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,730.00	1,410.00	2,320.00	62.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,901.25	10,285.99	2,615.26	20.27
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	12,101.25	9,485.99	2,615.26	21.61
+ GST 7.00/7.00% (S\$)	847.09	664.02	183.07	21.61
Nett Amount (S\$)	12,948.34	10,150.01	2,798.33	21.61

INSPECTION

Date of Assignment: 04/11/2019
Date Inspected: 04/11/2019 Inspected At: Tropical Success Auto Care (HQ)
BLK 5032 Ang Mo Kio Avenue 3, #01-303
Industrial Park 2
Singapore 569535
Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Feb 2020)
Parts:	143	BMW 530i 2.0 LED NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP9188G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BONNET (WCP)	Bent	1,350.00 F	*1,350.00 F
2	1	*FRONT KIDNEY GRILLE (LH) (WCP)	Cracked	90.00 F	*90.00 F
3	1	*FRONT KIDNEY GRILLE AIR DUCT (WCP)	Serviceable	220.00 F	*- F
4	1	*FRONT LH FENDER (WCP)	Buckled	580.00 F	*580.00 F
5	1	*FRONT LH FENDER 1ST BRACKET (WCP)	Distorted	25.00 F	*25.00 F
6	1	*FRONT LH FENDER COWLING (FRONT) (WCP)	Serviceable	90.00 F	*- F
7	1	*FRONT LED HEAD-LAMP (LH) (WCP)	Broken	3,250.00 F	*3,250.00 F
8	1	*FRONT LED HEAD-LAMP PANEL (LH) (WCP)	Repair	110.00 F	*- F
9	1	*FRONT BUMPER (WCP)	Buckled	900.00 F	*900.00 F
10	1	*FRONT BUMPER PARKTRONIC SENSOR (EXTREME, LH) (WCP)	Serviceable	150.00 F	*- F
11	1	*FRONT BUMPER LOWER SIDE GRILLE (LH) (WCP)	Cracked	70.00 F	*70.00 F
12	1	*FRONT BUMPER LOWER SIDE GRILLE CHROME (LH) (WCP)	Cracked	50.00 F	*50.00 F
13	1	*FRONT BUMPER FOG LAMP (LH) (WCP)	Mtg Cracked	230.00 F	*230.00 F
14	1	*FRONT BUMPER SIDE BRACKET (LH) (WCP)	Distorted	12.00 F	*12.00 F
15	1	*FRONT BUMPER FRAME (LH) (WCP)	Cracked	55.00 F	*55.00 F
16	1	*FRONT BUMPER REINFORCEMENT (WCP)	Bent	450.00 F	*440.00 F
17	2	*FRONT LH FENDER CHROME MOULDING RIVET (WCP)	Necessary	10.00 F	*8.40 F
18	1	*FRONT LH HEAD-LAMP DRIVING DAYLIGHT LED BALLAST (WCP)	Cracked	150.00 F	*150.00 F
19	1	*FRONT BUMPER UNDER SIDE DUST COVERING (LH) (WCP)	Serviceable	58.00 F	*- F
20	1	*FRONT BUMPER LOWER GRILLE AIR DUCT (CENTRE) (WCP)	Dented	40.00 F	*40.00 F
21	1	*FRONT BUMPER SPONGE (WCP)	Serviceable	60.00 F	*- F
22	1	*PARTS GST (7%)		-	*509.28 FS
23	1	*FRONT LH FENDER TOP COVERING (INSIDE) (WCP)	Cracked	25.00 F	*25.00 F

F=Franchise part. S=SpcNett.

Sub Total (S\$) 7,975.00 7,784.68

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				+ Margin on L,N Items 15.00/15.00% (S\$)	1,196.25	1,091.31
				Total Parts (S\$)	9,171.25	8,875.99

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PROGRAMMING FRONT HEAD-LAMP DRIVING DAYLIGHT BALLAST	New	600.00	0.00
2	PUTTY / PRIMER APPLICATION, SPRAY PAINTING ON FRONT LH DOOR	New	200.00	0.00
3	REMOVE AND TRANSFER FRONT BONNET NECESSARY ATTACHMENT SPART PART ITEMS (NPA)	New	0.00	0.00
4	REMOVE AND TRANSFER FRONT BUMPER NECESSARY ATTACHMENT SPART PART ITEMS (NPA)	New	0.00	0.00
5	REMOVE AND REFIT FRONT BONNET, FRONT KIDNEY GRILLE (LH), FRONT KIDNEY GRILLE AIR DUCT, FRONT LH FENDER, FRONT LH FENDER 1ST BRACKET, FRONT LH FENDER COWLING (FRONT), FRONT LED HEAD-LAMP (LH), FRONT LED HEAD-LAMP PANEL (LH), FRONT BUMPER, FRONT BUMPER PARKTRONIC SENSOR (EXTREME, LH), FRONT BUMPER LOWER SIDE GRILLE (LH), FRONT BUMPER LOWER SIDE GRILLE CHROME (LH), }	New	1,500.00	600.00
6	FRONT BUMPER FOG LAMP (LH), FRONT BUMPER SIDE BRACKET (LH), FRONT BUMPER FRAME (LH), FRONT BUMPER REINFORCEMENT }	New	0.00	0.00
7	HEAT / WELD / BEATING / PULL / STRAIGHTEN / ALIGN FRONT CHASSIS FRAME BY CHASSIS ALIGNMENT JACK (NPA)	New	0.00	0.00
8	TUFF KOTE FRONT DAMAGED PORTION	New	150.00	0.00
9	DIAGNOSTIC AND RESET FRONT PARKTRONIC SENSOR SYSTEM BY HHT	New	80.00	60.00
10	PUTTY / PRIMER APPLICATION, SPRAY PAINTING ON FRONT BONNET, FRONT LH FENDER, FRONT BUMPER, FRONT BUMPER PARKTRONIC SENSOR (EXTREME, LH)	New	1,200.00	750.00
Gross Labour Cost (S\$)			3,730.00	1,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >