

ASS. REC. BY:

REF: CS/PC1909402/Ey fb 02
Special Instruction:

Surveyor: Steve ASSIGNMENT (Office)

(cws) From (Person): Jason Tan chu tiat of Fc1 Date/Time: 1.11.19 754p.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLP 1894D Insured: SH 9709M

at Workshop m/s Trans Eurocars Tel: 81289802

of 27A Tanjong Penjun

Policy No: Claim No: D19006819MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 24.10.2019

(Client's Record)


CA / REV / REP. / REV 24 HRS

Date/Time: 4.11.19 10.51a.m Person Contacted: Jess Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SLP 1894P -x
	SH 9709M -CS / msg 18004204 / End 3h2 D.O.A. - 02/10/2018
11/11/19	@ 15:10pm revised PA to Jason via email.

ASSIGNMENT

From: _____ Date: 8/11/19
 Estimated Cost: _____
 OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SLP 1894D
 at Workshop m/s: TransEunokars
 of: 27A Tanjung Pongum
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: 11am (waiting)
Look for Jobi



(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS (DS)

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLP 1894D Yr Regn: 29/5/17
 Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Mazda 5 C.C: 1998
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 55632 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JM6CW1071H10125433
 Gen. Cond: ☒ Good / Fair / Poor / Burnt
 Steering: ☒ In order / Jammed / Leaked / Burnt or
 Brake: ☒ In order / Jammed / Leaked / Burnt or
 Modi: ☒ Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 205/55R1
 R: _____
☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: _____ Rear: _____
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 24/10/19 D.O.I. 8/11/19
 Survey held at Trans Eunokars
 Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>MV - 76K</u>
<u>01/1/20</u>	<u>PIP \$3187-40 @ 3 repair day (Red \$4043-60, 55%)</u>
RECEIVED 09 JAN 2020	

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) 9/1/20 Typist

Report Format:

Lump Sum / L.B.P. (C)

PIP \$3187-40

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

3-RS \$

Photos

Others

TOTAL

150

50

50

17

267



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19006819MFSH

Date: 11 November 2019

Our Ref: CS/FCI19019402/Eyf3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLP 1894D

Please be informed that we had conducted the inspection of the abovementioned vehicle on 08/11/2019 at the premises of M/s Trans Eurokars Pte Ltd and have the following to report:-


Workshop Estimate Amount	: S\$ <u>7,231.00</u>
Revised Estimate Amount	: S\$ <u>3,167.40</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the rear portion.

Comments/ Present Status:

Damages Consistent.
Repair days: 3 days



Yours faithfully

Steve Chen
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	25-10-2019	Our Ref No. D19006819MFSH
Accident Date	24-10-2019	Claim Type. Third Party
Insured Vehicle	SH9709M	Third Party Vehicle. SLP1894D
Survey Location	27A TANJONG PENJURU	
Contact Person.	JESS FRANCIS CARLOS	
Contact No.	81289802/ 81289802	Fax No. 0
Survey Type	DIRECT SETTLEMENT: TP VIDEO EVIDENCE (EST. COR - \$7231)	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS EUROKARS PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JASON TEA CHEE KIAT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Monday, 11 November 2019 3:10 pm
To: 'Jason Tea'; 'CWS Motor Claims'
Cc: assignments; SUR; Admin-D (LKKAuto)
Subject: RE: SURVEY ASSESSMENT - D19006819MFSH/1
Attachments: PRELI ADVISE - SLP 1894D.pdf

Dear Jason,

Enclosed preliminary revised of vehicle SLP 1894D.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Monday, 4 November 2019 10:52 am
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Jason Tea' <JasonTea@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19006819MFSH/1

Dear Sir/Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Steve Chen (LKK Auto)

From: Steve Chen (LKK Auto)
Sent: Tuesday, December 10, 2019 11:29 AM
To: catherinechua@eurokars.com.sg
Cc: jess.francis@eurokars.com.sg
Subject: RE: SLP1894D - FINALIZATION OF COR

Dear Catherine,

We confirm the finalize \$3187.40 (P/P, before GST). 3 repair days.

Thanks.

Best Regards,

Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: catherinechua@eurokars.com.sg [mailto:catherinechua@eurokars.com.sg]
Sent: Monday, December 09, 2019 5:32 PM
To: Steve Chen (LKK Auto)
Cc: jess.francis@eurokars.com.sg; CS A Team; Admin A
Subject: SLP1894D - FINALIZATION OF COR

Dear Steve

Our COR computation with B4 paint photos is attached for your agreement.

COR: \$3187.40 before GST

3 repair days (not including preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

Kindly confirm the above as soon as possible.

Thanks n Regards



Driving luxury experiences since 1985

Catherine Chua

Insurance Claims Executive

23 Leng Kee Road Singapore 159095

T: (65) 6603 6128 **D:** (65) 6603 6121 **F:** (65) 6476 7417

E: catherinechua@mazda.com.sg

This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	381H
Vehicle Details	
Vehicle No.:	SLP1894D
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Nov 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA5 5-DOOR WAGON 2.0L SP.6EAT SUNROOF
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	PE10467849
Chassis No.:	JM6CW1071H0125433
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$19,597.00
Original Registration Date:	29 May 2017
First Registration Date:	29 May 2017
Transfer Count:	0
Actual ARF Paid:	\$19,597.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 May 2027
PARF Rebate Amount:	\$14,697.00
Intended COE Rebate Details	
COE Expiry Date:	28 May 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$55,414.00
COE Rebate Amount:	\$41,813.00
Total Rebate Amount:	\$56,510.00

The information contained herein is correct as at 11 Nov 2019

OK

Motor Vehicles (Third-Party Risks And Compensation) Act (Chapter 189) (Republic of Singapore), Motor Vehicles (Third-Party Risks And Compensation) Rules, 1996 Edition (Republic of Singapore), Road Transport Act, 1987 (Malaysia), Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

Certificate Number P10055402R01 (Comprehensive / Named Driver Plan)

- | | | |
|--|---|--------------------|
| 1) Vehicle Registration Number | : | SLP1894D |
| Chassis Number | : | - |
| 2) Effective Date / Time of Commencement of Insurance for the Purpose of the Act | : | 29/05/2019 (00:00) |
| 3) Date / Time of Expiry of Insurance | : | 28/05/2020 (23:59) |
| 4) Excess (i) Policy | : | S\$ 500.00 |
| (ii) Windscreen | : | S\$ 100.00 |
| 5) Policyholder | : | Chong Xianming |

6) Persons or Classes of Persons Entitled to Drive*

Drivers named as a Main / Named Driver in this Certificate of Insurance only.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by any reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of accident or loss. Please refer to the Product Disclosure Document for full terms and conditions.

Main Driver / Date of Birth : Chong Xianming (15/03/1982)

Named Driver(s) / Date of Birth : Chua Lay Khim (01/12/1981)

7) Limitation as to use*

Use only for social, domestic and pleasure purposes. The Policy does not cover use for hire or reward, tuition or driving tests, racing, pace-making, reliability trials, speed-testing or the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

** Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.*

- | | | |
|--------------------|---|------------------------------|
| 8) Finance Company | : | United Overseas Bank Limited |
|--------------------|---|------------------------------|

I / We hereby certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

Issued in Singapore on
23/04/2019

Auto & General Insurance (Singapore) Pte. Limited
Trading as Budget Direct Insurance



Simon Birch



TRANS EUROKARS PTE LTD

ESTIMATE COST OF REPAIRS

2023/11/19
 930 hrs
 EUROKARS GROUP

FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877 ATTN. : MOTOR CLAIMS FAX :		NAME : Mr Chong Xianming ADDRESS : 511 Serangoon North Avenue 4 #11-314 Singapore 550511 TEL : 82004009		WIP : 39139 EXCESS : DATE : 29-Oct-19	
VEH NO :	SLP1894D	DATE IN :		CONTACT PERSON :	Jess 63957874
CHASSIS NO :	JM6CW1071H0125433	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA5	DATE REG. :	29-May-17	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY	REVISED	PRICES		
1	REAR BUMPER	1	MC513-50-221EBB		\$ 961.20
2	REAR BUMPER	2	MC235-56-B9XC		\$ 310.80
3	GROMMET, REAR BUMPER	4	MC235-50-ES1		\$ 18.80
4	GROMMET, REAR BUMPER	2	MBHN1-50-021A		\$ 5.40
5	GROMMET, REAR BUMPER	2	M9991-00-501		\$ 6.00
6	FASTENER, REAR BUMPER	2	MGD7A-50-EA1		\$ 6.40
7	FASTENER, REAR BUMPER	2	MB45A-56-146A		\$ 6.00
8	RIVET, REAR BUMPER	4	MBN8F-50-355		\$ 22.80
9	ORNAMENT, MAZDA	1	MCGY0-51-711		\$ 45.30
10	ORNAMENT, 5	1	MCGY0-51-721		\$ 36.30
11	MASCOT, REAR	1	MTD11-51-731		\$ 44.10
12	ORNAMENT, SKYACTIVE	1	MC597-51-771		\$ 80.00
13	CLIP, FINISHER	3	MEG21-51-SJ3		\$ 17.10
14	GASKET LHS, TAILGATE	1	MC513-51-3J8		\$ 95.40
15	GASKET RHS, TAILGATE	1	MC513-51-3H8		\$ 95.40
TOTAL PARTS					\$ 1,751.00
TOTAL PARTS COST					\$ 1,751.00
Labour Description					
1	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. TO REPAIR TAILGATE AND ALL AREAS AFFECTED BY THE ACCIDENT.			\$ 1,980.00
2	MZ-SP-SREAR4	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT AND TAILGATE.			\$ 1,890.00
3	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS. (WITH REVERSE SENSOR)			\$ 660.00
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.			\$ 250.00

5	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
7		TO SUPPLY BODY COATING.	X	NETT TBA
8	MZ-BR-SUNDRI	SUNDRIES.	NETT	\$ 100.00

TOTAL LABOUR	\$ -	\$ 5,480.00
TOTAL PARTS	\$ -	\$ 1,751.00
TOTAL	\$ -	\$ 7,231.00
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorized Signature

[Handwritten Signature]
3/1/2020

Steve (LKK)
8322 8813

W/L P/L 8/11/19, 11:30pm

3 day

P/P

Ry Bel SM

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



TRANS EUROKARS PTE LTD

ESTIMATE COST OF REPAIRS

2008/10/19

EUROKARS GROUP

930 hrs

FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877 ATTN. : FAX :	NAME : Mr Chong Xianming ADDRESS : 511 Serangoon North Avenue 4 #11-314 Singapore 550511 TEL : 82004009	WIP : 89139 EXCESS : DATE : 29-Oct-19
--	---	---

VEH NO : SLP1894D	DATE IN :	CONTACT PERSON : Jess 63957874
CHASSIS NO : JM6CW1071H0125433	MILEAGE :	TYPE OF CLAIM : THIRD PARTY CLAIM
MODEL : MAZDA5	DATE REG. 29-May-17	POLICY NO. :

NATURE OF WORKS

Parts Description

NO	QTY	REVISED	PRICES
1 REAR BUMPER Repair / 00	1	✓	MC513-50-221EBB \$ 961.20
2 REAR BUMPER X NAI	21		MC235-56-B9XC \$ 310.80
3 GROMMET, REAR BUMPER / N	4	✓	MC235-50-ES1 \$ 18.80
4 GROMMET, REAR BUMPER / N	2	✓	MBHN1-50-0Z1A \$ 5.40
5 GROMMET, REAR BUMPER / N	2	✓	M9991-00-501 \$ 6.00
6 FASTENER, REAR BUMPER / N	2	✓	MGD7A-50-EA1 \$ 6.40
7 FASTENER, REAR BUMPER / N	2	✓	MB45A-56-146A \$ 6.00
8 RIVET, REAR BUMPER / N	4	✓	MBN8F-50-355 \$ 22.80
9 ORNAMENT, MAZDA X NAI	1		MCGY0-51-711 \$ 45.30
10 ORNAMENT, 5 X NAI	1		MCGY0-51-721 \$ 36.30
11 MASCOT, REAR X NAI	1		MTD11-51-731 \$ 44.10
12 ORNAMENT, SKYACTIVE X NAI	1		MC597-51-771 \$ 80.00
13 CLIP, FINISHER X NAI	3		MEG21-51-SJ3 \$ 17.10
14 GASKET LHS, TAILGATE / N	1	✓	MC513-51-3JB \$ 95.40
15 GASKET RHS, TAILGATE / N	1	✓	MC513-51-3HB \$ 95.40
TOTAL PARTS			\$ 1,751.00
TOTAL PARTS COST			\$ 1,751.00

Labour Description

1 MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. TO REPAIR TAILGATE AND ALL AREAS AFFECTED BY THE ACCIDENT.	660	\$ 1,980.00
2 MZ-SP-SREAR4	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT AND TAILGATE.	630	\$ 1,890.00
3 MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS. (WITH REVERSE SENSOR)	330 NETT	\$ 660.00
4 MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	X	\$ 250.00

5	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
7		TO SUPPLY BODY COATING.	X	NETT TBA
8	MZ-BR-SUNDRI	SUNDRIES.	neu	NETT \$ 100.00
			TOTAL LABOUR	\$ - \$ 5,480.00
			TOTAL PARTS	\$ - \$ 1,751.00
			TOTAL	\$ - \$ 7,231.00
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ -
			GST 7%	\$ - \$ -
			GRAND TOTAL	\$ - \$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES

TRANS EUROKARS PTE LTD

Authorized Signature

Steve (LKK)
83228813

WHL Mil 8/11/19, 11:30pm

3 day

P/P

Ry Bel sm

1977



TRANS EUROKARS PTE LTD



FINALISED COST OF REPAIRS

FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877 ATTN : MOTOR CLAIMS FAX :		NAME : Mr Chong Xianming ADDRESS : 511 Serangoon North Avenue 4 #11-314 Singapore 550511 TEL : 82004009		WIP : 39139 EXCESS : DATE: 29-Oct-19	
VEH NO :	SLP1894D	DATE IN :		CONTACT PERSON :	Jess 63957874
CHASSIS NO :	JM6CW1071H0125433	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA5	DATE REG.:	29-May-17	POLICY NO. :	
NATURE OF WORKS					
<u>Parts Description</u>					
NO	QTY		REVISED	PRICES	
1	REAR BUMPER	1	MC513-50-221EBB	\$ 961.20	\$ 961.20
2	REAR BUMPER	2	MC235-56-B9XC		\$ 310.80
3	GROMMET, REAR BUMPER	4	MC235-50-ES1	\$ 18.80	\$ 18.80
4	GROMMET, REAR BUMPER	2	MBHN1-50-0Z1A	\$ 5.40	\$ 5.40
5	GROMMET, REAR BUMPER	2	M9991-00-501	\$ 6.00	\$ 6.00
6	FASTENER, REAR BUMPER	2	MGD7A-50-EA1	\$ 6.40	\$ 6.40
7	FASTENER, REAR BUMPER	2	MB45A-56-146A	\$ 6.00	\$ 6.00
8	RIVET, REAR BUMPER	4	MBN8F-50-355	\$ 22.80	\$ 22.80
9	ORNAMENT, MAZDA	1	MCGY0-51-711		\$ 45.30
10	ORNAMENT, 5	1	MCGY0-51-721		\$ 36.30
11	MASCOT, REAR	1	MTD11-51-731		\$ 44.10
12	ORNAMENT, SKYACTIVE	1	MC597-51-771		\$ 80.00
13	CLIP, FINISHER	3	MEG21-51-SJ3		\$ 17.10
14	GASKET LHS, TAILGATE	1	MC513-51-3J8	\$ 95.40	\$ 95.40
15	GASKET RHS, TAILGATE	1	MC513-51-3H8	\$ 95.40	\$ 95.40
TOTAL PARTS				\$ 1,217.40	\$ 1,751.00
TOTAL PARTS COST				\$ 1,217.40	\$ 1,751.00
<u>Labour Description</u>					
1	MZ-BR-REAR02	TO REPLACE REAR BUMPER. TO REPAIR AREAS AFFECTED BY THE ACCIDENT.		\$ 660.00	\$ 1,980.00
2	MZ-SP-SREAR4	TO RESPRAY REAR BUMPER.		\$ 630.00	\$ 1,890.00
3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS. (WITH REVERSE SENSOR)		\$ 330.00	\$ 660.00
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.			\$ 250.00

5	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 150.00	\$ 250.00
6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 180.00	\$ 350.00
7		TO SUPPLY BODY COATING.		TBA
8	MZ-BR-SUNDRI	SUNDRIES.	\$ 20.00	\$ 100.00
TOTAL LABOUR ✓			\$ 1,970.00	\$ 5,480.00
TOTAL PARTS ✓			\$ 1,217.40	\$ 1,751.00
TOTAL			\$ 3,187.40	\$ 7,231.00
LESS EXCESS			\$ -	\$ -
TOTAL AFTER EXCESS			\$ 3,187.40	
GST 7%			\$ 223.12	\$ -
GRAND TOTAL			\$ 3,410.52	\$ -

REMARKS:

3 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19019402/Eyf3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 15-01-2020	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 9709M	Veh. Inspected	SLP 1894D	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19006819MFSH	Excess (\$)	0.00	
Assign From	JASON TEA CHEE KIAT	Assign Date	01/11/2019	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 5	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JM6CW1071H0125433	Colour	BLUE	
Odometer	55632	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	BRIDGESTONE	5 mm	
L/H Front Tyre	205/55 R16	BRIDGESTONE	5 mm	
R/H Rear Tyre	205/55 R16	BRIDGESTONE	5 mm	
L/H Rear Tyre	205/55 R16	BRIDGESTONE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/10/2019	Inspection Date	08/11/2019	
Survey held at	27A TANJONG PENJURU			
Repairer	TRANS EUROKARS PTE LTD			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 1894D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (SN)	DENTED	961.20	961.20
4	GROMMET,REAR BUMPER (SN)	NECESSARY	18.80	18.80
2	GROMMET,REAR BUMPER (SN)	NECESSARY	5.40	5.40
2	GROMMET,REAR BUMPER (SN)	NECESSARY	6.00	6.00
2	FASTENER,REAR BUMPER (SN)	NECESSARY	6.40	6.40
2	FASTENER,REAR BUMPER (SN)	NECESSARY	6.00	6.00
4	RIVET,REAR BUMPER (SN)	NECESSARY	22.80	22.80
1	ORNAMENT,MAZDA (SN)	NOT NECESSARY	45.30	-
1	ORNAMENT,5 (SN)	NOT NECESSARY	36.30	-
1	MASCOT,REAR (SN)	NOT NECESSARY	44.10	-
1	ORNAMENT,SKYACTIVE (SN)	NOT NECESSARY	80.00	-
3	CLIP,FINISHER (SN)	NOT NECESSARY	17.10	-
1	GASKET LHS,TAILGATE (SN)	NECESSARY	95.40	95.40
1	REAR BUMPER (SN)	NOT NECESSARY	310.80	-
1	GASKET RHS,TAILGATE (SN)	NECESSARY	95.40	95.40
1	SUNDRIES (SN)	NECESSARY	100.00	20.00
			1,851.00	1,237.40
LABOUR				
TO REPLACE REAR BUMPER AND REAR REINFORCEMENT.TO REPAIR TAILGATE AND ALL AREAS AFFECTED BY THE ACCIDENT.			1,980.00	660.00
TO RESPRAY REAR BUMPER,REAR REINFORCEMENT AND TAILGATE.			1,890.00	630.00
TO TRANSFER REVERSE SENSORS.(WITH REVERSE SENSOR).			660.00	330.00
TO CARRY-OUT BODY CAVITY PRESERVATION.		NOT NECESSARY	250.00	-
TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			250.00	150.00
TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			350.00	180.00
TO SUPPLY BODY COATING (NPA).		NOT NECESSARY	-	-
			5,380.00	1,950.00



GRAND TOTAL		7,231.00	3,187.40
RECOMMENDED COST OF REPAIRS			3,187.40

Report Ref No. CS/FC119019402/Eyf3n2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.