

22/03/2002

ASS. REC. BY:

REF: CS/CT1 190 19404/Eqf322

Special Instruction:

Supervisor: Steve

ASSIGNMENT (Office)

From (Person): Chung Bun Sin

of CT1

Date/Time: 4.11.19 11.04a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

KET 6876

Insured:

PC21284

at Workshop m/s

Connect 3

Tel:

98509666

of

566 woodlands Rd

Policy No:

DUB15N17455719033

Claim No:

SNM19D20516002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 1.11.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

4.11.19 11.17a.m

Person Contacted:

Winnie

Vehicle: IN/OUT

Date/Time

Action/Instruction (✓) Estimate

KET 6876 - X

PC21284 - CC6/CT119017446/ AK93 RCA - 01/10/2019

Steve REF: CTI

ASSIGNMENT

From: Date: Estimated Cost: OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured.

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh. had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: KET 6876 Yr Regn: 7/10/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Benelli RFS 150i SE c.c. 150

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 3297 T/Radio: Insured / Std / NI / NA

Eng/No:

Ci/No: 2 BNL 26005 KBA 66588

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size: F:

F:

70/90-17

R:

120/70-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Vee Rubber

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

1/11/19

D.O.I.

4/11/19

Survey held at

Connect 3

Des. of Damages: (Frt) Rear / (O/S) / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

13/11/19 MIV - RM 7500 Finalize claim \$1190, 3 days (work) (Red \$1756.40, 61%)

RECEIVED 13 NOV 2019

Date/Time, File Pass to?



: Proll. Report

1) 13/11/19



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 2

Survey Fee: 220

Transportation:

S + RS, SI

Prisibe

Others

)

TOTAL

220

Report Format:

Lump Sum / I.B.A. (\$)

1100

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	(Not Notified)		04 Nov 2019 15:39 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:									
Main Claimant: LONGLIM PTE LTD, Co. Reg. No.: 201109995N									
Vehicle Reg. No.: KET6876		Date of Loss:	01/11/2019 07:00 - :59						
Claim Type: TP		Policy/Cover Note No.:							
Vehicle Reg. No. (Insured): PC2128Y		Policy No. (Claimant): DMB1SN1745521903							
		Excess: S\$0.00							
Repairer: Connect3 (woodlands) (HQ) 566 Woodlands Road, 728697 Woodlands - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]									
Claimant's Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 13/11/2019]									
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Summer Lee (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Monday, 4 November, 2019 11:04 AM
To: Winnie Chai
Cc: Jeffrey Tay; assignments
Subject: RE: OUR REF: SNM19D205160-PC2128Y-CBS- Request for pre repair inspection for accident involving KET6876 & PC2128Y (yr insured) on 01/11/19

WITHOUT PREJUDICE

Dear Sir

We will be assigning M/s LKK AUTO CONSULTANTS to survey your client's vehicle.

Aside to LKK AUTO CONSULTANTS,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Winnie Chai [mailto:connect3winnie@gmail.com]

Sent: Monday, November 4, 2019 11:00 AM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Jeffrey Tay <Jeffrey.Tay@sg.cntaiping.com>

Subject: Re: OUR REF: SNM19D205160-PC2128Y-CBS- Request for pre repair inspection for accident involving KET6876 & PC2128Y (yr insured) on 01/11/19

Hi Boon Sen

Pls kindly assign yr surveyor down for the PRI as tdy is the last day for PRI.

Thanks

On Fri, Nov 1, 2019 at 5:14 PM Claims Dept of CTI <claimsdept@sg.cntaiping.com> wrote:

Dear Boon Sen,

Please conduct PRS for KET6876.

Note : officer in charge – Boon Sen 63896171.

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Winnie Chai [mailto:connect3winnie@gmail.com]

Sent: Friday, 1 November, 2019 2:52 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: connect3lau@gmail.com

Subject: Request for pre repair inspection for accident involving KET6876 & PC2128Y (yr insured) on 01/11/19

Afternoon

We attached the police report for yr ref.

Pls kindly assign yr surveyor down for survey.

Survey location : 566 Woodlands Rd (Mandai Estate) S728697

Thanks

--

Winnie Chai

Connect3

HP:9850-9666

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

--

Winnie Chai

Connect3

HP:9850-9666

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Steve Chen (LKK Auto)

From: Winnie Chai <connect3winnie@gmail.com>
Sent: Wednesday, November 13, 2019 9:20 AM
To: Steve Chen (LKK Auto)
Subject: Re: Reminder - Finalization for KET6876

Yes, please proceed.

On Tue, Nov 12, 2019 at 7:18 PM Steve Chen (LKK Auto) <SteveChen@lkkauto.com> wrote:

Dear Winnie,

Kindly refer our finalize \$1100 (L/S, before GST). 3 repair days.

Kindly confirm.

Thanks

Best Regards,

Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SIJIL PEMILIKAN KENDERAAN

JABATAN PENGANGKUTAN JALAN

XL1QJJ0Y

No Pendaftaran : KET6876

No 10

330115018459

Nama Pemunya Berdaftar

KALAIYAMAN A/L CHANDRA SEKAR

Alamat

NO 404 LORONG 2 LADANG NORTH LABIS
85300 LABIS JOHOR

No Chasis/No Enjin

ZBNL26005KBA66588 / BJ15TMJ-3A95014531

Buatan/Name Model

BENELLI / RFS1501 SE (BJ15D-100)

Kapasiti Enjin

150

Bahan Bakar

PETROL

Status Asal

PEMASANGAN TEMPATAN

Kelas Penggunaan

MOTOSIKAL

Jenis Badan/Tahun Dibuat

MOTOSIKAL / 2019

Tarikh Pendaftaran

07/10/2019

S.O.M/B.G.K/STM

Syarat Pendaftaran 1

-

Syarat Pendaftaran 2

-

Syarat Pendaftaran 3

-

THE PACIFIC INSURANCE BERHAD

(Company No. 91603-K)
40-01, G-5, Jalan 2A, Jalan Selayang Sentral 2,
Kuala Lumpur Sentral, 50470 Kuala Lumpur
P.O. Box 12490, 50760 Kuala Lumpur
Tel: 03-7633 8330 Fax: 03-7633 8098
Website: www.pacificinsurance.com.my

Atas Pengantutan Jalan 1997 (Malaysia) dan Atas Kenderaan Bermotor (Risiko Pihak Ketiga dan Pampasan) (Republic of Singapore) dan Atas Insurans Kenderaan Bermotor (Risiko Pihak Ketiga) (Uab 50) Negara Brunei Darussalam, Road Transport Act 1987 (Malaysia), Motor Vehicles (Third Party Risks and Compensation) Ordinance 1960 (No. 1 of 1960) (Republic of Singapore), The Motor Vehicles Insurance (Third Party Risks and Compensation) Rules 1960 (Republic of Singapore), Motor Vehicle Insurance (Third Party Risks) Act (Cap 90) Negara Brunei Darussalam

NOTA PERLINDUNGAN MOTOR / MOTOR COVER NOTE

CASH BEFORE COVER REGULATION - Section 34 (1) of the Financial Services Act 2013

Tiada perlindungan akan diberikan sehingga premium dibayar mengikut peraturan perundangan yang dikeluarkan di bawah Seksyen 34 (1) Seksyen yang wajar mematuhi peraturan ini dan jika didapati bahawa akan dikenakan denda tidak melebihi RM500,000. Bayaran boleh dibuat melalui tunai, cek, wang khaman dan atau kad pos, draft bank atau cashier order kepada THE PACIFIC INSURANCE BERHAD dan dipanggil "Akaun Pembiayaan Sahaja".
No cover can be granted until the premium has been paid in accordance with the Regulations issued under the Section. Any person who fails to comply with this Section shall be guilty of an offence and shall on conviction be liable to a fine not exceeding RM 500,000. Where payment of the premium is made by cheque, money order, postal order, bank draft or cashier's order, the payment must be made in favour of THE PACIFIC INSURANCE BERHAD and crossed "Account Payee Only".

Dalamakanya Pemegang yang bernama KETTER dalam jadual di bawah telah membayar premium RM 425.55 untuk kenderaan Bermotor yang dinyatakan dalam jadual di bawah bagi perlindungan MOTORCYCLE - COMPREHENSIVE. Inaka risiko ini DILINDUNGI di bawah terma-terma Syarikat yang biasa untuk Perlindungan Polai yang dapat diberikan pada benukukasa dan 12:01 AM 07/10/2019 hingga 12:01 AM 07/10/2020 kecuali perlindungan ini diamatkan oleh Syarikat secara bersilat di mana kes ke insurans dihentikan dan Syarikat akan memulangkan secara benukukasa premium yang telah diterima untuk insurans tersebut selepas mengampun kes tersebut Syarikat telah menanggung risiko.
Whereas the Proposer named in the Schedule below having proposed for insurance and paid the sum of RM 425.55 in respect of the Motor Vehicle described in the Schedule below the risk is hereby FULLY COVERED in the terms of the Company's usual form of MOTORCYCLE - COMPREHENSIVE Policy applicable thereto for the period from 12:01 AM on 07/10/2019 to midnight on 06/10/2020 unless the cover be terminated by the Company by notice in writing in which case the insurance will terminate at once and the Company will return a proportionate part of the premium already collected for such insurance after that allowance for the period the Company has been on risk.

JADUAL / SCHEDULE

Pihak Dinsuranskan Name of Proposer	KALAIVAANAN AIL CHANDRASEKARAN		Tarikh Dikeluarkan Date of Issue
No. K.P.No. Daftar Perniagaan IC No./Business Reg. No.	950115-01-6459	Sewa Beli atau Pajakan Dengan Finance Interest	04-10-2019
Alamat Address	NO 404 LORONG 2 LADANG NORTH LABIS 85300 LABIS JOHOR		AEON CREDIT SERVICE (M) BERHAD
No Pendaftaran Registration No.	KET6676	Jumlah Dinsurans Sum Insured	RM 7500.00
No Kad Pendaftaran Registration Card No.	XLTOJJJOY	Lebihan Excess	RM 100.00
Kapasiti Roda/Tan Cubic Capacity/Tonnage	150 CC	No Enjin Engine No.	BJ157MJ-3A95014581
Buatan & Model Make & Model	BENELLI RFS150I SE BJ150-10B	No. Casis Chassis No.	ZBNL26005KBA66588
Tahun Dibuat Year of Make	2019	Ruang duduk Seating Capacity	2
Jenis Kenderaan Type of Vehicle	MOTOR CYCLE	Kegunaan Kenderaan Use of Vehicle	MOTOR CYCLES - PRIVATE
Perlindungan Tambahan Additional Covers	ALL RIDERS		
Nama Pemandu Named Drivers (other than Insured)	NIL		
Cukai dan Perkhidmatan / Services Tax	23.52	NCD	0.00 %

* POLISI INI TIDAK MELINDUNGI UNTUK KEGUNAAN SEWA ATAU GANJARAN THIS POLICY DOES NOT COVER USE FOR HIRE OR REWARD

Saya/Kami dengan ini menegaskan bahawa Nota Perlindungan ini dikeluarkan mengikut Peruntukan-peruntukan yang terdapat dalam Bahagian IV Akta Pengangkutan Jalan 1997 (Malaysia), Undang-Undang Kenderaan Bermotor (Risiko Pihak Ketiga) 1956 (Malaysia), The Motor Vehicles (Third Party Risks and Compensation) Ordinance 1960 (No. 1 of 1960) (Republic of Singapore), The Motor Vehicles Insurance (Third Party Risks and Compensation) Rules 1960 (Republic of Singapore), The Motor Vehicles Insurance (Third Party Risks) Rules 1960 (Brunei Darussalam).
We hereby certify that this Cover Note is issued in accordance with the provision of Part IV of the Road Transport Act, 1987 (Malaysia), Motor Vehicles (Third Party Risks and Compensation) Act (Cap 189) Republic of Singapore and the Motor Vehicles Insurance (Third Party Risks) Act (Cap 90) Negara Brunei Darussalam.

The Pacific Insurance Berhad
(Perniagaan Insurans) Berlesen / Approved Insurers

NEW INSURANCE
No. Pembinaan/Sambungan/Perindaan Polai / Renewal/Extension/Transfer
of Policy No. :
Login ID: V0015172

Manager / Authorised Agent



SINGAPORE POLICE FORCE



T/20191101/2031

1 of 3

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

Report No. T/20191101/2031

RM 7500

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 01/11/2019 10:23		Vide Report No.:		Station Diary No.: 29	
Informant's Particulars					
Name of Informant: KALAIVAANAN A/L CHANDRASEKARAN			Address:		
ID Type / ID No.: FIN NO / G2477181X			Contact No.: Home/Office:		Mobile: 0164660291
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 24	Date of Birth: 15/01/1995	Type of Informant: Driver		
Race: Indian			Language:		Institution / School Name:
Occupation: Cleaner			Driving Licence Information: Class:		Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 01/11/2019 08:10	Type of Location: Car Park
Location: Along Road 1 BISHAN STREET 22 Inside Catholic High School				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume:
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
KET6876	Motorcycle				Seriously Damaged	0
PC2128Y	Bus/Coach/Minibus	SUNLONG	SLK6770B14 R129 DIESEL TURBO MT 29 SEATER	White		0
SLW8660D	Car	KIA	CERATO K3 1.6A	White		0



Police Station Of Origin:

Bishan N.P.C

20 Bishan Street 23 SINGAPORE 579757

Tel No: 1800-5529999

2 of 3

Report No. T/20191101/2031

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	KALAIVAANAN A/L CHANDRASEKARAN	ID No.	G2477181X
Related Vehicle	KET6876 (Motorcycle)	Contact No.	0164660291
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	YE LIJUAN	ID No.	G5917604N
Related Vehicle	PC2128Y (Bus/Coach/Minibus)	Contact No.	81577008
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 01/11/2019 at around 0810hrs, I was informed by my supervisor that my vehicle: KET6876 had been involved in a road traffic accident. My vehicle was parked at the carpark lot of Catholic High School. The accident was caused by one vehicle: PC2128Y reversing and hit onto vehicle: SLW8660D which then hit my vehicle.

I made a check on my vehicle and saw that the rim, handle and spock were dented. I then took photographs of my vehicles before taking my leave. I wished to state that no one was injured.

I am lodging this report for insurance claims.



**SINGAPORE
POLICE FORCE**



T/20191101/2031

3 of 3

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

Report No. T/20191101/2031

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

E /

Sgt 2 KHAIRUL SYAZWAN BIN SAHAK

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

Sgt 2 SHARIFAH NOR FARIZAN BINTE SYED
MOHD SAID

Contact No.: 65476172

Authentication Stamp

NP168

Signature Of Informant:

Date/Time:

01/11/2019 10:23

Classification Of Case:



SINGAPORE
POLICE FORCE

SN 061

SIGNATURE

CONNECT 3

566 Woodlands Road (Mandai Estate) Singapore 728697

Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1 L

G S T : 5 3 3 6 0 0 6 1 L

QT19/KET6876/TPC-594

QUOTATION

China Taiping Insurance (Singapore) Pte Ltd
3 Anson Rd #15-02
Springleaf Tower
Singapore 079909

Dear Sir

Cost of Repair to Vehicle KET6876

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (\$\$)	AMOUNT (\$\$)
1.	Front fender / CUT	1	138.00	138.00 /
2.	Front fender LH & RH bracket X NN	2	5.50	11.00 X
3.	Rotor ? X NN	1	403.90	403.90 X
4.	Caliper X NN	1	210.70	210.70 X
5.	Brake disk ? X NN	1	65.80	65.80 X
6.	Side fairing / cowling X NN	1	62.80	62.80 X
7.	Rearset / footpeg RH / BR	1	68.00	68.00 /
8.	Lower fairing X NN	1	58.60	58.60 X
9.	Brake pedal / BT	1	21.30	21.30 /
10.	Front rim / CUT	1	419.70	419.70 /
11.	Rim valve / n/c	1	5.00	5.00 /
12.	Rearset pedal rubber RH X NN	1	5.40	5.40 X
13.	Front RH shock absorber (fork) ? (Local repair) n/c		492.00	492.00 209 /
14.	Front wheel axle ? X NN	1	49.20	49.20 X
15.	Stickers / n/c	1	40.00	40.00 /

892
-13%
802.80

Nett-50

16.	Bolts, nuts, tubes & hose etc / PC	1	65.00	65.00	29/11
17.	Check alignment for wheels / PC	1	40.00	40.00	30/11
18.	Labour charges	1	500.00	500.00	300
19.	Spray painting	1	200.00	200.00	/
SUB-TOTAL				S\$2,856.40	

- Price before 7% gst

[Handwritten signature]
5/1/19

Steve (LKK) with April 4/11/19, 12.11pm

L-500

3 days

L/S

By AL Sy

Thank you
Yours faithfully,

[Handwritten signature]

Winnie Chai
HP: 9850-9666



P-802-80

N-50

L-500

1352-80

L/S-1982-24

= 1100

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Nov 2019		04 Nov 2019 15:39 Edit Adj Rpt	S\$1,100.00 Edit Estimates	S\$1,100.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: 0 , Co. Reg. No.: 0									
Main Claimant: LONGLIM PTE LTD , Co. Reg. No.: 201109995N									
Vehicle Reg. No.: KET6876		Date of Loss: 01/11/2019 07:00 - :59 [25 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM19D205160C02		Policy/Cover Note No.: DMB1SN17455219033							
Vehicle Reg. No. (Insured): PC2128Y		Policy No. (Claimant): DMB1SN1745521903							
		Excess: S\$0.00							
Repairer: Connect3 (woodlands) (HQ) 566 Woodlands Road, 728697 Woodlands - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]									
Claimant's Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 13/11/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*KET6876 (SNM19D205160C02)
[PC2128Y]
TP
LONGLIM PTE LTD
Nov 1 2019 7:00AM
[0]
Connect3 (woodlands)

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Assessment Reports

1 per page

No

Finalized On

National Assessment Centre Services (Bukit Merah)

Thumbnail

Print

1

04/11/19 13:04

Accident Statement

Load HTM

Photos/Images

3 per page

No

Finalized On

National Assessment Centre Services (Bukit Merah)

Thumbnail

Print

1

04/11/19 10:06

Accident Photo

[Linked Accident Report Documents]

Load JPG

2

04/11/19 10:06

Accident Photo

[Linked Accident Report Documents]

Load JPG

3

04/11/19 10:06

Accident Photo

[Linked Accident Report Documents]

Load JPG

4

04/11/19 10:06

Accident Photo

[Linked Accident Report Documents]

Load JPG

5

04/11/19 10:06

Accident Photo

[Linked Accident Report Documents]

Load JPG

6

04/11/19 10:06

Accident Photo

[Linked Accident Report Documents]

Load JPG

7

04/11/19 10:06

Accident Photo

[Linked Accident Report Documents]

Load JPG

No

Relabel/Reorder

LKK Auto Consultants Pte Ltd (HQ)

Thumbnail

Print

1

13/11/19 09:26

General View

Load JPG

2

13/11/19 09:26

General View

Load JPG

3

13/11/19 09:26

General View

Load JPG

4

13/11/19 09:26

General View

Load JPG

5

13/11/19 09:26

General View

Load JPG

6

13/11/19 09:26

General View

Load JPG

7

13/11/19 09:26

General View

Load JPG

8

13/11/19 09:26

General View

Load JPG

9

13/11/19 09:26

General View

Load JPG

10

13/11/19 09:26

General View

Load JPG

11

13/11/19 09:26

General View

Load JPG

12

13/11/19 09:26

General View

Load JPG

13

13/11/19 09:26

General View

Load JPG

14

13/11/19 09:26

General View

Load JPG

15

13/11/19 09:26

General View

Load JPG

16

13/11/19 09:26

General View

Load JPG

17

13/11/19 09:26

General View

Load JPG

18

13/11/19 09:26

General View

Load JPG

19

13/11/19 09:26

General View

Load JPG

20

13/11/19 09:26

General View

Load JPG

21

13/11/19 09:26

General View

Load JPG

22

13/11/19 09:26

General View

Load JPG

23

13/11/19 09:26

General View

Load JPG

24

13/11/19 09:26

General View

Load JPG

25

13/11/19 09:26

General View

Load JPG

26

13/11/19 09:26

General View

Load JPG

27

13/11/19 09:26

General View

Load JPG

28

13/11/19 09:26

General View











































Load JPG

29

13/11/19 09:26

General View

Load JPG

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
30	13/11/19 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
31	13/11/19 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
32	13/11/19 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
33	13/11/19 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
34	13/11/19 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
35	13/11/19 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
36	13/11/19 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
37	13/11/19 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
38	13/11/19 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
39	13/11/19 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
40	13/11/19 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
41	13/11/19 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
42	13/11/19 09:26	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
43	13/11/19 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
44	13/11/19 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
45	13/11/19 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
46	13/11/19 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
47	13/11/19 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
48	13/11/19 09:26	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
49	13/11/19 09:27	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
50	13/11/19 09:27	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
51	13/11/19 09:27	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
52	13/11/19 09:27	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
53	13/11/19 09:27	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
54	13/11/19 09:27	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
55	13/11/19 09:27	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
56	13/11/19 09:27	Accident Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
57	13/11/19 09:27	Accident Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
58	13/11/19 09:27	Accident Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
59	13/11/19 09:27	Accident Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
60	13/11/19 09:27	Accident Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
61	13/11/19 09:28	Accident Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
62	13/11/19 09:28	Accident Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
63	13/11/19 09:28	Accident Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
64	13/11/19 09:28	Accident Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
65	13/11/19 09:28	Accident Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
1	04/11/19 10:08	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	04/11/19 10:08	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	04/11/19 10:08	POLICE REPORT [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	04/11/19 10:08	POLICE REPORT [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	04/11/19 10:08	POLICE REPORT [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	04/11/19 10:08	POLICE REPORT [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
1	04/11/19 13:04	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)		Thumbnail	Print
1	04/11/19 10:06	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	04/11/19 10:06	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	04/11/19 10:06	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	04/11/19 10:06	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	04/11/19 10:06	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	04/11/19 10:06	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	04/11/19 10:06	Accident Photo		Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)		Thumbnail	Print
1	04/11/19 10:08	Accident Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
2	04/11/19 10:08	Accident Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
3	04/11/19 10:08	POLICE REPORT		Load JPG	<input checked="" type="checkbox"/>
4	04/11/19 10:08	POLICE REPORT		Load JPG	<input checked="" type="checkbox"/>
5	04/11/19 10:08	POLICE REPORT		Load JPG	<input checked="" type="checkbox"/>
6	04/11/19 10:08	POLICE REPORT		Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<div> Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div> <div></div> <div></div> </div> </div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT19019404/EQF3E2

Date: 19/11/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMB1SN17455219033

Claimant
Vehicle No : KET6876Insured
Vehicle No : PC2128Y

Date of Loss: 01/11/2019

Nature of Claim: TP

Claim
No: SNM19D205160C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: KET6876

Make & Model: BENELLI RFS150I SE, 150cc

Engine No: BJ157MJ3A95014581

Reg. Date: 07/10/2019 (Man. Year: 2019)

Chassis No: ZBNL26005KBA66588

Colour: Blue

Odometer: 3297 km

Engine Capacity: 150 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	70/90-17	Rear Tyre Size:	120/70-17
Front Left Side:	Vee Rubber 5 mm	Rear Left Side:	Vee Rubber 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,051.40	822.80	1,228.60	59.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	805.00	550.00	255.00	31.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	2,856.40	1,372.80	1,483.60	51.94
Approved Total (Overridden) (\$\$)		1,100.00		
(\$\$)	2,856.40	1,100.00	1,756.40	61.49
+ GST 7.00/7.00% (\$\$)	199.95	77.00	122.95	61.49
Nett Amount (\$\$)	3,056.35	1,177.00	1,879.35	61.49

INSPECTION

Date of Assignment: 04/11/2019

Date Inspected:	04/11/2019	Inspected At:	Connect3 (woodlands) (HQ) 566 Woodlands Road Singapore 728697
-----------------	------------	---------------	---

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 19 Nov 2019)	
Parts:	N/A	BENELLI RFS150I SE 150cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for KET6876)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Cut	138.00 F	*138.00 FL
2	2		*FRONT FENDER LH & RH BRACKET	Not Necessary	11.00 F	*- FL
3	1		*ROTOR	Not Necessary	403.90 F	*- FL
4	1		*CALIPER	Not Necessary	210.70 F	*- FL
5	1		*BRAKE DISK	Not Necessary	65.80 F	*- FL
6	1		*SIDE FAIRING/COWLING	Not Necessary	62.80 F	*- FL
7	1		*REARSET/FOOTPEG RH	Broken	68.00 F	*68.00 FL
8	1		*LOWER FAIRING	Not Necessary	58.60 F	*- FL
9	1		*BRAKE PEDAL	Bent	21.30 F	*21.30 FL
10	1		*FRONT RIM	Cut	419.70 F	*419.70 FL
11	1		*RIM VALVE	Necessary	5.00 F	*5.00 FL
12	1		*REARSET PEDAL RUBBER RH	Not Necessary	5.40 F	*- FL
13	1		*FRONT RH SHOCK ABSORBER (FORK) (LOCAL REPAIR)	Necessary	492.00 FS	*200.00 FS
14	1		*FRONT WHEEL AXLE	Not Necessary	49.20 F	*- FL
15	1		*STICKERS	Necessary	40.00 F	*40.00 FL
				F=Franchise part. S=SpcNett. L=ListItemDisc.		
				Sub Total (\$\$)	2,051.40	892.00
				- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	69.20
				Total Parts (\$\$)	2,051.40	822.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	BOLTS, NUTS, TUBES & HOSE ETC	New	65.00	20.00
2	CHECK ALIGNMENT FOR WHEELS	New	40.00	30.00
3	LABOUR CHARGES	New	500.00	300.00
4	SPRAY PAINTING	New	200.00	200.00
Gross Labour Cost (S\$)			805.00	550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >