

ASS. REC. BY:

REF:

CS/LPC19019414/R13f3²

Special Instruction:

Surveyor: RUSU

ASSIGNMENT (Office)

From (Person): Ong Li Li

of

LPC

Date/Time:

4/11/2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SKR1995Y

Insured:

at Workshop m/s

Cycle & Carriage

Tel:

9126 5109of 188 Pardan Loop

Policy No:

Claim No:

19/19/19/VPOS/022596

Sum Insured:

Excess:

\$3000

Make of Veh:

D.O.A.

01.11.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

4/11

Person Contacted:

Mr Yik

Vehicle

IN / OUT

Date/Time

Action/Instruction

Estimate (✓)SKR1995Y-X04/11/19@ 17:11 pm revert to Li Li via email.05/11/19@ 16:43 pm authorize spare by my Li Li via email.05/11/19@ 17:37 pm informed CIA to Yik (repairer) via email.

Page

CS/LPC19019414/RI sf3

1546

ASSIGNMENT

Form: _____ Date: _____

Estimated Cost: _____

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKR 19954

at Workshop m/s: Cycle & Carriage

of 188, Pandan Loop

Insured: LPC

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 3000

(Client's Record)

Make of Veh: _____

(Policy Condition) YIK

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 79K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKR 19954 yr Regn: 2015 / Jan

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: MERCEDES BENZ CLA 180 (R18) cc 1595

Colour: GRAY A/C: _____ Insured / Std / NI / NA

Sp Reading: 48686 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD1173422N140029

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F: 225/40 R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mm


L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 01/11/19 D.O.I. 04/11/19

Survey held at: Cycle & Carriage (PL)

Des. of Damages: ☒ FR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.



Date / Time	Action / Instruction
20/11/19	Confirmed P/P \$ 6,722.59 @ 5 days with Resal (\$ 4,154.68 Red - 38%)

RECEIVED 22 NOV 2019

Signature
20/11/2019

Date/Time, File Pass to? 22/11/19

1) Typist

Date/Time, File Return to? _____

2) _____

☐ : Preli. Report

☒ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp. (\$)

☐ Interview (\$)

☐ Tech. Insp. (\$)

☐ Workshop (\$)

Survey Fee: 350

Transportation: _____

_____ + PS. _____

Photos: _____

Notes: _____

Repair Formed: 1

Comp. Sum: \$6,722.59 P/P

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Monday, 4 November 2019 9:38 AM
To: Yik Chan Hoe; MT_Claim_SG; assignments; Admin-D (LKKAuto); SUR
Subject: RE: SKR1995Y OD Claim Our Ref: 19/19/19/VP05/022596
Attachments: img-Y02114548-0001.pdf

Dear Mr Yik

We shall appoint LKK Auto Consultants Pte Ltd to conduct OD survey.

Please note that the OD excess is \$3,000.00 (young driver<26 yr old).

Dear LKK

Please arrange OD survey (non-Merimen).

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse
Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

-----Original Message-----

From: Yik Chan Hoe [mailto:chanhoe.yik@cyclecarriage.com.sg]
Sent: Saturday, 2 November 2019 11:51 AM
To: MT_Claim_SG
Subject: FW: SKR1995Y OD Claim

Dear Sir/Mdm,

Kindly arrange survey asap.

Thanks & Regards,

Yik Chan Hoe
Mercedes-Benz Body Care & Repair Center
Cycle & Carriage Industries Pte Ltd
Pandan Loop Service Center
Mobile: 9186 5109 | DID: 6771 4353 | Fax: 6872 1272
Website: www.mercedes-benz.com.sg

Yeh Lu-Raen

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are

notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Friday, 22 November 2019 9:36 am
To: Yik Chan Hoe
Cc: Dennis Yap
Subject: RE: SKR1995Y final bill

Dear Yik,

Supplementary approved by MSIG.

Finalize amount confirmed.

Final invoice and all supporting documents sent over to Lonpac Insurance Bhd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yik Chan Hoe <chanhoe.yik@cyclecarriage.com.sg>

Sent: Wednesday, 13 November 2019 6:12 pm

To: Rasul (LKKAuto) <Rasul@lkkauto.com>; Dennis Yap <dennis.yap@cyclecarriage.com.sg>

Subject: SKR1995Y final bill

Hi Rasul,

Attached fyn.

Aside to Dennis,

Please forward the photos to Rasul.

Thanks & Regards,

Yik Chan Hoe

Mercedes-Benz Body Care & Repair Center

Cycle & Carriage Industries Pte Ltd

Pandan Loop Service Center

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Tuesday, 5 November 2019 5:37 pm
To: Yik Chan Hoe
Cc: Dennis Yap Kian Meng; Cheong Chin Leong; SUR
Subject: SKR 1995Y OD (LPC) Date of Loss: 01/11/2019

Dear Mr. Yik,

As instructed by our client, please proceed to repair the insured vehicle **SKR 1995Y (Excess \$ 3,000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shirley Hiew (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Thursday, 21 November 2019 2:24 pm
To: Shirley Hiew (LKK Auto); MT_Claim_SG
Cc: Admin-D (LKKAuto); assignments; SUR
Subject: RE: SKR1995Y OD Claim Our Ref: 19/19/19/VP05/022596 [External General]

Lonpac External - General
Dear Shirley

Please go ahead since the total adjusted cost of repairs of \$6,722.59 is still within the surveyor's recommendation in your previous advice.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse
Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

Lonpac External - General data is for internal / external use.

-----Original Message-----

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Wednesday, 20 November 2019 5:12 PM
To: ONG LI LI; MT_Claim_SG
Cc: Admin-D (LKKAuto); assignments; SUR
Subject: RE: SKR1995Y OD Claim Our Ref: 19/19/19/VP05/022596

Dear Li Li,

Enclosed preliminary revised of vehicle SKR 1995Y.
Date of survey: 04/11/2019
Number of days : 3 days

Please let us have your supplementary approval please.

Thank you.
Best Regards,
Shirley Hiew | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shirley Hiew (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Tuesday, 5 November 2019 4:43 pm
To: Shirley Hiew (LKK Auto); MT_Claim_SG
Cc: Admin-D (LKKAuto); assignments; SUR
Subject: RE: SKR1995Y OD Claim Our Ref: 19/19/19/VP05/022596

Dear Shirley

Please proceed to authorise OD repairs as recommended by the surveyor if the damages are consistent and within repair limit.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse
Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

-----Original Message-----

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Tuesday, 5 November 2019 1:58 PM
To: ONG LI LI; MT_Claim_SG
Cc: Admin-D (LKKAuto); assignments; SUR
Subject: RE: SKR1995Y OD Claim Our Ref: 19/19/19/VP05/022596

Dear Li Li,

Enclosed estimate & photo.

We have checked with our surveyor, check items are hidden parts and will verify after the dismantle conduct.

Thank you.
Best Regards,
Shirley Hiew | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: ONG LI LI <llong@lonpac.com>
Sent: Monday, 4 November 2019 5:25 pm

To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>; MT_Claim_SG <mt_claim@lonpac.com>
Cc: Admin-D (LKKAuto) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: SKR1995Y OD Claim Our Ref: 19/19/19/VP05/022596

Hi Shirley

Please provide survey photos and marked estimate.

Why is the amount of check items so high?

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse
Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

-----Original Message-----

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Monday, 4 November 2019 5:11 PM
To: ONG LI LI; MT_Claim_SG
Cc: Admin-D (LKKAuto); assignments; SUR
Subject: RE: SKR1995Y OD Claim Our Ref: 19/19/19/VP05/022596

Dear Li Li,

Enclosed preliminary revised of vehicle SKR 1995Y Date of survey: 04/11/2019 Number of days : 3 days

We have Not authorise repair.

Kindly let us have your approval please.

Thank you.
Best Regards,
Shirley Hiew | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Monday, 4 November 2019 10:52 am
To: 'ONG LI LI' <llong@lonpac.com>; 'MT_Claim_SG' <mt_claim@lonpac.com>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: SKR1995Y OD Claim Our Ref: 19/19/19/VP05/022596

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Monday, 4 November 2019 5:11 pm
To: 'ONG LI LI'; 'MT_Claim_SG'
Cc: Admin-D (LKKAuto); assignments; SUR
Subject: RE: SKR1995Y OD Claim Our Ref: 19/19/19/VP05/022596
Attachments: PRELI ADVISE (OD) - SKR 1995Y.pdf

Dear Li Li,

Enclosed preliminary revised of vehicle SKR 1995Y Date of survey: 04/11/2019 Number of days : 3 days

We have Not authorise repair.

Kindly let us have your approval please.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>

Sent: Monday, 4 November 2019 10:52 am

To: 'ONG LI LI' <llong@lonpac.com>; 'MT_Claim_SG' <mt_claim@lonpac.com>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: RE: SKR1995Y OD Claim Our Ref: 19/19/19/VP05/022596

Dear Li Li,

Thank you for the assignment.

Celine Fong

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: ONG LI LI [mailto:llong@lonpac.com]



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: 19/19/19/VP05/022596

Date: 20 November 2019

Our Ref: CS/LPC19019414/R1sf3

The Motor Claims Department
LONPAC INSURANCE BHD

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKR 1995Y

Please be informed that we had conducted the inspection of the abovementioned vehicle on 04/11/2019 at the premises of M/s Cycle & Carriage Industries Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>10,877.27</u> . (inclusive supp)
Revised Estimate Amount	: S\$ <u>6,722.59</u> . (inclusive supp)
"Check" Items Amount	: S\$ <u>-</u> .
Total	: S\$ <u>6,722.59</u> .
Market Value	: S\$ <u>79,000.00</u> .
LTA Reimbursement Value	: S\$ <u>49,892.00</u> .
Nett Value	: S\$ <u>29,108.00</u> .

Description of Damage:

The vehicle sustained damages at the front portion.





Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Comments/ Present Status:

Damages Consistent. Repair cost economical.

We have received supplementary from repairer. Our surveyor had since checked and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident and is economical to repair. Supplementary amount is \$ 340.09 and its still within the repair limit.

Repair days: 3 days

Yours faithfully

Mohammed Rasul
Automotive Assessor



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: 19/19/19/VP05/022596

Date: 04 November 2019

Our Ref: CS/LPC19019414/R1sf3

The Motor Claims Department
LONPAC INSURANCE BHD

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKR 1995Y .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 04/11/2019 at the premises of M/s Cycle & Carriage Industries Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ 10,537.18 .
Revised Estimate Amount	: S\$ 2,429.93 .
"Check" Items Amount	: S\$ 7,117.25 .
Total	: S\$ 9,547.18 .
Market Value	: S\$ 79,000.00 .
LTA Reimbursement Value	: S\$ 49,892.00 .
Nett Value	: S\$ 29,108.00 .

Description of Damage:

The vehicle sustained damages at the front portion.



Comments/ Present Status:

Damages Consistent. Repair cost economical.
We have not authorize repair.
Repair days: 3 days

Yours faithfully

Mohammed Rasul
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/11/2019 09:48
Date Of Accident	01/11/2019 11:50
Exact Location Of Accident	SIGLAP HILL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKR1995Y
Insured/Policyholder	
Name Of Registered Owner	CHUA BEE LAY
NRIC No	S6927154E
Email Address	AMANDA.TGSBV@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-97936009
Alternative Phone No	OFFICE-69503198

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	CLA 200-1.6 SHOOTING BRAKE (R18 BI) (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USED
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z19VP05021873
Cover Note Number	

Driver

Name of Driver	PECK ZI XIN, ISAAC
NRIC No	S9535288Z
Date Of Birth	30/09/1995
Occupation	INDOOR
Date Of Driving Pass	16/10/2014
Driving Experience	5 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90485775
Fax Number	
Contact Number	
Email Address	ZIXINISAAC@GMAIL.COM

Address	33E SIGLAP HILL
Postcode	456103
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : PECK YI SHAN GENDER: : MALE
Passenger 2	NAME: : DEVI GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AT ABOUT 11.50 AM ON 1ST NOVEMBER 2019, I WAS DRIVING THE MERCEDES OUT OF THE HOUSE, THROUGH THE HOUSE GATE RIGHT AFTER I EXITED, I NOTICED A BLUE HONDA CAR B (SJD 9668 A) ON THE OPPOSING LANE. I SAW DRIVING UNUSUALLY TURNING INTO MY LANE, AS I THOUGH HE WAS AVOIDING SOMETHING, I STOPPED TO GIVE HIM SPACE TO TURN BACK INTO HIS LANE. HOWEVER, HE DID NOT STOP AND RAN STRAIGHT INTO ME, RESULTING IN DAMAGE TO MY FRONT RIGHT BUMPER AND HIS FRONT RIGHT BUMPER FELLING OFF.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJD9668A
Vehicle Make/Model/Colour	HONDA
Details Of Properties	CAR B
Vehicle Category	PRIVATE CAR
Name of Driver	MUHAMMAD IZZ KHAIRIN BIN MOHAMMED HISHAM
NRIC/Passport Number	S9746747A
Contact Number	87799069

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
 Date & Time: 10.11
 02/11/19

Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 10.16 02/11/19

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


At about 11.50am on 1st November 2019. I was driving the mercedes out of the house, through the house gate right after I exited, I noticed a blue Honda car B (SJD9668A) on the opposing lane. I saw driving unusually turning into my lane. As I through was avoiding something, I stopped to give him space to turn back into his lane. However, he did not stop and ran straight into me, resulting in damage to my front right bumper and his front right bumper falling off.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature

Date & Time: 10.14
02/11/2019


Driver's Signature

(If driver is not the policyholder)
Date & Time: 10:10 02/11/19




Reporting Centre Personnel's Signature

Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	154E
Vehicle Details	
Vehicle No.:	SKR1995Y
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Nov 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	CLA180 (R18 BI)
Primary Colour:	Grey
Manufacturing Year:	2014
Engine No.:	27091030503930
Chassis No.:	WDD1173422N140029
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$27,649.00
Original Registration Date:	23 Jan 2015
First Registration Date:	23 Jan 2015
Transfer Count:	0
Actual ARF Paid:	\$20,709.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Jan 2025
PARF Rebate Amount:	\$15,531.00
Intended COE Rebate Details	
COE Expiry Date:	22 Jan 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$65,889.00
COE Rebate Amount:	\$34,361.00
Total Rebate Amount:	\$49,892.00

The information contained herein is correct as at 04 Nov 2019

OK

**LONPAC INSURANCE BHD** (S98FC5635C)

(Incorporated in Malaysia)

Singapore Office: 300, Beach Road #17-04/07, The Concourse, Singapore 199555.

Tel: (65) 6250 7388 Fax: (65) 6296 3767 Website: www.lonpac.com.sg

GST Reg No.: F0-0005635-C

MX1

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CAP 189) REPUBLIC OF SINGAPORE.
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES 1960 (REPUBLIC OF SINGAPORE).
ROAD TRANSPORT ACT 1987 (MALAYSIA).
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA).

Certificate No. : Z19VP05021873

Type of Cover : COMPREHENSIVE

1. Index Mark and Vehicle Registration Number

MERCEDES-BENZ CLA180 1.6
- SKR1995Y

2. Name of Policy Holder

CHUA BEE LAY

3. Effective Date of the Commencement of Insurance
for the purpose of the Act

23/01/2019

4. Date of Expiry of the Insurance

22/01/2020

5. Persons or Classes of Persons entitled to drive

(A) THE POLICYHOLDER (B) ANY OTHER PERSON WHO IS DRIVING ON THE POLICYHOLDER'S ORDER OR WITH HIS/HER PERMISSION
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use

USE ONLY FOR SOCIAL, DOMESTIC AND PLEASURE PURPOSES AND FOR THE POLICYHOLDER'S BUSINESS. THE POLICY DOES NOT
COVER USE FOR HIRE OR REWARD, RACING, PACE-MAKING, RELIABILITY TRIAL, SPEED-TESTING OR THE CARRIAGE OF GOODS
(OTHER THAN SAMPLES) IN CONNECTION WITH ANY TRADE OR BUSINESS OR USED FOR ANY PURPOSE IN CONNECTION WITH THE
MOTOR TRADE.

Excess : S\$ 0.00 (SECTION 1) INSURED / NAMED DRIVERS

S\$ 1,000.00 (SECTION 1) UNNAMED DRIVERS

S\$ 3,000.00 (SECTION 1) ADDITIONAL EXCESS FOR ELDERLY OR YOUNG AND/OR INEXPERIENCED DRIVERS

S\$ 100.00 WINDSCREEN EXCESS

Condition : ACCIDENT REPAIRS AT LONPAC'S AUTHORISED WORKSHOPS OR DISTRIBUTOR-OWNED MOTOR WORKSHOP

* Limitations rendered inoperative by Section 95 of the Road Transport Act 1987 (Malaysia) or Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap 189) Republic of Singapore are not included under heading.

I/WE hereby certify that this covering Note is issued in accordance with the provisions of Part IV of the Road Transport Act 1987 (Malaysia) and Motor Vehicles (Third-Party Risks and Compensation) Act (Cap 189) Republic of Singapore.

H.P. Owner : MAYBANK

CHIEF EXECUTIVE
(Singapore Branch)User ID: MRMLP0014
Date Issued: 11/01/2019



Accident Photo



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKR1995Y

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
62507388

Vehicle & Document Information

WIP No 38450
Reg No/Reg Date SKR1995Y / 23/01/2015
Date In/Mileage / 0
Chassis No WDD1173422N140029
Engine No 27091030503930
Make/Model MB/CLA 180 BlueEFFICIENCY (C
Colour/Trim 027 787 Mountain Gr/ 041 151-Leather Twi

Account No	Terms	Date/Time Printed	CSE	Operator				
WL001605	Credit	02/11/2019/ 11:43	YK	395 / Yik Chan Hoe				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
Z REQUEST								
Customer Request								
M BPNSUN								
POLICY NO/ACC DATE : Z19VP05021873 // 01/11/2019								
DRIVE IN/EXCESS : 02/11/2019 // TBA								
DATE IN/DATE SURVEY:								
BY/AUTHORIZED ON :								
S BPNSUB								
1 PC FRONT NO PLATE								
A BPILAB								
PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW								
BODY PANELS WITH REFINISH								
A BPIRES								
RESPRAY FRONT BUMPER								
A BPILAB							0.10	380.00
USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET SYSTEM TO								
STANDARD SETTINGS								
A BPILAB								120.00
CHECK HEADLAMP WITH FOCUS ADJUSTMENT								
M RIGHT HEADLAMP ? Xsuc					1.00	2540.64	00.00	2540.64 Xsuc
M FRONT TRIM BUMPER ? de					1.00	1372.13	00.00	1372.13 ✓
M FRONT LICENSE PLATE MOLDING de					1.00	97.95	00.00	97.95 ✓
M FRONT BUMPER GRILLE ? ca					1.00	150.79	00.00	150.79 ✓
M FRONT BUMPER UNDER COVER ? ca					1.00	328.72	00.00	328.72 ✓
M RIGHT FRONT BUMPER GRILLE ? Xsuc					1.00	46.15	00.00	46.15 Xsuc
M FRONT BUMPER COVER F TOWING EYE ? ca					1.00	60.25	00.00	60.25 ✓
M FRONT CPA RADAR SENSOR ? ca					1.00	1189.99	00.00	1189.99 ✓
M FRONT CPA RADAR SENSOR FIXTURE ? ca					1.00	71.03	00.00	71.03 ✓
M FRONT IMPACT ABSORBER ? ca					1.00	151.73	00.00	151.73 ✓
M FRONT BASIC MOUNTING FOR BUMPER ? ca					1.00	169.60	00.00	169.60 ✓
M RIGHT FRONT BASIC MOUNTING FOR BUMPER ? Xsuc					1.00	31.07	00.00	31.07 Xsuc
M RADIATOR GRILLE ? ca					1.00	670.31	00.00	670.31 ✓
M FRONT CROSS MEMBER ? Xsuc					1.00	322.40	00.00	322.40 Xsuc

Confirmed & accepted by

Yik Chan Hoe
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chanhoe.yik@cyclecarriage.com.sg

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKR1995Y

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
62507388

Vehicle & Document Information

WIP No **38450**
Reg No/Reg Date **SKR1995Y / 23/01/2015**
Date In/Mileage **/ 0**
Chassis No **WDD1173422N140029**
Engine No **27091030503930**
Make/Model **MB/CLA 180 BlueEFFICIENCY (C**
Colour/Trim **027 787 Mountain Gr/ 041 151-Leather Twi**

Account No	Terms	Date/Time Printed	CSE	Operator
WL001605	Credit	02/11/2019/ 11:43	YK	395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M RIGHT FRONT CROSS MEMBER ABSORBER ? XSV	1.00	151.76	00.00	151.76
M FRONT COVER F CROSS MEMBER ? XSV	1.00	72.66	00.00	72.66

THIS IS NOT AN OFFICIAL TAX INVOICE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

ESTIMATE

Rasul
Hy 90010068
3 days
04/11/19 @ 1445
EXCESS: 3000
REVERT
Resurvey before paint

Yik Chan Hoe
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
OID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chunhoe.yik@cyclocarriage.com.sg

Confirmed & accepted by

10877.27x
Nett 10,537.18
7% GST on 10537.18 737.60
Total Payable 11,274.78

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

SUPPLEMENTARY

ESTIMATE FOR SKR1995Y

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
62507388

Vehicle & Document Information

WIP No 38450
Reg No/Reg Date SKR1995Y / 23/01/2015
Date In/Mileage 05/11/2019 / 48686
Chassis No WDD1774422N140029
Engine No 27091030503930
Make/Model MB/CLA 180 BlueEFFICIENCY (C
Colour/Trim 027 787 Mountain Gr/ 041 151-Leather Twi

Account No	Terms	Date/Time Printed	GSE	Operator	Qty	Unit Price	Disc%	Amount
WL001605	Credit	13/11/2019/ 18:05		395 / Yik Chan Hoe	1.00	340.09	00.00	340.09
Description of Goods / Services								
X FRONT BUMPER ELECTRICAL WIRING HARNESS								

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Yik Chan Hoe
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chanhoe.yik@cyclecarriage.com.sg

Confirmed & accepted by

	Nett	340.09
7% GST on	340.09	23.81
Total Payable		363.90

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorized Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKR1995Y

Finalization

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
62507388

Vehicle & Document Information

WIP No 38450
Reg No/Reg Date SKR1995Y / 23/01/2015
Date In/Mileage 05/11/2019 / 48686
Chassis No WDD1173422N140028
Engine No 27091030503930
Make/Model MB/CLA 180 BlueEFFICIENCY (C
Colour/Trim 027 787 Mountain Gr/ 041 151-Leather Twi

Account No	Terms	Date/Time Printed	CSE	Operator
WL001605	Credit	13/11/2019/ 18:05		395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
---------------------------------	-----	------------	-------	--------

THIS IS NOT AN OFFICIAL TAX INVOICE				
Attn: RASUL				
03 Working Days				
ESTIMATE				
Z REQUEST				
Customer Request				
M BRANSON				
POLICY NO/ACC DATE : Z19VP05021873 // 01/11/2019				
DRIVE IN/EXCESS : 02/11/2019 // \$3000.00				
DATE IN/DATE SURVEY: 04/11/2019 // RASUL LKK				
BY/AUTHORIZED ON : 05/11/2019 @ 1730 // SHIRLEY LKK				
S BPNSUB				60.00
SUPPLY 1 PC NO PLATE				
A BPILAB				960.00
PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLAGE WITH NEW				
BODY PANELS WITH REFINISH				
A BPIRES				600.00
RESPRAY FRONT BUMPER				
A BPILAB		0.10		380.00
USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET SYSTEM TO				
STANDARD SETTINGS				
A BPILAB				120.00
CHECK HEADLAMP WITH FOCUS ADJUSTMENT				
X BPNEXC				-3000.00
INSURANCE EXCESS				
X FRONT TRIM BUMPER	1.00	1372.13	00.00	1372.13
X FRONT LICENSE PLATE MOLDING	1.00	97.95	00.00	97.95
X FRONT BUMPER GRILLE	1.00	150.79	00.00	150.79
X FRONT BUMPER UNDER COVER	1.00	328.72	00.00	328.72
X FRONT BUMPER COVER F TOWING EYE	1.00	60.25	00.00	60.25
X FRONT CPA RADAR SENSOR	1.00	1189.99	00.00	1189.99
X FRONT CPA RADAR SENSOR FIXTURE	1.00	71.03	00.00	71.03
X FRONT IMPACT ABSORBER	1.00	151.73	00.00	151.73
X FRONT BASIC MOUNTING FOR BUMPER	1.00	169.60	00.00	169.60
X RADIATOR GRILLE	1.00	670.31	00.00	670.31
X FRONT BUMPER ELECTRICAL WIRING HARNESS	1.00	340.09	00.00	340.09

Confirmed & accepted by

Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center

BIB: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chanhoe.yik@cyclecarriage.com.sg

Nett	3,722.59
7% GST on	260.58
Total Payable	3,983.17

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS/LPC19019414/R1sf3s2

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 29-11-2019



Code : LPC2

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SKR 1995Y
Policy No.	Z19VP05021873	Coverage (\$)	0.00
Claim No.	19/19/19/VP05/022596	Excess (\$)	3,000.00
Assign From	ONG LI LI	Assign Date	04/11/2019

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ CLA180 (R18)	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WDD1173422N140029	Colour	GREY
Odometer	48686	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/40 R18	PIRELLI	6 mm
L/H Front Tyre	225/40 R18	PIRELLI	6 mm
R/H Rear Tyre	225/40 R18	PIRELLI	6 mm
L/H Rear Tyre	225/40 R18	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	01/11/2019	Inspection Date	04/11/2019
Survey held at	CYCLE & CARRIAGE INDUSTRIES (1986) PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		

5a. Remarks

- A)THE MARKET VALUE IS S\$79,000.00(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKR 1995Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	RIGHT HEADLAMP (SN)	SERVICEABLE	2,540.64	-
1	FRONT TRIM BUMPER (SN)	DEFORMED	1,372.13	1,372.13
1	FRONT LICENCE PLATE MOULDING (SN)	DEFORMED	97.95	97.95
1	FRONT BUMPER GRILLE (SN)	CRACKED	150.79	150.79
1	FRONT BUMPER UNDER COVER (SN)	CRACKED	328.72	328.72
1	RIGHT FRONT BUMPER GRILLE (SN)	SERVICEABLE	46.15	-
1	FRONT BUMPER COVER F TOWING EYE (SN)	MISSING	60.25	60.25
1	FRONT CPA RADAR SENSOR (SN)	CRACKED	1,189.99	1,189.99
1	FRONT CPA RADAR SENSOR FIXTURE (SN)	CRACKED	71.03	71.03
1	FRONT IMPACT ABSORBER (SN)	CUT	151.73	151.73
1	FRONT BASIC MOUNTING FOR BUMPER (SN)	CRACKED	169.60	169.60
1	RIGHT FRONT BASIC MOUNTING FOR BUMPER (SN)	SERVICEABLE	31.07	-
1	RADIATOR GRILLE (SN)	CRACKED	670.31	670.31
1	FRONT CROSS MEMBER (SN)	SERVICEABLE	322.40	-
1	RIGHT FRONT CROSS MEMBER ABSORBER (SN)	SERVICEABLE	151.76	-
1	FRONT COVER F CROSS MEMBER (SN)	SERVICEABLE	72.66	-
1	FRONT NO. PLATE (SN)	BENT	60.00	60.00
1	FRONT BUMPER ELECTRICAL WIRING HARNESS (SN) (ADDITIONAL)	CUT	340.09	340.09
			7,827.27	4,662.59
	<u>LABOUR</u>			
	PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH.		1,800.00	960.00
	RESPRAY FRONT BUMPER.		750.00	600.00
	USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET SYSTEM TO STANDARD SETTINGS.		380.00	380.00
	CHECK HEADLAMP WITH FOCUS ADJUSTMENT.		120.00	120.00
			3,050.00	2,060.00
	GRAND TOTAL		10,877.27	6,722.59
	RECOMMENDED COST OF REPAIRS			6,722.59
	LESS EXCESS			-3,000.00
	NETT LIABILITY			3,722.59

Report Ref No. CS/LPC19019414/R1sf3s2



Report Ref No. CS/LPC19019414/R1sf3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.