

INS. CASE OWNER:

CC 6 /AIG1901

LKK:
IDAC:

Surveyor:

marcus

DOI:

4/11/19

Date / Time:

4/11/19

Registered in Merimen:

4/11/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLW 304K

Claim No.:

1104614M456

Name of Insured:

ALEXANDER LEOPOLD MARCELLIUS
JORANSA

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :\$

D.O.A.:

01/11/19

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: SUSANTI INORATHI WARDJOJO

OI GIA REPORT: YES NO ; TP GIA REPORT: YES NO

Driver Tel No.:

(V/L: YES NO)

Insured Liability: %

Final ? Yes / No

SJW 3611C

INSRS:
WSP:
Tel:
Liability:
RMKS:

Hup motor

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

06/11 - 01MR

15/11 02 GIA Report in

18/11/19 • MIE KOLEKES. OLD KOLEKES &
HIC TP BEHIND. SEND LETTER OI
TO KOTAY TP CLAIM & NEW ISSUES.
- BUND LIABILITY CLARKE
- ORIGINAL TP LOD IN

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI: 18/11/19 - vic

After call ltr to OI: 18/11/19 - vic

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: CMS

Repair Cost:

4% \$5,100.00

(3 days) Reduction:

67 %

Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time: 02-01-20

Confirm with: CMS

Email ☒ Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

NIL

If NO or B 28, Ass. Lia:

(OLD KOLEKES)

Repair Cost:

\$5,100.00

Loss of Rental (LOR):

\$5 -

(days)

Loss of Use (LOU):

\$5,100.00

(\$100 x 3 days)

Loss of Income (LOI):

\$5 -

(\$ x days)

LOR only ☐LOU only ☒LOR + LOU ☐LOR + LO ☐

[Tick only one]

GIA/LTA Search

\$5,200

Medical:

\$5 -

Disbursement:

\$5 -

(e.g. Tow/ Independent)

Legal Cost

\$5 -

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: +320

Total:

\$5,100.00

Global Sum \$5:

FINAL PAYMENT

Date/Time: 02-01-20

Confirm with: CMS

Email ☒ Call ☐

Payee 1:

\$5,100.00

Name 1:

Hup MOTOR TRADING & SERVICE

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

ASS. FEO. BY:

DATE:

A16/

ACRUS

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SJW361K
 at Workshop mile by road 01-98
 of SLW304K
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Velt: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bail. or Market Value: 23k.
 IDAC Accident Rport: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

2202C

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJW361K Yr Regn: 3 / 10
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CA1
 Make: Toyota Estima Aeris C.C. 2362
 Colour: Purple A/C: Insured / Std / NI / NA
 Sp. Reading: 177651 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: ACR500107504
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Good / Jammed / Leaked / Burnt / or
 Brake: Good / Jammed / Leaked / Burnt / or
 Modi: Nil / S/Rim / STD A/Rim / or
 Tyre Size: F: 215/55R17
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MICA / OHTSU / PIR / SUMI /
 TOYO / YOKO / or

Front: 6 mm Rear: 6 mm
 R/Bal: 6 mm L/Bal: 6 mm
 D.O.A. 01-11-19 D.O.I. 4/11/19

Survey held at: _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop / or

RP.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>17A 18326 4mth.</u>
	<u>40: +1,100 (RED: + 2,336.80 61%)</u>

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair: _____

ii

☐

: Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

iii

Add Fee:

☐

: Site Insp. (\$

☐

: Interview (\$

☐

: Tech. Inve (\$

☐

: Wast and %

Survey Fee:

Transportation:

3 + PC. \$

Phone

Other

TOTAL

Report Format:

Lump Sum / B.B.I.:

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: **TP 2957/11719**

Your Ref: _____

Date: **4th NOV 2019**

MR SEAM KOK YONG
23, Jalan Sinar Bintang
Singapore 509245

Not Attached
4/11/19
Take photo after repair
1/2 1100
327

Estimate cost of repair to TOYOTA ESTIMA ABRAS 2.4 (A) S/Wgn - SJW 3611 C

1 pc front bumper		<i>repaired</i> \$ 545.20
15 pcs front bumper top & low clips	@ \$ 3.90	<i>new</i> 62.40
1 pc front bumper sponge damper		<i>17</i> 65.60 X
1 pc front bumper reinforcement		<i>new</i> 404.20 X
2 pcs front bumper o/s & n/s side retainer	@ \$ 66.80	<i>17</i> 133.60 X
1 pc front bumper lower aircoop grille		<i>new</i> 213.90
1 pc front grille		<i>new</i> 460.10 X
8 pcs front grille clips	@ \$ 3.90	<i>new</i> 31.20 1pc
1 pc front grille logo emblem		<i>17</i> 47.90 X
1 pc front bumper aircoop grille chrome moulding		<i>new</i> 160.30
1 pc front number plate & frame (Enforce)		<i>new</i> 60.00 405.00
		\$ 2,182.40
	Less 25%	\$ 545.60
		\$ 1,636.80

To wiring check up & adjust headlight alignment. 50.00 20

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out front bumper reinforcement, front top panel & necessary parts, to weld, renew & align above parts. 750.00 280

To patty & respray painting on all affected accident parts. 900.00 300

\$ 3,336.80

Dollars : Three Thousand Three Hundred Thirty Six And Cents Eighty Only.

HUP MOTOR TRADING & SERVICE

LKK Auto Consultants hence notify the Repairer of the following:

- 1. All items before/after spray painting
- 2. All items damaged parts/ body resurvey
- 3. All items subject to confirmation
- 4. All items "Without Prejudice" basis
- 5. All items subject to approval
- 6. Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

98670
252
74002
1380.02
202
1104.01

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 202C

Vehicle Details

Vehicle No.: SJW3611C

Vehicle to be Exported: No

Intended Deregistration Date: 04 Nov 2019

Vehicle Make: TOYOTA

Vehicle Model: ESTIMA AERAS 2.4 A

Primary Colour: Purple

Manufacturing Year: 2009

Engine No.: 2AZF350188

Chassis No.: ACR500107504

Maximum Power Output: 125.0 kW (167 bhp)

Open Market Value: \$35,231.00

Original Registration Date: 19 Mar 2010

First Registration Date: 19 Mar 2010

Transfer Count: 1

Actual ARF Paid: \$35,231.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 18 Mar 2020

PARF Rebate Amount: \$17,615.00

Intended COE Rebate Details

COE Expiry Date: 18 Mar 2020

COE Category: B - Car (1601cc & above)

COE Period(Years): 10

QP Paid: \$19,190.00

COE Rebate Amount: \$711.00

Total Rebate Amount: \$18,326.00

The information contained herein is correct as at 04 Nov 2019

OK



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)



[Advanced Search](#)

Home » Used Cars » Direct Owners » Toyota Estima 2.4A Aeras G Moonroof

Toyota Estima 2.4A Aeras G Moonroof

- [Overview](#) [Financial](#) [Insurance](#) [Accessories](#) [Similar](#) [Research](#) [Photos](#) [Map](#) [DIRECT OWNER](#)

Price	\$33,150		
Depreciation	N.A.	Reg Date	27-Apr-2010 (5mths 22days COE left)
Mileage	N.A.	Manufactured	2010
Road Tax	\$1,638 /yr	Transmission	Auto
Dereg Value	\$19,495 as of today (change)	OMV	\$35,177
COE	\$40,001	ARF	\$35,177
Engine Cap	2,362 cc	Power	125.0 kW (167 bhp)
Curb Weight	1,770 kg	No. of Owners	3
Type of Vehicle	MPV		



GET YOUR
COE
RENEWAL
LOAN

Preferred Viewing Area

- [Shortlist](#) [Compare](#) [Add note](#)
- [Report Error](#) [More Actions](#)

Features
Always Park Under Shelter. Well Maintained For Long Driving Distance Anytime. View specs of the Toyota Estima (2006-2010)

Accessories
Full Range.

Description
Road Tax Till COE Expiry.

Category
PART Car, Direct Owner Sale

Status
Available

Resources



Car Valuation - Free
Find out the market value of your existing car for free. [Get started](#)



Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. [Find out more](#)

Posted on: 03-Nov-2019 | Last Updated on: 03-Nov-2019

Upfront Payment [» more Financial info](#)

Transfer Fee \$25
[Compare](#)

Seller Information

Contact Person(s) Y K Yong
Contact No. 92343773
Enquiry ☒ Contact Seller

ESSENTIAL TRANSACTION FORMS

- [» Indemnity form](#) [» Sales agreement](#)
- [» Receipt](#) [» Hand-over form](#)
- [» Ownership Transfer](#)



GET HELP WITH
PAPERWORK



sgCarMart Connect handles your transaction paperwork - send us your completed Sales Agreement, and we'll help with **Car Loans, Insurance, Payments & Ownership Transfer**. FREE for all sgCarMart Advertised Vehicles.

[Upload your Sales Agreement](#)

[Read our 8 Step Guide for Direct Buyers & Sellers](#)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG19019428/Uhb3

06 November, 2019

Alexander Leopold Marcellius Joramsa

72 Bayshore Road
#08-13 Costa De Sol
Singapore 469988

Dear Sirs,

**ACCIDENT INVOLVING SLW 304K AND SJW 3611C ON 01/11/2019 ALONG/
AT NEW LOYANG LINK TO OLD TAMPINESE ROAD**

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, AIG Asia Pacific Insurance Pte Ltd (AIG) to settle a THIRD PARTY claim against you for an accident which happened on the above-mentioned date and location.

Kindly proceed to lodge your GIA report within five (05) working days of receipt of this letter, giving the version of the accident amongst other things related to the accident. The GIA report can be lodged at any of AIG reporting centres. You may refer to your Certificate of Insurance for the list of the reporting centres.

If you have any information to add or any amendments to make, please contact the undersigned within five days from the date of this letter.

Please note that the standing of your insurance policy such as NCD, premium & etc would be affected.

Yours faithfully,

Vic Alpeh Sanghilan
Claims
Tel : 6841 2096
Fax: 6741 4108
Email : vicalpeh@lkkauto.com

c.c. *Claims Manager*
AIG Asia Pacific Insurance Pte Ltd

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To : AIG Asia Pacific Insurance Pte. Ltd.
Attn : Chan, Klan-Meng

Your Ref : 1104619434SG
Our Ref : CC6/AIG19019428/UHB3
Date : 02 Jan 2020

"WITHOUT PREJUDICE"**ACCIDENT INVOLVING SLW304K & SJW3611C ON 01/11/2019**

Refer to the above accident.

The accident occurred when insured reversed and hit third party vehicle. We have clarified with the OI on the nature of the accident and he/she is aware that his/her NCD would be affected.

On behalf of AIG Asia Pacific Insurance Pte. Ltd., we have **successfully / not successfully** carried out **TP Express Settlement** between your insured (vehicle no. SLW304K) and third party claimant (vehicle no. SJW3611C).

Summary of offer made to workshop Hup Motor Trading & Service is as follows :

	Claimed	Revised
Cost of Repairs	\$ 3,336.80	\$ 1,100.00
Loss of Use (3days x \$100)	\$ 300.00	\$ 300.00 (3days x \$100)
LTA Search Fee	\$ 2.00	\$ 2.00

Amount of claim at **Liability 100%** \$ 1,402.00

Our surveyor recommended 3days repair.

Enclose herewith the relevant supporting documents for your perusal.

For your approval please.

Regards,
Asher Sng Rong Yi
LKK Auto Consultants Pte Ltd

Print Received Message

This mail is associated with :

***SJW3611C (1104619434SG)**
[SLW304K]

TP

SEAH KOK YONG

Nov 1 2019 11:05AM

[ALEXANDER LEOPOLD MARCELL]

Hup Motor Trading & Service

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 02/01/2020 15:00 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$1402.00) - SJW3611C - Claim Handler: Chan, Kian-Meng

Approved:1402.00:Kindly settle at best and please upload the necessary documents

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Nov 2019 Edit Reg		04 Nov 2019 00:00 Edit Adj Rpt	S\$1,100.00 Edit Estimates	S\$1,100.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: ALEXANDER LEOPOLD MARCELLIUS JORAMSA , ID: S7069726B									
Main Claimant: SEAH KOK YONG , ID: S7702202C									
Vehicle Reg. No.:	SJW3611C	Date of Loss:	01/11/2019 11:00 - :59 [115 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1104619434SG	Policy/Cover Note No.:	1800006214 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLW304K	Policy No. (Claimant):	19-MW011636-R03						
Excess:									
Repairer: Hup Motor Trading & Service (HQ) Blk 9004 Tampines Street 93, #01-120, 528838 Tampines - Tel: 67840039/98154655									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com									
Claimant's Insurer: Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 13/11/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (02/01/2020): Alert - Adj Mandate Approved (S\$1402.00) - SJW3611C - Claim Handler: Chan, Kian-... - AIG_SG (15/11/2019): Re: No OI GIA Report - AIG_SG (05/11/2019): No OI GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJW3611C (1104619434SG)
[SLW304K]

TP

SEAH KOK YONG

Nov 1 2019 11:05AM

[ALEXANDER LEOPOLD MARCELLIUS JORAMSA]
Hup Motor Trading & Service

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

Letters/Correspondences

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Edit	

Assessment Reports

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	02/01/20 12:37	Adjuster Immediate Advice		Load HTM	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	04/11/19 18:51	Odometer Reading		Load JPG	
2	04/11/19 18:51	Chassis Number		Load JPG	
3	04/11/19 18:51	General View		Load JPG	
4	04/11/19 18:51	General View		Load JPG	
5	04/11/19 18:51	General View		Load JPG	
6	04/11/19 18:51	General View		Load JPG	
7	04/11/19 18:51	General View		Load JPG	
8	04/11/19 18:51	General View		Load JPG	
9	04/11/19 18:51	General View		Load JPG	
10	04/11/19 18:51	General View		Load JPG	
11	04/11/19 18:51	General View		Load JPG	
12	04/11/19 18:51	General View		Load JPG	
13	04/11/19 18:51	General View		Load JPG	
14	04/11/19 18:51	General View		Load JPG	
15	04/11/19 18:51	General View		Load JPG	
16	04/11/19 18:51	General View		Load JPG	
17	04/11/19 18:51	General View		Load JPG	
18	04/11/19 18:51	General View		Load JPG	
19	04/11/19 18:51	General View		Load JPG	
20	04/11/19 18:51	General View		Load JPG	
21	04/11/19 18:51	General View		Load JPG	
22	04/11/19 18:51	General View		Load JPG	
23	04/11/19 18:51	General View		Load JPG	
24	04/11/19 18:51	General View		Load JPG	
25	04/11/19 18:51	General View		Load JPG	
26	04/11/19 18:51	General View		Load JPG	
27	04/11/19 18:51	General View		Load JPG	
28	04/11/19 18:51	General View		Load JPG	
29	04/11/19 18:51	General View		Load JPG	
30	04/11/19 18:51	General View		Load JPG	
31	04/11/19 18:51	General View		Load JPG	
32	04/11/19 18:51	General View		Load JPG	
33	04/11/19 18:51	General View		Load JPG	
34	04/11/19 18:51	General View		Load JPG	
35	04/11/19 18:51	General View		Load JPG	
36	27/11/19 18:16	After Repair Photo		Load JPG	

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
37	27/11/19 18:16	After Repair Photo		Load JPG	☒
38	27/11/19 18:16	After Repair Photo		Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	04/11/19 15:05	TP EST & GIA REPORT.		Load PDF	
2	06/11/19 14:16	Ltr to Insured -non reporting		Load PDF	
3	18/11/19 12:02	LETTER TO OI		Load PDF	
4	02/01/20 12:34	TP ESTIMATE - MARKED (FINAL)		Load PDF	
5	09/01/20 08:52	WORKSHOP INVOICE		Load PDF	
6	09/01/20 08:52	AUTHORISATION TO ACT FORM		Load PDF	
7	09/01/20 08:52	Release Voucher		Load PDF	
8	09/01/20 08:52	GIA SEARCH		Load PDF	
9	09/01/20 08:52	LOD		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	15/11/19 13:58	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLW304K (Insd veh)	Model:	TOYOTA ESTIMA 2.4 (A)
	SJW3611C (TP veh)		
Date of Accident:	01/11/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	3,336.80
Final Repair Cost	:	\$	1,100.00
Loss of Use	:	\$	300.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	1,402.00

3.00 days at \$100.00 per day
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____100____(%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Hup Motor Trading & Service	:	\$ 1,402.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

09 Jan
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19019428/UHA3Q2

Date: 09/01/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800006214
 Claimant: SJW3611C Insured Vehicle No: SLW304K
 Vehicle No: SJW3611C
 Date of Loss: 01/11/2019 Nature of Claim: TP Claim No: 1104619434SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJW3611C
 Make & Model: TOYOTA ESTIMA, 2.4 (A) Engine No: 2AZF350188
 Reg. Date: 18/03/2010 (Man. Year: 2009) Chassis No: ACR500107504
 Colour: Purple Odometer: 177651 km
 Engine Capacity: 2362 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55Z R17 Rear Tyre Size: 215/55Z R17
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,636.80	780.02	856.78	52.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,700.00	600.00	1,100.00	64.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,336.80	1,380.02	1,956.78	58.64
Approved Total (Overridden) (S\$)		1,100.00		
Nett Amount (S\$)	3,336.80	1,100.00	2,236.80	67.03
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,402.00		

INSPECTION

Date of Assignment: 04/11/2019
 Date Inspected: 04/11/2019 Inspected At: Hup Motor Trading & Service (HQ)
 Blk 9004 Tampines Street 93, #01-120
 Singapore 528838
 Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented / Warped	546.20 FL	*546.20 FL
2	16		*FRONT BUMPER TOP & LOW CLIPS	Necessary	62.40 FL	*62.40 FL
3	1		*FRONT BUMPER SPONGE DAMPER	Not Necessary	65.60 FL	*- FL
4	1		*FRONT BUMPER REINFORCEMENT	Serviceable	401.20 FL	*- FL
5	2		*FRONT BUMPER O/S & N/S SIDE RETAINER	Not Necessary	133.60 FL	*- FL
6	1		*FRONT BUMPER LOWER AIRSCOOP GRILLE	Twisted	213.90 FL	*213.90 FL
7	1		*FRONT GRILLE	Serviceable	460.10 FL	*- FL
8	1		*FRONT GRILLE CLIPS (8 PCS)	Missing (1 PCS ONLY)	31.20 FL	*3.90 FL
9	1		*FRONT GRILLE LOGO EMBLEMS	Not Necessary	47.90 FL	*- FL
10	1		*FRONT BUMPER AIRSCOOP GRILLE CHROME MOULDING	Scratched	160.30 FL	*160.30 FL
11	1		*FRONT NUMBER PLATE & FRAME (ENFORCE)	Bent	45.00 FS	*40.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					2,167.40	1,026.70
- List Item Discount on L Items 25.00/25.00% (\$\$)					530.60	246.68
Total Parts (\$\$)					1,636.80	780.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO WIRING CHECK UP & ADJUST HEADLIGHT ALIGNMENT	New	50.00	20.00
2	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS ,TO JACK ,STRAIGHTEN & KNOCKING OUT FRONT BUMPER REINFORCEMENT ,FRONT TOP PANEL & NECESSARY PARTS ,TO WELD ,RENEW & ALIGN ABOVE PARTS	New	750.00	280.00
3	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS	New	900.00	300.00
Gross Labour Cost (S\$)			1,700.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >