



Case Details

Case Reference Number : TAX/10/19/2110
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHC4971K

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-9109-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 30/10/2019 04:40 PM
 Vehicle Age(In Months) : 24

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	317.92	Replace ▾	✓ pp.
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace ▾	✓ Nec
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 1	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace ▾	✓ Nec
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 2	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace ▾	✓ Nec
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 3	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace ▾	✓ Nec
One Time Key In	Main			SEAL, RR BUMPER ARM, RH & LH	2	11.00	22.00	25.00	16.50	Replace	2	16.50	Replace ▾	✓ Nec
One Time Key In	Main			FILLER, RR BUMPER , RH	1	119.90	119.90	25.00	89.93	Replace	1	0	Repair ▾	X R
One Time Key In	Main			REAR BUMPER REINFORCEMENT	1	318.80	318.80	25.00	239.10	Replace	0	0	Not Givr ▾	X suc
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Givr ▾	X suc

Total Spare Part Cost 6,113.93

Surveyor Total 920.89

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 6,113.93

Final Sur Total 920.89

				SMRT Recommendation							Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace ▾	✓ Nec
One Time Key In	Main			RETAINER, RR BUMPER, RH	1	112.70	112.70	25.00	84.53	Replace	0	0	Check ▾	X SVC
One Time Key In	Main			SEAL, RR BUMPER, RH	1	85.20	85.20	25.00	63.90	Replace	0	0	Check ▾	X SVC
One Time Key In	Main			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.72	Replace	0	0	Not Givr ▾	X SVC
One Time Key In	Main			COVER, GUARD RR BUMPER LOWER	1	14.80	14.80	25.00	11.10	Replace	0	0	Not Givr ▾	X SVC
One Time Key In	Main			PAD, RR BUMPER, CTR	3	2.20	6.60	25.00	4.95	Replace	0	0	Not Givr ▾	X SVC
One Time Key In	Main			LENS & BODY ASSY, RR BUMPER, RH	1	486.80	486.80	10.00	438.12	Replace	1	438.12	Replace ▾	✓ SCR
One Time Key In	Main			COVER, REAR FLOOR UNDER, RH	1	169.50	169.50	25.00	127.13	Replace	0	0	Not Givr ▾	X SVC
One Time Key In	Main			END PANEL SUBASSY, BODY LOWER BACK	1	629.80	629.80	25.00	472.35	Replace	0	0	Not Givr ▾	X SVC
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Givr ▾	X SVC
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP, RH	1	438.10	438.10	10.00	394.29	Replace	0	0	Not Givr ▾	X SVC
One Time Key In	Main			TROUGH, BACK DOOR, RH	1	99.80	99.80	25.00	74.85	Replace	0	0	Not Givr ▾	X SVC
One Time Key In	Main			PANEL SUB-ASSY, FENDER REAR RH	1	824.80	824.80	25.00	618.60	Replace	1	0	Repair ▾	X R
One Time Key In	Main			DUCT ASSY, QUARTER VENT, RH & LH	1	65.00	65.00	25.00	48.75	Replace	0	0	Not Givr ▾	X SVC

Total Spare Part Cost 6,113.93

Surveyor Total 920.89

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 6,113.93

Final Sur Total 920.89

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			LINER, REAR FENDER, RH	1	135.80	135.80	25.00	101.85	Replace	0	0	Not Given	X SVC
One Time Key In	Main			PANEL SUB-ASSY, REAR DOOR, RH	1	1,243.90	1,243.90	25.00	932.93	Replace	1	0	Repair	X R
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Given	X SVC
One Time Key In	Main			WHEEL, DISC	1	1,555.10	1,555.10	25.00	1,166.32	Replace	0	0	Not Given	X SVC
Total Spare Part Cost									6,113.93	Surveyor Total		920.89		
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)		0		
Final Spare Part Cost									6,113.93	Final Sur Total		920.89		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH PORTION	845.00	400	
Total:			845.00	400.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY FILLER RR BUMPER RH	180.00	60	
3	Main	TO RESPRAY BUMPER BEAM	180.00	0	X
4	Main	TO RESPRAY REAR PANEL	180.00	0	
5	Main	TO RESPRAY TROUGH BACK DOOR RH	180.00	0	
6	Main	TO RESPRAY REAR FENDER RH	378.00	200	
7	Main	TO RESPRAY RH REAR DOOR	378.00	200	
8	Main	TO RESPRAY RIM	180.00	0	
Total:			2,034.00	660.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TOWING CHARGE	56.00	0	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	✓ Nec
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20	✓ Nec
4	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	
5	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0	
6	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20	✓ Nec.
7	Main	TO REMOVE AND REFIT WIRE HARDESS	200.00	0	
8	Main	TO REPLACE SUNDRY PARTS	100.00	0	
9	Main	TO WASH AND VACUUM	60.00	0	
Total:			956.00	60.00	


Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	6,113.93	920.89
Total Labour Cost	0.00	400.00
Total Spray Painting	0.00	660.00
Other	0.00	60.00
Overall Total	6,113.93	2,040.89
Lump Sum Repair Option	☐	☐
Lump Sum Total	0.00	2,040.89
Surveyor Approved Amount		2,040.89
No of Repair Days*	6	4
Remarks	-	P/P, BEFORE SPAY PHOTO. CHECK ITEM AND REPLACE ITEM PLEASE CALL SUN PIN (LKK) / HP : 9921 2877 & Email:
Surveyor Name		Sun Pin (LKK)

Estimator Assesment(\$)

Surveyor Assesment(\$)

Signature



Save

Clear

Survey Date

01/11/2019

TP without Prejudice.

Sun Pin.

P/P Repair.

Before spray photo.

01/11/2019.

3.00 p.m.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: