

Pass to vic, Thanks

Section A - Accident Details	
Registration Number	SHC4971K
Case Reference Number	TAX/10/19/2110
Registration Date	10/10/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	TAN BENG SOON
Type of Accident	Side Swipe
Accident Date and Time	31/10/2019 12:40 AM
Accident Reported Date and Time	31/10/2019 10:00 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	31/10/2019 12:40 AM
Replacement Vehicle issued?	No
Job Card Number	24104086
Special Instruction to ARC, if any	TOWED \$40 /RIGHT PORTION
Prepared Date and Time	31/10/2019 3:48 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$400.00
Total Spray Cost	\$2,034.00	\$660.00
Total Spare Part Cost	\$6,113.93	\$920.90
Total Other Cost	\$956.00	\$100.00
TOTAL COST	\$9,948.93	\$2,080.90 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	4.0
Prepared / Adjusted By	Tuck Foo Kok	Sun Pin (LKK) / AIG
ARC / Surveyor Sign Off Date	31/10/2019 4:22 PM	01/11/2019 3:00 PM
Signature		
Remarks	P/P, BEFORE SPAY PHOTO. CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR Sun Pin (LKK) / HP : 8661 2627 & Email:	

920.90
+ 400.00
+ 760.00

2080.90

Repair day
4 days.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1911-0146	Invoice Number	
Quotation Date	13.11.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	\$845.00	\$400.00
Total Labour	\$845.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY FILLER RR BUMPER RH	\$180.00	\$60.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY TROUGH BACK DOOR RH	\$180.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
TO RESPRAY RH REAR DOOR	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$2,034.00	\$660.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$56.00	\$40.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$20.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$956.00	\$100.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159479 13	COVER, RR BUMPER ASSY	1.00	\$423.90	25.00	\$317.93	Replace	Replace
		52161160 10	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace
		52462470 30	PAD, RR BUMPER, RH & LH, 1	2.00	\$3.80	25.00	\$5.70	Replace	Replace
		52462470 20	PAD, RR BUMPER, RH & LH, 2	2.00	\$3.80	25.00	\$5.70	Replace	Replace
		52462470 10	PAD, RR BUMPER, RH & LH, 3	2.00	\$3.80	25.00	\$5.70	Replace	Replace

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685562
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 13/11/2019

User ID : PohSuan

	52191470 30	SEAL, RR BUMPER ARM, RH & LH	2.00	\$11.00	25.00	\$16.50	Replace	Replace	✓
	52565479 00	FILLER, RR BUMPER, RH	1.00	\$119.90	100.00	\$0.00	Replace	Repair	✓
	52023470 30	REAR BUMPER REINFORCEMENT	0.00	\$318.80	0.00	\$0.00	Replace	Not Given	X
		SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given	X
		PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	✓
	52575470 40	RETAINER, RR BUMPER, RH	0.00	\$112.70	0.00	\$0.00	Replace	Check	✓
	52591470 50	SEAL, RR BUMPER, RH	0.00	\$85.20	0.00	\$0.00	Replace	Check	X
	52453470 10	GUARD, RR BUMPER, LOWER	0.00	\$558.30	0.00	\$0.00	Replace	Not Given	X
	52169470 20	COVER, GUARD RR BUMPER LOWER	0.00	\$14.80	0.00	\$0.00	Replace	Not Given	X
	52461470 10	PAD, RR BUMPER, CTR	0.00	\$2.20	0.00	\$0.00	Replace	Not Given	X
	81581470 10	LENS & BODY ASSY, RR BUMPER, RH	1.00	\$486.80	10.00	\$438.12	Replace	Replace	✓
	58398470 50	COVER, REAR FLOOR UNDER, RH	0.00	\$169.50	0.00	\$0.00	Replace	Not Given	X
	58307470 90	END PANEL SUBASSY, BODY LOWER BACK	0.00	\$629.80	0.00	\$0.00	Replace	Not Given	X
		SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X
	81551472 81	LENS & BODY, REAR COMBINATION LAMP, RH	0.00	\$438.10	0.00	\$0.00	Replace	Not Given	X
	61621470 50	TROUGH, BACK DOOR, RH	0.00	\$99.80	0.00	\$0.00	Replace	Not Given	X
	61601471 50	PANEL SUB-ASSY, FENDER REAR RH	1.00	\$824.80	100.00	\$0.00	Replace	Repair	✓
	62940470 10	DUCT ASSY, QUARTER VENT, RH & LH	0.00	\$65.00	0.00	\$0.00	Replace	Not Given	X
	65637470 60	LINER, REAR FENDER, RH	0.00	\$135.80	0.00	\$0.00	Replace	Not Given	X
	67003472 10	PANEL SUB-ASSY, REAR DOOR, RH	1.00	\$1,243.90	100.00	\$0.00	Replace	Repair	✓
		TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X
	42611474 50	WHEEL, DISC	0.00	\$1,555.10	0.00	\$0.00	Replace	Not Given	X
Total				\$7,712.04		\$920.90			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

920.90
+ 400.00
+ 760.00

2080.90



Case Details

Case Reference Number : TAX/10/19/2110
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHC4971K

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-9109-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 30/10/2019 04:40 PM
 Vehicle Age(In Months) : 24

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	317.92	Replace	✓ / PD
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace	✓ / Nec
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 1	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	✓ / Nec
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 2	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	✓ / Nec
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 3	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	✓ / Nec
One Time Key In	Main			SEAL, RR BUMPER ARM, RH & LH	2	11.00	22.00	25.00	16.50	Replace	2	16.50	Replace	✓ / Nec
One Time Key In	Main			FILLER, RR BUMPER, RH	1	119.90	119.90	25.00	89.93	Replace	1	0	Repair	✓ X R
One Time Key In	Main			REAR BUMPER REINFORCEMENT	1	318.80	318.80	25.00	239.10	Replace	0	0	Not Given	✓ X Svc
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Given	✓ X Svc

Total Spare Part Cost 6,113.93

Surveyor Total 920.88

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 6,113.93

Final Sur Total 920.88

11/1/2019

<https://vacswb.smr.com.sg/Estimation.aspx>

SMRT Recommendation												Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	✓ NEC
One Time Key In	Main			RETAINER, RR BUMPER, RH	1	112.70	112.70	25.00	84.53	Replace	0	0	Check	✗ SVC
One Time Key In	Main			SEAL, RR BUMPER , RH	1	85.20	85.20	25.00	63.90	Replace	0	0	Check	✗ SVC
One Time Key In	Main			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.72	Replace	0	0	Not Give	✗ SVC
One Time Key In	Main			COVER, GUARD RR BUMPER LOWER	1	14.80	14.80	25.00	11.10	Replace	0	0	Not Give	✗ SVC
One Time Key In	Main			PAD, RR BUMPER, CTR	3	2.20	6.60	25.00	4.95	Replace	0	0	Not Give	✗ SVC
One Time Key In	Main			LENS & BODY ASSY , RR BUMPER , RH	1	486.80	486.80	10.00	438.12	Replace	1	438.12	Replace	✓ SCR
One Time Key In	Main			COVER, REAR FLOOR UNDER , RH	1	169.50	169.50	25.00	127.13	Replace	0	0	Not Give	✗ SVC
One Time Key In	Main			END PANEL SUBASSY, BODY LOWER BACK	1	629.80	629.80	25.00	472.35	Replace	0	0	Not Give	✗ SVC
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Give	✗ SVC
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP , RH	1	438.10	438.10	10.00	394.29	Replace	0	0	Not Give	✗ SVC
One Time Key In	Main			TROUGH, BACK DOOR , RH	1	99.80	99.80	25.00	74.85	Replace	0	0	Not Give	✗ SVC
One Time Key In	Main			PANEL SUB-ASSY, FENDER REAR RH	1	824.80	824.80	25.00	618.60	Replace	1	0	Repair	✗ R
One Time Key In	Main			DUCT ASSY, QUARTER VENT , RH & LH	1	65.00	65.00	25.00	48.75	Replace	0	0	Not Give	✗ SVC

Total Spare Part Cost 6,113.93

Surveyor Total 920.89

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 6,113.93

Final Sur Total 920.89

920.90

<https://vacswb.smr.com.sg/Estimation.aspx>

2/1

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			LINER, REAR FENDER, RH	1	135.90	135.90	25.00	101.85	Replace	0	0	Not Give	X SVC
One Time Key In	Main			PANEL SUB-ASSY, REAR DOOR, RH	1	1,243.90	1,243.90	25.00	932.93	Replace	1	0	Repair	X R
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	X SVC
One Time Key In	Main			WHEEL, DISC	1	1,595.10	1,595.10	25.00	1,196.32	Replace	0	0	Not Give	X SVC
Total Spare Part Cost									6,113.93	Surveyor Total 920.89				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0				
Final Spare Part Cost									6,113.93	Final Sur Total 920.89				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH PORTION	845.00	400	/
Total:			845.00	400.00	/

Spray Coat Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	/
2	Main	TO RESPRAY FILLER RR BUMPER RH	180.00	60	/
3	Main	TO RESPRAY BUMPER BEAM	180.00	0	X
4	Main	TO RESPRAY REAR PANEL	180.00	0	.
5	Main	TO RESPRAY TROUGH BACK DOOR RH	180.00	0	.
6	Main	TO RESPRAY REAR FENDER RH	378.00	200	/
7	Main	TO RESPRAY RH REAR DOOR	378.00	200	/
8	Main	TO RESPRAY RIM	180.00	0	.
Total:			2,034.00	660.00	/

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TOWING CHARGE	56.00	0 <i>40</i>	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	<i>/ Nec</i>
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20	<i>/ Nec</i>
4	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	
5	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0	
6	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20	<i>/ Nec.</i>
7	Main	TO REMOVE AND REFIT WIRE HARDESS	200.00	0	
8	Main	TO REPLACE SUNDRY PARTS	100.00	0	
9	Main	TO WASH AND VACUUM	60.00	0	
Total:			956.00	60.00 100	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	6,113.93	920.89
Total Labour Cost	0.00	400.00
Total Spray Painting	0.00	660.00
Other	0.00	80.00
Overall Total:	6,113.93	2,040.89
Lump Sum Repair Option		
Lump Sum Total:	0.00	2,040.89
Surveyor Approved Amount		2,040.89
No of Repair Days*	6	4
Remarks		P/P, BEFORE SPAY PHOTO. CHECK ITEM AND REPLACE ITEM PLEASE CALL SUPERVISOR @ 686 0 000 / 686 0 000 1 6977 8 6977
Surveyor Name		Sun Pin (LKK)

11/1/2019

<https://vacswb.smrt.com.sg/Estimation.aspx>

Estimator Assessment(\$)

Surveyor Assessment(\$)

Signature



Save Clear

Survey Date

01/11/2019

TP Without Prejudice.

Sun P.m.

P/P Repair.

Before spray photo

01/11/2019.

3.00 p.m.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: