

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5483X**AAD1910-241**

Not Authorized
Li Sup \$ 22506

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

01 NOV 2019

SHC 5483X

VF1ABL15AUC277525

RENAULT

LATITUDE

30.10.19

AIG

11/7/2014

PART		LIST	
1	BUMPER COVER FRT	\$	<i>Buc</i> 747.20 —
1	BUMPER SPOILER FRT	\$	<i>SL</i> 344.70 X
1	BUMPER ABSORBER FRT	\$	<i>SL</i> 394.68 X
1	BUMPER RETAINER FRT RH	\$	<i>Mr</i> 101.40 —
1	BUMPER SUPPORT FRT	\$	<i>SL</i> 10.70 X
1	BUMPER UNDERTRAY FRT	\$	<i>SL</i> 292.50 X
1	BUMPER GRILLE LOWER FRT	\$	<i>SL</i> 147.00 X
1	BUMPER FOG LAMP GRILLE RH	\$	<i>SL</i> 207.21 X
1	BUMPER BEAM FRT	\$	<i>M</i> 663.70 X
1	HEADLAMP RH	\$	<i>Cur</i> 743.60 —
1	HEADLAMP PANEL FRT RH	\$	<i>M</i> 128.30 X
1	FENDER PANEL FRT RH	\$	<i>B</i> 437.10 —
1	WHEELARCH FRT RH	\$	<i>SL</i> 191.40
1	FENDER BRACKET LOWER RH	\$	<i>SL</i> 11.80
1	FENDER BRACKET FRT RH	\$	<i>M</i> 106.40
1	FENDER INSULATOR RH	\$	<i>SL</i> 66.30
1	TOW COVER FRT	\$	<i>SL</i> 60.90
1	FRONT BRACE PANEL	\$	<i>M</i> 177.22
1	RADIATOR GRILLE	\$	<i>SL</i> 969.90
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>SL</i> 225.36
1	RADIATOR GRILLE FRAME	\$	<i>SL</i> 686.00
1	FRAME FULL SUPPORT PANEL	\$	<i>SL</i> 592.70
1	FRAME FULL SUPPORT BRACKET	\$	<i>M</i> 41.60
1	BONNET	\$	<i>M</i> 1,312.70
1	BONNET INSULATOR	\$	<i>SL</i> 294.30
1	BONNET STRUT RH	\$	<i>SL</i> 53.30
1	BONNET HINGE RH	\$	<i>SL</i> 237.40

Trans-cab Auto Services Pte Ltd**AAD1910-241**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5483X

1	BONNET LOCK	\$	Rs	152.80	}	X
1	BONNET CABLE	\$	Rs	55.20		
1	BONNET CABLE COVER	\$	Rs	80.60		
1	BONNET SEAL OUTER	\$	Rs	83.20		
1	BONNET SEAL INNER	\$	Rs	70.10		
1	LOWER ARM RH L70Y	\$	Rs	192.70		
1	KNUCKLE ARM RH L70Y	\$	Rs	481.50		
1	ABSORBER FRT RH L70Y	\$	Rs	203.50		
1	DRIVESHAFT RH	\$	Rs	1,355.70		
1	STABILIZER BAR FRT	\$	Rs	427.90		
1	WIPER RESERVOIR MOTOR	\$	Rs	82.60		
1	WIPER RESERVOIR	\$	Rs	179.60		
1	WIPER RESERVOIR NECK	\$	Rs	29.30		
1	DOOR PANEL FRT RH	\$	Rs	2,844.66		
1	DOOR MIRROR RH ASSY	\$	Rs	727.90		
TOTAL		\$		16,212.63		
10%		\$		1,621.26		
		\$		14,591.37		

Special Nett

1	BUMPER CLIP FRT	\$	Rs 66.00	}	X
1	BUMPER BRACKET CLIP FRT RH	\$	Rs 12.00		
1	BUMPER SUPPORT CLIP FRT RH	\$	Rs 10.50		
1	BUMPER GRILLE LOWER CLIP	\$	Rs 69.00		
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	Rs 70.00		
2	FRAME FULL SUPPORT PANEL NUT	\$	Rs 20.00		
2	FRAME FULL SUPPORT PANEL STUD	\$	Rs 30.00		
1	WHEELARCH CLIP FRT RH	\$	Rs 30.50		
1	FRONT RIGHT TYRE	\$	Rs 300.00		
1	FRONT RIGHT TYRE RIM	\$	Rs 380.00		
1SET	Front licence plate with holder	\$	Rs 80.00		
1SET	RADIATOR GRILLE SCREW	\$	Rs 16.00		
1SET	RADIATOR GRILLE FRAME CLIP	\$	Rs 52.00		
6	BONNET INSULATOR CLIP L70Y	\$	Rs 7.30		
2	BONNET CABLE COVER SCREW L70Y	\$	Rs 10.85		
2	BONNET CABLE CLIP L70Y	\$	Rs 6.31		

Trans-cab Auto Services Pte Ltd**AAD1910-241**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5483X

1	WINDSCREEN SEALANT	\$	<i>nn</i> 253.80	X
1	FRONT WINDSCREEN MOULDING	\$	<i>nn</i> 120.00	X
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i> 100.00	X
1	FRONT DOOR STICKER 'Trans-Cab'	\$	<i>nn</i> 80.00	X
1	FRONT DOOR STICKER 'Classic'	\$	<i>nn</i> 80.00	X
TOTAL		\$	1,794.27	

TOTAL PARTS	\$	16,385.64
--------------------	-----------	------------------

LABOUR

Putty and spray painting of the affected portion.	\$	6,000.00	<i>4401</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>201</i>
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	6,000.00	<i>4001</i>
To rust-proofing of the affected areas.	\$	170.00	<i>301</i>
To transfer of front tender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	X
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	<i>nn</i> 380.00	X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	X

Trans-cab Auto Services Pte Ltd**AAD1910-241**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5483X

To remove and refit interior fittings, trimings,
garnish, fittings and other, to enable repair. \$ *nn* 380.00 X

Labour charge to mount and dismount vehicle
on jig bench, to facilitate repair. \$ *nn* 380.00 X

Towing Fees \$ *nn* 170.00 X

To Remove And Retit Front W/Screen Glass To
Facilitate Bodywork Repair. \$ *nn* 170.00 X

To transfer of front door fittings, attachment
and perform water seepage test. \$ *nn* 170.00 X

TOTAL \$ 14,890.00

Over All Total \$ 31,275.64

LUMP SUM (REPAIR DAY)**20 DAYS***2 day,*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: