

ESTIMATE TO REPAIR

VEHICLE NO. : SLG 25 A
MAKE : MITSUBISHI
MODEL : EVO 9 MR GSR 2.0 M
YEAR : 2006
CHASSIS NO : CT9A0500890

SURVEYOR NAME :
DATE OF SURVEY : 14/02/20
TIME OF SURVEY :

DATE : 31-Oct-19
DATE OF ACCIDENT : 24-Oct-19
THIRD PARTY REF : SKQ 5373 X
THIRD PARTY REF : AIG ASIA PACIFIC INSURANCE PTE LTD

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	front bumper			\$ 769.00	✓
1 pc	front bumper bean			\$ 90.00	
2 pcs	front bumper retainer		\$ 46.00	\$ 92.00	
1 pc	front bumper clips		\$ 5.00	\$ 50.00	✓
2 pcs	front bumper number plate lamp		\$ 48.00	\$ 96.00	
				819	\$ 1,097.00
	Less 10%			-10%: 737.1	\$ 109.70
					\$ 987.30
1 pc	rear number plate	S.NETT			\$ 40.00
	To putty & spray paint.			200	\$ 300.00
	To paint treating			250	\$ 300.00
	Labour charges.			200	\$ 250.00
TG/VL	TOTAL				\$ 1,877.30

37 Days &
lumpsum repair.
After repair photos.
Guo Qianf - 82880282
14/2/2020.

650

1387.1

-20%: 1100

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Lim Tan Motor Pte Ltd
Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
Tel: 65-64520893 Fax: 65-64589127 Email: edmund@ltm.sg
Co. Reg No. 199307277D GST Reg No. M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without prior written consent of Lim Tan Motor Pte Ltd