

SJE : _____
Date of Survey : _____
Date of ReSurvey: _____ After-Paint: _____
Contacts : _____

Vehicle Nos : **SLW 8071 D**
Model : BMW 523i
Year : _____
Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____ Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	Bootlid	1	\$ 1,488.90	\$1325.00 1,488.90	DDV
2	Bootlid logo	1	\$ 106.00	\$ 54.95 106.00	NEC
3	Bootlid emblem '523i'	1	\$ 84.00	\$ 75.20 84.00	✓
4	Bootlid inner trim	1	\$ 179.70	✓ 179.70	ND
5	Bootlid lock mechanism	1	\$ 345.60	\$211.85 345.60	IMV
6	Bootlid lock striker	1	\$ 84.10	\$ 84.10	ND
7	Bootlid lock switch	1	\$ 298.50	\$ 278.00 298.50	PERV
8	Bootlid hinge	2	\$ 154.80	\$ 309.60	NDX
9	Bootlid outer garnish	1	\$ 289.10	\$ 289.10	NSX
10	Bootlid lamp	2	\$ 392.00 486.00	\$ 784.00 973.80	SUT
11	Bootlid weatherstrip	1	\$ 188.50	✓ 188.50	CUT
12	Bootlid no plate lamp	2	\$ 56.20	\$ 112.40	NDX
13	Rear bumper	1	\$ 1,496.00	\$ 1,135.32 1,496.00	BRV
14	Rear bumper lower	1	\$ 132.60	✓ 132.60	DLV
15	Rear bumper reinforcement	1	\$ 479.90	✓ 479.90	BRV
16	Rear bumper reinforcement bracket	2	\$ 152.00	\$ 232.00 304.00	BT
17	Rear bumper retainer	2	\$ 68.50	✓ 137.00	NEC
18	Rear bumper bracket	2	\$ 69.70	\$ 139.40	RPT
19	Rear bumper reflector	2	\$ 86.10	\$ 172.20 140.00	BRV
20	Rear bumper tow cap	1	\$ 65.30	\$ 65.30 55.75	MISV
21	Rear bumper centre beam	1	\$ 383.00	✓ 383.00	BT
22	Rear bumper lower centre cover	1	\$ 456.00	✓ 456.00	BT
23	Rear bumper reverse sensor wiring harness	1	\$ 480.00	\$ 480.00 200.00	CUT
24	Rear end panel	1	\$ 982.20	\$ 982.20 856.90	DDV
25	Rear end panel top garnish	1	\$ 187.40	✓ 187.40	CRV
26	Spare tyre panel	1	\$ 1,998.70	\$ 1,998.70	
27	Spare tyre panel inner trim	1	\$ 125.50	\$ 125.50	
28	Spare tyre panel insulator	1	\$ 300.00	\$ 300.00	?ND
29	Spare tyre panel inner sponge	1	\$ 70.80	\$ 70.80	
30	Head restraint system	2	\$ 2,500.00 2,500.00	\$ 5,000.00 600.00	Active
31	Head restraint system control unit	1	\$ 2,280.00	\$ 2,280.00	ND
32	Rear twin exhaust muffler complete assy	1	\$ 1,681.30	\$ 1,681.30 1,615.00	DDV
33	Rear exhaust muffler rubber mounting	1	\$ 60.00	✓ 60.00	MISV
34	Rear exhaust tail end pipe	1	\$ 450.00	\$ 450.00 450.00	BT
35	Rear twin exhaust muffler tip	1	\$ 227.20 113.60	✓ 227.20	MISV
36	Tail lamp	2	\$ 598.80	✓ 1,197.60	CRV
Parts Sub Total :				\$ 23,266.30	
5% Discount				\$ 1,163.32	
PARTS TOTAL :				\$ 22,102.99	

@ 5%
11642.27
582.11
11060.16

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$	
1	Bootlid inner trim clips	1	\$ 50.00	\$ 30.00	50.00
2	Bootlid reflector clips	2	\$ 50.00	\$ 30.00	100.00
3	Rear bumper clips	1	\$ 50.00	\$ 30.00	50.00
4	Rear bumper lower clips	1	\$ 50.00	\$ 30.00	50.00
5	Rear end panel top garnish clips	1	\$ 50.00	\$ 30.00	50.00
6	Rear floor compartment sealant	1	\$ 100.00	\$	100.00
7	Rear no plate with garnish	1	\$ 80.00	\$	80.00
8	Reverse sensor	2	\$ 250.00	\$ 200.00	1,000.00
9	Reverse sensor holder	1	\$ 600.00	\$ 40.00	600.00
10	Rear end panel sealant	1	\$ 100.00	\$ 60.00	100.00
11	Bootlid reflector seal	2	\$ 100.00	\$	200.00
12	Tail lamp clips	2	\$ 50.00	\$ 30.00	100.00
13	Tail lamp seal	2	\$ 100.00	\$	200.00
SPECIAL NETT TOTAL :				\$ 480.00	2,680.00

Nos.	LABOUR	S\$	
1	R&R bootlid component	\$ 30.00	100.00
2	R&R reverse sensor	\$ 60.00	80.00
3	R&R exhaust muffler complete assy	\$ 80.00	150.00
4	R&R inner trim and inner garnish to facilitate repairs	\$ 50.00	150.00
5	R&R head restraint system	\$	350.00
6	Reset head restraint system control unit	\$	500.00
7	Spray reverse sensor (4 pcs)	\$ 40.00	80.00
8	Check wiring	\$ 30.00	60.00
9	Panel beat	\$ 800.00	1,600.00
10	Rust proofing	\$ 60.00	100.00
11	Spray painting	\$ 800.00	1,600.00
12	To reset engine control unit system to original specification	\$	180.00
13	To use diagnostic equipment to scan and calibrate rear electrical system	\$	250.00
LABOUR TOTAL :		\$ 2100.00	5,200.00

TGtim
4/11/19
1500
Lump sum repairs

PARTS TOTAL : \$11060.16 22,102.99
SPECIAL NETT TOTAL : \$ 480.00 2,680.00
LABOUR TOTAL : \$ 2100.00 5,200.00
GRAND TOTAL : \$13640.16 29,982.99

@20% 2728.03
10912.13

TGtim 4/5 109900/2 TGtim
Resurvey 20/11/19

5/11/19

1315

lw

Repair days 7

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: