

**CAS GARAGE PTE LTD**

(Reg No: 201828067M)

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY, SINGAPORE 417883

VEHICLE REPAIR ESTIMATE

Insurance Company: AIG ASIA PACIFIC INSURANCE PTE LTD

Address: NO 78, SHENTON WAY, #07-16
S(079120)

Jiale.

Telephone: 64193000

Fax: 68357416

Email: shengyang.lim@aig.com

noormarriesa.abukassim@aig.com

Make/ Model : HYUNDAI ELANTRA

Date: 04.11.2019

Chassis No : KMHD841CMJU736861

Vehicle No: SMD7717U

Date/Time of Accide 25.10.2019/22 25

Year of Reg: 03.09.2018

Materials Cost/ Spare Parts Cost**TO BE COMPLETED BY SERVICE ADVISOR**

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$		FINAL PRICE \$
1	FRONT BUMPER <i>Deformed</i>	1	\$ 598.60		\$ ✓ 598.60
2	FRONT BUMPER SIDE AIR GUIDE <i>new</i>	1	\$ 145.60		\$ + 145.60
3	FRONT BUMPER TOP SEAL(RUBBER) <i>new</i>	1	\$ 98.70		\$ + 98.70
4	FRONT BUMPER LOWER STIFFENER <i>new</i>	1	\$ 186.50		\$ + 186.50
5	FRONT BUMPER SIDE RETAINERS <i>LH new</i>	2	\$ 86.30		\$ 86.30 172.60
6	FRONT BUMPER REINFORCEMENT <i>new</i>	1	\$ 385.50		\$ + 385.50
7	FRONT BUMPER SPONGE <i>new</i>	1	\$ 189.70		\$ + 189.70
8	FRONT FOG LAMP COVER LH <i>cut</i>	1	\$ 156.30		\$ ✓ 156.30
9	FRONT FOG LAMP LH <i>cut</i>	1	\$ 286.30		\$ ✓ 286.30
10	FRONT BONNET <i>new</i>	1	\$ 1,740.50		\$ + 1,740.50
11	FRONT ENGINE UNDERCOVER <i>new</i>	1	\$ 286.50		\$ + 286.50
12	FRONT HEADLAMP LH <i>cut</i>	1	\$ 1,248.60		\$ ✓ 1,248.60
13	FRONT HEADLAMP BRACKET LH <i>new</i>	1	\$ 89.70		\$ + 89.70
14	FRONT SUPPORT PANEL <i>new</i>	1	\$ 1,045.20		\$ + 1,045.20
15	FRONT SUPPORT PANEL TOP GARNISH <i>new</i>	1	\$ 224.60		\$ + 224.60
16	FRONT FENDER LH <i>Deformed</i>	1	\$ 496.50		\$ ✓ 496.50
17	FRONT FENDER INNER COWLING LH <i>new</i>	1	\$ 156.30		\$ ✓ 156.30
18	FRONT SIDE MIRROR ASSY LH <i>cut</i>	1	\$ 1,054.60		\$ ✓ 1,054.60
19	FRONT DOOR LH <i>new</i>	1	\$ 1,785.60		\$ + 1,785.60
20	FRONT DOOR HINGE UPPER LH	1	\$ 65.30		\$ + 65.30
21	FRONT DOOR HINGE LOWER LH	1	\$ 65.30		\$ + 65.30
22	FRONT DOOR OUTER HANDLE LH	1	\$ 185.30		\$ + 185.30
23	FRONT DOOR OUTER HANDLE COVER LH	1	\$ 56.80		\$ + 56.80
24	FRONT DOOR CHECKER LH	1	\$ 67.20		\$ + 67.20
25	FRONT DOOR OUTER MOLDING LH	1	\$ 125.60		\$ + 125.60
26	FRONT DOOR WEATHERSTRIP LH(DOOR)	1	\$ 167.80		\$ + 167.80
27	FRONT DOOR WEATHERSTRIP LH(FRAME)	1	\$ 167.30		\$ + 167.30
28	FRONT DOOR RUNCHANNEL LH	1	\$ 152.30		\$ + 152.30
29	FRONT DOOR STICKER LH	2	\$ 65.80		\$ + 131.60
30	SIDE ROCKER PANEL LH	1	\$ 785.60		\$ + 785.60
31	REAR DOOR LH	1	\$ 1,782.30		\$ + 1,782.30

32	FRONT RIM LH <i>Cut</i>	1	\$ 856.20	\$ <i>✓</i> 856.20
33	FRONT LOWER ARM LH <i>Best</i>	1	\$ 395.80	\$ <i>✓</i> 395.80
34	FRONT WHEEL HUB BEARING LH <i>Best</i>	1	\$ 402.50	\$ <i>✓</i> 402.50
35	FRONT ABSORBER LH <i>New</i>	1	\$ 397.60	\$ <i>+</i> 397.60
36	FRONT ABSORBER MOUNTING LH <i>New</i>	1	\$ 85.30	\$ <i>+</i> 85.30
37	FRONT KNUCKE ARM LH <i>Best</i>	1	\$ 425.60	\$ <i>✓</i> 425.60
38	FRONT STABILIZER LINK <i>3 new</i>	1	\$ 108.50	\$ <i>+</i> 108.50
39	FRONT STABILIZER BAR	1	\$ 345.20	\$ <i>+</i> 345.20
Total List Price Cost				\$ 17,117.00

6163.60

PARTS DISCOUNT 20%

\$ 13,693.60

4930.88

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
1	FRONT BUMPER CLIPS <i>New</i>	1 SET	\$ 30.00	\$ <i>✓</i> 30.00
2	FRONT BUMPER LOWER LIP (ACCESSORIES)	1	\$ 700.00	\$ <i>600</i> 700.00
3	FRONT ENGINE UNDERCOVER CLIPS <i>New</i>	1 SET	\$ 30.00	\$ <i>+</i> 30.00
4	FRONT FENDER INNER COWLING CLIPS <i>New</i>	1 SET	\$ 30.00	\$ <i>✓</i> 30.00
Total Special Nett Items				\$ 790.00

660

Labour Works/ Panel Beating Related Works

Job Scope	Quotation
TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGNE ALL PARTS	\$ 1,800.00

Spray Painting

Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 1,800.00

Others Cost (Accident Repair Related Expenses)

Job Scope	Quotation
TO TUFFCOAT AFFECTED AREA	\$ <i>x</i> 200.00
TO REMOVE/ REFIT WIRING CHECKS ON FRONT HEADLAMPS	\$ <i>30</i> 150.00
TO PERFORM COMPUTERISED WHEEL ALIGNMENT, BEFORE AND AFTER	\$ <i>80</i> 160.00
LABOUR TO REMOVE FRONT UNDERCARRIAGE	\$ <i>220</i> 300.00
TO REMOVE /REFIT AND REPLACE FRONT DOOR MECHANISM	\$ <i>x</i> 120.00
Total Others Cost	\$ 930.00

1330

CAS GARAGE PTE LTD

GRAND TOTAL

\$ 19,013.60

UEN 201828067M

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY,
SINGAPORE 417883

CAS GARAGE PTE LTD

Person Incharge: Allan

Direct Contact: +65 8782 7171/ FAX: +65 65099501

Email: allangoh.cas@gmail.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
4/5 05/11/19

05 Days

total: 6920.88

w/s: 5.5K ✓