

**CAS GARAGE PTE LTD**

(Reg No: 201828067M)

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY, SINGAPORE 417883

VEHICLE REPAIR ESTIMATE

Insurance Company: AIG ASIA PACIFIC INSURANCE PTE LTD

Address: NO 78, SHENTON WAY, #07-16
S(079120)

Asher

Telephone: 64193000

Fax: 68357416

Email assignments@lkkauto.com

Make/ Model : HONDA CIVIC 1.6 VTI CVT

Date: 11.04.2019

Chassis No : MRHFC5650JT000051

Vehicle No: SLX3063E

Date/Time of Accide 25.10.2019/20 20

Year of Reg: 23.03.2018

Materials Cost/ Spare Parts Cost**TO BE COMPLETED BY SERVICE ADVISOR**

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$		FINAL PRICE \$
1	BOOTLID <i>Dented</i>	1	\$ 785.60		\$ 785.60 <i>572.10</i>
2	BOOTLID STOPPER <i>new</i>	2	\$ 20.00		\$ + 40.00
3	BOOTLID OUTER GARNISH <i>new</i>	1	\$ 298.60		\$ + 298.60
4	BOOTLID SMART KEY ANTENNA <i>Exchd.</i>	1	\$ 152.30		\$ + 152.30
5	BOOTLID BUZZER <i>Exchd.</i>	1	\$ 105.60		\$ + 105.60
6	BOOTLID INNER TRIM <i>new</i>	1	\$ 215.60		\$ + 215.60
7	BOOTLID EMBLEM "CIVIC" <i>new</i>	1	\$ 78.50		\$ + 78.50
8	BOOTLID EMBLEM "I V-TEC" <i>new</i>	1	\$ 73.60		\$ + 73.60
9	BOOTLID LOGO <i>new</i>	1	\$ 89.70		\$ + 89.70
10	BOOTLID LAMP <i>new</i>	2	\$ 205.60		\$ + 411.20
11	BOOTLID LAMP INNER SEALER <i>new</i>	2	\$ 38.00		\$ + 76.00
12	BOOTLID INNER LOCK <i>new</i>	1	\$ 169.50		\$ + 169.50
13	BOOTLID LOWER CATCH <i>new</i>	1	\$ 46.20		\$ + 46.20
14	BOOTLID HINGES <i>new</i>	2	\$ 75.20		\$ + 150.40
15	BOOTLID WEATHERSTRIP <i>new cut</i>	1	\$ 159.20		\$ + 159.20
16	REAR BUMPER <i>Dented</i>	1	\$ 758.90	<i>688.20</i>	\$ 758.90 <i>688.20</i>
17	REAR BUMPER RETAINERS <i>new</i>	2	\$ 52.30		\$ + 104.60
18	REAR BUMPER CENTRE BRACKETS <i>new</i>	2	\$ 45.60		\$ + 91.20
19	REAR BUMPER LOWER SIDE GARNISH RH <i>new</i>	1	\$ 69.70		\$ + 69.70
20	REAR BUMPER REINFORCEMENT <i>Dented</i>	1	\$ 305.80		\$ + 305.80
21	REAR BUMPER SIDE REFLECTORS <i>new</i>	2	\$ 59.80		\$ + 119.60
22	REAR BUMPER SIDE REFLECTORS COVER <i>new</i>	2	\$ 98.70		\$ + 197.40
23	REAR BUMPER REVERSE SENSOR <i>new 2pin</i>	4	\$ 145.00		\$ 580.00 <i>250</i>
24	REAR BUMPER REVERSE SENSOR HOLDER <i>new</i>	4	\$ 36.00		\$ + 144.00
25	REAR REVERSE SENSOR HARDNESS <i>new</i>	1	\$ 252.30		\$ + 252.30
26	TAILAMPS <i>LH Exchd.</i>	2	\$ 392.60	<i>546</i>	\$ 785.20 <i>382.60</i>
27	TAILAMPS INNER SEALER <i>2 pin new</i>	2	\$ 38.20		\$ 76.40 <i>38.20</i>
28	TAILAMPS PANEL <i>new</i>	2	\$ 345.80		\$ + 691.60
29	REAR FENDER INNER COWLING <i>new</i>	2	\$ 156.20		\$ + 312.40
30	REAR END PANEL <i>Dented</i>	1	\$ 568.20	<i>385</i>	\$ 568.20 <i>385</i>
31	REAR END PANEL TOP GARNISH <i>Dented</i>	1	\$ 125.60		\$ + 125.60

