

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 743M**AAD1910-239***Not Authoised
L1 Sup & 8300h*

Vehicle No.:

Chassis No.:

01 NOV 2019

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHF 743M

VF1ABL15AUC282731

RENAULT

LATITUDE

30.10.19

III

30/6/2016

		PART	LIST
1	1	BUMPER COVER REAR	\$ <i>By</i> 561.70 ✓
2	1	BUMPER LOWER REAR	\$ <i>nd/dp</i> 411.90 ✓
3	1	BUMPER BRACKET CTR REAR	\$ <i>SL</i> 98.10 X
4	1	BUMPER BRACKET SIDE RH REAR	\$ <i>dit</i> 82.10 ✓
5	1	BUMPER RETAINER RH REAR	\$ <i>CM</i> 59.80 ✓
6	1	BUMPER REFLECTOR RH	\$ <i>CM</i> 16.60 ✓
7	1	BUMPER BRACKET SIDE LH REAR	\$ <i>RL</i> 80.80 X
8	1	BUMPER RETAINER LH REAR	\$ <i>SL</i> 54.20 X
9	1	BUMPER REFLECTOR LH	\$ <i>SL</i> 16.60 X
10	1	BUMPER BEAM REAR	\$ <i>By</i> 547.80 ✓
11	1	BUMPER BEAM BRACKET LH REAR	\$ <i>RL</i> 114.50 X
12	1	BUMPER BEAM BRACKET RH REAR	\$ <i>RL</i> 100.90 X
13	1	BUMPER BLOCK RH REAR	\$ <i>SL</i> 76.50 X
14	1	BOOT REAR	\$ <i>By</i> 1,677.20 ✓
15	1	BOOT FINISHER	\$ <i>SL</i> 344.70 X
16	1	BOOT WHEATERSTRIP	\$ <i>dit/nd</i> 178.20 <i>502SL 89.10SL</i>
17	1	BOOT REFLECTOR LAMP LH	\$ <i>SL</i> 277.70 X
18	1	BOOT REFLECTOR LAMP RH	\$ <i>nd</i> 277.70 ✓
19	1	BOOT BADGE 'RENAULT'	\$ <i>RL</i> 82.40 ✓
20	1	BOOT BADGE	\$ <i>RL</i> 95.80 ✓
21	1	BOOT STRUT LH	\$ <i>SL</i> 145.10
22	1	BOOT STRUT RH	\$ <i>SL</i> 145.10
23	1	BOOT HINGE LH	\$ <i>RL</i> 254.20
24	1	BOOT HINGE RH	\$ <i>RL</i> 253.80
25	1	BOOT INNER TRIM BOARD	\$ <i>SL</i> 611.00
26	1	BOOT SWITCH	\$ <i>SL</i> 113.00

Trans-cab Auto Services Pte Ltd**AAD1910-239**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 743M

27	1	BOOT LOCK	\$	N	246.60	
28	1	BOOT LOCK CATCH	\$	N	41.70	
29	2	LICENCE PLATE LAMP	\$	SL	26.30	
30	2	BOOT RUBBER PLUG	\$	SL	139.30	
31	2	BOOT BUFFER	\$	SL	26.80	
32	1	BOOT LOCK LINKAGE HOLDER	\$	SL	99.50	
33	1	BOOT LOCK LINKAGE	\$	SL	20.60	
34	1	CHASSIS PANEL REAR RH	\$	N	2,192.40	
35	1	FENDER WHEEL HOUSE PANEL REAR RH	\$	N	1,933.20	
36	1	FENDER INNER BOARD RH	\$	N	561.40	
37	1	FENDER PANEL INNER REAR RH	\$	N	952.50	
38	1	FENDER PANEL INNER TRIM REAR RH	\$	reborn	671.45	✓
39	1	FENDER PANEL REAR RH	\$	Bu	1,933.20	✓
40	1	WHEELARCH REAR RH	\$	SL	275.40	X
41	1	SPARE TYRE BOARD	\$	SL	680.90	X
42	1	TAILLAMP RH	\$	CM	313.10	✓
43	1	TAILLAMP PANEL RH	\$	R	401.40	✓
44	1	TAILLAMP LH	\$	SL	401.40	X
45	1	TAILLAMP PANEL LH	\$	N	401.40	X
46	1	AIR VENT RH	\$	SL	59.40	X
47	1	OUTER PANEL REAR (End Panel)	\$	R	745.80	✓
48	1	OUTER PANEL REAR (End Panel) TRIM	\$	SL	404.56	
49	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	N	1,229.40	
50	1	SPARE WHEEL PANEL TRIM	\$	SL	612.21	
51	1	EXHAUST REAR	\$	N	5,263.60	
52	1	EXHAUST CAP REAR	\$	N	125.40	
53	1	EXHAUST PIPE CLAMP	\$	SL	68.80	
54	1	EXHAUST HEAT SHIELD REAR	\$	SL	134.60	
55	1	EXHAUST HEAT SHIELD TUNNEL	\$	SL	131.00	
56	1	BUMPER HARNESS REAR	\$	SL	301.10	
57	1	KNUCKLE ARM REAR RH	\$	SL	472.10	
58	1	BRAKE DISC REAR	\$	SM	266.50	
59	1	ABS SENSOR REAR RH	\$	SL	190.50	
60	1	WHEEL HUB NUT	\$	SL	41.80	
61	1	WHEEL HUB CAP	\$	SL	30.50	
62	1	KNUCKLE HUB+ BEARING RH	\$	SL	272.30	

Trans-cab Auto Services Pte Ltd**AAD1910-239**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 743M

63	1	REAR AXLE	\$	3,469.00	}
64	1	AXLE ARM RH	\$	69.50	
65	2	REAR AXLE SPACER	\$	49.00	
66	1	REAR AXLE ARM ROD	\$	69.50	
67	1	LOWER ARM REAR RH	\$	543.50	
68	1	AXLE SPRING ARM RH	\$	220.60	
69	1	AXLE SPRING ARM BUSH UPPER	\$	42.50	
70	1	AXLE SPRING ARM BUSH LOWER	\$	30.80	
71	1	ABSORBER REAR	\$	217.30	
72	1	ABSORBER DUST COVER REAR	\$	47.10	
73	1	ABSORBER MOUNTING REAR	\$	49.40	
74	1	STABILIZER BAR REAR	\$	427.90	
75	1	STABILIZER LINK REAR	\$	55.20	
76	1	BRAKE CALIPER REAR RH	\$	659.10	
77	1	BRAKE PAD REAR	\$	145.60	
78	1	BRAKE CALIPER BRACKET REAR RH	\$	384.00	
79	1	BRAKE HOSE REAR RH	\$	79.50	
80	1	SUBFRAME ARM REAR	\$	198.33	
81	1	RODE- LONG REAR	\$	120.16	
82	1	DOOR PANEL REAR RH	\$	758.70	
TOTAL			\$	35,982.21	
10%			\$	3,598.22	
			\$	32,383.99	

Special Nett

1	1SET	PARKING AID	\$	700.00	Shay 400.00
2	1SET	REAR BUMPER CLIP	\$	66.00	na —
3	1SET	BUMPER BRACKET CTR CLIP	\$	33.00	na —
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	10.00	na X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	20.00	na X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	10.00	na X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	20.00	na X
8	1SET	BUMPER LOWER REAR RIVET	\$	22.00	na X
9	1SET	BUMPER LOWER REAR CLIP	\$	66.00	na ✓
10	1	EXHAUST MOUNTING REAR	\$	16.00	na X
11	1	EXHAUST BRACKET REAR	\$	24.80	na X

Trans-cab Auto Services Pte Ltd**AAD1910-239**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 743M

12	1SET	BOOT FINISHER CLIP	\$	na	24.20	X
13	1	BOOT STICKER "Trans-cab"	\$	na	30.00	—
14	1	BOOT STICKER "6555-3333"	\$	na	30.00	—
15	1	BOOT INNER TRIM CLIP	\$	na	45.00	X
16	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	Sh	385.00	X
17	1	SPARE TYRE	\$	Sh	330.00	X
18	1	TAILLAMP CLIP RH	\$	na	5.00	✓
19	2	REAR WINDSCREEN SEALANT	\$	na	80.00	4000
20	1	WINDSCREEN MOULDING	\$	na	100.00	X
21	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	3000
22	1	TAILLAMP CLIP LH	\$	na	5.00	X
23	1	Rear Bumper Protector	\$	na	100.00	X
24	2	AXLE BOLT	\$	na	26.20	X
25	2	AXLE NUT	\$	na	60.80	
26	2	AXLE SPRING ARM BOLT	\$	na	30.80	
27	2	AXLE SPRING ARM BOLT	\$	na	25.80	
28	4	AXLE SPRING ARM NUT	\$	na	9.70	
29	4	LOWER ARM BOLT	\$	na	25.80	
30	4	LOWER ARM NUT	\$	na	9.70	
31	1	LOWER ARM BALANCER REAR RH	\$	na	20.50	
32	2	ABSORBER BOLT REAR	\$	na	29.90	
33	1	BRAKE CALIPER BRACKET BOLT REAR RH	\$	na	29.60	
34	1SET	Rear licence plate with holder	\$	Sh	80.00	X
35	1	REAR RIGHT TYRE	\$	Sh	300.00	
36	1	REAR RIGHT TYRE RIM	\$	Sh	380.00	
37	1SET	FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	
38	1	FENDER INNER TRIM CLIP RH	\$	na	28.00	
39	1	REAR DOOR STICKER "6555-3333"	\$	na	80.00	

TOTAL \$ 3,393.80**TOTAL PARTS \$ 35,777.79****LABOUR**Putty And Spray Painting Of The Affected Portion. \$ 9,000.00 *Shel*

Trans-cab Auto Services Pte Ltd**AAD1910-239**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 743M

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	9,000.00	12001
To supply and re-do rear luggage floor panel insulation padding.	\$	nn 380.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	601
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	} 1001
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To Rust-Proofing Of The Affected Areas.	\$	170.00	901
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To transfer of rear tender fittings, attachment and perform water seepage test.	\$	nn 170.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	170.00	1201
To repair and realign rear exhaust pipe.	\$	nn 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	601

Trans-cab Auto Services Pte Ltd

AAD1910-239

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 743M

To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	na	380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na	380.00	X
To Check Electrical Lighting Concerned.	\$		170.00	201
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	na	380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	na	380.00	X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	na	380.00	X
To dismantle and refit rear undercarriage parts, final checking and testing.	\$	na	380.00	X
To dismantle and refit rear axle assy, remove and renewal of parts, final checking and testing.	\$	na	380.00	X
To transfer of door fittings, attachment and perform water seepage test.	\$	na	170.00	X
To check ABS and brake efficiency, final checking and testing.	\$	na	380.00	X
TOTAL	\$		23,680.00	
Over All Total	\$		59,457.79	

(LUMP SUM) Repair Days**30 DAYS**

7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: