

REG. NUMBER:

SLC 323K

MAKE/MODEL:

Nissan Qashqai 2.0

CHASSIS MEMBER:

SJNJBNS104702438C

14 days
nett 10%

QUANTITY	SPARE PARTS		
1 PC		Front Bumper	cm
1 PC ⁰²⁸⁷	n/s	" " side retainers	cm
10 PC		" " clips	cm
1 PC 0391		" " & Lower Rubber Lid	
0343 PC 0687	n/s	" " Fog Cover (chrome)	
1 PC 0637	"	" " Fog Lamp	cm
PC 99	"	" " Bracket	
1 PC 0409		Front Grille	
6 PC		" " clips	
PC			
2 PC		Headlamp Assy (LH/RH)	mm
2 PC 0515/0516		" " Lower Bracket (LH/RH)	
PC			
1 PC	n/s	Front Sender	Bz
1 PC 0883	"	" " wheel arch garnish	
1 PC	"	" " inner bracket	
1 PC 0844	"	" " inner shield	
8 PC	"	" " clips	
1 PC 99	"	" " Lamp	
1 PC	"	" " mud flap	Bz
1 PC 99	"	" " inner vertical sponge	
1 PC 0891	"	" " Lower Garnish	
PC 1421		Front Front windscreen Glass moulding	
PC		" " sealant	
PC	n/s	Door Front 'A' Pillar	R
PC	n/s	Front Door	Bz
PC	"	" " weatherstrip	R
2 PC	"	" " Hinges (Top/Lower)	

LIST

777.10N ✓
 35.20N ✓
 2.60N X 10 ✓
 80.30N Bu/m ✓
 70 130.10N 2112
 327.30N ✓
 53.80N ✓
 422.10N ✓
 21 5.50N X 6 ?
 672.20N X 2 ✓
 41.70N X 2 ?
 753.50N ✓
 654N m.i. ✓
 156.10N cm ✓
 2.60N X 8 m. ✓
 60.10N ?
 123.20SN ✓
 22.10N ?
 39.20N ?
 155.50N ?
 40.5N SN ?
 1566.50N X
 1282.80N ✓
 181.60N X
 69.10N X 2 ?

K. KIM HIN AUTO PTE LTD

FAX: 64583895

COST

\$27,187.50

NUMBER:

SLC 323K

/MODEL:

MASSIS MEMBER:

QUANTITY	SPARE PARTS	
1 PC 1505	1/5 Front Door checker	R _L
1 PC 1681	" " " Protector	R _L
1 PC	Air Resonator	
1 PC	1/5 Front Door Lower Garnish	
1 PC		
1 PC 99	Air Resonator	CMA
1 PC		
1 PC	1/5 Front tyre	P _n
1 PC	" " Sport Rim P?	R _L
1 PC	" " Knuckle Arm	R _L
1 PC 7131	" " " " Bearing	R _L
1 PC	" " Bearing Hub	R _L
1 PC	" " Drive Shaft	R _L
1 PC 7055	" " Lower Arm	R _L
1 PC	" " Rotor Disc	
1 PC 7133	" " " " Back Plate	
1 PC 7165	" " Brake Hose	
1 PC 7185	" " " " Pipe	
1 PC	" " Brake Sensor	
1 PC	" " tie rod	
1 PC 7311	" " tie rod end.	R _L
1 PC	" " stabilizer Bar Linkage	
1 PC	" " shock absorber	R _L
1 PC 7103	" " " " stopper (LWR)	
1 PC 7095	" " " " mounting	
1 PC 7097	" " " " Bearing	
1 PC 7115	" " " " coil spring	
1 PC 7099	" " " " " Lower	
1 PC 7101	" " " " stopper (UPP)	

LIST

50.90N X

382.10N

134.40 SN

280 SN John 224 SN

850 SN

557 SN

336.50 SN

1159.80 SN

232.80 N

205.20 SN

196.90 SN

64.80 SN

55 SN

383.10 SN

140.20 SN

44.30 N

431 SN

51 SN

103.10 N

133.30 SN

248.10 SN

33 SN

51 SN

NUMBER: _____

SLC 323K

E/MODEL: _____

CHASSIS MEMBER: _____

QUANTITY	SPARE PARTS	
1 PC	Front steering cross member	
2 PC	Front stabilizer Bar Bush	
1 PC	" " Bar	
1 PC	" Steering rack & pinion B/L	
1 PC roll	Engine sub Frame	
4 PC	" " " screw	1
1 PC	Tyre Pressure sensor	
1 PC 8915	Engine Mounting - LH	
1 PC	" " - RH	
1 PC 8644	" " - Rear	K42
1 PC		K42
1 PC		K11
1 PC		K16
1 PC		K20
1 PC		K01
1 PC		K24
1 PC		K26
1 PC		K41
1 PC		K04
1 PC	To remove and refit front windscreen	
1 PC	and conduct water leak test	
1 PC		
1 PC		
1 PC		
1 PC		
1 PC		
1 PC		
1 PC		
1 PC		
1 PC		

LIST

17.80N x 2?

353.60SN 7

1617.90SN 7

817.80SN 7

17.40SN 7

250SN 7

151.10SN 7

243.70SN 7

95.10SN 7

120

1600

120

150

300

300

80

300

80

1400

120

50

4620

22762.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Any item(s) must be resurveyed and approved by the Insurance Company

Approved by the Repairer
Signature

K. KIM HIN AUTO PTE LTD

FAX: 64583895