

ASS. REC. BY:

REF:

C9/SPF19019470/Kgf302

Special Instruction:

Surveyor: KenneenASSIGNMENT (Office)

From (Person):

Hafiml Kanan

of

SPF

Date/Time:

04/11/19

Estimated Cost:

Bill to:

OD-TPY/WS/TPRES/ODRES/EVA/INV/MV/CS

To Inspect Vehicle No:

SMC 6826A

Insured:

84 4807R

at Workshop m/s

Tomp Luck Auto

Tel:

6750088 Candy

of

160 S/m Drive 407-01/06 S/m Auto City

Policy No:

Claim No:

AEMD/105/009/2019/109

Sum Insured:

Excess:

Make of Veh:

D.O.A.

21/10/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

1wp1

H.O.D. Endorsement:

Date/Time:

04/11/19 @ 4.38pm

Person Contacted:

Vehicle IN / OUT

Date/Time

Action/Instruction

Estimate ()SMC 6826A X84 4807R XB5083.20 (Red & 7706, 60%)Range car: B5083.20 - B10000; weekend: 2 days**Do Not Finalise**

ASS. REC. BY:

REF:

SPF

Kenneth

ASSIGNMENT

From:

Date:

05/11/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

Sinc 6826A

at Workshop m/s

Tony Luck Auto

of

160 S/M drive #07-01/06 S/M

Insured:

Mutualty.

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

wpl

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res.: Yes or No

Lum Sum:

1-B1

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

Sinc 6826A

Yr Regn:

07 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(A)

Make:

Mer

E250

C.C

1991

Colour

M. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

20144

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WDD 2130 452 A 465953

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/45R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU (PIR) SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

22/10/19

D.O.I.

5/11/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S New body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 22 NOV 2019

Do Not Finalise

Date/Time, File Pass to?

1) 22/11/19

Date/Time, File Return to?

2)

Rep. Format:

Lump Sum / L.B. / C

☐

: Preli. Report

☐

: Final Report

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

220

Transportation:

S + RS. SI

Photos

Others

TOTAL

220

Summer Lee (LKK Auto)

From: Hafizul Farhan RAHMAT (SPF) <Hafizul_Farhan_RAHMAT@spf.gov.sg>
Sent: Monday, 4 November, 2019 4:30 PM
To: assignments; SUR; Admin-D (LKKAuto)
Cc: Cui Fen ENG (SPF); Frankie THAY (SPF)
Subject: PRE-REPAIR SURVEY OF SMC6826A (vs GY4007R ON 22/10/2019 ALONG OPEN CP BETWEEN BLK 461 AND 462 TAMPINES ST 44)

Our ref: AEMD/105/009/2019/109

Hi,

Kindly conduct pre-repair survey of SMC6826A at:

Tong Luck Auto Pte Ltd
160 Sin Ming Drive
#07-01/06 Sin Ming Autocity
Singapore 575722

Contact: Candy, Tel: 6250 0088

Best Regards,

Hafizul Farhan Bin Rahmat
Assistant Logistics Support Officer
Logistics Support and Services Division
Police Logistics Department | Singapore Police Force
DID: (65) 6478 4840 | FAX: (65) 6478 4848



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/10/2019 17:19
Date Of Accident	22/10/2019 13:40
Exact Location Of Accident	OPEN CP BETWEEN BLK 461 AND 462 TAMPINES ST 44
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMC6826A
Insured/Policyholder	
Name Of Registered Owner	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.
Co Reg No	199803778Z
Email Address	BENNY.CHONG@DAIMLER.COM
Mobile Phone No	
Alternative Phone No	OFFICE-82821711

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E250 AVG (R18 LED)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995580
Cover Note Number	

Driver

Name of Driver	WEE BOON KIAT SHADRACH
NRIC No	S7239268Z
Date Of Birth	26/10/1972
Occupation	INDOOR
Date Of Driving Pass	28/06/1997
Driving Experience	22 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97823197
Fax Number	
Contact Number	
Email Address	EDMUND@LNHENTERPRISE.COM

Address	NA
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : DAWN WEE
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	TAMPINES NORTH NPP
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Refer to police report no: t/20191022/2117 On the above mentioned date, time and said location, I was driving my Mercedes vehicle car, SMC6826A black in colour inside the open carpark in between Blk461 and 462 Tampines St 44 with my daughter seated behind on the left side. While I was inside the carpark, there is one police vehicle car GY4007R stationary along the carpark (lean more to the right side of the road). and not inside any of the lot. I am not too sure whether his hazard light was on or not, however my initial thought is he was going to park his car and hence I proceed to wait. After waiting for about 10 seconds, the police car still remain stationary and hence I proceed to wait. After waiting for about 10 seconds, the police car still remain stationary and hence I proceed to move forward to pass the police car. When already more than half of my vehicle went pass the police car, suddenly I felt an impact on my right rear portion. I then notice the police car front left portion collided onto my right rear portion near to the rear tyre. I then proceed out of my vehicle and wish to state that no one was injured. Due to the accident my vehicle damages is the right rear portion dented with scratches. After about 20 mins, Traffic Police and inform me to lodge a traffic accident report and hand over a case card G/20191022/0102 to me. I wish to state that I have in car camera installed at the front and back and it is in working condition. Traffic Police had also took my in car camera SD card.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	NA
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GY4007R
Vehicle Make/Model/Colour	ISUZU / TFS54HDR (POLICE CAR)
Details Of Properties	

GOVERNMENT

NRIC/Passport Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

SMC6826A

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time **23/10/19, 10:41**
AM

VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER
MOHAMMAD AZALY BIN ABDULLAH


Reporting Centre Personnel's Signature
Name
NRIC/FIN No.

Sketch Plan #2

SKETCH PLAN

SHELTER.

OPEN CARPARK
BTWN BLK 461 & 462
TAMPINES ST 44.



SHELTER

A - SMC 6826A

B - GY4007R
(REVERSING)

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO ATTACHED STATEMENT.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 23/10/19

VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER
MOHAMMAD AZALY BIN ABDULLAH


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #3



TRAFFIC INVESTIGATION BRANCH
TRAFFIC POLICE
101 ROYAL AVENUE 2
SINGAPORE 408602
Fax: 67474749

CASE CARD



T/20191022/2117

REPORT NO: TG/20191022/0102

Traffic Accident Date: 22/10/2019 15:42

Involved Vehicles: GY4007R SMC6826A

at 22/10/19 at about 15:42 on road

With reference to the above, you are advised to lodge an accident report within 24 hours via the SPV Electronic Police Station website (<http://www.police.gov.sg/epst>) within 24 hours.

1 of 3
Report No: T/20191022/2117

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 22/10/2019 15:42	Vide Report No.:	Station Diary No.: 28
--	------------------	--------------------------

Informant's Particulars

Name of Informant: WEE BOON KIAT SHADRACH		Address: APT BLK 462 TAMPINES STREET 44 #09-64 SINGAPORE 520462	
ID Type / ID No.: NRIC NO / S7239268Z		Contact No.: Home/Office: Mobile: 97823197	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 46	Date of Birth: 25/10/1972	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: DIRECTOR		Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident

Type of Accident:	Non-Injury Government Vehicle	Drink Drive: No	Date/Time of Accident: 22/10/2019 13:40	Type of Location: Car Park
Location: Along Road 1 TAMPINES STREET 44				
Open Carpark in between Blk 461 and Blk 462 Tampines St 44				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GY4007R	Car				Slightly Damaged	1
SMC6826A	Car				Slightly Damaged	1



SINGAPORE
POLICE FORCE



T/20191022/2117

2 of 3

Report No. T/20191022/2117

Police Station Of Origin:
Tampines North NPP
461 Tampines Street 44 #01-56 SINGAPORE
520461
Tel No: 1800-7818999

CONTINUATION OF REPORT

Brief Details.

On the above mentioned date, time and said location, I was driving my Mercedes vehicle car, SMC6826A, black in colour inside the open carpark in between Blk 461 and 462 Tampines St 44 with my daughter seated behind on the left side. While I was inside the carpark, there is one police vehicle car GY4007R stationary along the carpark (lean more to the right side of the road) and not inside any of the lot. I am not too sure whether his hazard light was on or not, however my initial thought is he was going to park his car and hence I proceed to wait. After waiting for about 10 seconds, the police car still remain stationary and hence I proceed to move forward to pass the police car. When already more than half of my vehicle went pass the police car, suddenly I felt an impact on my right rear portion. I then notice the police car front left portion collided onto my right rear portion near to the rear tyre. I then proceed out of my vehicle and wish to state no one was injured. Due to the accident my vehicle damages is the right rear portion dented with scratches. After about 20min, Traffic police and inform me to lodge a traffic accident report and handover a case card G/20191022/0102 to me. I wish to state I have in car camera installed at the front and back and it is in working condition. Traffic police had also took my in car camera SD card.

Sketch Plan #5



**SINGAPORE
POLICE FORCE**



T/20191022/2117

3 of 3

Report No. T/20191022/2117

Police Station Of Origin:
Tampines North NPP
461 Tampines Street 44 #01-56 SINGAPORE
520461
Tel No. 1800-7818999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
G /
Staff Sgt TAN YI KUN

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
22/10/2019 15:42

Officer in Charge Of Case:
TP / GIA /
Staff Sgt WONG SIEU LUI
Contact No.: 65476151

Classification Of Case:

Authentication Stamp
NP168

SIGNATURE



SINGAPORE POLICE FORCE ACKNOWLEDGEMENT SLIP

Ref. Report No: 716/2019/022/0129 0102

I, Sgt T03415 Sofian
(Recipient's Name, NRIC or Passport No. / Rank and No.)

of TP
(Address / Police Station / NPC / NPP)

hereby acknowledge receipt of the below mentioned items of:

1 1X 1660 mm SA Thetware deal cam

- 2 _____
- 3 _____
- 4 _____
- 5 _____
- 6 _____
- 7 _____
- 8 _____
- 9 _____
- 10 _____

from S72392682, WEE BOON KIAT SHADRACH
(Name, NRIC or Passport No. / Rank and No.)

of BIR 462 Tampines St 84 # 09-64
(Address / Police Station / NPC / NPP)

on 22/10/19 at 1430 hrs
(Date) (Time)

Witnessed by / * Handed over by:
(* Delete if applicable)

Received by:

WEE BOON KIAT S72392682
(Signature)
(Name, NRIC or Passport No. / Rank and No.)

Sgt T03415 Sofian
(Signature)
(Name, NRIC or Passport No. / Rank and No.)

Other Remarks: SMC 6836A more / Dist.



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : GY4007R

CLAIM TYPE : THIRD PARTY

TP INS. CO. : SINGAPORE POLICE FORCE

ACCIDENT DATE : 22/10/2019

TP VEH REG NO : GY4007R

ESTIMATE

NO : QUOT201911-000005(00)

DATE : 04/11/2019

POLICY NO : 999995580

VEH REG NO : SMC6826A

MAKE/MODEL : MERCEDES BENZ E250 AVG
(R18 LED)

CHASSIS NO : WDD2130452A465953

ENGINE NO : 27492031499679

REG. DATE : 2018

Not Notarise
Re survey B4 paint
5 day

Estimate Repair Cost to Vehicle No : SMC6826A

Description	Quantity	Unit Price	Amount
		<u>S\$</u>	<u>S\$</u>
NET PRICE			
1 Side Skirt chrome - RH (front)	1	170.00	170.00 X
2 Side skirt chrome - RH (rear)	1	86.00	86.00 ✓
3 Rear door - RH	1	2,290.00	2,290.00 ✓
4 Rear door weatherstrip - RH	1	312.00	312.00 ✓
5 Rear door trimboard rivets - RH	20	12.00	240.00 X
6 Rear door outer handle - RH	1	640.00	640.00 X
7 Rear fender - RH	1	2,250.00	2,250.00 X
8 Rear fender inner shield - RH	1	192.00	192.00 X
9 Rear fender inner shield clips - RH	15	9.00	135.00 X
10 Rear bumper	1	2,035.00	2,035.00 X
11 Rear bumper side retainer - RH	1	83.00	83.00 X
12 Rear bumper clips	15	9.00	135.00 X
13 Rear bumper reverse sensor	1	188.00	188.00 X
14 Rear bumper reverse sensor seals	6	12.00	72.00 X
15 Rear sport rim - RH	1	760.00	760.00 ✓
			9,588.00
		Less 10%	958.80
			8,629.20
SPECIAL NET			
16 Rear tyre - RH	1	380.00	380.00 X
17 Rear windscreen sealant	1	60.00	60.00 X
			440.00
LABOUR			
18 To remove and refit rear windscreen glass	1	150.00	150.00 X
19 To remove and refit rear petrol tank to facilitates the repairs	1	160.00	160.00 X
20 To remove and refit rear interior garnishes and trimboard to facilitates the repairs	1	280.00	280.00 100.
21 To transfer RH rear damaged door interior mechanish and glass to new door	1	150.00	150.00 80.
22 To remove and refit rear bumper sensor and reset fault code	1	100.00	100.00 X
23 To check and rectify wiring system	1	80.00	80.00 20.
24 To panel beat and straighten RH rear fender inner panel, RH rear chassis frame, to cut out and weld RH rear fender, including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00 500.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : GY4007R

CLAIM TYPE : THIRD PARTY

TP INS. CO. : SINGAPORE POLICE FORCE

ACCIDENT DATE : 22/10/2019

TP VEH REG NO : GY4007R

ESTIMATE

NO : QUOT201911-000005(00)

DATE : 04/11/2019

POLICY NO : 999995580

VEH REG NO : SMC6826A

MAKE/MODEL : MERCEDES BENZ E250 AVG
(R18 LED)

CHASSIS NO : WDD2130452A465953

ENGINE NO : 27492031499679

REG. DATE : 2018

Estimate Repair Cost to Vehicle No : SMC6826A

Description	Quantity	Unit Price	Amount
		S\$ 1000/ S\$	
25 To putty and spray paint on affected areas	1	1,500.00	1,500.00
26 To apply rust-proofing on repaired and replace panels	1	160.00	160.00
27 To computerised check wheel alignment	1	120.00	120.00
			3,700.00
		TOTAL	S\$ 12,769.20
		ADD GST @ 7%	893.84
		GRAND TOTAL	S\$ 13,663.04

SINGAPORE DOLLAR THIRTEEN THOUSAND SIX HUNDRED SIXTY-THREE AND CENTS FOUR ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF19019470/Kqf3e2	
ACCIDENT CLAIM SECTION (SPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMY SINGAPORE 298333		Date : 25-11-2019	
ATTN : HAFIZUL FARHAN RAHMAT		Code : SPF	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GY 4007R	Veh. Inspected	SMC 6826A
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2019/109	Excess (\$)	0.00
Assign From	HAFIZUL FARHAN RAHMAT	Assign Date	04/11/2019
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ E250 (A)	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	WDD2130452A465953	Colour	METALLIC BLACK
Odometer	20144	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	245/45 R18	PIRELLI	8 mm
L/H Front Tyre	245/45 R18	PIRELLI	8 mm
R/H Rear Tyre	245/45 R18	PIRELLI	8 mm
L/H Rear Tyre	245/45 R18	PIRELLI	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	22/10/2019	Inspection Date	05/11/2019
Survey held at	TONG LUCK AUTO PL 160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMC 6826A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SIDE SKIRT CHROME - RH (FRONT)	SERVICEABLE	170.00	-
1	SIDE SKIRT CHROME - RH (REAR)	DENTED	86.00	86.00
1	REAR DOOR - RH	BENT	2,290.00	2,290.00
1	REAR DOOR WEATHERSTRIP - RH	NECESSARY	312.00	312.00
20	REAR DOOR TRIMBOARD RIVETS - RH @\$12.00	SERVICEABLE	240.00	-
1	REAR DOOR OUTAR HANDLE - RH	SERVICEABLE	640.00	-
1	REAR FENDER - RH	TO REPAIR SEE LABOUR	2,250.00	-
1	REAR FENDER INNER SHIELD - RH	SERVICEABLE	192.00	-
15	REAR FENDER INNER SHIELD CLIPS - RH @\$9.00	NOT NECESSARY	135.00	-
1	REAR BUMPER	TO REPAIR SEE LABOUR	2,035.00	-
1	REAR BUMPER SIDE RETAINER - RH	SERVICEABLE	83.00	-
15	REAR BUMPER CLIPS @\$9.00	NOT NECESSARY	135.00	-
1	REAR BUMPER REVERSE SENSOR	SERVICEABLE	188.00	-
6	REAR BUMPER REVERSE SENSOR SEALS @\$12.00	SERVICEABLE	72.00	-
1	REAR SPORT RIM - RH	DENTED	760.00	760.00
	LESS 10% DISCOUNT		-958.80	-344.80
			8,629.20	3,103.20
SPECIAL NETT ITEMS				
1	REAR TYRE - RH (SN)	SERVICEABLE	380.00	-
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	60.00	-
			440.00	-
LABOUR				
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.	NOT NECESSARY	150.00	-
	TO REMOVE AND REFIT REAR PETROL TANK TO FACILITATES THE REPAIRS.	NOT NECESSARY	160.00	-
	TO REMOVE AND REFIT REAR INTERIOR GARNISHES AND TRIMBOARD TO FACILITATES THE REPAIRS.		280.00	100.00
	TO TRANSFER RH REAR DAMAGED DOOR INTERIOR MECHANISM AND GLASS TO NEW DOOR.		150.00	80.00
	TO REMOVE AND REFIT REAR BUMPER SENSOR AND RESET FAULT CODE.	NOT NECESSARY	100.00	-
	TO CHECK AND RECTIFY WIRING SYSTEM.		80.00	20.00

Report Ref No. CS/SPF19019470/Kqf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PANEL BEAT AND STRAIGHTEN RH REAR FENDER INNER PANEL, RH REAR CHASSIS FRAME, TO CUT OUT AND WELD RH REAR FENDER, INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY, TO REFIT AND ADJUST THE SAME. INCLUSIVE OF THE REPAIR OF REAR FENDER - RH AND REAR BUMPER.		1,000.00	650.00
	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS.		1,500.00	1,000.00
	TO APPLY RUST-PROOFING ON REPAIRED AND REPLACE PANELS.		160.00	30.00
	TO COMPUTERISED CHECK WHEEL ALIGNMENT.		120.00	80.00
			3,700.00	1,960.00
GRAND TOTAL			12,769.20	5,063.20

RECOMMENDED COST OF REPAIRS				5,063.20
-----------------------------	--	--	--	----------

Report Ref No. CS/SPF19019470/Kqf3e2

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$5,063.20-\$10,000.00

RECOMMENDED REPAIR DAYS : 5

WEEKEND : 2

TOTAL DAYS : 7

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.