

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

04 NOV 2019

E S T I M A T E

1414727

Estimate No. : b1 53310
Date Estimated : 04/11/2019
Prepared By : Han Kwan Yong

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Sim Kian Hwee Dennis
18 Springside View

- ACCOUNT - 40000
Cash Sales - Service
Singapore

Singapore 786249

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKK636C	WBAHS120705H48618	25/05/2017	X1 sDrive18i	0

DESCRIPTIONVALUE

To replace rear bumper & attachments including to knock out
tail panel and dented area caused by the accident 850

850 2,125.00

To respray rear bumper and tail panel

934 1,923.00

To remove old PDC assembly, replace damaged parts and
reconnect to new bumper including conduct checks for
proper function.

150 177.00

To check electrical wiring systems and lightings at the
rear section for proper function.

150 177.00

Sundries.

80.00

Total Labour 1: 4,482.00

DESCRIPTIONQTYPRICVALUE

REAR LH BUMPER MOUNT

1

161.40

161.40

REAR RH BUMPER MOUNT

1

161.40

161.40

RR BUMPER CARRIER

1

496.35

496.35

MOUNTING SMART OPENER

1

45.55

45.55

REAR TRIM UNDERRIDE PROTECTION (X.L (S/L)) / CUT

1

109.70

109.70

RR BUMPER LH CORNER MOUNTING

1

142.65

142.65

RR BUMPER RH CORNER MOUNTING

1

142.65

142.65

REAR BUMPER PANEL PRIMED

1

903.40

903.40

REAR BUMPER MIDDLE TRIM PANE

1

265.65

265.65

REAR BUMPER TRIM BOTTOM (LINES)

1

232.45

232.45

EXPANDING RIVET BLACK

30

1.40

42.00

ULTRASONIC SENSOR BLACK

2

249.95

499.90

DECOUPING RING PDC TORQUE CONVERTER

2

5.10

10.20

Total Parts : 3,213.30

Performance Motors Limited

A Sime Darby Motors Company

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 53310
Date Estimated : 04/11/2019
Prepared By : Han Kwan Yong

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKK636C	WBAHS120705H48618	25/05/2017	X1 sDrive18i	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
 Date & Time 18/11/19, 4.00pm Excess S\$ _____
 Surveyor's Name Steve (LKK) Sign _____
 Surveyor's Tel 83228815 Authorised Yes / No
 Authorised Date _____ Time _____
 RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____
 Surveyor's E-mail _____
 No. of Working Days Recommend _____

w/L Prindic

3 days

P/P

Ry BeL spy

Labour 1	:	4,482.00
Parts	:	3,213.30
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	538.67
Grand Total	:	<u>8,233.97</u>

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **