

INS. CASE OWNER: **CHAN KIAN MENG**

CC6/AIG19019495/Ada3

LKK:
IDAC:

ASSIGNMENT

Surveyor: **ADRIAN**

DOI: **04.11.2019**

Date / Time: **04.11.2019**

Registered in Merimen: **04.11.2019**

Pre-assign / CCU / FTE



Insured Vehicle No. : **SKF 685L**
 Name of Insured : **SIM CHIN BENG WILSON**
 Insured Tel No. : _____ HP: **+65-96823543**
Excess Sec II :SS _____ D.O.A. : **03.11.2019**
 Is driver the owner? (YES / NO) Nature of Accident : _____

Claim No. : **0487533672SG**
 Policy No. : **1800033894**
 Make / Model : **HONDA CIVIC 1.6 VTIS AT**
 Place of Accident : **CTE TOWARDS CITY AT CTE 14 1/2 KM MARK**

If NO, Driver Name / Age :

Driver Tel No. : _____ (V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability : % **Final ? Yes / No**

SMD 1218H



INSRS:
WSP: **NHT**
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/Time	STAGE	DATE / PIC
	SKF 685L - NA/MSG18013145/z4; DOA: 10.07.18 - CC3/CTI17018646/K1hb3n2; DOA: 26.9.17	
	SMD 1218H- X	
26/2/2020	FILE PASS TO HMM TO CLOSE	
	<i>GIA search done 0 diff w DOA.</i>	
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input type="checkbox"/> <input type="checkbox"/>
	After call ltr to OI:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/> <input type="checkbox"/>
	Towing Invoice	<input type="checkbox"/> <input type="checkbox"/>
	LTA / GIA :	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Medical Bill:	<input type="checkbox"/> <input type="checkbox"/>
	PBR:	<input type="checkbox"/> <input type="checkbox"/>
	Mandate/Reject Instruction:	<input type="checkbox"/> <input type="checkbox"/>
	LOD	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/> <input type="checkbox"/>
	Others:	<input type="checkbox"/> <input type="checkbox"/>

PRELIMINARY ADVICE	Date/Time:	Sent By:	
FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	SS	(days) Reduction: %	Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT	Date/Time: 6/2/2020	Confirm with <i>Subj:</i>	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No. : 28	If NO or B 28, Ass. Lia : 01
Repair Cost: (w/ GST)	SS 6848.00		3 vol c.c. 02 was 2nd
Loss of Rental (LOR):	SS -	(days)	
Loss of Use (LOU):	SS 400.00	(\$ 60 x 15 days)	
Loss of Income (LOI):	SS -	(\$ x days)	
LOR only <input type="checkbox"/> LOU only <input checked="" type="checkbox"/>	LOR + LOU <input type="checkbox"/>	LOR + LOI <input type="checkbox"/>	[Tick only one]
GIA/LTA Search	SS 2.00		
Medical:	SS -		
Disbursement:	SS -	(e.g. Tow/Independent)	
Legal Cost	SS -		
Total:	SS 7750.00	Global Sum SS:	
FINAL PAYMENT	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	SS 7750.00	Name 1: New Hock Teck Motor Pte Ltd	
Payee 2: (Strike if N.A.)	SS	Name 2:	
Payee 3: (Strike if N.A.)	SS	Name 3:	

COPY SENT
26/02/2020

- 1) Claim status: Non-pickup/Reject/Private Settle
- 2) Report Format: *TP*
- 3) Survey fee: **\$320**

9498 / Ad.

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop no: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SMD128H. Reg: 2015 April
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Honda City. C.C. 1497
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 76018 T/Radio: Insured / Std / NI / NA
 Eng No: _____
 C.No: MRHGMB66067000070
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Good / Jammed / Leaked / Burnt or _____
 Brake: Good / Jammed / Leaked / Burnt or _____
 Modi: NIL / S/Rim / STD A/Rim or _____
 Tyre Size: F: 185/55R16
 R: 185/55R12

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front: _____ Rear: _____
 R/Bal. 06 mm F/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 04/11/15.
 Survey held at NHT.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 12 days Res: Yes or No
 Lum Sum: 20 % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	TP ALG.
	41- \$ 6400 (Red \$ 1635.40 / 60%)
	MV: 50K
	PV: 43K
	Nett: 7K.

Date/Time, File Pres to? : Prel. Report
 : Final Report

Days Of Repair: _____
 Resurvey No. of Trip: _____

329I.

Date/Time, File Return to? _____
 Report Format: _____
 Insp. Sim / LB: _____

Add Fee: Site Insp: \$
 Interview: \$
 Tech. Insp: \$
 Report: \$

Survey Fee:
Transport:
1-PE: \$
Other:
Other:
Other:



新福德車廠私人有限公司

(41E)

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

04/11/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPAIG

MRHGM6660GP000070

Jia Le.

Accident date: 03/11/2019

Estimated repair cost for vehicle no: SMD1218H HONDA CITY 1.5 A '15

CHASSIS: MRHGM6660GP000070

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid Distorted		\$638.70 ✓
2	2	Rear Boot Lid Hinge Bent	\$51.80	\$103.60 ✓
3	1	Rear Boot Lid Lock Damaged		\$90.30 ✓
4	1	Rear Boot Lid Weatherstrip ut		\$71.60 ✓
5	1	Rear Boot Lid Inner Trim Board		\$130.20 ✓
6	8	Rear Boot Lid Inner Trim Board Clip <i>New</i>	\$6.50	\$52.00 ✓
7	1	Rear Boot Lid Emblem Logo		\$24.70 ✓
8	1	Rear Boot Lid City Logo <i>New</i>		\$21.30 ✓
9	1	Rear Boot Lid I-Vtec Logo		\$32.30 ✓
10	1	Rear Boot Lid Center Chrome Moulding cracked.		\$165.00 ✓
11	1	Rear Boot Lid Number Plate Bent		\$50.00 ✓
12	2	Rear Boot Lid Side Reflector ut	\$402.90	\$402.90 ✓
13	1	Rear Boot Lid Camera Not Nec		\$392.60 ✗
14	2	Rear Taillamp crushed	\$225.70	\$451.40 ✓
15	4	Rear Taillamp Clip <i>New</i>	\$6.50	\$26.00 ✓
16	2	Rear Taillamp Panel RH Dented	\$89.80	\$179.60 89.80
17	1	Rear Bumper Distorted		\$483.70 ✓
18	10	Rear Bumper Clip <i>New</i>	\$6.50	\$65.00 30
19	2	Rear Bumper Side Retainer <i>New</i>	\$15.90	\$31.80 ✓
20	2	Rear Bumper Side Reflector RH crushed	\$30.00	\$60.00 30
21	2	Rear Bumper Side Under Cover 1 piece deformed	\$30.10	\$60.20 30.10
22	2	Rear Fender RH Buckled	\$1,109.40	\$2,218.80 795
23	2	Rear Fender Cowling <i>New</i>	\$30.20	\$60.40 ✗
24	16	Rear Fender Cowling Clip <i>New</i>	\$6.50	\$104.00 ✗
25	2	Rear Fender Inner Trim Board Not Nec	\$70.80	\$141.60 ✗
26	16	Rear Fender Inner Trim Board Clip Not Nec	\$6.50	\$104.00 ✗
27	1	Rear End Panel Distorted		\$336.90 ✓
28	1	Rear End Panel Top Garnish Deformed		\$86.40 ✓
29	1	Rear Spare Tyre Panel Buckled		\$450.80 ✓

30	1	Rear Spare Tyre Panel Top Cover	torn		\$65.00	✓
31	1	Rear Spare Tyre Panel Sealant	Not		\$450.00	250(SA)
32	1	Rear Exhaust	Bent		\$455.30	✓
33	2	Rear Exhaust Mounting	Not Not	\$19.00	\$38.00	✓
34	1	Rear Exhaust Insulation Cover	Crumpled		\$68.00	✓
35	1	Rear Center Exhaust	Repair		\$291.70	✓
36	1	Rear Windscreen Moulding	Not Not		\$131.80	✓
37	1	Reverse Sensor	Damaged	5330.60	SN450	
				4024.48		
					Subtotal :-	\$8,335.40

Labour charges

To remove & refit rear windscreen	\$120.00	✓
Gum	\$60.00	✓
To remove & refit reverse camera	\$180.00	60
To remove & refit reverse sensor	\$100.00	60
To remove & refit rear & center exhaust	\$380.00	160
To check wiring	\$150.00	30
Towing fee	\$150.00	60
Tuff kote	\$200.00	120
Panel beating	\$3,600.00	1600
Spray painting	\$2,800.00	1300
Subtotal :-	\$7,740.00	

3570

Total:- \$16,075.40

total 8044.48
 2/5 6.4K
 12 Days

6.4K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	329I
Vehicle Details	
Vehicle No.:	SMD1218H
Vehicle to be Exported:	Yes
Intended Deregistration Date:	04 Nov 2019
Vehicle Make:	HONDA
Vehicle Model:	CITY 1.5 SV CVT
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	L15Z12702725
Chassis No.:	MRHGM6660GP000070
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$17,833.00
Original Registration Date:	29 Apr 2015
First Registration Date:	29 Apr 2015
Transfer Count:	1
Actual ARF Paid:	\$7,833.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Apr 2025
PARF Rebate Amount:	\$5,874.00
Intended COE Rebate Details	
COE Expiry Date:	28 Apr 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$67,749.00
COE Rebate Amount:	\$37,149.00
Total Rebate Amount:	\$43,023.00

The information contained herein is correct as at 04 Nov 2019

OK

Google Pixel 4 XL

Meet the new Pixel 4 XL, built around the helpful Google software

SEARCH
 Price Range
 Depreciation
 2015
 Vehicle Type

[Advanced Search](#)

Used Car Comparison

— Comparing 3 Vehicles —

Honda City 1.5A SV



Honda City 1.5A SV



Honda City 1.5A SV



The search bar above is to be complete.

[Back to search result](#)

CAR DETAILS				
Price	\$56,500	\$56,800	\$61,900	-
Instalment	\$663	\$667	\$718	-
Registration Date	22-Sep-2015	22-Sep-2015	19-Oct-2015	-
Manufactured	2015	2015	2015	-
Mileage	57,381 km	48,000 km	56,000 km	-
Transmission	Auto	Auto	Auto	-
Engine Cap	1,497 cc	1,497 cc	1,497 cc	-
Road Tax	\$684 /yr	\$684 /yr	\$684 /yr	-
Power	88.0 kW (118 bhp)	88.0 kW (118 bhp)	88.0 kW (118 bhp)	-
Curb Weight	1,096 kg	1,096 kg	1,096 kg	-
Features	1.5L I-VTEC Engine, 118Bhp/145Nm Torque, Earth Dreams CVT Automatic, ABS, Airbags, Cruise Control, Knockdown Rear Seats, Keyless Entry/Start/Stop.	1.5L I-VTEC Engine, 118 BHP/145 Nm Torque, Earth Dreams CVT Automatic, ABS, Airbags, Cruise Control, Knockdown Rear Seats, Keyless Entry/Start/Stop.	Maroon Red Color, ABS, EBD, VSC, Airbags, Immobilizer, Keyless Entry, I-Vtec Engine.	-
Accessories	Leather Seats, Alloy Rims, Touchscreen Intuitive Display With Smartphone/HDMI/AUX Input, Bluetooth, Reverse Camera, Paddle Shifter, Window Visors.	Leather Seats, Alloy Rims, Touchscreen Intuitive Display With Smartphone/HDMI/Aux Input, Bluetooth, Reverse Camera, Paddle Shifter, Keyless Entry/Start	Brown Color Leather Upholstery, 16" Sports Rims With New Michelin XM2 Tyres X4, Rike Cool Solar Film, Multi-Function Sports Steering Wheel.	-
Description	Latest Arrival! Low Fuel Consumption And Low Maintenance! Left 1 Year Agent Warranty, Clean And Neat Interior! Flexible Loan To Cater Different Need! Please Call Or Text For Car's Availability Before Coming Over, Thanks.	Powerful, Responsive Yet Fuel Efficient. A Very Easy To Maintain Car. Only 1 Previous Owner. Car In Original Condition, Original Paintwork/Leather Interior. Flexible Loan Packages Available With Attractive Interest Rates. Welcome All Trade In. Call Our Friendly Representatives For More Information Or For A Viewing Of The Car.	Immaculate Condition, Maroon Red Honda City 1.5A SV With Matching Brown Leather Upholstery Owned By Just 1 Executive Owner Selling Due To Upgrading. Agent Unit Maintained And Serviced, Very Seldom Use And Parked At Sheltered Area, Very Good Fuel Consumption, Additional Muffler Installed And Rear Boot Modified, Selling On Behalf Of Private Owner, Please Call To Arrange Before Viewing.	-
COE	\$57,089	\$57,498	\$56,001	-
OMV	\$18,174	\$18,174	\$18,174	-
ARF	\$13,174	\$13,174	\$13,174	-
Depreciation	\$8,480 /yr	\$8,530 /yr	\$9,280 /yr	-
No. of Owners	1	1	1	-
Type of Vehicle	Sedan	Sedan	Sedan	-
Category	PARF Car, Premium Ad Car	PARF Car, Premium Ad Car	PARF Car, Premium Ad Car	-
Availability	Available	Available	Available	-

View Received Message

This mail is associated with :

***SMD1218H (0487533672SG)**
[SKF685L]
TP
CHEN JUNJIE
Nov 3 2019 10:00AM
[SIM CHIN BENG WILSON]
New Hock Teck Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 06/02/2020 10:21 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$7750.00) - SMD1218H - Claim Handler: Chan, Kian Meng

Approved:7750.00:Kindly settle at best.

DOCUMENTS SUMMARY

There are no documents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Nov 2019 Edit Reg		04 Nov 2019 00:00 Edit Adj Rpt	\$56,400.00 Edit Estimates	\$56,400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	SIM CHIN BENG WILSON , ID: 57511781G								
Main Claimant:	CHEN JUNJIE , ID: S9005329I								
Vehicle Reg. No.:	SMD1218H	Date of Loss:	03/11/2019 10:00 - :59 [54 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 04875336725G	Policy/Cover Note No.:	1800033894 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKF685L	Policy No. (Claimant):	5104535323-01						
Repairer:	New Hock Teck Motor Pte Ltd (HQ) 1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 6747 9241								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 13/11/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> • AIG_SG_EXPRESS (06/02/2020): Alert - Adj Mandate Approved (\$57750.00) - SMD1218H - Claim Handler: Chan, Kian ... • AIG_SG (05/11/2019): TP GIA report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMD1218H (0487533672SG)
[SKF685L]
TP
CHEN JUNJIE
Nov 3 2019 10:00AM
[SIM CHIN BENG WILSON]
New Hock Teck Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View <input type="button" value="View in Browser"/>		
Video															1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)										Thumbnail	Print				
1	05/11/19 13:11	OI VIDEO											Load MP4				
Letters/Correspondences															1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print				
1	(Draft)	Third Party Express Settlement - Payment Breakdown											Edit				
Assessment Reports															1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print				
1	11/12/19 17:00	Adjuster Immediate Advice											Load HTM				
Photos/Images															3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print				
1	10/12/19 09:21	General View											Load JPG <input checked="" type="checkbox"/>				
2	10/12/19 09:21	General View											Load JPG <input checked="" type="checkbox"/>				
3	10/12/19 09:21	General View											Load JPG <input checked="" type="checkbox"/>				
4	10/12/19 09:21	General View											Load JPG <input checked="" type="checkbox"/>				
5	10/12/19 09:21	General View											Load JPG <input checked="" type="checkbox"/>				
6	10/12/19 09:21	General View											Load JPG <input checked="" type="checkbox"/>				
7	10/12/19 09:21	General View											Load JPG <input checked="" type="checkbox"/>				
8	10/12/19 09:21	General View											Load JPG <input checked="" type="checkbox"/>				
9	10/12/19 09:21	General View											Load JPG <input checked="" type="checkbox"/>				
10	10/12/19 09:21	General View											Load JPG <input checked="" type="checkbox"/>				
11	10/12/19 09:21	General View											Load JPG <input checked="" type="checkbox"/>				
12	10/12/19 09:21	General View											Load JPG <input checked="" type="checkbox"/>				
13	10/12/19 09:21	General View											Load JPG <input checked="" type="checkbox"/>				
14	10/12/19 09:21	General View											Load JPG <input checked="" type="checkbox"/>				
15	10/12/19 09:21	General View											Load JPG <input checked="" type="checkbox"/>				
16	10/12/19 09:21	General View											Load JPG <input checked="" type="checkbox"/>				
17	10/12/19 09:21	General View											Load JPG <input checked="" type="checkbox"/>				
18	10/12/19 09:21	General View											Load JPG <input checked="" type="checkbox"/>				
19	10/12/19 09:21	General View											Load JPG <input checked="" type="checkbox"/>				
20	10/12/19 09:21	General View											Load JPG <input checked="" type="checkbox"/>				
21	10/12/19 09:21	General View											Load JPG <input checked="" type="checkbox"/>				
22	10/12/19 09:21	General View											Load JPG <input checked="" type="checkbox"/>				
23	10/12/19 09:21	General View											Load JPG <input checked="" type="checkbox"/>				
24	10/12/19 09:21	General View											Load JPG <input checked="" type="checkbox"/>				
25	10/12/19 09:21	General View											Load JPG <input checked="" type="checkbox"/>				
26	10/12/19 09:21	General View											Load JPG <input checked="" type="checkbox"/>				
27	10/12/19 09:21	General View											Load JPG <input checked="" type="checkbox"/>				
28	10/12/19 09:21	General View											Load JPG <input checked="" type="checkbox"/>				
29	10/12/19 09:21	General View											Load JPG <input checked="" type="checkbox"/>				
30	10/12/19 09:21	General View											Load JPG <input checked="" type="checkbox"/>				
31	10/12/19 09:21	General View											Load JPG <input checked="" type="checkbox"/>				
32	10/12/19 09:21	General View											Load JPG <input checked="" type="checkbox"/>				
33	10/12/19 09:21	General View											Load JPG <input checked="" type="checkbox"/>				

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
34	10/12/19 09:21	General View	 Load JPG	<input checked="" type="checkbox"/>
35	10/12/19 09:21	General View	 Load JPG	<input checked="" type="checkbox"/>
36	10/12/19 09:21	General View	 Load JPG	<input checked="" type="checkbox"/>
37	10/12/19 09:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	10/12/19 09:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	10/12/19 09:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	10/12/19 09:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	10/12/19 09:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	10/12/19 09:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	10/12/19 09:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	10/12/19 09:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	10/12/19 09:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	10/12/19 09:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	10/12/19 09:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	10/12/19 09:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	10/12/19 09:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	10/12/19 09:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	10/12/19 09:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	10/12/19 09:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	10/12/19 09:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	10/12/19 09:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	10/12/19 09:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	10/12/19 09:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	10/12/19 09:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	10/12/19 09:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	10/12/19 09:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	10/12/19 09:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	10/12/19 09:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	10/12/19 09:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	10/12/19 09:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	10/12/19 09:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	10/12/19 09:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	10/12/19 09:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	10/12/19 09:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	10/12/19 09:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	10/12/19 09:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	10/12/19 09:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	10/12/19 09:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	10/12/19 09:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	10/12/19 09:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	10/12/19 09:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	10/12/19 09:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	10/12/19 09:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	10/12/19 09:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	10/12/19 09:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	10/12/19 09:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	10/12/19 09:22	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
81	10/12/19 09:22	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
82	10/12/19 09:22	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
83	10/12/19 09:22	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
84	10/12/19 09:22	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
85	10/12/19 09:22	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
86	10/12/19 09:22	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
87	10/12/19 09:22	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
88	10/12/19 09:22	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
89	10/12/19 09:22	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
90	10/12/19 09:22	Reinspection Photo		<input checked="" type="checkbox"/>
91	10/12/19 09:22	Reinspection Photo		<input checked="" type="checkbox"/>
92	10/12/19 09:22	Reinspection Photo		<input checked="" type="checkbox"/>
93	10/12/19 09:22	Reinspection Photo		<input checked="" type="checkbox"/>
94	10/12/19 09:22	Reinspection Photo		<input checked="" type="checkbox"/>
95	10/12/19 09:22	Reinspection Photo		<input checked="" type="checkbox"/>
96	10/12/19 09:22	Reinspection Photo		<input checked="" type="checkbox"/>
97	10/12/19 09:22	Reinspection Photo		<input checked="" type="checkbox"/>
98	10/12/19 09:22	Reinspection Photo		<input checked="" type="checkbox"/>
99	10/12/19 09:22	Reinspection Photo		<input checked="" type="checkbox"/>
100	10/12/19 09:22	Reinspection Photo		<input checked="" type="checkbox"/>
101	10/12/19 09:22	Reinspection Photo		<input checked="" type="checkbox"/>
102	10/12/19 09:22	Reinspection Photo		<input checked="" type="checkbox"/>
103	10/12/19 09:22	Reinspection Photo		<input checked="" type="checkbox"/>
104	10/12/19 09:22	Reinspection Photo		<input checked="" type="checkbox"/>
105	10/12/19 09:22	Reinspection Photo		<input checked="" type="checkbox"/>
106	10/12/19 09:22	Reinspection Photo		<input checked="" type="checkbox"/>
107	10/12/19 09:22	Reinspection Photo		<input checked="" type="checkbox"/>
108	10/12/19 09:22	Reinspection Photo		<input checked="" type="checkbox"/>
109	10/12/19 09:22	Reinspection Photo		<input checked="" type="checkbox"/>
110	10/12/19 09:22	Reinspection Photo		<input checked="" type="checkbox"/>
111	10/12/19 09:22	Reinspection Photo		<input checked="" type="checkbox"/>
112	10/12/19 09:22	Reinspection Photo		<input checked="" type="checkbox"/>
113	10/12/19 09:22	Reinspection Photo		<input checked="" type="checkbox"/>
114	10/12/19 09:22	Reinspection Photo		<input checked="" type="checkbox"/>
115	10/12/19 09:22	Reinspection Photo		<input checked="" type="checkbox"/>
116	10/12/19 09:22	Reinspection Photo		<input checked="" type="checkbox"/>
117	10/12/19 09:22	Reinspection Photo		<input checked="" type="checkbox"/>
118	10/12/19 09:22	Reinspection Photo		<input checked="" type="checkbox"/>
119	10/12/19 09:22	Reinspection Photo		<input checked="" type="checkbox"/>
120	10/12/19 09:22	Reinspection Photo		<input checked="" type="checkbox"/>
121	10/12/19 09:22	Reinspection Photo		<input checked="" type="checkbox"/>
122	10/12/19 09:22	Reinspection Photo		<input checked="" type="checkbox"/>
123	10/12/19 09:22	Reinspection Photo		<input checked="" type="checkbox"/>
124	10/12/19 09:22	Reinspection Photo		<input checked="" type="checkbox"/>
125	10/12/19 09:22	Reinspection Photo		<input checked="" type="checkbox"/>
126	10/12/19 09:22	Reinspection Photo		<input checked="" type="checkbox"/>
127	10/12/19 09:22	Reinspection Photo		<input checked="" type="checkbox"/>
128	10/12/19 09:22	Reinspection Photo		<input checked="" type="checkbox"/>
129	10/12/19 09:22	Reinspection Photo		<input checked="" type="checkbox"/>
130	10/12/19 09:22	Reinspection Photo		<input checked="" type="checkbox"/>
131	10/12/19 09:22	Reinspection Photo		<input checked="" type="checkbox"/>
132	10/12/19 09:22	Reinspection Photo		<input checked="" type="checkbox"/>
133	10/12/19 09:22	Reinspection Photo		<input checked="" type="checkbox"/>
134	10/12/19 09:22	Reinspection Photo		<input checked="" type="checkbox"/>
135	10/12/19 09:22	Reinspection Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/11/19 13:44	TP GIA REPORT		<input type="checkbox"/>
2	11/12/19 16:48	TP_ESTIMATE_MARKED		<input type="checkbox"/>
3	11/12/19 16:48	LOD		<input type="checkbox"/>
4	11/12/19 16:48	GIA SEARCH FEE		<input type="checkbox"/>
5	20/12/19 17:22	PIR		<input checked="" type="checkbox"/>
6	27/02/20 09:17	WORKSHOP INVOICE		<input type="checkbox"/>
7	27/02/20 09:17	AUTHORISATION TO ACT FORM		<input type="checkbox"/>
8	27/02/20 09:17	Release Voucher		<input type="checkbox"/>
9	27/02/20 09:17	LETTER TO OI		<input type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	05/11/19 13:10	OI GIA REPORT		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SKF685L (Insd veh)	Model:	HONDA CITY 1.5 SV CVT (A)
	SMD1218H (TP veh)		
Date of Accident:	03/11/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$	17,789.39	
Final Repair Cost	:	\$	6,848.00	
Loss of Use	:	\$	900.00	15.00 days at \$60.00 per day
Rental (if any)	:	\$	0.00	days
LTA / GIA Search Fee	:	\$	2.00	
Others:	:	\$	0.00	
	:	\$		
Final Settlement Sum	:	\$	7,750.00	
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)				
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ (%)		Assessed Liability (*): _____ 0 _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	New Hock Teck Motor Pte Ltd	:	\$ 7,750.00
2)		:	\$
3)		:	\$

 JOANNE LEE KHANG MIN
 LKK Auto Consultants Pte Ltd

27 Feb
 2020

 Date

Please attach all the supporting documents to the form.
 (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
 Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19019495/ADA3Q2

Date: 27/02/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800033894
 Claimant: SMD1218H Insured Vehicle No : SKF685L
 Vehicle No : SMD1218H Nature of Claim: TP Claim No: 0487533672SG
 Date of Loss: 03/11/2019

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMD1218H
 Make & Model: HONDA CITY, 1.5 SV CVT (A) Engine No: L15Z12702725
 Reg. Date: 29/04/2015 (Man. Year: 2015) Chassis No: MRHGM6660GP000070
 Colour: Black Odometer: 76018 km
 Engine Capacity: 1497 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 185/55 R15 Rear Tyre Size: 185/55 R12
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,885.60	4,474.48	4,411.12	49.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,740.00	3,570.00	4,170.00	53.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,625.60	8,044.48	8,581.12	51.61
Approved Total (Overridden) (S\$)		6,400.00		
(S\$)	16,625.60	6,400.00	10,225.60	61.51
+ GST 7.00/7.00% (S\$)	1,163.79	448.00	715.79	61.51
Nett Amount (S\$)	17,789.39	6,848.00	10,941.39	61.51
+ Loss of Use (15.0 x S\$60.00/day) (S\$)		900.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		7,750.00		

INSPECTION

Date of Assignment: 04/11/2019
 Date Inspected: 04/11/2019 Inspected At: New Hock Teck Motor Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, Blk C #01-43
 Autobay@Kaki Bukit
 Singapore 417883
 Estimated Period of Repair: 12.0 days

Adjuster: ADRIAN LING

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Distorted	638.70 F	*638.70 FL
2	2		*REAR BOOT LID HINGE	Bent	103.60 F	*103.60 FL
3	1		*REAR BOOT LID LOCK	Damaged	90.30 F	*90.30 FL
4	1		*REAR BOOT LID WEATHERSTRIP	Cut	71.60 F	*71.60 FL
5	1		*REAR BOOT LID INNER TRIM BOARD	Not Necessary	130.20 F	*- FL
6	8		*REAR BOOT LID INNER TRIM BOARD CLIP	Not Necessary	52.00 F	*- FL
7	1		*REAR BOOT LID EMBLEM LOGO	Necessary	24.70 F	*24.70 FL
8	1		*REAR BOOT LID CITY LOGO	Necessary	21.30 F	*21.30 FL
9	1		*REAR BOOT LID I-VTEC LOGO	Necessary	32.30 F	*32.30 FL
10	1		*REAR BOOT LID CENTER CHROME MOULDING	Cracked	165.00 F	*165.00 FL
11	1		*REAR BOOT LID NUMBER PLATE	Bent	50.00 F	*50.00 FL
12	2		*REAR BOOT LID SIDE REFLECTOR	Cut	402.90 F	*402.90 FL
13	1		*REAR BOOT LID CAMERA	Not Necessary	392.60 F	*- FL
14	2		*REAR TAILLAMP	Cracked	451.40 F	*451.40 FL
15	4		*REAR TAILLAMP CLIP	Necessary	26.00 F	*26.00 FL
16	1		*REAR TAILLAMP PANEL	O/S Dented	179.60 F	*89.80 FL
17	1		*REAR BUMPER	Distorted	483.70 F	*483.70 FL
18	10		*REAR BUMPER CLIP	Necessary	65.00 F	*30.00 FL
19	2		*REAR BUMPER SIDE RETAINER	Necessary	31.80 F	*31.80 FL
20	1		*REAR BUMPER SIDE REFLECTOR	O/S Cracked	60.00 F	*30.00 FL
21	2		*REAR BUMPER SIDE UNDER COVER	Deformed (1 PCS ONLY)	60.20 F	*30.10 FL
22	1		*REAR FENDER	O/S Buckled	2,218.80 F	*795.00 FL
23	2		*REAR FENDER COWLING	Not Necessary	60.40 F	*- FL
24	16		*REAR FENDER COWLING CLIP	Not Necessary	104.00 F	*- FL
25	2		*REAR FENDER INNER TRIM BOARD	Not Necessary	141.60 F	*- FL
26	16		*REAR FENDER INNER TRIM BOARD CLIP	Not Necessary	104.00 F	*- FL
27	1		*REAR END PANEL	Distorted	336.90 F	*336.90 FL
28	1		*REAR END PANEL TOP GARNISH	Deformed	86.40 F	*86.40 FL
29	1		*REAR SPARE TYRE PANEL	Buckled	450.80 F	*450.80 FL
30	1		*REAR SPARE TYRE PANEL TOP COVER	Torn	65.00 F	*65.00 FL
31	1		*REAR SPARE TYRE PANEL SEALANT	Necessary	450.00 FS	*250.00 FS
32	1		*REAR EXHAUST	Bent	455.30 F	*455.30 FL
33	2		*REAR EXHAUST MOUNTING	Not Necessary	38.00 F	*- FL
34	1		*REAR EXHAUST INSULATION COVER	Crumpled	68.00 F	*68.00 FL
35	1		*REAR CENTER EXHAUST	Repair	291.70 F	*- FL
36	1		*REAR WINDSCREEN MOULDING	Not Necessary	131.80 F	*- FL
37	1		*REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$) 8,885.60 5,480.60
- List Item Discount on L Items 0.00/20.00% (\$\$) 0.00 1,006.12

Total Parts (\$\$) 8,885.60 4,474.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	120.00
2	GUM	New	60.00	60.00
3	TO REMOVE & REFIT REVERSE CAMERA	New	180.00	60.00
4	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	60.00
5	TO REMOVE & REFIT REAR & CENTER EXHAUST	New	380.00	160.00
6	TO CHECK WIRING	New	150.00	30.00
7	TOWING FEE	New	150.00	60.00
8	TUFF KOTE	New	200.00	120.00
9	PANEL BEATING	New	3,600.00	1,600.00
10	SPRAY PAINTING	New	2,800.00	1,300.00
Gross Labour Cost (S\$)			7,740.00	3,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >