

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 3745P

DATE 4/11/2019 14:30

MAKE :

MODEL : HYUNDAI i40

Hankook 205/60R16

LKK-

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover cut			\$ 544.50
	Front Bumper Bracket Top (LH) xnn			\$ 22.40
	Front Bumper Bracket (LH) rec			\$ 24.60
	Headlamp (LH) scr			\$ 1,388.00
	Front Fender (LH) BU			\$ 566.30
	Front Fender Shield (LH) mis			\$ 175.90
	Front Fender Retainer xnn			\$ 24.60
	Front Wheel Alignment cover cut			\$ 107.10
	Front LH			
	SUB TOTAL			\$ 2,853.40
	LESS 20%			\$ 570.68
	DISCOUNTED TOTAL			\$ 2,282.72
	Front Fender Advertisement Logo (LH) rec			\$ 100.00
	merima fee - \$11/-			\$ 11
				\$ 100.00
	Labour Charge			
	Panel Beating			\$ 560.00
	Spray Painting Charge			\$ 500.00
	Wiring			\$ 50.00
	Tuff Kote			\$ 50.00
	Frt Wheel Alignment			\$ 80.00
	TOTAL LABOUR			\$ 1,240.00
	ESTIMATE TOTAL			\$ 3,622.72

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tokio Marine -

JH

6/11/19
Ram (LKK)
88622778 hp
Parasuram@lkkauto.com

repairs (3)
aft repair photos
4/11/19 1560hrs

4/5

\$1052.20

\$3314.1

\$662.82

\$2651.28

Nett \$90

\$280

\$400

\$30

\$30

xnn

\$3502.28

4/5: \$2800/-

4039.88