

Surveyor *John*

REF: NTUC NS / INC 401501 REF 302

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s

of

Insured: *SMN 7910A*

Policy No. *507067072-04 (22/03/2019)*

Claims No. *MT/1069899-002*

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR. Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: *SHB 5063E* Yr Regn: *12/10/17*
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: *Toyota Prius* c.c. *1798*
 Colour: *Maroon* A/C: Insured / Std / NI / NA
 Sp. Reading: *256128* T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: *JTDKB3AU80S7J901*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/R/m / STD A/R/m or

Tyre Size: F: *195/50R15*
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or *WHTK*

Front	Rear
R/Bal. <i>5</i> mm	R/Bal. <i>5</i> mm
L/Bal. <i>5</i> mm	L/Bal. <i>5</i> mm
D.O.A. <i>2/11/19</i>	D.O.I. <i>4/11/19</i>

Survey held at *SMRT*

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

GIA report will sent to LRA. (Alex)

SHB 5063E - CC3 / ALG 1900072 / 125352

SMN 7910A - X

20/11/19 Finalize confirm \$5480.16, 3 days (Poh Sun)
(\$ 4,151.14 Red - 43%)

RECEIVED 22 NOV 2019

11/11/2019
SMN 7910A

21/11/2019

Date/Time, File Pass to?

22/11/19

1) *Type 4*
 Date/Time, File Return to?

☐ : Proll. Report
☒ : Final Report

Days Of Repair: *3*

Resurvey No. of Trip: *1*

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech Invs (\$)
☐ : Weekend (\$)

Survey Fee: *160*
 Transportation: _____
 Photos: _____
 Others: _____

TOTAL

160

Report Format:

Lump Sum / I.B.I: (\$ *5,480.16 P/P*)

eBaoTech

General Claim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident
Vehicle No. (For Motor) Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☒	S070670731-04		SINGAPORE MOBILITY CORPORATION PTE LTD	200603234Z	GFT	Drive CLASSIC	SMN7910A	SMN7910A	28/08/2019	

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	369K
Vehicle Details	
Vehicle No.:	SHB5063E
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Nov 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZRS098462
Chassis No.:	JTDKB3FU803573001
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	12 Oct 2017
First Registration Date:	12 Oct 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Oct 2025
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	11 Oct 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$34,052.00
COE Rebate Amount:	\$25,264.00
Total Rebate Amount:	\$29,014.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 04 Nov 2019

OK

TP Claims against NTUC Income: Follow-Through Survey

Date : 21/11/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate
1	MT/1069899-002	SMRT TAXI PTE LTD	SHB 5063E	SMN 7910A	02/11/2019	4:30	\$ 11,390.64
2	MT/1044567-005	SMRT TAXI PTE LTD	SHC 4605T	SLZ 2993S	14/05/2019	14:20	\$ 19,823.50
3	MT/1070570-002	SMRT TAXI PTE LTD	SHD 6222X	PC 5240K	06/11/2019	10:15	\$ 5,017.40

Shirley Hiew (LKK Auto)

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) <YeoPohsuan@smrt.com.sg>
Sent: Wednesday, 20 November 2019 5:58 pm
To: Steve Chen (LKK Auto)
Cc: SUR; CS A Team
Subject: RE: SHB5063E

Hi,

Amount confirmed as per your recommendation, thanks.

Regards
Poh Suan

-----Original Message-----

From: Steve Chen (LKK Auto) [mailto:SteveChen@lkkauto.com]
Sent: Wednesday, 20 November 2019 5:53 PM
To: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)
Subject: SHB5063E

Dear Poh Suan,

We confirm the finalize \$5480.16 (P/P, before GST). 3 repair days.

Thanks.

Best Regards,
Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,
#02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Wednesday, November 20, 2019 4:11 PM
To: Steve Chen (LKK Auto)
Cc: SUR; CS A Team
Subject: SHB5063E

Hi Steve,

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/11/2019 11:02
Date Of Accident	02/11/2019 04:30
Exact Location Of Accident	GEYLANG ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB5063E
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-800000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	

Driver

Name of Driver	BENNY NG FOOK LOY
NRIC No	S1229388G
Date Of Birth	03/08/1957
Occupation	OUTDOOR
Date Of Driving Pass	19/10/1990
Driving Experience	29 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-800000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	11
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	QUEENSTOWN NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: NO. 15 COMMONWEALTH AVENUE , POSTCODE: 149725 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4719999 - FAX NO: 64715289
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20191104/2124

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMN7910A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	BENNY NG FOOK LOY
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SHB5063E
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

A - SHB5063E

B - SMN 7910A

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. On the left side, there is a vertical margin line, creating a narrow left margin. The paper appears to be from a notebook or a standard ruled document. There is no handwriting or other markings on the page.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



are true in every respect.

Driver's Signature
(If driver is not the policyholder)
Date & Time:

2/11/2019

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**

Police Station Of Origin
Queenstown N.P.C.
3 Queensway #01-03 SINGAPORE 149073
Tel No: 1800-4719999



7/20191104/2124

1 of 3

Report No: 7/20191104/2124

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made 04/11/2019 17:37	Vide Report No. G/20191102/0056	Station Diary No. 72
---	------------------------------------	-------------------------

Informant's Particulars

Name of Informant BENNY NG FOOK LOY		Address: APT BLK 4 TELOK BLANGAH CRESCENT #08-454 SINGAPORE 090004	
ID Type / ID No. NRIC NO / S1229388G	Contact No. Home/Office	Mobile: 91337773	
Nationality SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 62	Date of Birth: 03/08/1957	Type of Informant: Driver
Race: Chinese	Language: English		Institution / School Name:
Occupation: Taxi driver	Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: Yes	Date/Time of Accident: 02/11/2019 04:30	Type of Location: Straight Road
Location: Junction of Road 1 and Road 2 GEYLANG ROAD LORONG 14 GEYLANG AT THE JUNCTION OF GEYLANG ROAD AND LORONG 14 GEYLANG				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SHB5063E	Car				Seriously Damaged	0
SMN7910A	Car					0

Details of Person Involved

Any Pedestrian Involved: No	Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL	



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Queenstown N.P.C
3 Queensway #01-03 SINGAPORE 149073
Tel No. 1800-47 19999



T/20191104/2124

2 of 3

Report No. T/20191104/2124

CONTINUATION OF REPORT

Driver Name	BENNY NG FOOK LOY	ID No	S1229388G
Related Vehicle	SHB5063E (Car)	Contact No.	91337773
Hospital/Clinic	TAN TOCK SENG HOSPITAL	Class of Driving Licence & Expiry Date	Class 3 Date of Expiry: NIL
Date Treatment	02/11/2019	Date Discharge	02/11/2019
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

On the 2nd November 2019 at about 0430hrs, I was driving along Geylang Road near to Lorong 14 Geylang with my SMRT taxi bearing the vehicle number SHB5063E. It was a one way road with 3 lanes. The road surface was dry and the weather was clear. I was driving on the left lane of the road.

While nearing to the Lorong 14 Geylang, I felt an impact on my right front headlight and saw a red car. I got down from the vehicle and asked him what happened. He said he wanted to turn left to Lorong 14 Geylang. He smelt strongly of alcohol and I called for police. The police came down and brought him back. The police also asked for my SD card and I hand over to them. I wish to state that I felt giddy and pain on my neck. I was conveyed to Tan Tock Seng Hospital and was given 3 days MC from 2nd November 2019 to 4th November 2019.

 SINGAPORE POLICE FORCE			
Police Station Of Origin: Queenstown N.P.C. 1 Queenstown Road SINGAPORE 188073 Tel No: 6500-4778998		Report No: Q25067042204	
CONTINUATION OF REPORT			
Sketch Plan Informant is not able to provide sketch plan			
			
IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the <u>report number</u> as reference.			
Signature Of Officer Recording The Report D / Sgt 3 DAMIEN LEONG JUN SIAN		Signature Of Informant 	
Signature Of Interpreter Not applicable		Date/Time: 04/11/2019 17:37	
Officer In Charge Of Case: TP / GIT / Sgt 3 RASHIDAH BINTE AZMAN Contact No. 65476216		Classification Of Case	
Authentication Stamp NP168		SN 49	
			
SIGNATURE			

Case Details

Case Reference Number :

TAX/11/19/2004

Type of Repair : Accident Repair

Vehicle Registration Number : SHB5063E

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-9143-ID

Assigned By : Taxi Claims Manager Team

Insurance Company Name : NTUC Income Insurance Co-operative Ltd

Accident Date and Time : 01/11/2019 08:30 PM

Vehicle Age(In Months) : 25

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval				
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key in	Main			COVER, FR BUMPER	1	495.50	495.50	25.00	371.63	Replace	1	371.63	Replace	• / BR
One Time Key in	Main			SUPPORT, FR BUMPER RH	1	76.90	76.90	25.00	57.68	Replace	1	57.68	Replace	• / MTS BR
One Time Key in	Main			SUPPORT, FR BUMPER LH	1	82.30	82.30	25.00	61.72	Replace	0	0	Not Give	• X MTS
One Time Key in	Main			COVER, FR BUMPER RH	1	28.10	28.10	25.00	21.08	Replace	1	21.08	Replace	• / MTS
One Time Key in	Main			GRILLE, RADIATOR	1	165.00	165.00	25.00	123.75	Replace	0	0	Not Give	• X MTS
One Time Key in	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace	• / MTS
One Time Key in	Main			COVER ASSY, ENGINE	1	180.10	180.10	25.00	135.07	Replace	0	0	Not Give	• X MTS
One Time Key in	Main			COVER ASSY, ENGINE UNDER CENTER SET	1	452.80	452.80	25.00	339.60	Replace	0	0	Not Give	• X MTS
One Time Key in	Main			COVER, ENGINE UNDER CENTER	1	94.50	94.50	25.00	70.88	Replace	0	0	Not Give	• X MTS

Total Spare Part Cost 7,486.30

Surveyor Total 4,570.16

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 7,486.30

Final Sur Total 4,570.16

SMRT Recommendation											Surveyor Approval			
BQM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, ENGINE UNDER SIDE RH	1	76.90	76.90	25.00	57.68	Replace	0	0	Not Give	X NN
One Time Key In	Main			COVER, ENGINE UNDER SIDE LH	1	76.90	76.90	25.00	57.68	Replace	0	0	Not Give	X NN
One Time Key In	Main			GRILLE SUB-ASSY	1	335.60	335.60	25.00	251.70	Replace	0	0	Not Give	X NN
One Time Key In	Main			FENDER SUB-ASSY, FR, RH	1	933.10	933.10	25.00	699.83	Replace	1	699.83	Replace	/ RD
One Time Key In	Main			LINER, FR FENDER, RH	1	198.40	198.40	25.00	148.80	Replace	1	148.80	Replace	/ TN
One Time Key In	Main			PROTECTOR, FR FENDER RH	1	90.40	90.40	25.00	67.80	Replace	0	0	Not Give	X NN
One Time Key In	Main			LAMP ASSY, FOG, RH	1	810.20	810.20	10.00	819.18	Replace	1	819.18	Replace	/ BR
One Time Key In	Main			UNIT, HEADLAMP, RH	1	2,558.90	2,558.90	10.00	2,303.01	Replace	1	2,303.01	Replace	/ CR
One Time Key In	Main			WHEEL, DISC	1	1,555.10	1,555.10	25.00	1,166.32	Replace	1	0	Repair	X R
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	X NN
One Time Key In	Main			HUB & BEARING ASSY, RH & LH	2	554.20	554.20	25.00	415.65	Replace	0	0	Not Give	X NN
One Time Key In	Main			WIPER WASHER JAR	1	183.60	183.60	25.00	137.70	Replace	1	137.70	Replace	/ CRU
One Time Key In	Main			WIPER WASHER INLET	1	55.40	55.40	25.00	41.55	Replace	0	0	Not Give	X NN
Total Spare Part Cost									7,486.30	Surveyor Total		4,570.16		
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)		0		
Final Spare Part Cost									7,486.30	Final Sur Total		4,570.16		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT RH PORTION	507.00	400	
Total:			507.00	400.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO RESPRAY FRONT BUMPER LOWER GRILLE	180.00	0	
3	Main	TO RESPRAY FRONT FENDER RH	378.00	200	
4	Main	TO RESPRAY RIM	180.00	50	
Total:			1,116.00	450.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TOWING CHARGE	182.00	0	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20	/ PR
3	Main	TO REPLACE SUNDRY PARTS	100.00	20	/ PR
4	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	/ PR
5	Main	TO WASH AND VACUUM	80.00	0	
Total:			522.00	60.00	

11390.64

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	7,486.30	4,570.16
Total Labour Cost	0.00	400.00
Total Spray Painting	0.00	450.00
Other	0.00	60.00
Overall Total	7,486.30 9631.30	5,480.16
Lump Sum Repair Option		
Lump Sum Total	0.00	5,480.16
Surveyor Approved Amount		5,480.16
No of Repair Days*	5	3
Remarks		P/P repair, take before spray

Estimator Assessment(\$)

Surveyor Assessment(\$)

Surveyor Name

STEVE CHEN

Signature



Save Clear


6/11/19

Survey Date

04/11/2019

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section A - Accident Details	
Registration Number	SHB5083E
Case Reference Number	TAX/11/19/2004
Registration Date	12/10/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	BENNY NG FOOK LOY
Type of Accident	Head To Side
Accident Date and Time	2/11/2019 4:30 AM
Accident Reported Date and Time	2/11/2019 10:35 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle Is Towed Back?	Yes
Towed Back Date and Time	2/11/2019 4:31 AM
Replacement Vehicle Issued?	No
Job Card Number	24104122
Special Instruction to ARC, if any	TP/ RIGHT FRONT PORTION / TOWED \$90 + \$40 = \$130
Prepared Date and Time	2/11/2019 12:45 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$400.00
Total Spray Cost	\$1,116.00	\$450.00
Total Spare Part Cost	\$7,466.30	\$4,570.16
Total Other Cost	\$522.00	\$60.00
TOTAL COST	\$9,631.30	\$5,480.16 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Ang Bang Kien	STEVE CHEN (LKK) / NTUC
ARC / Surveyor Sign Off Date	02/11/2019 1:52 PM	04/11/2019 2:07 PM
Signature		
Remarks	P/P repair, take before spray.	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1911-0311	Invoice Number	
Quotation Date	20.11.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT RH PORTION	\$507.00	\$400.00
Total Labour	\$507.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	\$0.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$50.00
Total Spray Painting & Panel Beating	\$1,116.00	\$450.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$182.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$20.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO WASH AND VACUUM	\$80.00	\$0.00
Total Other Costs	\$522.00	\$60.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119479 62	COVER, FR BUMPER	1.00	\$495.50	25.00	\$371.63	Replace	Replace ✓
		52115470 50	SUPPORT, FR BUMPER RH	1.00	\$78.90	25.00	\$59.18	Replace	Replace ✓
		52116470 50	SUPPORT, FR BUMPER LH	0.00	\$82.30	0.00	\$0.00	Replace	Not Given X
		52127479 07	COVER, FR BUMPER RH	1.00	\$28.10	25.00	\$21.08	Replace	Replace ✓
		53112472 40	GRILLE, RADIATOR	0.00	\$185.00	0.00	\$0.00	Replace	Not Given X
		52161160 10	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace ✓
		51420470 30	COVER ASSY, ENGINE	0.00	\$180.10	0.00	\$0.00	Replace	Not Given X
		51410470 20	COVER ASSY, ENGINE UNDER CENTER SET	0.00	\$452.80	0.00	\$0.00	Replace	Not Given X
		51447470 30	COVER, ENGINE UNDER CENTER	0.00	\$94.50	0.00	\$0.00	Replace	Not Given X
		51443470 20	COVER, ENGINE UNDER SIDE RH	0.00	\$78.90	0.00	\$0.00	Replace	Not Given X
		51444470 10	COVER, ENGINE UNDER SIDE LH	0.00	\$75.90	0.00	\$0.00	Replace	Not Given X
		53101470 80	GRILLE SUB-ASSY	0.00	\$335.90	0.00	\$0.00	Replace	Not Given X
		53801470 80	FENDER SUB-ASSY, FR RH	1.00	\$933.10	25.00	\$699.83	Replace	Replace ✓

53875470 70	LINER, FR FENDER, RH	1.00	\$198.40	25.00	\$148.80	Replace	Replace	✓
53827470 50	PROTECTOR, FR FENDER RH	0.00	\$90.40	0.00	\$0.00	Replace	Not Given	X
81210470 20	LAMP ASSY, FOG, RH	1.00	\$910.20	10.00	\$819.18	Replace	Replace	✓
81145478 91	UNIT, HEADLAMP, RH	1.00	\$2,558.90	10.00	\$2,303.01	Replace	Replace	✓
42611474 50	WHEEL, DISC	1.00	\$1,555.10	100.00	\$0.00	Replace	Repair	✓
	TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X
43550470 20	HUB & BEARING ASSY, RH & LH	0.00	\$554.20	0.00	\$0.00	Replace	Not Given	X
85315471 60	WIPER WASHER JAR	1.00	\$183.60	25.00	\$137.70	Replace	Replace	✓
85319471 70	WIPER WASHER INLET	0.00	\$55.40	0.00	\$0.00	Replace	Not Given	X
Total			\$9,232.14		\$4,570.16			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

$$\begin{array}{r}
 4570.16 \\
 + 400.00 \\
 + 510.00 \\
 \hline
 5480.16
 \end{array}$$

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19019500/Esf3e2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 26-11-2019	
Code: INC4				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMN 7910A	Veh. Inspected	SHB 5063E	
Policy No.	5070670731-04	Coverage (\$)	0.00	
Claim No.	MT/1069899-002	Excess (\$)	0.00	
Assign From		Assign Date	04/11/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FU803573001	Colour	MAROON	
Odometer	256128	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/50 R15	WEST LAKE	5 mm	
L/H Front Tyre	195/50 R15	WEST LAKE	5 mm	
R/H Rear Tyre	195/50 R15	WEST LAKE	5 mm	
L/H Rear Tyre	195/50 R15	WEST LAKE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/11/2019	Inspection Date	04/11/2019	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 5063E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	COVER, FR BUMPER (DISC 25%)	BROKEN	495.50	371.63
1	SUPPORT, FR BUMPER RH (DISC 25%)	BROKEN	76.90	57.68
1	COVER, FR BUMPER RH (DISC 25%)	MISSING	28.10	21.08
10	CLIPS PIECE, FRT & RR BUMPER @\$1.50 (DISC 25%)	NECESSARY	15.00	11.25
1	FENDER SUB-ASSY, FR, RH (DISC 25%)	DENTED	933.10	699.83
1	LINER, FR FENDER, RH (DISC 25%)	TORN	198.40	148.80
1	WIPER WASHER JAR (DISC 25%)	CRUSHED	183.60	137.70
1	LAMP ASSY, FOG, RH (DISC 10%)	BROKEN	910.20	819.18
1	UNIT, HEADLAMP, RH (DISC 10%)	CUT	2,558.90	2,303.01
1	SUPPORT, FR BUMPER LH	NOT NECESSARY	82.30	-
1	GRILLE, RADIATOR	NOT NECESSARY	165.00	-
1	COVER ASSY, ENGINE	NOT NECESSARY	180.10	-
1	SET COVER ASSY, ENGINE UNDER CENTER	NOT NECESSARY	452.80	-
1	COVER, ENGINE UNDER CENTER	NOT NECESSARY	94.50	-
1	COVER, ENGINE UNDER SIDE RH	NOT NECESSARY	76.90	-
1	COVER, ENGINE UNDER SIDE LH	NOT NECESSARY	76.90	-
1	GRILLE SUB-ASSY	NOT NECESSARY	335.60	-
1	PROTECTOR, FR FENDER RH	NOT NECESSARY	90.40	-
1	TYRE	NOT NECESSARY	126.74	-
2	HUB & BEARING ASSY, RH & LH	NOT NECESSARY	554.20	-
1	WIPER WASHER INLET	NOT NECESSARY	55.40	-
1	WHEEL, DISC	TO REPAIR SEE LABOUR	1,555.10	-
			9,245.64	4,570.16
LABOUR				
PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF WHEEL, DISC.			507.00	400.00
SPRAY PAINT.			1,116.00	450.00
TOWING CHARGE.			182.00	-
TO APPLY RUST-PROOFING ON AFFECTED AREA.			100.00	20.00

Report Ref No. NS/INC19019500/Esf3e2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	20.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TO WASH AND VACUUM.		60.00	-
			2,145.00	910.00
GRAND TOTAL			11,390.64	5,480.16
RECOMMENDED COST OF REPAIRS (CONFIRMED)				5,480.16

Report Ref No. NS/INC19019500/Esf3e2

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.