

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Tham

Date: 19 May 2020

Preliminary Advice

Insured Vehicle No	: SLN5616A		
TP Vehicle No	: SMM9349M	Accident Date	: 31/10/2019
Make	: MERCEDES-BENZ C180	Assignment Date	: 04/11/2019
Date of Inspection	: 05/11/2019	Est. Duration of Repair	: 5
Inspection At	: ACE AUTOLUTION PTE LTD (KAKI BUKIT) 13 KAKI BUKIT ROAD 4, #03-29/30 BARTLEY BIZ CENTRE SINGAPORE 417807		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	22,563.07
Revised Amount	:S\$	8,200.00 (LUMP SUM)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	8,200.00
 Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.