

**ACE AUTOLUTION PTE LTD**

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel:6702 4282 Fax:6702 4202

TPMS16.

Veron.

WDD2043312632 T707

Page No. 1

Vehicle No. SMM9349M MERCEDES C180

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR ADJUSTMENT
	<u>PARTS (LIST ITEMS)</u>			
1	FRONT BUMPER <i>Distorted</i>		1391.00	✓
2	FRONT BUMPER SIDE BRACKET LH & RH @ \$135.00 <i>RH cracked</i>		260.00	<i>135</i>
1	FRONT BUMPER LOWER BRACKET RH <i>Best</i>		110.00	✓
1	FRONT BUMPER LOWER GRILLE <i>Garnish (Inner) Delcd</i>		286.00	✓
1	FRONT BUMPER FOGLAMP GARNISH RH <i>cracked</i>		155.00	✓
1	FRONT BUMPER LOWER LAMP RH <i>cracked</i>		325.00	✓
1	FRONT BUMPER LOWER CHROME <i>cracked</i>		210.00	✓
1	FRONT BUMPER TOW COVER <i>new</i>		110.00	+
1	FRONT BUMPER LOWER LAMP CHROME RH <i>new</i>		195.00	+
1	FRONT BUMPER REINFORCEMENT <i>Best</i>		855.00	<i>678</i>
1	FRONT HEADLAMP RH <i>cracked</i>		3345.10	<i>1610</i>
2	FRONT HEADLAMP CONTRL UNIT LH & RH @ \$571.50 <i>new</i>		1143.00	+
1	FRONT BONNET <i>Bye</i>		1999.27	+
1	FRONT RADIATOR GRILLE STAR HOLDER <i>new</i>		75.60	+
1	FRONT RADIATOR GRILLE TRIM <i>new</i>		198.00	+
1	FRONT RADIATOR GRILLE <i>new cracked</i>		658.00	+
1	FRONT RADIATOR GRILLE MERCEDES STAR <i>new</i>		138.00	+
1	FRONT SUPPORT PANEL <i>new</i>		740.10	+
2	FRONT FENDER LH & RH @ \$925.60 <i>RH Delcd.</i>		1851.20	<i>925.60</i>
2	FRONT FENDER INNER SILED LH & RH @ \$125.00 <i>RH Delcd</i>		250.00	<i>125</i>
1	FRONT CROSS MEMBER <i>new</i>		436.50	+
1	FRONT SHOCK ABSORBER RH <i>Best</i>		355.00	✓
2	FRONT KNUCKLE ARM RH <i>Best</i>		342.00	✓
2	FRONT WHEEL HUB LH & RH @ \$295.10 <i>RH 2nd</i>		590.20	<i>295.10</i>
2	FRONT WHEEL HUB BEARING LH & RH @ \$221.00 <i>RH new</i>		442.00	<i>221.</i>
2	FRONT CONTROL ARM LH & RH @ \$166.00 <i>RH Best</i>		332.00	<i>166.</i>
1	FRONT UNDERCARRIAGE COVER <i>torn</i>		185.00	✓
1	FRONT LOWER ARM RH <i>Best</i>		135.00	✓
1	FRONT COOLANT TANK <i>new</i>		125.00	+
1	FRONT TIE ROD ARM RH <i>new</i>		250.00	+
1	FRONT BAR LINKAGE RH <i>new</i>		246.00	+
1	FRONT ABS SENSOR		155.00	+
			17375.97	
less 10%			1737.60	10%
			15638.37	

SPECIAL ITEMS			
1	FRONT FENDER INNER SHIELD CLIPS <i>16</i>	70.00	<i>30</i>
1	FRONT RIM RH <i>cut</i>	1674.00	<i>1200</i>
1	FRONT TYRE RH <i>16 per</i>	350.00	<i>x</i>
1 SET	FRONT BUMPER CLIPS <i>100</i>	80.00	<i>30</i>
1 SET	FRONT FENDER CLIPS <i>24 n</i>	100.00	<i>x.</i>
Total Parts		17912.37	

1260.



ACE AUTOLUTION PTE LTD
13 Kaki Bukit Road 4 Bartley Biz Centre #03-29
Singapore 417807
Tel:6702 4282 Fax:6702 4202

Page No. 2

Vehicle No. SMM9349M MERCEDES C180

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	1800.00	600
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1400.00	600
3	To remove and refix wiring at damaged areas	180.00	30
4	To perform anti rust treatment on affected areas	150.00	x
6	To remove and replace undercarriage part	200.00	x
7	To conduct full computerised wheel alignment	120.00	80
8	To remove and replace front headlamp beam	80.00	30
9	To clear fault code with diagnostic computer and reset to Mercedes specification .	250.00	100
Labour Total :		4180.00	1440
TOTAL (PARTS & LABOUR):		22092.37	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian L
L/S 05/11/12
05 days

total : 10301.13
L/S. 8-21C

8-21C