

ASS. REC. BY:

REF: CS1MSG 19019509 / U4f3

Special Instruction:

Surveyor: Marcus ASSIGNMENT (Office)

From (Person): Pauline Tham of MSIG Date/Time: 5.11.19 10

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMD 740Y Insured: SMG 566T

at Workshop m/s Sm Spray Painting Tel: 9622 8346

of 1 Kaki Bukit Ave 6 #01-13

Policy No: A24110468 AVW Claim No: 610288

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 1.11.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement: _____

Date/Time: 5.11.19 11.19 a.m Person Contacted: wendy Vehicle IN / OUT

Date/Time	Action/Instruction
	(✓) Estimate Input: <u>140 Tax # 25 Kaki Bukit road 4 #08-30</u> <u>Kaki Bukit</u>
	<u>SMD 740Y - X</u>
	<u>SMG 566T - X</u>
	<u>Revised via menimen preli</u>

Minivan

ASS. REC. BY:

mcus

File:

MS14/
ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMD 740Y

at Workshop n/s

SM Spg

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

74k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

039i

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMD 740Y

Yr Regn:

613

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Volkswagen Golf GTi.c.c 1984

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading

119046

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WVWZZZAU2DW156412

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / STD A/Rim or

Tyre Size:

F: 225/40 R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

1/11/19

D.O.I.

5/11/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear 1/5

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LTA 51793 3yrs. 7ml. dep 16

8/11/19 contact n/s → 2800 with tag wendy. (Red. 12711; 81%)
(Red.)

RECEIVED 11 NOV 2019

8/11/2019

Date/Time, File Pass to?

: Preli. Report

all Typst

: Final Report

Date/Time, File Return to?

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

200

Photos

11

Other

TOTAL

211

Add Fee:

: Site Insp (\$

: Interview (\$

: Tech. Invs (\$

: Wisel end (\$

Report Formist:

TP

Estimate Form / 1/2/1/1/1

2800/-

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Tham

Date: 06 Nov 2019

Preliminary Advice

Insured Vehicle No	: SMG566T	Accident Date	: 01/11/2019
TP Vehicle No	: SMD740Y	Assignment Date	: 05/11/2019
Make	: VOLKSWAGEN GOLF GTI	Est. Duration of Repair	: 4.00
Date of Inspection	: 05/11/2019		
Inspection At	: SM SPRAY PANTING (HQ) 1 KAKI BUKIT AVENUE 6, #01-13 AUTOBAY SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,511.00
Revised Amount	:S\$	3,508.20
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,508.20
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Nov 2019 15:30		05 Nov 2019 10:38 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	TANG TECK HOCK, ID: S1809169J	
Main Claimant:	CHUA WEE MENG PATRICK, ID: S1260039I	
Vehicle Reg. No.:	SMD740Y	Date of Loss: 01/11/2019 14:00 - :59 [76 Months and 12 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 610288	Policy/Cover Note No.: A29110468AVW (Comprehensive) Coverage: 30/11/2018 - 29/11/2019
Vehicle Reg. No. (Insured):	SMG566T	Policy No. (Claimant): Excess: S\$4,500.00
Repairer:	Sm Spray Panting (HQ) 1 Kaki Bukit Avenue 6, #01-13 Autobay, 417883 Kaki Bukit - Tel: 98228346	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 06/11/2019]	
Driver/Custodian (Insured):	WYBERT TANG SUAN YAN (/ Male), NRIC: S9644640C Email:	
Adj Asg. Remarks:	on WP. CAR IN. Liab: clear. Agree on SJE. Assign: Marcus Chua from LKK Auto Consultants Pte Ltd. Contact: Wendy @ 6384 1755 / 1766.	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)


golf gti

Price Range

Depreciation

2013

Vehicle Type



Submit

Advanced Search

Home » Used Cars » Direct Owners » Volkswagen Golf GTI 5DR

Volkswagen Golf GTI 5DR

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

DIRECT OWNER

Price \$79,888**Depreciation** \$16,470 /yr
View models with similar depre**Reg Date** 29-Aug-2013
(3yrs 9mths 23days COE left)**Mileage** 52,500 km (8.5k /yr)**Manufactured** 2013**Road Tax** \$1,194 /yr**Transmission** Auto**Dereg Value** \$51,783 as of today (change)**OMV** \$33,669**COE** \$77,600**ARF** \$34,137**Engine Cap** 1,984 cc**Power** 162.0 kW (217 bhp)**Curb Weight** 1,370 kg**No. of Owners** 2**Type of Vehicle** Sports Car**Features**

Latest VW EA888 Gen3 TSI Engine, 6 Speed DSG Transmission. Original MK7.5 Active Info Display (Virtual Cockpit) With 9.2" Infotainment. Carbon Bonnet View specs of the Volkswagen Golf GTI (2013-2017)

Accessories

Original Rays ZE40 TimeAttack Rim. Full Maxton Kit. Original AP-Racing Radical 2 Brake Kit. Fully Serviced And Maintained By MTR Workshop.

Description

Low Mileage, Serviced Every 8,000km Mileage. DSG Oil Servicing Done Every 30,000km. Newly Sprayed 7.5 White Silver Paint Done In July 2019. New GTI Tartan Seat Cover<1 Week. Accident Free Car. One And Only Mk7.5 Converted GTI. Reliable And Powerful Car To Be Driven For A Long Time, Potential COE Renewal Car. View To Believe. Disclaimer: Rims And Brakes Are To Be Dekitted Unless Price Is Met.

Category

PARF Car, Direct Owner Sale, Low Mileage Car

Status

Available

Resources**Vehicle Evaluation**

Afraid of lemons? Request to have this car evaluated professionally. [Find out more](#)

**Car Valuation - Free**

Find out the market value of your existing car for free. [Get started](#)

Posted on: 02-Nov-2019 | Last Updated on: 04-Nov-2019
[Compare](#)



Preferred Viewing Area

Shortlist

Compare

Add note

Report Error

More Actions

Seller Information**Contact Person(s)** Ken**Contact No.** 90218126**Enquiry** [✉ Contact Seller](#)**ESSENTIAL TRANSACTION FORMS**

» Indemnity form » Sales agreement

» Receipt » Hand-over form

» Ownership Transfer



GET HELP WITH
PAPERWORK

sgCARMART
CONNECT

sgCarMart Connect handles your transaction paperwork - send us your completed Sales Agreement, and we'll help with **Car Loans, Insurance, Payments & Ownership Transfer**. FREE for all sgCarMart Advertised Vehicles.

[Upload your Sales Agreement](#)

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	039I
Vehicle Details	
Vehicle No.:	SMD740Y
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Nov 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	GOLF GTI 2.0 TSI 5G19TY
Primary Colour:	Black
Manufacturing Year:	2013
Engine No.:	CHH003786
Chassis No.:	WWZZZAUZDW156412
Maximum Power Output:	162.0 kW (217 bhp)
Open Market Value:	\$33,661.00
Original Registration Date:	20 Jun 2013
First Registration Date:	20 Jun 2013
Transfer Count:	2
Actual ARF Paid:	\$34,126.00 <i>17063</i>
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Jun 2023
PARF Rebate Amount:	\$22,181.00
Intended COE Rebate Details	
COE Expiry Date:	19 Jun 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$81,751.00
COE Rebate Amount:	\$29,612.00
Total Rebate Amount:	\$51,793.00

The information contained herein is correct as at 05 Nov 2019

OK

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19019509/UTF3N2
Date: 12/11/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A29110468AVW
Claimant Vehicle No :	SMD740Y	Insured Vehicle No :	SMG566T
Date of Loss:	01/11/2019	Nature of Claim:	TP Claim No: 610288

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD740Y	Engine No:	CHH003786
Make & Model:	VOLKSWAGEN GOLF GTI, 2.0 TSI (A)	Chassis No:	WWZZZAUZDW156412
Reg. Date:	20/06/2013 (Man. Year: 2013)	Odometer:	119046 km
Colour:	Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/40R18	Rear Tyre Size:	225/40R18
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	12,871.00	2,198.20	10,672.80	82.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,640.00	1,310.00	1,330.00	50.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,511.00	3,508.20	12,002.80	77.38
Approved Total (Overridden) (\$\$)		2,800.00		
	(\$\$)	15,511.00	2,800.00	12,711.00
	+ GST 7.00/7.00% (\$\$)	1,085.77	196.00	889.77
	Nett Amount (\$\$)	16,596.77	2,996.00	13,600.77

INSPECTION

Date of Assignment:	05/11/2019	
Date Inspected:	05/11/2019	Inspected At:
		Sm Spray Panting (HQ) 1 Kaki Bukit Avenue 6, #01-13 Autobay Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 12 Nov 2019)
Parts: 144	VOLKSWAGEN GOLF GTI 2.0 TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMD740Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	820.00 FL	*820.00 FL
2	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	110.00 FL	*- FL
3	1		*REAR BUMPER SIDE RETAINER LH	Bent	110.00 FL	*45.00 FL
4	1		*REAR BUMPER LOWER SPOILER	Deformed/Cut	300.00 FL	*300.00 FL
5	1		*REAR BUMPER REFLECTOR RH	Not Necessary	65.00 FL	*- FL
6	1		*REAR BUMPER REFLECTOR LH	Scratched	65.00 FL	*65.00 FL
7	1		*REAR BUMPER BRACKET RH	Not Necessary	75.00 FL	*- FL
8	1		*REAR BUMPER BRACKET LH	Not Necessary	75.00 FL	*- FL
9	1		*REAR BUMPER REINFORCEMENT	Bent	500.00 FL	*481.00 FL
10	1		*REAR BUMPER INNER SPONGE	Not fitted	85.00 FL	*- FL
11	1		*REAR TAILGATE	Repair	1,470.00 FL	*- FL
12	1		*TAILGATE HINGE RH	Not Necessary	20.00 FL	*- FL
13	1		*TAILGATE HINGE LH	Not Necessary	20.00 FL	*- FL
14	1		*TAILGATE LOCK	Not Necessary	250.00 FL	*- FL
15	1		*TAILGATE EMBLEM	Not Necessary	100.00 FL	*- FL
16	1		*TAILGATE GTI EMBLEM	Necessary	95.00 FL	*95.00 FL
17	1		*TAILGATE INNER BOARD	Not Necessary	310.00 FL	*- FL
18	1		*REAR END PANEL	Repair	900.00 FL	*- FL
19	1		*REAR END PANEL TOP GARNISH	Not Necessary	230.00 FL	*- FL
20	1		*SPARE TYRE PANEL	Not Necessary	1,400.00 FL	*- FL
21	1		*SPARE TYRE TOP BOARD	Not Necessary	350.00 FL	*- FL
22	1		*REAR EXHAUST LH CHROME	Bent	990.00 FL	*250.00 FL
23	1		*REAR EXHAUST RH	No such part	990.00 FL	*- FL
24	1		*REAR EXHAUST MOUNTING LH	Not Necessary	40.00 FL	*- FL
25	1		*REAR EXHAUST MOUNTING RH	Not Necessary	40.00 FL	*- FL
26	1		*BOOTLID LAMP LH	Not Necessary	350.00 FL	*- FL
27	1		*BOOTLID LAMP RH	Not Necessary	350.00 FL	*- FL
28	1		*REAR TAILLAMP LH	Not Necessary	380.00 FL	*- FL
29	1		*REAR TAILLAMP RH	Not Necessary	380.00 FL	*- FL
30	1		*REAR LH FENDER	Repair	1,700.00 FL	*- FL
31	1		*REAR LH FENDER INNER SHIELD	Not Necessary	160.00 FL	*- FL
32	1		*REAR LH FENDER INNER TRIM	Not Necessary	250.00 FL	*- FL
33	1		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	20.00 FS	*- FS
34	1		*REAR WINDSCREEN GLASS SEALANT	Not Necessary	60.00 FS	*- FS
35	1		*REAR NUMBER PLATE	Serviceable	45.00 FS	*- FS
36	1		*REAR BUMPER SENSOR	Shorted	280.00 FS	*200.00 FS
37	1		*REAR BUMPER CLIP	Necessary	45.00 FS	*45.00 FS
38	1		*FENDER INNER SHIELD CLIP	Not Necessary	45.00 FS	*- FS
39	1		*BOOT LID INNER TRIM CLIPS	Not Necessary	45.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,520.00	2,301.00
- List Item Discount on L Items 5.00/5.00% (\$\$)	649.00	102.80

Total Parts (\$\$)	12,871.00	2,198.20
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
-----	-----	----------	-------------	-----------	------------	--------

Report was unsubmitted during this print-out.						
---	--	--	--	--	--	--

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE AND REFIT REAR WINDSCREEN GLASS	New	100.00	0.00
2	TO REMOVE AND REFIT, STRAIGHTEN AND RE-ADJUST EXHAUST PIPE AND REAR EXHAUST SILENCER AND MOUNTINGS	New	100.00	80.00
3	TO REMOVE AND REFIT REAR BUMPER SENSOR	New	80.00	50.00
4	TO TRANSFER REAR TAILGATE	New	100.00	0.00
5	TO DISCONNECT AND RECONNECT, CHECK ELECTRICAL WIRING HARNESS WIRE, SOCKETS, REPLACE DAMAGED PARTS	New	80.00	30.00
6	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	1,200.00	550.00
7	TO CARRY-OUT BODY CAVITY PRESERVATION	New	100.00	0.00
8	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS	New	80.00	0.00
9	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	800.00	600.00
Gross Labour Cost (S\$)			2,640.00	1,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >