

**ACE AUTOLUTION PTE LTD**

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel:6702 4282 Fax:6702 4202

Page No. 2

Vehicle No. SLV2650C MERCEDES GLA180

S/N	DESCRIPTION	REPAIRER'S ESTIMATE	OUR ASSESSMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	1200.00	\$00
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1000.00	700
3	To remove and refix wiring at damaged areas	180.00	30
4	To perform anti rust treatment on affected areas	150.00	X
5	To remove and replace rear exhaust silencer assembly , realign and check exhaust system function	120.00	X
6	To remove & replace parking sensor	120.00	50
7	To conduct full computerised wheel alignment	120.00	X
8	To clear fault code with diagnostic computer and reset to Mercedes specification .	250.00	X
Labour Total :		3140.00	1280
TOTAL (PARTS & LABOUR):		10668.18	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 6556.73
w/s: 5.2K ✓
040mgs.
5.2K



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel:6702 4282 Fax:6702 4202

TP China.

Page No. 1

Denise

Vehicle No. SLV2650C MERCEDES GLA180

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE (S\$)		SURVEYOR ADJUSTMENT	
PARTS (LIST ITEMS)						
1	FRONT BUMPER <i>dent</i>	<i>5829.70</i> <i>5246.73</i>		1015.30	<i>✓</i>	
1	FRONT BUMPER FOGLAMP COVER LH <i>new</i>			95.00	<i>x</i>	
1	FRONT HEADLAMP LH <i>cracked</i>			2455.00	<i>✓</i>	
1	FRONT FENDER LH <i>Dented</i>			1050.00	<i>✓</i>	
1	FRONT FENDER WHEEL ARCH GARNISH LH <i>at</i>			225.00	<i>✓</i>	
1	FRONT FENDER INNER SHIELD LH <i>Detained</i>			235.40	<i>✓</i>	
1	FRONT DOOR LH <i>Repair</i>			1153.50	<i>x</i>	
1	FRONT DOOR HINGE LH <i>new</i>			110.00	<i>x</i>	
1	FRONT SIDE MIRROR LH <i>at</i>			849.00	<i>✓</i>	
1	FRONT SIDE MIRROR COVER LH <i>Repair</i>			182.00	<i>x</i>	
				7370.20		
			less 10%	737.02	10%	
				6633.18		
SPECIAL ITEMS						
2	PARKING SENSOR @\$310.00 <i>2 new</i>	<i>30</i>		620.00	<i>x</i>	
1 SET	PARKING SENSOR WIRE HARNESS			175.00	<i>x</i>	
1 SET	FRONT BUMPER CLIPS <i>new</i>			100.00	<i>x</i>	
1	FRONT FENDER INNER SHIELD CLIPS <i>new</i>			100.00	<i>30</i>	
Total Parts				7528.18		