

ABWIN SERVICE PTE LTD

8 KAKI BUKIT AVENUE 4 - GATE 2
 #07-48 PREMIER @ KAKI BUKIT SINGAPORE 415875
 Tel: 67139400 Fax: 67139415
 Email: servicecentre@abwinm9.com Website: www.abwinm9.com
 Company Reg. No: 201318685G GST Reg. No: 201318685G



not added here
n/s
4/5
6/11/19
Take the other way
 Tel: 62563561

ESTIMATED COST: HQQ000154

TO : INDIA INTERNATIONAL INSURANCE PTE LTD
ATTN : MOTOR CLAIM DEPARTMENT

DATE : 05-NOV-2019
 MAKE : SUBARU
 MODEL : SUBARU XV 1.6I AWD CVT
 CHASSIS NO : JF1GP3KC5EG146099
 ENGINE NO : FB161256871
 SERVICE ADVISOR : GERINE
 PAGE : 1 OF 2

SKP1728M
ASTIQUE DESIGN PTE LTD
 37 DEFU LANE 9
 DEFU INDUSTRIAL ESTATE
 SINGAPORE 539277
 CONTACT NO : 86662780

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
-----	-------------	---------------------	--------------------

LIST ITEM

1	REAR BUMPER	<i>D.S</i> 414.00	✓
1	REAR BUMPER SIDE RETAINER LH	<i>11</i> 14.40	✓
1	REAR BUMPER SIDE RETAINER RH	<i>11</i> 14.40	X
1	REAR BUMPER REINFORCEMENT	218.70	?
1	REAR BUMPER BRACKET LH	22.40	?
1	REAR BUMPER BRACKET RH	22.40	?
1	TAILGATE	<i>no/rel</i> 910.20	✓
1	TAILGATE LOCK	<i>11</i> 200.30	X
1	REAR END PANEL	388.20	?
Sub Total		<i>202</i> 2,205.00	0.00

SPECIAL NETT

10	REAR BUMPER CLIPS	<i>nu</i> 50.00	✓
1	REAR END PANEL SEALANT	50.00	?
1	REAR WINDSCREEN SEALANT	<i>nu</i> 50.00	40
2	REVERSE SENSOR	<i>subst</i> 500.00	X
1	TAILGATE SEALANT	<i>Repld</i> 50.00	X
Sub Total		700.00	0.00

LABOUR

1	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS	800.00	<i>480</i>
1	TO SPRAY PAINT ON AFFECTED AREAS	800.00	<i>600</i>
1	TO DISMANTLE, REPLACE AND/OR REPAIR REAR TAILGATE COMPONENTS	150.00	<i>60</i>
1	TO DISMANTLE AND REPLACE REAR WINDSCREEN COMPONENTS	150.00	<i>120</i>
1	TO DISMANTLE, REPLACE AND/OR REPAIR REVERSE SENSOR & TESTING	100.00	<i>50</i>

ABWIN SERVICE PTE LTD

8 KAKI BUKIT AVENUE 4 - GATE 2
 #07-48 PREMIER @ KAKI BUKIT SINGAPORE 415875
 Tel: 67139400 Fax: 67139415
 Email: servicecentre@abwinm9.com Website: www.abwinm9.com
 Company Reg. No: 201318685G GST Reg. No: 201318685G

**ESTIMATED COST: HQQ000154**

TO : INDIA INTERNATIONAL INSURANCE PTE LTD
ATTN : MOTOR CLAIM DEPARTMENT

DATE : 05-NOV-2019
 MAKE : SUBARU
 MODEL : SUBARU XV 1.6I AWD CVT
 CHASSIS NO : JF1GP3KC5EG146099
 ENGINE NO : FB161256871
 SERVICE ADVISOR : GERINE
 PAGE : 2 OF 2

SKP1728M
ASTIQUE DESIGN PTE LTD
 37 DEFU LANE 9
 DEFU INDUSTRIAL ESTATE
 SINGAPORE 539277
 CONTACT NO : 86662780

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
1	TO APPLY UNDERCOATING FOR RUST PROOFING	150.00	40
1	TO DISMANTLE & REFIX INTERIOR UPHOLSTERY	120.00	60
1	TO CHECK WIRING	120.00	20
Sub Total		2,390.00	0.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

SUB-TOTAL	5,295.00	0.00
GST - 7 %	370.65	0.00
TOTAL	5,665.65	0.00

ABWIN SERVICE PTE LTD

Prepared By