

ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com



Zoom Autowerks Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- Parts damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

6 November 2019

Not Acknowledged

d/s 4000

Hdy.

5/11/19 Take up to Hdy. again

REG NO.: SDL 9000 E

MAKE/MODEL: TOYOTA VELLFIRE

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	<u>LIST ITEMS</u>	
1	Rear windscreen inner seal	85.00
1	Rear tailgate	1,593.98
1	Rear tailgate lock	350.90
1	Rear tailgate rubber	300.40
1	Rear tailgate "Vellfire" emblem	75.76
1	Rear end panel	755.60
1	Rear end panel inner garnish <i>side</i>	265.90
1	Rear bumper	1,575.88
1	Rear bumper side <i>o/s</i>	685.00
1	Rear bumper side bracket <i>o/s</i>	120.10
1	Rear bumper reflector	85.70
1	Rear bumper side retainer	115.33
2	Rear bumper PDC sensors	1,040.60
1	Rear bumper tow hook cover	45.00
1	Rear smart keyless keyless sensor	235.00
1	Rear fender	1,557.30
		\$ 8,887.45
	Less 25%	\$ 2,221.86
		\$ 6,665.59

SPECIAL NETT ITEMS

1	Rear windscreen sealant	80.00
1	Rear bumper clip (1 set)	50.00
		\$ 130.00

LABOUR CHARGES

S/N	DESCRIPTION	AMT(\$)
1	To remove, replaced damaged lamps and check up rear wiring.	80.00
2	To remove and refit inner garnishes.	150.00
3	To remove and refit rear reverse sensor.	150.00
4	To transfer rear tailgate mechanism and wiring assembly.	120.00
5	To remove and refit rear windscreen glass.	180.00
6	To apply undercoating.	150.00
7	Panel beating.	1,500.00
8	To re-spray painting on the affected areas.	1,400.00
		\$ 3,730.00

GRAND TOTAL :

\$ 10,525.59

p 4532.32
257
3399.24
5029.24