

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____ **After-Paint:** _____
 Contacts : _____

Vehicle Nos : **SGG 6609 K**
 Model : Honda Edix
 Year : _____
 Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	Tailgate	1	\$ 1,168.90	\$ 1,168.90 ✓1,168.90	DD✓
2	Tailgate inner lock	1	\$ 288.60	\$ 288.60	} NDX
3	Tailgate striker	1	\$ 48.90	\$ 48.90	
4	Tailgate weatherstrip	1	\$ 165.60	\$ ✓165.60	TN✓
5	Tailgate inner trim board	1	\$ 296.30	\$ 296.30	NDX
6	Tailgate inner handle	1	\$ 36.00	\$ 36.00	NDX
7	Tailgate outer chrome garnish	1	\$ 198.00	\$ 198.00	NDX
8	Tailgate no plate lamp	2	\$ 88.50	\$ 177.00	NDX
9	Tailgate windscreen moulding	1	\$ 90.50	\$ ✓90.50	NEC✓
10	Rear bumper	1	\$ 680.90	\$ ✓680.90	BR✓
12	Rear bumper side retainer	2	\$ 48.60	\$ ✓97.20	NEC✓
13	Rear bumper bracket	2	\$ 39.60	\$ ✓79.20	BT✓
14	Rear end panel	1	\$ 525.60	\$ ✓525.60	DD✓
15	Rear end panel top garnish	1	\$ 124.80	\$ ✓124.80	DL✓
17	Taillamp rh	1	\$ 386.00	\$ ✓386.00	BR✓
18	Taillamp lower bracket rh	1	\$ 48.40	\$ 48.40	NDX
19	Taillamp base panel rh	1	\$ 138.00	\$ 138.00	NDX
20	Taillamp lh	1	\$ 386.00	\$ 386.00	NDX
21	Taillamp bracket lh	1	\$ 48.40	\$ 48.40	NDX
22	Taillamp panel lh	1	\$ 138.00	\$ 138.00	NDX
23	Exhaust pipe	1	\$ 728.20	\$ 728.20	} NDX
24	Exhaust pipe mounting	2	\$ 38.20	\$ 76.40	
25	Exhaust pipe heat sheild	1	\$ 156.00	\$ 156.00	
Parts Sub Total :				\$ 6,082.90	
20% Discount				\$ 1,216.58	
PARTS TOTAL :				\$ 4,866.32	

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$	
1	Sundries	1	\$ 60.00	\$ 60.00	NNX
11	Rear bumper clips	1	\$ 50.00	\$ 30.00 50.00	NECV
16	Rear end panel top garnish clips	1	\$ 50.00	\$ 30.00 50.00	NECV
2	Tailgate inner trim board clips	1	\$ 50.00	\$ 30.00 50.00	NECV
3	Tailgate outer garnish clips	1	\$ 50.00	\$ 30.00 50.00	NECV
4	Tailgate windscreen clips	1	\$ 50.00	\$ 30.00 50.00	NECV
5	Tailgate primer and cleaner	1	\$ 80.00	\$ 80.00	NNX
6	Tailgate windscreen sealant	1	\$ 100.00	\$ 50.00 100.00	NECV
7	Rear no plate with cover	1	\$ 80.00	\$ 80.00	NNX
8	Rear bumper reverse sensor	2	\$ 200.00	\$ 200.00 400.00	NECV
9	Rear end panel sealant	1	\$ 100.00	\$ 60.00 100.00	NECV
10	Wrap	1	\$ 800.00	\$ 300.00 800.00	NECV
11	Taillamp clips	1	\$ 50.00	\$ 30.00 50.00	NECV
12	Taillamp inner seal	2	\$ 80.00	\$ 160.00	NNX
13	Spare tyre panel sealant	1	\$ 100.00	\$ 100.00	NNX
SPECIAL NETT TOTAL :				\$ 790.00 2,180.00	

Nos.	LABOUR	S\$
1	R&R tailgate component	\$ 50.00 100.00 ✓
2	R&R rear windscreen	\$ 120.00 250.00 ✓
3	R&R upholstery	\$ 180.00
4	R&R exhaust pipe assy	\$ 250.00
5	R&R reverse sensor	\$ 60.00 80.00 ✓
6	Disconnect wire harness to facilitate repair, reconnect and check function	\$ 30.00 80.00 ✓
7	Panel beat	\$ 800.00 1,500.00
8	Rust proofing	\$ 50.00 150.00 ✓
9	Spray painting	\$ 800.00 1,500.00
LABOUR TOTAL :		\$ 4,090.00

TCCim
 5/11/19
 1500 hrs

Resurvey 6/11/19
 TCCim
 1530 hrs
 L/s repair
 Repair days 5

PARTS TOTAL : \$ 4,866.32
 SPECIAL NETT TOTAL : \$ 2,180.00
 LABOUR TOTAL : \$ 4,090.00
GRAND TOTAL : \$ 11,136.32

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: