



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

AlGAsia Insured's Veh No : SLV3528S

Date of Accident : 01 November 2019

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Miss Lim Lucy

Date : 06 November 2019

Estimate To Repair SKL63A - Maserati Grancabrio
Chassis No : ZAMKM45C000053232

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	front bumper <i>cut / punctured</i>	\$ 5,450.00
02	1 pc	front bumper side retainer left <i>NH</i>	\$ 150.00
03	1 pc	front bumper side lower grille left <i>NH</i>	\$ 520.00
04	1 pc	left front fender <i>ray</i>	\$ 3,500.00
			\$ 9,620.00
		Less 10 %	\$ 962.00
			\$ 8,658.00
		<u>LABOUR & MISC. CHARGES</u>	
01		To check electrical lighting concerned.	\$ 60.00
02		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,000.00
03		Putty and spray painting of the affected portion. <i>1100</i>	\$ 1,500.00
			\$ 2,560.00
		Total	\$ 11,218.00

04/11/2019 @ 1535hr

NH Arnold

L/Sund 3 days.

Ray

LKK Auto

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: