

ASS. REC. BY:

REF: CS/AG1/901952/Hq f302

Special Instruction:

Surveyor: Hock Ann

ASSIGNMENT (Office)

From (Person): Ivy Ratilla

of

AG1

Date/Time: 5.11.19 1.21pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKU 9582L

Insured:

SLE 6349L

at Workshop m/s

Teamwork Garage

Tel:

68442475

of

Blk 53 ub Ave 1 #01-24

Policy No:

Claim No:

C10004492

Sum Insured:

Excess:

Make of Veh:

D.O.A. 3.11.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

5.11.19 2.43pm

Person Contacted:

Shy Shan

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKU 9582L - NA / INCL 19019486 / 2K RDA - 03/11/2019
	SLE 6349L - NA / INCL 19019483 / 2K RDA - 03/11/2019

s/n/n

ASS. REC. BY:

H. ANN

REF:

AG1

ASSIGNMENT

From: _____ Date: 5.11.2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKU 9582L

at Workshop m/s Teamwork
of 51 ub Anc1 # 01-25

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

my

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKU 9582L Yr Regn: 25/08/2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: T. corolla Altis C.C. 1598

Colour: m - Gray / Blue A/C: Insured / Std / NI / NA

Sp. Reading: 386 476 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: M2053 REH 104537040

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55/R16

R: 205/55/R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 5 mm

L/Bal. 5 mm

D.O.A. 3/11/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 5 mm

L/Bal. 5 mm

D.O.I. 5/11/19

Team work

Date / Time

Action / Instruction

* Finalised total 4/sump Amt cor \$ 4700,000 8 Days

* SKU 9582L

Agree by workshop Team work person (Damen)

do sumit

(Red \$ 18718.83, 79%)

by Bacher.

MV - 54000

* NON complete file.

PV - 45960

NV - 8000

RECEIVED 16 DEC 2019

Date/Time, File Pass to?

Prel. Report

1) 12/12/2019

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 8

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

450

Add Fee: Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

Rep. Form:

Lump Sum / Fee:

TP

4700

Summer Lee (LKK Auto)

From: Ivy Ratilla <ivy.r@budgetdirect.com.sg>
Sent: Tuesday, 5 November, 2019 1:21 PM
To: Admin-D (LKKAuto)
Cc: SUR; Loganathan Agoram
Subject: FW: OUR REF : 1911-05 // YOUR REF : SLE6349L ACCIDENT INVOLVINGSLE6349L AND SKU9582L || C10004492
Attachments: image001.png; image002.jpg; image003.jpg

Hi Team,

We would like to arrange TP PRS for SKU9582L.


Workshop information:
Teamwork Garage Pte Ltd
Blk 53 Ubi Avenue 1
#01-24
Paya Ubi Industrial Park
Singapore 408934
Tel: 6844 2475
Fax: 6844 2474

Please confirm. Thank you.

Regards,

Ivy Ratilla
Executive, Claims Admin

T +65 6540 2185
F +65 6725 0853
E ivy.r@budgetdirect.com.sg



Customer Care +65 6221 2111
Claims +65 6221 2199
Claims (Int.) +65 6540 2199

190 Clemenceau Avenue, #03-01
Singapore Shopping Centre
Singapore
239924
budgetdirect.com.sg



Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as **Budget Direct Insurance**.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

From: TEAMWORK <claims@teamworkgarage.com>

Sent: Tuesday, 5 November 2019 12:35 PM

To: Ivy Ratilla <ivy.r@budgetdirect.com.sg>; Claims <claims@budgetdirect.com.sg>

Cc: Loganathan Agoram <loganathan.a@budgetdirect.com.sg>; TEAMWORK <claims@teamworkgarage.com>

Subject: RE: OUR REF : 1911-05 // YOUR REF : SLE6349L ACCIDENT INVOLVING SLE6349L AND SKU9582L || C10004492

WITHOUT PREJUDICE

Dear Ivy,

We agreed on LKK.

Thank you and have a nice day.

Regards,

Shu Shan

Teamwork Garage Pte Ltd
Blk 53 Ubi Avenue 1
#01-24
Paya Ubi Industrial Park
Singapore 408934
Tel: 6844 2475
Fax: 6844 2474

From: TEAMWORK <claims@teamworkgarage.com>

Sent: Monday, 4 November 2019 6:38 PM

To: Claims <claims@budgetdirect.com.sg>

Cc: TEAMWORK <claims@teamworkgarage.com>

Subject: OUR REF : 1911-05 // YOUR REF : SLE6349L ACCIDENT INVOLVING SLE6349L AND SKU9582L

WITHOUT PREJUDICE

OUR REF : 1911-05

YOUR REF : SLE6349L

Dear Sir / Madam,

PRE-REPAIR INSPECTION FOR SKU9582L

ACCIDENT INVOLVING SLE6349L AND SKU9582L ON 03.11.2019.

We refer to the above matter and enclosed herewith our client's GIA report and notification of Pre-repair inspection for your attention.

We also enclosed herewith the State Court of the Republic of Singapore Practice Direction-Amendment No. 1 of 2016 of 2016 of Pre-repair Inspection for your attention.

Thank you and have a nice day.

Regards,

Shu Shan

Teamwork Garage Pte Ltd
Blk 53 Ubi Avenue 1
#01-24
Paya Ubi Industrial Park
Singapore 408934
Tel: 6844 2475
Fax:6844 2474

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

Hock Ann (LKK Auto)

From: Hock Ann (LKK Auto)
Sent: Monday, 16 December, 2019 9:34 AM
To: Darren
Cc: Shiau Chan (LKKAUTO); Bryan Ang (LKKAUTO)
Subject: RE: SKU 9582L FINALIZED EXTIMATE CALCULATE UPDATED 26.11.2019

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Darren ,

Good day, o.k will be process base on finalized total amount COR \$ 4700 L /SUMP REPAIR and DOR 8 days close.

Thanks.

Best Regards,
Hock Ann | Assistant Automotive Assessor
LKK Auto Consultants
Phone: 6741 3061 | Email: HockAnn@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Darren [mailto:claims@teamworkgarage.com]
Sent: Monday, 16 December, 2019 9:24 AM
To: Hock Ann (LKK Auto)
Cc: Shiau Chan (LKKAUTO); Bryan Ang (LKKAUTO)
Subject: RE: SKU 9582L FINALIZED EXTIMATE CALCULATE UPDATED 26.11.2019

Hi Hock Ann,

We confirmed COR @ \$4700 and DOR @ 8 Days

Darren
Teamwork Garage Pte Ltd
53 Ubi Avenue 1
#01-24 Paya Ubi Industrial Park
Singapore 408934
Tel: 68442475
Fax: 68442474

From: [Hock Ann \(LKK Auto\)](#)
Sent: Monday, 16 December 2019 9:20 AM
To: [Darren](#)
Cc: [Shiau Chan \(LKKAUTO\)](#); [Bryan Ang \(LKKAUTO\)](#)
Subject: RE: SKU 9582L FINALIZED EXTIMATE CALCULATE UPDATED 26.11.2019

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear darran,

Good day, regarding last 2 week 29.11.19 have update on yours second adjustment finalized L/sump amount total is COR \$4700 and DOR 8 day for vehicle SKU 9582L Toyota altis ,may know yours agree amount ? coz you havan.t update back on email ,please update soon email asap .

Thanks.

Best Regards,
Hock Ann | Assistant Automotive Assessor
LKK Auto Consultants
Phone: 6741 3061 | Email: HockAnn@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hock Ann (LKK Auto)
Sent: Friday, 29 November, 2019 10:31 AM
To: 'Darren'
Cc: Shiau Chan (LKKAuto); Bryan Ang (LKKAuto)
Subject: RE: SKU 9582L FINALIZED EXTIMATE CALCULATE UPDATED 26.11.2019

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear darran,

Good day, regarding yours requisied about front fender R/H I olready check back and refer to my senior, after will given one side front fender R/H for your only

Another side L/H is repair back , after adjustment updated L/sump amount total is COR \$4700 AND DOR 8 day. If yours agree amount ,please update soon asap.

Thanks.

Best Regards,
Hock Ann | Assistant Automotive Assessor
LKK Auto Consultants
Phone: 6741 3061 | Email: HockAnn@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Darren [<mailto:claims@teamworkgarage.com>]
Sent: Thursday, 28 November, 2019 9:45 AM
To: Hock Ann (LKK Auto)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	179N
Vehicle Details	
Vehicle No.:	SKU9582L
Vehicle to be Exported:	Yes
Intended Deregistration Date:	05 Nov 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS CLASSIC 1.6 CVT
Primary Colour:	Grey
Manufacturing Year:	2015
Engine No.:	1ZRX525488
Chassis No.:	MR053REH104537040
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$17,804.00
Original Registration Date:	25 Aug 2015
First Registration Date:	25 Aug 2015
Transfer Count:	0
Actual ARF Paid:	\$17,804.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Aug 2025
PARF Rebate Amount:	\$13,353.00
Intended COE Rebate Details	
COE Expiry Date:	24 Aug 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,209.00
COE Rebate Amount:	\$32,607.00
Total Rebate Amount:	\$45,960.00

The information contained herein is correct as at 05 Nov 2019

OK

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Re

AVIVA

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

2016 Lexus NX200T Classic Turbo At \$131,888



Very Low Mileage At Only
58800, Under Authorized Dealer
5 Years Warranty.
Direct Owner StarAd

KA-HUP
VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND
HOTLINE: 6741 9997 [view our](#)

Browse by Category

« Back (1 2) Next »




Sort by Date Posted

20 results/

21 vehicles

toyota altis

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Stat
Search Selection	toyota altis		Any	Any	2015	Any	Any	Any	Av
	Toyota Corolla Altis 1.6A Classic		\$61,200	\$8,500 /yr	30-Dec-2015	1,598 cc	50,000 km	Sedan	Av
1 Careful Owner! 5Y Borneo Motors Warranty! Agent Maintained Unit! Showroom Condition! Original Toyota Paint! 100% Loan Approval! Full Loan Available! Bank/In House Loan Available! 120 Point Check Done, STA Welcomed! 6 Months Comprehensive Warranty!									
Posted: 04-Nov-2019 Tags: 2015 Toyota Corolla, 2015 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota									
	Toyota Corolla Altis 1.6A Classic		\$59,800	\$8,280 /yr	28-Dec-2015	1,598 cc	72,340 km	Sedan	Av
100% Loan Available, Full Agent Serviced Since Day 1! We Are Full Loan Specialist, 1 Owner, Accident Free Unit, Act Now To Test Drive Now!									
1axis Posted: 04-Nov-2019 Tags: 2015 Toyota Corolla, 2015 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota									
	Toyota Corolla Altis 1.6A Elegance		\$59,888	\$9,460 /yr	28-May-2015	1,598 cc	88,000 km	Sedan	Av
Well Maintained Vehicle By Owner. Good Condition Vehicle That You Shouldn't Miss! Call For Appointment Now To View The Vehicle!									
Posted: 03-Nov-2019 Tags: 2015 Toyota Corolla, 2015 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota									
	Toyota Corolla Altis 1.6A Elegance		\$62,000	\$9,050 /yr	12-Aug-2015	1,598 cc	82,100 km	Sedan	Av
1 Owner Only. Superb Smooth And Powerful Toyota Altis 1.6A Elegance Driving Feels. Start/Stop Button. Electric Seats. Accident Free. Serviced From Borneo Motor. Genuine Lowest Mileage Clocked. Original Silver Exterior And Black Interior. Only Sent For Professional Gro...									
Posted: 02-Nov-2019 Tags: 2015 Toyota Corolla, 2015 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota									
	Alliance Auto Pte Ltd - Specialist for Toyota Car repair, servicing & maintenance A Lexus specialise workshop with an extensive investment in the manpower, equipment and genuine parts for Lexus. More info about this shop <div> <div> DOA = 3/11/19 Baku 5yr 9mth Apun 8000 yr 8000 + 12 = 666 mth 40000 + 5994 + 8902 = 54896 </div> <div> MY - 54000 PV - 45960 NV - 8000 </div> </div>								
	Toyota Corolla Altis 1.6A Classic		\$61,800	\$9,020 /yr	16-Sep-2015	1,598 cc	56,018 km	Sedan	Av
\$800 Warranty-Workshop Credits, 1 Year Warranty Cover Engine And Gear Box By Our Authorized Workshop, Excellent Condition. Well, Maintain By Previous Owner, Can Arrange For STA Evaluation, Drive With Peace Of Mind! High Trade In And Flexible High Loan Available...									
Accendore Autolution Pte Ltd Posted: 02-Nov-2019 Tags: 2015 Toyota Corolla, 2015 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota									
	ta Corolla Altis 1.6A sic		\$56,800	\$9,500 /yr	04-Mar-2015	1,598 cc	73,196 km	Sedan	Av

Compare



1 Owner. Fully Maintained And Serviced By Borneo Motors. 5 Years Warranty And Servicing Package From Borneo Motors. Car In Showroom Condition. Pristine Interior. 1.98% Bank Loan Available, Flexible In House Loan Package With Attractive Interest Rate. View T...

Posted: 01-Nov-2019

Tags: 2015 Toyota Corolla, 2015 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A Elegance

\$59,800

\$8,590 /yr

01-Sep-2015

1,598 cc

65,622 km

Sedan

Av

100% Loan Available With Our Flexible In-House Loan Options! Bank Loan Interest Rate At 2.28%. Warranty By Borneo Motors Till Sep 2020. Premium Black With Premium Beige Leather Seats. Well Maintained By One Owner. Excellent Condition! Call Our Friendly Salesper...

Jack Cars Enterprise Pte Ltd

Posted: 01-Nov-2019

Tags: 2015 Toyota Corolla, 2015 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A

\$54,068

\$9,050 /yr

14-Jan-2015

1,598 cc

48,000 km

Sedan

Av

Consignment Unit, Well Maintained By One Careful Owner. Free 2x Servicing With Agent. 100% Loan Available With Our Flexible In House Loan! Bank Loan Interest Rate At 2.98%. Call To Arrange For An Appointment.

Posted: 27-Oct-2019

Tags: 2015 Toyota Corolla, 2015 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A Elegance

\$63,800

\$9,010 /yr

02-Nov-2015

1,598 cc

53,000 km

Sedan

Av

One Owner, Flexible Loan Available, Direct Borneo Unit, Elegance Model. Still Under Agent Warranty. Extremely Reliable & Fuel Efficiency. Responsive Engine, Smooth Transmission & Quiet Undercarriage. Beautiful Exterior & Well Kept Interior. Spacious Inner Cabin & Boot Sp...

Posted: 26-Oct-2019

Tags: 2015 Toyota Corolla, 2015 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A Classic

\$57,800

\$8,540 /yr

27-Jul-2015

1,598 cc

89,000 km

Sedan

Av

1 Owner Well Maintained Call Now For Viewing

Posted: 26-Oct-2019

Tags: 2015 Toyota Corolla, 2015 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Save up to 24%

Save on petrol with UOB One card!

Enjoy huge petrol savings of up to 24%, attractive cashback on your monthly spend, and 1-year annual fee waiver. Apply now and start enjoying today.

Find out more!



Toyota Corolla Altis 1.6A Elegance

\$65,800

\$9,160 /yr

15-Dec-2015

1,598 cc

26,400 km

Sedan

Av

1 Owner, Low Mileage Done Only 26,400Km, Full Serviced And 5 Years Unlimited Mileage Warranty By Borneo Motors, 100% Loan Available, Ex-Bankruptcy And Bad Credit Welcome, High Trade In.

Faster Auto Trading

Posted: 25-Oct-2019

Tags: 2015 Toyota Corolla, 2015 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A Elegance

\$62,800

\$9,040 /yr

15-Sep-2015

1,598 cc

83,668 km

Sedan

Av

Like New Very Well Maintained By 1 Previous Owner. High ARF! Unit Maintained In Good Condition! Clean Paintwork Paired With Grey Leather Interior! Trade In Welcome. 100% In House Loan And Bank Loan Available, Viewing Strongly Encouraged! Call Now To View And...

Tai Huat Automobile

Posted: 23-Oct-2019

Tags: 2015 Toyota Corolla, 2015 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A Elegance

\$62,800

\$8,870 /yr

27-Oct-2015

1,598 cc

59,900 km

Sedan

Av

1 Owner. In Showroom Condition, View To Believe! Hua Yang Group Since 1984' Iso 9001:2000 Certified, Bank Loan, In House Loan, Balloon Scheme, 100% Loan Available! Attractive Interest Rate! Trade-In/Over Trade Welcome. 100% Accident-Free, Hassle-Free Deals....

Hua Yang Credit Pte Ltd

Posted: 21-Oct-2019

Tags: 2015 Toyota Corolla, 2015 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A Classic

\$65,800

\$9,610 /yr

07-Oct-2015

1,598 cc

63,000 km

Sedan

Av

Fully Agent Maintained. Non Phv Unit! In Showroom Condition, View To Believe! Hua Yang Group Since 1984' Iso 9001:2000 Certified, Bank Loan, In House Loan, 100% Loan Available! Attractive Interest Rate! Trade-In/Over Trade Welcome. 100% Accident-Free. 3k Dep...

Hua Yang Credit Pte Ltd

Posted: 21-Oct-2019

Tags: 2015 Toyota Corolla, 2015 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	04/11/2019 18:25
Date Of Accident	03/11/2019 14:10
Exact Location Of Accident	BLK 205 MARSILING DR CARPARK
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKU9582L
Insured/Policyholder	
Name Of Registered Owner	ONE2RENT CARS PTE LTD
Co Reg No	201306179N
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-89999999
Vehicle Particulars	
Manufacturer	TOYOTA
Model	COROLLA ALTIS CLASSIC 1.6 CVT
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5108639457
Cover Note Number	
Driver	
Name of Driver	KOH HUAN PING
NRIC No	S7836862D
Date Of Birth	09/12/1978
Occupation	OUTDOOR
Date Of Driving Pass	04/12/1997
Driving Experience	21 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91386898
Fax Number	
Contact Number	OFFICE-91386898
EMail Address	NOEMAIL

Address	BLK 432D YISHUN AVENUE 1 #10-561
Postcode	764432
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO FOOTAGE WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLE6349L <i>T. with (npv)</i>
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	HARON BIN MAWAS
NRIC/Passport Number	S1484187C
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Person's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along Bk 205 Marsiling Drive carpark heading towards the gantry. My vehicle was going straight suddenly vehicle B (SLE 6349L) came out of his carpark lot behind the stationary lorry, and his front left portion of his vehicle collided onto the front right side of my vehicle. After the incident, the driver of vehicle B acknowledge that the unknown lorry was his as well which blocked his vision while coming out of the parking lot.

DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

quanyAC SketchPlanForm_V3



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKU 9582L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	CUT	557.75	400.75
2	FRONT BUMPER RETAINER	O/S NECESSARY / N/S SERVICEABLE	253.00	90.50
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	495.52	-
1	FRONT BUMPER LOWER GRILLE	SERVICEABLE	255.94	-
2	FRONT FOG LAMP COVER	O/S CRUSHED / N/S SERVICEABLE	232.30	77.80
2	FRONT FOG LAMP	SERVICEABLE	747.50	-
1	FRONT GRILLE	CRUSHED	713.00	290.70
1	FRONT GRILLE EMBLEM LOGO	NECESSARY	74.75	41.70
1	FRONT SUPPORT PANEL	BENT	1,132.75	638.70
2	FRONT HEADLAMP	O/S CRACKED / N/S SERVICEABLE	1,955.00	520.30
1	FRONT RH FENDER INNER SHIELD R/H	MISSING	253.00	143.70
1	FRONT RH WIPER TOP GARNISH	SERVICEABLE	59.30	-
1	FRONT BONNET	TO REPAIR SEE LABOUR	1,207.50	-
1	FRONT BONNET LOCK	SERVICEABLE	166.75	-
1	FRONT BONNET INSULATOR	SERVICEABLE	325.45	-
2	FRONT BONNET HINGE	SERVICEABLE	172.50	-
1	FRONT RH SHOCK ABSORBER	SERVICEABLE	457.70	-
1	FRONT RH KNUCKLE ARM	CRUSHED <i>DD</i>	603.75	215.70
1	FRONT RH KNUCKLE BEARING	CRUSHED <i>DD</i>	155.25	89.60
1	FRONT RH LOWER ARM	CRUSHED <i>BT</i>	616.60	230.80
1	FRONT BUMPER SPONGE (ADDITIONAL)	CRUSHED	80.40	59.40
1	FRONT SUPPORT PANEL (ADDITIONAL)	REPEATED	1,132.75	-
2	FRONT HEADLAMP (ADDITIONAL)	REPEATED	1,955.00	-
2	FRONT HEADLAMP OUTER CHROME GARNISH (ADDITIONAL)	O/S NECESSARY	212.80	87.80
2	FRONT FENDER (ADDITIONAL)	O/S BENT / N/S SERVICEABLE	1,828.50	750.50
1	FRONT RH FENDER EMBER LOGO - VVTI (ADDITIONAL)	NECESSARY	40.25	27.70
1	FRONT RH FENDER INNER WHEELHOUSE (ADDITIONAL)	TO REPAIR SEE LABOUR	492.20	-
1	FRONT RH STEERING TIE ROD END (ADDITIONAL)	SERVICEABLE	195.50	-

Report Ref No. CS/AGI19019532/Hqf3e2



Pte Ltd

TeamWork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475

E-mail : claims@teamworkgarage.com

Register number : 201015366H

REPAIR PERFORMA INVOICE

AUTO & GENERAL

Vehicle number	SKU9582L
Make / Model	TOYOTA/ALTIS
Chassis number	MR053REH104537040
Accident date	03 NOV 2019
Reference	1911-05

Qty Particulars

Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS		
1	FRONT BUMPER ✓ cut	557.75 400.75 ✓
1	FRONT BUMPER RETAINER RH only ✓ 4H X svc	253.00 90.50 ✓
1	FRONT BUMPER REINFORCEMENT X R	495.52
1	FRONT BUMPER LOWER GRILLE X (svc)	255.94
1	FRONT FOG LAMP COVER RH only ✓ cmr 1/H (svc) X	232.30 77.80 ✓
1	FRONT FOG LAMP RH only X svc 1/H (svc) X	747.50
1	FRONT GRILLE ✓ cmr	713.00 290.70 ✓
1	FRONT GRILLE EMBLEM LOGO ✓ mcr	74.75 41.70 ✓
1	FRONT SUPPORT PANEL ✓ BT	1132.75 638.70 ✓
1	FRONT HEADLAMP RH only ✓ cmr 1/H X (svc)	1955.00 520.70 ✓
1	FRONT RH FENDER INNER SHIELD ✓ mcr RH	253.00 143.20 ✓
1	FRONT RH WIPER TOP GARNISH X (svc)	59.30
1	FRONT BONNET X (svc) R	1207.50
1	FRONT BONNET LOCK X (svc)	166.75
1	FRONT BONNET INSULATOR (svc) X	325.45
2	FRONT BONNET HINGE (svc) X	172.50
1	FRONT RH SHOCK ABSORBER X (svc)	457.70
1	FRONT RH KNUCKLE ARM ✓ cmr ✓ DP	603.75 215.70 ✓
1	FRONT RH KNUCKLE BEARING ✓ photo - cmr ✓ DP	155.25 89.60 ✓
1	FRONT RH LOWER ARM ✓ cmr ✓ BT	616.60 230.80 ✓
		10435.31
Less 25%		4577.62
Subtotal		5857.69
Balance C/F		5857.69

<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		Balance B/F	5857.69
1 SET	FRONT BUMPER CLIP ✓ <i>me</i>		40.00 15 ✓
1 SET	FRONT RH FENDER INNER SHIELD CLIP ✓ <i>me</i>		30.00 15 ✓
1	RIM ✓ <i>cut R/H</i>		600.00 380 ✓
1 BOT	BRAKE FULD X (SVC)		50.00 X ✓
1 BOT	COOLANT ✓ <i>me</i>		50.00 15 ✓
Subtotal			770.00
Balance C/F			6627.69
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		Balance B/F	6627.69
1	CHECK FRONT WIRING AND LIGHTNING SYSTEM		60.00
2	COMPUTERISED AND CHECK FRONT WHEEL ALIGNMENT		150.00
3	REMOVE AND RENEW FRONT UNDERCARRIAGE PARTS		200.00
4	PANEL BEATING ON AFFECTED AREAS		1200.00
5	SPRAY PAINTING ON AFFECTED AREAS		1200.00
6	APPLY ANTI RUST ON AFFECTED AREAS		150.00
Subtotal			2960.00
Grand total			9587.69

2/11/19
5/11/19
days
without
pre-approval
L/S repair
resurvey after paint
5.40pm
8531483
Hoch Ann @ LK Auto
21927.62
22918.93

Parts	3745.45
Parts less	25%
	2809.08
spe nett	425
196m	2610
	5844.08
L/S less	20%
	4675.26
Total	↓
L/S Amount	\$4700#

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Pte Ltd

TeamWork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475

E-mail : claims@teamworkgarage.com

Register number : 201015366H

SUPPLEMENTARY

AUTO & GENERAL

Vehicle number	SKU9582L
Make / Model	TOYOTA/ALTIS
Chassis number	MR053REH104537040
Accident date	03 NOV 2019
Reference	1911-05

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT BUMPER SPONGE ✓ <i>crn</i>	80.40 59.40 ✓
1	FRONT SUPPORT PANEL X RPT	1132.75
2	FRONT HEADLAMP X RPT	1955.00
2	FRONT HEADLAMP OUTER CHROME GARNISH R/L only ✓ <i>crn</i>	212.80 87.80 ✓
2	FRONT FENDER R/H ✓ <i>B-t 4/H X (sue)</i>	1828.50 750.50 ✓
1	FRONT RH FENDER EMBER LOGO-VVTI ✓ <i>crn</i>	40.25 27.70 ✓
1	FRONT RH FENDER INNER WHEELHOUSE X (R) SVC	492.20
1	FRONT RH STEERING TIE ROD END X SVC	195.50
1	STEERING RACK AND PINION X (SVC)	1880.25
1	WIPER TANK ✓ <i>crn</i>	176.40 79.80 ✓
1	FRONT RH CHASSIS X R	700.80
		8694.85
	Less 25%	2173.71
	Subtotal	6521.14
	Balance C/F	6521.14
S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	
	Balance B/F	6521.14
1	CHECK FRONT WIRING AND LIGHTNING SYSTEM	60.00 20 ✓
2	REMOVE, REFIT RADITATOR AND TOP UP COOLANT	150.00 50 ✓
3	REMOVE, RENEW CONDENSER AND TOP UP GAS	200.00 70 ✓
4	MOUNT VEHICLE ON BENCH FOR FRONT CHASSIS REPLACEMNT X	500.00 X
5	COMPUTERISED AND CHECK FRONT WHEEL ALIGNMENT - <i>align report</i>	150.00 60 ✓
6	REMOVE AND RENEW FRONT UNDERCARRIAGE PARTS R/L only	200.00 80 ✓
7	PANEL BEATING ON AFFECTED AREAS + rep wheel house R/L and chassis R/L	3000.00 1100 ✓
8	SPRAY PAINTING ON AFFECTED AREAS	2400.00 1200 ✓
9	APPLY ANTI RUST ON AFFECTED AREAS	150.00 30 ✓
	Subtotal	6810.00
	Grand total	13331.14

Resung
6/11/19
3:00pm
Resung after paint
8 day
14. Jan



Chassis Measurement Chart

Subsidiary/Branch-Company no.

C&Y AUTO PTE LTD

53 UBI AVE 1 #01-28 PAYA UBI INDUSTRIAL PARK

S'PORE 408934

Customer:

TEAM WORK

Vehicle ident. no.

Repair order no.

Measurement made: Name

Date:

WEI KEN

09/11/2019

Reg. N.:

First registration:

Type

Mileage: Km/miles

SKU 9582 L

1911-05

TOYOTA ALTIS ZRE17 2013 - (64548)

km

Complaint or reason for measurement

Tyres: make

Description

Mileage: Km/miles

		front LH	front RH	rear LH	rear RH
Pressure measured (cold) bar/psi/kPa		2.2	2.2	2.2	2.2
Tread depth (mm)	external				
	centre				
	internal				
		Before correction		After correction	
Vehicle level					
Camber +/- (°)	LH	-01.24°	-01.48° / +00.50° -00.50°	-01.24°	
	RH	-01.63°	-01.48° / +00.50° -00.50°	-01.63°	
REAR AXLE	total	-00.22° *	+00.48° / +00.40° -00.40°	-00.22° *	
Toe +/- (°)	LH	+00.30°	+00.24° / +00.20° -00.20°	+00.30°	
	RH	-00.52° *	+00.24° / +00.20° -00.20°	-00.52° *	
Thrust angle		+00.41°		+00.41°	
Camber +/- (°)	LH	-00.49°	-00.58° / +00.75° -00.75°	-00.51°	
	RH	-00.31°	-00.58° / +00.75° -00.75°	-00.33°	
Caster (°)	LH		+02.95° / +00.75° -00.75°		
	RH		+02.95° / +00.75° -00.75°		
FRONT AXLE	Lh steering lock lh wheel 20°				
	Rh steering lock rh wheel 20°				
Set Back		-00.19°		-00.20°	
	total	-00.58° *	+00.00° / +00.32° -00.32°	-00.22°	
Toe +/- (°)	LH	-00.36° *	+00.00° / +00.16° -00.16°	-00.12°	
	RH	-00.22° *	+00.00° / +00.16° -00.16°	-00.10°	
Maximum steering angle on wheel side on inside of bend (°)	LH				
	RH				

4/11 check & print result (15)

9/11 Adjust front wheel Alignment (30)

H 45



Chassis Measurement Chart

Subsidiary/Branch-Company no.

Customer:

C&Y AUTO PTE LTD

TEAM WORK

53 UBI AVE 1 #01-28 PAYA UBI INDUSTRIAL PARK

S'PORE 408934

Vehicle ident. no.

Repair order no.

Measurement made Name

Date:

WEI KEN

04/11/2019

Reg. N.:

First registration:

Type

Mileage:Km/miles

SKU 9582 L

TOYOTA ALTIS 2001 - 2003 (64545)

km

Complaint or reason for measurement

Tyres:make

Description

Mileage:Km/miles

		front LH	front RH	rear LH	rear RH
Pressure measured (cold) bar/psi/kPa		2.2	2.2	2.2	2.2
Tread depth (mm)	external				
	centre				
	internal				
		Before correction		After correction	
Vehicle level					
Camber +/- (°)	LH	-01.32°	-01.00°/ +00.75°-00.75°	-01.32°	
	RH	-01.62°	-01.00°/ +00.75°-00.75°	-01.62°	
REAR AXLE	total	-00.22° *	+00.43°/ +00.17°-00.23°	-00.22° *	
Toe +/- (°)	LH	+00.31° *	+00.22°/ +00.08°-00.12°	+00.31° *	
	RH	-00.53° *	+00.22°/ +00.08°-00.12°	-00.53° *	
Thrust angle		+00.42°		+00.42°	
Camber +/- (°)	LH	-00.53°	-00.22°/ +00.75°-00.75°	-00.52°	
	RH	-01.38° *	-00.22°/ +00.75°-00.75°	-01.38° *	
Caster (°)	LH		+01.40°/ +00.75°-00.75°		
	RH		+01.40°/ +00.75°-00.75°		
FRONT AXLE	Lh steering lock lh wheel 20°				
	Rh steering lock rh wheel 20°				
Set Back		-00.35°		-00.35°	
Toe +/- (°)	total	-00.08°	+00.10°/ +00.20°-00.20°	-00.08°	
	LH	+00.10°	+00.05°/ +00.10°-00.10°	+00.10°	
	RH	-00.18° *	+00.05°/ +00.10°-00.10°	-00.18° *	
Maximum steering angle on wheel side on inside of bend(°)	LH				
	RH				



Chassis Measurement Chart

Subsidiary/Branch-Company no.

Customer:

C&Y AUTO PTE LTD
53 UBI AVE 1 #01-28 PAYA UBI INDUSTRIAL PARK
S'PORE 408934

TEAM WORK

Vehicle ident. no.

Repair order no.

Measurement made: Name

Date:

WEI KEN

04/11/2019

Reg. N.:

First registration:

Type

Mileage: Km/miles

SKU 9582 L

1911-05

TOYOTA ALTIS 2001 - 2003 (64545)

km

Complaint or reason for measurement

Tyres: make

Description

Mileage: Km/miles

		front LH	front RH	rear LH	rear RH
Pressure measured (cold) bar/psi/kPa		2.2	2.2	2.2	2.2
external					
Tread depth (mm)		centre			
internal					
		Before correction		After correction	
Vehicle level					
REAR AXLE	Camber +/- (°)	LH	-01.32°	-01.00°/ +00.75°-00.75°	-01.32°
		RH	-01.62°	-01.00°/ +00.75°-00.75°	-01.62°
	total		-00.22° *	+00.43°/ +00.17°-00.23°	-00.22° *
	Toe +/- (°)	LH	+00.31° *	+00.22°/ +00.08°-00.12°	+00.31° *
		RH	-00.53° *	+00.22°/ +00.08°-00.12°	-00.53° *
	Thrust angle		+00.42°		+00.42°
FRONT AXLE	Camber +/- (°)	LH	-00.53°	-00.22°/ +00.75°-00.75°	-00.52°
		RH	-01.38° *	-00.22°/ +00.75°-00.75°	-01.38° *
	Caster (°)	LH		+01.40°/ +00.75°-00.75°	
		RH		+01.40°/ +00.75°-00.75°	
	Lh steering lock lh wheel 20°				
	Rh steering lock rh wheel 20°				
Set Back			-00.35°		-00.35°
Toe +/- (°)	total		-00.08°	+00.10°/ +00.20°-00.20°	-00.08°
	LH		+00.10°	+00.05°/ +00.10°-00.10°	+00.10°
	RH		-00.18° *	+00.05°/ +00.10°-00.10°	-00.18° *
Maximum steering angle on wheel side on inside of bend (°)		LH			
		RH			



Chassis Measurement Chart

Subsidiary/Branch-Company no.

Customer:

C&Y AUTO PTE LTD

TEAM WORK

53 UBI AVE 1 #01-28 PAYA UBI INDUSTRIAL PARK

S'PORE 408934

Vehicle ident. no.

Repair order no.

Measurement made: Name

Date:

WEI KEN

09/11/2019

Reg. N.:

First registration:

Type

Mileage: Km/miles

SKU 9582 L

1911-05

TOYOTA ALTIS ZRE17 2013 - (64548)

km

Complaint or reason for measurement

Tyres: make

Description

Mileage: Km/miles

		front LH	front RH	rear LH	rear RH
Pressure measured (cold) bar/psi/kPa		2.2	2.2	2.2	2.2
	external				
Tread depth (mm)	centre				
	internal				
		Before correction		After correction	
Vehicle level					
REAR AXLE	Camber +/- (°)	LH	-01.24°	-01.48°/ +00.50°-00.50°	-01.24°
		RH	-01.63°	-01.48°/ +00.50°-00.50°	-01.63°
	total		-00.22° *	+00.48°/ +00.40°-00.40°	-00.22° *
	Toe +/- (°)	LH	+00.30°	+00.24°/ +00.20°-00.20°	+00.30°
		RH	-00.52° *	+00.24°/ +00.20°-00.20°	-00.52° *
	Thrust angle		+00.41°		+00.41°
FRONT AXLE	Camber +/- (°)	LH	-00.49°	-00.58°/ +00.75°-00.75°	-00.51°
		RH	-00.31°	-00.58°/ +00.75°-00.75°	-00.33°
	Caster (°)	LH		+02.95°/ +00.75°-00.75°	
		RH		+02.95°/ +00.75°-00.75°	
	Lh steering lock lh wheel 20°				
	Rh steering lock rh wheel 20°				
Set Back			-00.19°		-00.20°
Toe +/- (°)	total		-00.58° *	+00.00°/ +00.32°-00.32°	-00.22°
	LH		-00.36° *	+00.00°/ +00.16°-00.16°	-00.12°
	RH		-00.22° *	+00.00°/ +00.16°-00.16°	-00.10°
Maximum steering angle on wheel side on inside of bend (°)	LH				
	RH				



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL		Ref : CS/AGI19019532/Hqf3e2	
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Date : 18-12-2019	
		Code : AGI	
1. Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh. SLE 6349L	Veh. Inspected	SKU 9582L
	Policy No.	Coverage (\$)	0.00
	Claim No. C10004492	Excess (\$)	0.00
	Assign From IVY RATILLA	Assign Date	05/11/2019
2. Vehicle Particulars & Condition			
	Make & Model TOYOTA COROLLA ALTIS	c.c	1598
	Engine No. HIDDEN	Year of Reg.	2015
	Chassis No. MR053REH104537040	Colour	METALLIC GREY / BLUE
	Odometer 386487	Steering	IN ORDER
	Brakes IN ORDER	Modification	SPORTS RIM
	General GOOD		
3. Conditions of Tyres			
		Size	Make
	R/H Front Tyre	205/55 R16	KUMHO
	L/H Front Tyre	205/55 R16	KUMHO
	R/H Rear Tyre	205/55 R16	KUMHO
	L/H Rear Tyre	205/55 R16	KUMHO
			Balance
			5 mm
			5 mm
			5 mm
			5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
	Accident Date 03/11/2019	Inspection Date	05/11/2019
	Survey held at TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKU 9582L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	CUT	557.75	400.75
2	FRONT BUMPER RETAINER	O/S NECESSARY / N/S SERVICEABLE	253.00	90.50
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	495.52	-
1	FRONT BUMPER LOWER GRILLE	SERVICEABLE	255.94	-
2	FRONT FOG LAMP COVER	O/S CRUSHED / N/S SERVICEABLE	232.30	77.80
2	FRONT FOG LAMP	SERVICEABLE	747.50	-
1	FRONT GRILLE	CRUSHED	713.00	290.70
1	FRONT GRILLE EMBLEM LOGO	NECESSARY	74.75	41.70
1	FRONT SUPPORT PANEL	BENT	1,132.75	638.70
2	FRONT HEADLAMP	O/S CRACKED / N/S SERVICEABLE	1,955.00	520.30
1	FRONT RH FENDER INNER SHIELD R/H	MISSING	253.00	143.70
1	FRONT RH WIPER TOP GARNISH	SERVICEABLE	59.30	-
1	FRONT BONNET	TO REPAIR SEE LABOUR	1,207.50	-
1	FRONT BONNET LOCK	SERVICEABLE	166.75	-
1	FRONT BONNET INSULATOR	SERVICEABLE	325.45	-
2	FRONT BONNET HINGE	SERVICEABLE	172.50	-
1	FRONT RH SHOCK ABSORBER	SERVICEABLE	457.70	-
1	FRONT RH KNUCKLE ARM	DENTED	603.75	215.70
1	FRONT RH KNUCKLE BEARING	DENTED	155.25	89.60
1	FRONT RH LOWER ARM	BENT	616.60	230.80
1	FRONT BUMPER SPONGE (ADDITIONAL)	CRUSHED	80.40	59.40
1	FRONT SUPPORT PANEL (ADDITIONAL)	REPEATED	1,132.75	-
2	FRONT HEADLAMP (ADDITIONAL)	REPEATED	1,955.00	-
2	FRONT HEADLAMP OUTER CHROME GARNISH (ADDITIONAL)	O/S NECESSARY	212.80	87.80
2	FRONT FENDER (ADDITIONAL)	O/S BENT / N/S SERVICEABLE	1,828.50	750.50
1	FRONT RH FENDER EMBER LOGO - VVTI (ADDITIONAL)	NECESSARY	40.25	27.70
1	FRONT RH FENDER INNER WHEELHOUSE (ADDITIONAL)	TO REPAIR SEE LABOUR	492.20	-
1	FRONT RH STEERING TIE ROD END (ADDITIONAL)	SERVICEABLE	195.50	-

Report Ref No. CS/AGI19019532/Hqf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	STEERING RACK AND PINION (ADDITIONAL)	SERVICEABLE	1,880.25	-
1	WIPER TANK (ADDITIONAL)	CRUSHED	176.40	79.80
1	FRONT RH CHASSIS (ADDITIONAL)	TO REPAIR SEE LABOUR	700.80	-
	LESS 25% DISCOUNT		-4,782.54	-936.36
			14,347.62	2,809.09
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	40.00	15.00
1	SET FRONT RH FENDER INNER SHIELD CLIP (SN)	NECESSARY	30.00	15.00
1	RIM R/H (SN)	CUT	600.00	380.00
1	BOT BRAKE FLUID (SN)	SERVICEABLE	50.00	-
1	BOT COOLANT (SN)	NECESSARY	50.00	15.00
			770.00	425.00
	<u>LABOUR</u>			
	CHECK FRONT WIRING AND LIGHTNING SYSTEM. (ADDITIONAL)		60.00	20.00
	REMOVE, REFIT RADIATOR AND TOP UP COOLANT. (ADDITIONAL)		150.00	50.00
	REMOVE, RENEW CONDENSER AND TOP UP GAS. (ADDITIONAL)		200.00	70.00
	MOUNT VEHICLE ON BENCH FOR FRONT CHASSIS REPLACEMENT (ADDITIONAL)	NOT NECESSARY	500.00	-
	COMPUTERISED AND CHECK FRONT WHEEL ALIGNMENT. (ADDITIONAL)		150.00	60.00
	REMOVE AND RENEW FRONT UNDERCARRIAGE PARTS (ADDITIONAL)		200.00	80.00
	PANEL BEATING ON AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT, FRONT BONNET, FRONT RH FENDER INNER WHEELHOUSE AND FRONT RH CHASSIS. (ADDITIONAL)		3,000.00	1,100.00
	SPRAY PAINTING ON AFFECTED AREAS. (ADDITIONAL)		2,400.00	1,200.00
	APPLY ANTI RUST ON AFFECTED AREAS. (ADDITIONAL)		150.00	30.00
			-	-
			-	-
			6,810.00	2,610.00
	GRAND TOTAL		21,927.62	5,844.09
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,700.00

Report Ref No. CS/AGI19019532/Hqf3e2



Report Ref No. CS/AGI19019532/Hqf3e2



LEE HOCK ANN

Asst. Automotive Assessor



ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.