

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5323A

AAD1911-001

Not Authorized
11 Pny @ 3800h

Vehicle No.:
Chassis No.:
Vehicle Make: **04 NOV 2019**
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration:

SHC 5323A
VF1ABL15AUC276868
RENAULT
LATITUDE
1.11.19
III
21/3/2014

PART			LIST	
1	DOOR PANEL FRT RH	\$	<i>Bn</i> 2,844.66	✓
1	DOOR HINGE UPPER RH	\$	<i>R</i> 261.28	X
1	DOOR HINGE LOWER RH	\$	<i>R</i> 300.55	X
1	DOOR CHECK FRT RH	\$	<i>Su</i> 90.90	X
1	DOOR LOCK FRT RH	\$	<i>R</i> 453.80	X
1	DOOR CATCH FRT RH	\$	<i>R</i> 73.70	X
1	DOOR REGULATOR FRT RH	\$	<i>Ts</i> 758.10	✓
1	DOOR REGULATOR MOTOR FRT RH	\$	<i>Su</i> 501.40	} X
1	DOOR REGULATOR GUIDE FRT RH	\$	<i>Su</i> 69.00	
1	DOOR MOULDING FRONT RH	\$	<i>Su</i> 100.50	
1	DOOR FINISHER FRONT RH	\$	<i>Su</i> 258.90	
1	DOOR BLIND FRONT RH	\$	<i>Su</i> 506.90	
1	DOOR WHEATHESTRIIP FRONT RH	\$	<i>Su</i> 316.00	
1	DOOR SEAL FRONT RH	\$	<i>Su</i> 59.40	
1	DOOR GLASS RUNNER SEAL FRONT RH	\$	<i>Su</i> 332.00	
1	DOOR WAIST SEAL OUTER FRONT RH	\$	<i>Su</i> 92.20	
1	DOOR HANDLE OUTER FRONT RH	\$	<i>Su</i> 477.76	
1	DOOR HANDLE CAP FRONT RH	\$	<i>Su</i> 35.52	
1	DOOR HANDLE MODULE FRT RH L70Y	\$	<i>Su</i> 133.40	
1	ROCKER PANEL INNER GARNISH RH	\$	<i>Su</i> 466.51	
1	ROCKER PANEL INNER RH	\$	<i>R</i> 1,024.79	
1	ROCKER PANEL OUTER RH	\$	<i>R</i> 1,184.99	
1	ROCKER PANEL CENTER RH	\$	<i>R</i> 990.25	
1	DOOR GLASS FRT RH	\$	<i>Su</i> 625.96	
1	DOOR MIRROR ASSY RH	\$	<i>Bn</i> 727.90	✓
1	DOOR MIRROR BACK COVER RH	\$	<i>Mrs</i> 128.70	✓
1	DOOR MIRROR GLASS RH	\$	<i>Su</i> 242.33	X
1	DOOR MIRROR LAMP RH	\$	<i>Su</i> 134.10	X

Trans-cab Auto Services Pte Ltd

AAD1911-001

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5323A

1	DOOR SEAL LOWER FRONT RH	\$	S ₂ 91.17	X
1	DOOR HARNESS WIRE RH	\$	S ₂ 2,670.00	X
1	DOOR HINGE PILLAR PANEL OUTER FRT RH	\$	S ₂ 2,896.14	X
1	FENDER PANEL FRT RH	\$	A 437.10	X
TOTAL		\$	19,285.91	
10%		\$	1,928.59	
		\$	17,357.32	

Special Nett

1	FRONT DOOR STICKER 'Trans-Cab'	\$	M 80.00	605m
1	FRONT DOOR STICKER 'Classic'	\$	M 80.00	155m
1	DOOR CHECK BOLT	\$	S ₂ 22.69	} X
1	DOOR GUIDE SCREW	\$	S ₂ 10.85	
1	DOOR HINGE BOLT	\$	S ₂ 10.85	
1	DOOR HINGE NUT RH	\$	S ₂ 14.60	
1	DOOR CHECK NUT	\$	S ₂ 3.75	
1	DOOR LOCK SCREW L70Y	\$	S ₂ 6.12	
1	DOOR CATCH SCREW L70Y	\$	S ₂ 10.06	
1	FRONT RIGHT TYRE	\$	S ₂ 300.00	
1	FRONT RIGHT TYRE RIM	\$	S ₂ 380.00	
TOTAL		\$	918.94	
TOTAL PARTS		\$	18,276.26	

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	7,500.00	2501
Putty and spray painting of the affected portion.	\$	7,500.00	2801
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	M 380.00	X
To check steering geometry and computer wheel alignment	\$	M 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	M 170.00	X

Trans-cab Auto Services Pte Ltd

AAD1911-001

No. 2 Ang Mo Kio Street 63 Singapore 569111
Tel No. : 6287 6666 Fax No. : 6257 1330
CO./GST Reg. No. 201019626G

SHC 5323A

To Check Electrical Lighting Concerned.	\$	170.00	<i>201</i>
To rust-proofing of the affected areas.	\$	170.00	<i>301</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00	<i>X</i>
To transfer of door fittings, attachment and perform water seepage test.	\$	380.00	<i>601</i>
TOTAL	\$	16,870.00	
Over All Total	\$	35,146.26	

LUMP SUM (REPAIR DAY)

~~25 DAYS~~

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: