

1009000

INS. CASE OWNER:

CC 4/III1901

9576, A g... s3

LKK: IDAC:

Surveyor:

Adrian

DOI:

ASSIGNMENT

5/11/19

Date / Time:

4/11/19

Registered in Merimen:

5/11/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHC 8961M

Claim No.:

Name of Insured:

LTDL

Policy No.:

MILANO 015

Insured Tel No.:

HP:

Make / Model:

LANCOST

Excess Sec II :\$:

D.O.A.:

2/11/19

Place of Accident:

TAMPINES AVE 9 THOS

Is driver the owner? (YES / NO)

(YES / NO)

Nature of Accident:

TAMPINES AVE 12

If NO, Driver Name / Age:

AND TONY BOON

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

SLT 2761B



INSRS: WSP: Tel: Liability: RMKS: W-51



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:

Date/Time	STAGE	DATE / PIC
26/12	Pending liability approval ✓	
15/1	Check to Adrian on LOR amt. Not reply to WSP calculation.	
16/1	File PASS RT type report ✓	
26/1	Under mandate approval ✓	
26/1	Off GRS #7190 (pending acceptance) to recall off, please #7200, 15, re-off GRS #7200 (pending acceptance).	
27/1	Letter to GRS #7200, the pic to be send on.	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input checked="" type="checkbox"/>
	After call ltr to OI:	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice:	<input checked="" type="checkbox"/>
	LTA / GIA:	<input checked="" type="checkbox"/>
	Medical Bill:	<input checked="" type="checkbox"/>
	PIR:	<input checked="" type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD:	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input checked="" type="checkbox"/>
	Post-Repair Photos:	<input checked="" type="checkbox"/>
	Others:	<input checked="" type="checkbox"/>

PRELIMINARY ADVICE Date/Time: Sent By: Confirm with: Confirm by: Adrian

FINALIZATION Repair Cost: \$6,700.00 (6 days) Reduction: \$350.40 @ 5% Email: Call:

FINAL SETTLEMENT Date/Time: Confirm with: Email: Call:

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 29.
 Repair Cost: (MOT) \$6,741.00
 Loss of Rental (LOR): \$540.00 (\$60 x 9 days)
 Loss of Use (LOU): \$540.00 (\$60 x 9 days)
 Loss of Income (LOI): \$ - (\$ x days)
 LOR only LOU only LOR + LOU LOR + LO (Tick only one)
 GIA/LTA Search: \$ -
 Medical: \$ -
 Disbursement: \$ - (e.g. Tow/ Independent)
 Legal Cost: \$ -
 Total: \$7,281.00 Global Sum \$: \$7,280.00

COPY SENT 5/3/2020

FINAL PAYMENT Date/Time: Confirm with: Email: Call:

Payee 1: \$7,200.00 Name 1: N-51 Automotive PR Ltd
 Payee 2: (Strike if N.A.) \$ Name 2:
 Payee 3: (Strike if N.A.) \$ Name 3:

ASS. REC. BY:

REP:

TD

ASSIGNMENT

From: _____ Date: 05/11/19

Veh No: SLT2761B Yr Regn: 2017, Oct.

Estimated Cost: _____

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or _____

To Inspect Vehicle No: SLT 2761B

Make: Honda Vezel Hybrid

at Workshop m/s N51

Colour: Black A/C: Insured / Std / NI / NA

of 2 KINGS BUCKET AVE 2401-18

Sp. Reading: 150995 T/Radio: Insured / Std / NI / NA

Insured: _____

Eng/No: _____

Policy No. _____

C/No: Ru31253153

Claims No. _____

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: _____ Excess: _____

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh: _____

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Tyre Size: F: 215/60R16

R: 215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Habilead.

Bal. or Market Value: _____

Front R/Bal. 06 mm

Rear R/Bal. 06 mm

IDAC Accident Rpt: _____ Consistent? : Yes or No

L/Bal. 06 mm

D.O.A. _____ D.O.I. 05/11/19

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

Survey held at N51

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP III
	L/S #6300/- (Red = #7650.40 / 37/-)
	* 6 repair days + 2 PRS + 1 Sunday = 9 days.

Date/Time, File Pass to? : Preli. Report

Days Of Repair: _____

1) : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee:	
Transportation:	
S + RS	\$
Phone	
Other	
TOTAL	

2) _____

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Report Format: _____

Lump Sum / T.E.P.: _____

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-08 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005-GRAB 87484016

TP III
 Cecilia

ESTIMATE

Repair Code : CLM15743
 Date in : 02/11/2019
 Vehicle Num. : SLT2761B
 Model : HONDA VEZEL HYBRID 1.5X AUTO
 Chassis/Eng# : RU31253153/LEB5953172

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Rehd</i>	1	762.70	✓ 762.70
REAR BUMPER LOWER COVER <i>to m</i>	1	250.00	✓ 250.00
REAR BUMPER REFLECTOR L/R <i>cauld</i>	2	141.10	✓ 282.20
REAR BUMPER SIDE L/R <i>Rehd</i>	2	195.00	✓ 390.00
REAR BUMPER SIDE RETAINER L/R <i>neu</i>	2	23.00	✓ 46.00
REAR END PANEL <i>Dented</i>	1	415.60	✓ 415.60
REAR END PANEL ANTENNA SENSOR <i>cauld</i>	1	60.10	✓ 60.10
REAR END PANEL BUZZLE SENSOR <i>cauld</i>	1	85.20	✓ 85.20
REAR END PANEL INNER TOP GARNISH <i>deloimed</i>	1	98.00	✓ 98.00
REAR EXHAUST CHROME TAIL PIPE <i>neu neu</i>	1	135.00	X 135.00
REAR FENDER ARCH GARNISH L/R <i>neu</i>	2	195.00	+ 390.00
REAR FLOOR JACK PANEL <i>Repair</i>	1	95.00	X 95.00
REAR FLOOR PANEL COMPARTMENT TRAY GARNISH <i>cauld</i>	1	485.30	327 485.30
REAR FLOOR PANEL INNER TOP BOARD COVER <i>deloimed</i>	1	430.30	265 430.30
REAR LH FENDER INNER TRIM GARNISH <i>Rehd</i>	1	295.00	✓ 295.00
REAR TAILGATE <i>Distorted</i>	1	953.30	✓ 953.30
REAR TAILGATE 'HYBRID' EMBLEM	1	75.80	✓ 75.80
REAR TAILGATE 'VEZEL' EMBLEM <i>neu</i>	1	56.20	✓ 56.20

*** This is a computer-generated document which requires no signature.***

-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-08 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005-GRAB 87484016

ESTIMATE

Repair Code : CLM15743
 Date in : 02/11/2019
 Vehicle Num. : SLT2761B
 Model : HONDA VEZEL HYBRID 1.5X AUTO
 Chassis/Eng# : RU31253153/LEB5953172

REAR TAILGATE INNER PULL GARNISH <i>neu</i>	1	27.50	X 27.50
REAR TAILGATE INNER TRIM GARNISH <i>could</i>	1	153.40	/ 153.40
REAR TAILGATE MECHANISM LOCK <i>Damaged</i>	1	180.00	✓ 180.00
REAR TAILGATE MECHANISM LOCK STRIKER <i>neu</i>	1	27.50	X 27.50
REAR TAILGATE OUTER GARNISH <i>could</i>	1	220.00	/ 220.00
REAR TAILGATE OUTER GARNISH 'H' LOGO EMBLEM <i>neu</i>	1	25.00	/ 25.00
REAR TAILGATE REFLECTOR BACK RUBBER GASKET L/R <i>neu</i>	2	38.50	40 77.00
REAR TAILGATE REFLECTOR L/R <i>could</i>	2	413.20	826.40 852.40
REAR TAILGATE RUBBER GUIDE STOPPER L/R <i>neu</i>	2	18.50	X 37.00
REAR TAILGATE WEATHER STRIP <i>wt</i>	1	96.80	/ 96.80
REAR TAILGATE WINDSCREEN INNER SEAL <i>neu</i>	2	50.00	100.00 6711.90
REAR TAILGATE WINDSCREEN MOULDING <i>neu</i>	2	50.00	100.00 5369.52
REAR TAILLAMP L/R <i>could</i>	2	474.60	✓ 949.20
Subtotal before discount			8,125.50
Percentage discount 20%			1,625.10
Sub-total 1			6,500.40
REAR BUMPER CLIPS - SET <i>neu</i>	1	50.00	50.00 30
REAR BUMPER REVERSE SENSOR - SET <i>Damaged</i>	1	250.00	250.00 200

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-08 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005-GRAB 87484016

ESTIMATE

Repair Code : CLM15743
 Date in : 02/11/2019
 Vehicle Num. : SLT2761B
 Model : HONDA VEZEL HYBRID 1.5X AUTO
 Chassis/Eng# : RU31253153/LEB5953172

REAR FENDER ARCH GARNISH CLIPS L/R - SET <i>new</i>	2	30.00	40 60.00
REAR FENDER INNER TRIM GARNISH CLIPS L/R - SET <i>new</i>	2	50.00	30 100.00
REAR TAILGATE INNER TRIM GARNISH CLIPS - SET <i>new</i>	1	50.00	30 50.00
REAR TAILLAMP CLIPS L/R - SET <i>new</i>	2	20.00	✓ 40.00
Subtotal before discount			550.00
Percentage discount 0%			0.00
Sub-total 2			550.00
Parts-total			7,050.40

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.			✓ 50.00
To remove, reinstall tailgate windscreen			120 150.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	2/70		60 120.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.			820 1,300.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.			820 820 1,100.00
To apply anti-rust chemical on repaired and replaced panel.			60 100.00
To remove, reinstall tailgate mechanism and check for function			✓ 80.00
Labour Total			2,900.00
Parts & Labour Total			9,950.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices and ***** This is a computer-generated document which requires no signature.*****
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

page 3

Adrian Lij total: 7909.52
 1/2 05/11/19. 1/2: 63K
 0.6 Days. 63K

Summer Lee (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Monday, 4 November, 2019 4:10 PM
To: Chio Ziting; 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: Zuhaidah Samsuri
Subject: RE: SLT2761B & SHC8961M - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS
Attachments: 04112019123831-0001.pdf; 2761.pdf

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SLT2761B and let us have your report urgently.

This claim will be handled by Ms Aida.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee

Adrian



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Chio Ziting [mailto:ziting@n51.com.sg]
Sent: 04 November, 2019 3:46 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Re: SLT2761B & SHC8961M - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS

Dear Sir / Madam,

We appoint your surveyor Mr Adrian Ling from Lkk Auto Consultants Pte Ltd.

Please see attached.

Thank you.

Regards,
Zi Ting

P: Sabrina

T: 4.14pm

V: 1y

G: ✓

N-51 Automotive Pte Ltd

Office: 6842 0051

Fax: 6741 0510

www.n51.com.sg



On Mon, Nov 4, 2019 at 1:22 PM Motor Claim - III <motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee



64 Cecil Street; #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext – 248

From: Chio Ziting [mailto:ziting@n51.com.sg]

Sent: 04 November, 2019 12:47 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: SLT2761B & SHC8961M - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS

Dear Sir/Madam,

As per above subject,

Please refer to attachment and:-

Kindly propose / provide your 10 surveyors

Thank you

Regards,

Zi Ting

N-51 Automotive Pte Ltd

Office: 6842 0051

Fax: 6741 0510

www.n51.com.sg



Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful.

Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful.

Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K



CONFIDENTIAL

Date:

Grab Rentals Pte Ltd
201617200G
Grab Rentals 2 Pte. Ltd.
201701345N

28 Sin Ming Lane
#01-138 Midview City
Singapore 573972

Dear Sir / Madam,

Accident Date:	02/11/2019	Time:	15:30 HRS
Accident Location:	TAMPINES ROAD		

We refer to the above-mentioned accident & wish to inform the following details at the time of occurrence of the aforementioned accident:

Registered Owner:	* (Grab Rentals Pte. Ltd.) Grab Rentals 2 Pte. Ltd.*		
Vehicle Registration No. (the "private hire"):	CLT 2761B		
Registered Hirer Name:	CHONG KIM HOE		
Registered Hirer NRIC:			
Rental Rate (per day inclusive of GST):	SG\$	76.95	
Rental Period:			

* delete as applicable

The following procedures were followed:

Period of repair	From:	02/11/2019
	To:	08/11/2019
Rental	The company:	Collects / Does not collect*.
	Replacement vehicle:	Provided / Not provided*
	From:	
	To:	

* delete as applicable

Please liaise with our appointed workshop, N51 Automotive Pte. Ltd. directly for any settlement of claims in respect of the said accident.

We hereby authorize all agreed settlement payments made in favour of N51 Automotive Pte. Ltd.

Yours faithfully



Name: Tay Chee Wee
Senior Operations Associate

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Nov 2019 Edit Reg		04 Nov 2019 00:00 Edit Adj Rpt	S\$6,300.00 Edit Estimates	S\$6,300.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Main Claimant:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G								
Vehicle Reg. No.:	SLT2761B	Date of Loss:	02/11/2019 15:00 - :59 [24 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT19110040	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHC8961M	Policy No. (Claimant):	A29114756MKF						
		Excess:							
Repairer:	N-51 Automotive Pte Ltd (kaki Bukit Autohub) (HQ) KAKI BUKIT AUTOHUB 2 KAKI BVUKIT AVE 2 #01-18, 417921 Kaki Bukit - Tel:								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 14/11/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> III_SG (21/02/2020): Alert - Adj Mandate Approved (S\$7281.00) - SLT2761B - Claim Handler: Zuhaidah Bt... III_SG (26/12/2019): Alert - Adj Mandate Approved (S\$0.00) - SLT2761B - Claim Handler: Zuhaidah Bte S... 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLT2761B (MCT19110040)
[SHC8961M]
TP
GRAB RENTALS PTE LTD
Nov 2 2019 3:00PM
[COMFORT TRANSPORTATION PTE LTD]
N-51 Automotive Pte Ltd (kaki Bukit Autohub)

Upload Documents			Upload Photos		Compose New Letter		View	View in Browser
Photos/Images							3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	11/11/19 10:20	General View		Load JPG	<input checked="" type="checkbox"/>			
2	11/11/19 10:20	General View		Load JPG	<input checked="" type="checkbox"/>			
3	11/11/19 10:20	General View		Load JPG	<input checked="" type="checkbox"/>			
4	11/11/19 10:20	General View		Load JPG	<input checked="" type="checkbox"/>			
5	11/11/19 10:20	General View		Load JPG	<input checked="" type="checkbox"/>			
6	11/11/19 10:20	General View		Load JPG	<input checked="" type="checkbox"/>			
7	11/11/19 10:20	General View		Load JPG	<input checked="" type="checkbox"/>			
8	11/11/19 10:20	General View		Load JPG	<input checked="" type="checkbox"/>			
9	11/11/19 10:20	General View		Load JPG	<input checked="" type="checkbox"/>			
10	11/11/19 10:20	General View		Load JPG	<input checked="" type="checkbox"/>			
11	11/11/19 10:20	General View		Load JPG	<input checked="" type="checkbox"/>			
12	11/11/19 10:20	General View		Load JPG	<input checked="" type="checkbox"/>			
13	11/11/19 10:20	General View		Load JPG	<input checked="" type="checkbox"/>			
14	11/11/19 10:20	General View		Load JPG	<input checked="" type="checkbox"/>			
15	11/11/19 10:20	General View		Load JPG	<input checked="" type="checkbox"/>			
16	11/11/19 10:20	General View		Load JPG	<input checked="" type="checkbox"/>			
17	11/11/19 10:20	General View		Load JPG	<input checked="" type="checkbox"/>			
18	11/11/19 10:20	General View		Load JPG	<input checked="" type="checkbox"/>			
19	11/11/19 10:20	General View		Load JPG	<input checked="" type="checkbox"/>			
20	11/11/19 10:20	General View		Load JPG	<input checked="" type="checkbox"/>			
21	11/11/19 10:20	General View		Load JPG	<input checked="" type="checkbox"/>			
22	11/11/19 10:20	General View		Load JPG	<input checked="" type="checkbox"/>			
23	11/11/19 10:20	General View		Load JPG	<input checked="" type="checkbox"/>			
24	11/11/19 10:20	General View		Load JPG	<input checked="" type="checkbox"/>			
25	11/11/19 10:20	General View		Load JPG	<input checked="" type="checkbox"/>			
26	11/11/19 10:20	General View		Load JPG	<input checked="" type="checkbox"/>			
27	11/11/19 10:20	General View		Load JPG	<input checked="" type="checkbox"/>			
28	11/11/19 10:20	General View		Load JPG	<input checked="" type="checkbox"/>			
29	11/11/19 10:20	General View		Load JPG	<input checked="" type="checkbox"/>			
30	11/11/19 10:20	General View		Load JPG	<input checked="" type="checkbox"/>			
31	11/11/19 10:20	General View		Load JPG	<input checked="" type="checkbox"/>			
32	11/11/19 10:20	General View		Load JPG	<input checked="" type="checkbox"/>			
33	11/11/19 10:20	General View		Load JPG	<input checked="" type="checkbox"/>			
34	11/11/19 10:20	General View		Load JPG	<input checked="" type="checkbox"/>			
35	11/11/19 10:20	General View		Load JPG	<input checked="" type="checkbox"/>			
36	11/11/19 10:20	General View		Load JPG	<input checked="" type="checkbox"/>			
37	11/11/19 10:20	General View		Load JPG	<input checked="" type="checkbox"/>			
38	11/11/19 10:20	General View		Load JPG	<input checked="" type="checkbox"/>			
39	11/11/19 10:32	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>			
40	11/11/19 10:32	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>			
41	11/11/19 10:32	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>			
Documentation							1 per page	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/11/19 15:26	EMAIL FROM III DD 04112019	 Load PDF	
2	05/11/19 15:26	NOTICE & GIA REPORT	 Load PDF	
3	16/01/20 10:16	LOD AND OTHER DOCUMENTS	 Load PDF	
4	05/02/20 15:28	WORKSHOP INVOICE	 Load PDF	
5	05/02/20 15:28	LTA SEARCH	 Load PDF	
6	05/02/20 15:28	LOD	 Load PDF	
7	06/03/20 10:03	AUTHORISATION TO ACT FORM	 Load PDF	
8	06/03/20 10:03	DISCHARGE VOUCHER	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	06/11/19 08:32	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 30px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19019536/AGS3Q2

Date: 06/03/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant Vehicle No : SLT2761B Insured Vehicle No : SHC8961M
 Date of Loss: 02/11/2019 Nature of Claim: TP Claim No: MCT19110040

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLT2761B
 Make & Model: HONDA VEZEL, 1.5 HYBRID X (A) Engine No: LEB5953172
 Reg. Date: 24/10/2017 (Man. Year: 2017) Chassis No: RU31253153
 Colour: Black Odometer: 150995 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: Habilead 6 mm Rear Left Side: Habilead 6 mm
 Front Right Side: Habilead 6 mm Rear Right Side: Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,050.40	5,889.12	1,161.28	16.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,900.00	2,070.00	830.00	28.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,950.40	7,959.12	1,991.28	20.01
Approved Total (Overridden) (S\$)		6,300.00		
(S\$)	9,950.40	6,300.00	3,650.40	36.69
+ GST 7.00/7.00% (S\$)	696.53	441.00	255.53	36.69
Nett Amount (S\$)	10,646.93	6,741.00	3,905.93	36.69
+ Loss of Use (9.0 x S\$60.00/day) (S\$)		540.00		
Nett Liability (S\$)		7,281.00		
Global Sum Settlement (S\$)		7,200.00		

INSPECTION

Date of Assignment: 04/11/2019
 Date Inspected: 05/11/2019 Inspected At: N-51 Automotive Pte Ltd (kaki Bukit Autohub) (HQ)
 KAKI BUKIT AUTOHUB 2 KAKI
 BVUKIT AVE 2 #01-18
 Singapore 417921
 Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 22 Jan 2020)	
Parts: M1-SUV	HONDA VEZEL 1.5 HYBRID X (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SLT2761B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	762.70 FL	*762.70 FL
2	1		*REAR BUMPER LOWER COVER	Torn	250.00 FL	*250.00 FL
3	2		*REAR BUMPER REFLECTOR L/R	Cracked	282.20 FL	*282.20 FL
4	2		*REAR BUMPER SIDE L/R	Deformed	390.00 FL	*390.00 FL
5	2		*REAR BUMPER SIDE RETAINER L/R	Necessary	46.00 FL	*46.00 FL
6	1		*REAR END PANEL	Dented	415.60 FL	*415.60 FL
7	1		*REAR END PANEL ANTENNA SENSOR	Cracked	60.10 FL	*60.10 FL
8	1		*REAR END PANEL BUZZLE SENSOR	Cracked	85.20 FL	*85.20 FL
9	1		*REAR END PANEL INNER TOP GARNISH	Deformed	98.00 FL	*98.00 FL
10	1		*REAR EXHAUST CHROME TAIL PIPE	Not Necessary	135.00 FL	*- FL
11	2		*REAR FENDER ARCH GARNISH L/R	Not Necessary	390.00 FL	*- FL
12	1		*REAR FLOOR JACK PANEL	Repair	95.00 FL	*- FL
13	1		*REAR FLOOR PANEL COMPARTMENT TRAY GARNISH	Cracked	485.30 FL	*327.00 FL
14	1		*REAR FLOOR PANEL INNER TOP BOARD COVER	Deformed	430.30 FL	*285.00 FL
15	1		*REAR LH FENDER INNER TRIM GARNISH	Deformed	295.00 FL	*295.00 FL
16	1		*REAR TAILGATE	Distorted	953.30 FL	*953.30 FL
17	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	75.80 FL	*75.80 FL
18	1		*REAR TAILGATE VEZEL EMBLEM	Necessary	56.20 FL	*56.20 FL
19	1		*REAR TAILGATE INNER PULL GARNISH	Not Necessary	27.50 FL	*- FL
20	1		*REAR TAILGATE INNER TRIM GARNISH	Cracked	153.40 FL	*153.40 FL
21	1		*REAR TAILGATE MECHANISM LOCK	Damaged	180.00 FL	*180.00 FL
22	1		*REAR TAILGATE MECHANISM LOCK STRIKER	Not Necessary	27.50 FL	*- FL
23	1		*REAR TAILGATE OUTER GARNISH	Cracked	220.00 FL	*220.00 FL
24	1		*REAR TAILGATE OUTER GARNISH H LOGO EMBLEM	Necessary	25.00 FL	*25.00 FL
25	2		*REAR TAILGATE REFLECTOR BACK RUBBER GASKET L/R	Necessary	77.00 FL	*40.00 FL
26	2		*REAR TAILGATE REFLECTOR L/R	Cracked	826.40 FL	*652.40 FL
27	2		*REAR TAILGATE RUBBER GUIDE STOPPER L/R	Not Necessary	37.00 FL	*- FL
28	1		*REAR TAILGATE WEATHER STRIP	Cut	96.80 FL	*96.80 FL
29	2		*REAR TAILGATE WINDSCREEN INNER SEAL	Necessary	100.00 FL	*100.00 FL
30	2		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	100.00 FL	*100.00 FL
31	2		*REAR TAILLAMP L/R	Cracked	949.20 FL	*949.20 FL
32	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
33	1		*SET REAR BUMPER REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
34	2		*SET REAR FENDER ARCH GARNISH CLIPS L/R	Necessary	60.00 FS	*40.00 FS
35	2		*SET REAR FENDER INNER TRIM GARNISH CLIPS L/R	Necessary	100.00 FS	*30.00 FS
36	1		*SET REAR TAILGATE INNER TRIM GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
37	2		*SET REAR TAILLAMP CLIPS L/R	Necessary	40.00 FS	*40.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
F=Franchise part. S=SpcNett. L=ListItemDisc.							
					Sub Total (\$\$)	8,675.50	7,268.90
					- List Item Discount on L Items 20.00/20.00% (\$\$)	1,625.10	1,379.78
					Total Parts (\$\$)	7,050.40	5,889.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, AND REWIRE FOR PARKING SENSOR.	New	50.00	50.00
2	TO REMOVE, REINSTALL TAILGATE WINDSCREEN.	New	150.00	120.00
3	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)	New	120.00	60.00
4	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.	New	1,300.00	900.00
5	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.	New	1,100.00	800.00
6	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.	New	100.00	60.00
7	TO REMOVE, REINSTALL TAILGATE MECHANISM AND CHECK FOR FUNCTION.	New	80.00	80.00
Gross Labour Cost (S\$)			2,900.00	2,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >