

INS. CASE OWNER:

Shervini

CC 3 / III 1901 9542, 12983

LKK:
IDAC:

ASSIGNMENT

Surveyor:

TANJEN

DOI:

20/11/19

Date / Time:

5/11/19

Registered in Merimen:

5/11/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHC 3372X

Name of Insured:

LPL

Insured Tel No.:

HP:

Excess Sec II :S\$

D.O.A.:

20/10/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Ang Leong Yoke

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

M1/MODVH

Hyundai

LIMONTI ave 3.

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

SKN 18715



INSRS:

WSP:

Tel:

Liability:

RMKS:

Performance



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

4/11/19 - 1

SHC 3372X - 1

STAGE

DATE / PIC

7/11

Pending liability approval (approved)

Non-Reporting 1st (1st):

Non-Reporting 1st (2nd):

Non-Reporting 1st (Final):

Notification 1st (if non-pickup):

Call OI:

After call 1st to OI:

11/11

Waiting clear call to

12/11

2nd call to TP (pending LOD)

13/11

LOD in, file pass RT type report

20/11

Pending mandate approval

5/12

off & settle @ \$4357.47, in m, file

RAGI MP to close

Documentation Check List: Handler Typist

Notification 1st (if non-pickup)

After call 1st to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: TANJEN

Repair Cost:

P/P

S\$ 3135.95

(3

days) Reduction:

\$839.70

% 18

Email

Call

FINAL SETTLEMENT

Date/Time:

5/12/2020

Confirm with:

Caroline

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

79

If NO or B 28, Ass. Lia:

Repair Cost:

(UNASS)

S\$ 3135.95

Loss of Rental (LOR):

S\$ -

(

days)

Loss of Use (LOU):

S\$ 360.00

(\$ 120

x 3

days)

Loss of Income (LOI):

S\$ -

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

S\$ -

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

Total:

S\$

4357.47

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

4357.47

Name 1:

Performance Motors Limited

Payee 2: (Strike if N.A.)

S\$ -

Name 2:

Payee 3: (Strike if N.A.)

S\$ -

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

\$350

COPY SENT
6/2/2020

www.Darby.com

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401339W GST Reg. No. M2-0020081-X
Toll-Free Number (1800-2335289)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

289, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796401 (AfterSales)
64796424 (MotorVad)



GST REG. NO : M2 - 0020081 - X

05 NOV 2019

ESTIMATE

Estimate No. : b1 53326
Date Estimated : 05/11/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -
Sim Kin Song
341 Upper Bukit Timah Road
#06-05

Singapore 588195

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKN1871S	WBA5A32000D334505	21/05/2014	5201A	0

DESCRIPTION

To replace rear bumper and attachments.

Painting rear bumper.

To check electrical wiring systems and lightings at the rear section for proper function.

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.

Sundries.

LKK Auto Consultants hence notify the Repairer of the following:
• No resurvey before/after spray painting
• To employ competent painter during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

VALUE
850 1,275.00
474 1,038.00
150 177.00
150 177.00
80.00

Total Labour 1: 2,747.00

DESCRIPTION

Set of mount
RR RH MOUNT
REAR BUMPER PRIMED (PDC)

QTY	PRIC	VALUE
1	63.55	63.55
1	193.15	193.15
1	1,571.95	1,571.95

Total Parts : 1,828.65

Claims OD / 3rd Party / Uninsured losses / Direct Settlement
Claim No.

Work Time: 20/11/2019
Surveyor's Name: Tan Jie
Signature: [Signature]
Authorised: Yes / No
Time: 03 days
RE: UNQUOTE BY SURVEYOR Yes / No PNL Yes / No
Surveyor's Name: Tan Jie

Labour 1	:	2,747.00
Parts	:	1,828.65
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	320.30
Grand Total	:	4,895.95

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Email To 04/12/19
COR 93735.95, 1 days



Final Report

Estimate No. : **b1 53326**
Date Estimated : **05/11/2019**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -
Sim Kin Song
341 Upper Bukit Timah Road
#06-05

Singapore 588195

- ACCOUNT - 219
India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKN1871S	WBA5A32000D33450	21/05/2014	520iA	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper including to remove and install body parts in order to carry out painting job.	850.00	0	850.00
To respray rear bumper.	934.00	0	934.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00	0	150.00
To remove old PDC assembly and reconnect to new bumper including conduct checks for proper function.	150.00	0	150.00
Sundries.	80.00	0	80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER PRIMED (PDC)	1,571.95	1.00	0	1,571.95

Total Labour :	2,164.00
Total Parts :	1,571.95
Total Labour & Parts :	3,735.95 ✓
GST @7%:	261.52
Grand Total :	3,997.47

LOSS OF USE = \$120 X 3 DAYS

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159943
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 436180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

05 NOV 2019

ESTIMATE

Estimate No. : b1 53326 1415945
Date Estimated : 05/11/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

Sim Kin Song
341 Upper Bukit Timah Road
#06-05

Singapore 588195

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKN1871S	WBA5A32000D334505	21/05/2014	520iA	0

DESCRIPTION

To replace rear bumper and attachments.

VALUE

850 1,275.00

Painting rear bumper.

934 1,038.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.

150 177.00

Sundries.

80.00

Total Labour 1: 2,747.00

DESCRIPTION

Set of mount
RR RH MOUNT
REAR BUMPER PRIMED (PDC)

QTY	PRIC	VALUE
1	63.55	NE 63.55
1	193.15	193.15
1	1,571.95	del 1,571.95

Total Parts : 1,828.65

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Bump No. Claim No.

Time 20/11/2019 Excess \$5

Surveyor's Name Tan M Sign

Surveyor Tel 97495749 Authorised Yes / No

A. W. up Time

RE PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's L. up

03 days

Labour 1 : 2,747.00

Parts : 1,828.65

Labour 2 : 0.00

Excess : 0.00

Total GST @ 7% : 320.30

Grand Total : 4,895.95

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Certificate of Insurance

**MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
 MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
 ROAD TRANSPORT ACT, 1987 (MALAYSIA)
 MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)**

Cert No./Policy No. : D19MTPV0100503
Insured : SIM KIN SONG
Motor Car (Registration No.) : SKN1871S
Cover : Comprehensive - EXCELDRIVE PRESTIGE
Policy Commencement Date : 21 MAY 2019 00:00
Policy Expiry Date : 20 MAY 2020 23:59
Maximum Liability (Section I) : Market value at time of loss
Excess* : \$500 - Section I
 (Waived up to S\$1,000 if accident repair is done at ExcelDrive Workshops for the first claim per policy year)
Voluntary Excess* : N/A
Windscreen Excess* : S\$100.00 - Waived if Repair at ExcelDrive Workshop
Loss of Use : Per Policy Schedule
 * Subject to GST wherever applicable

Persons or Classes of Persons entitled to drive*

1. The Insured.
2. Any other person who is driving on the Insured's order or with his permission.
3. In the event of the death of the Insured,
 - a. any member of the Insured's family, or a paid driver who has been driving the Motor Car during the life of the Insured and permission to drive had not been withdrawn prior to the death of the Insured; and
 - b. any other person who has been given permission to drive the Motor Car prior to the death and such permission had not been withdrawn by the Insured.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Car or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Car. And provided further that the Motor Car is registered under the Road Traffic Act (Chapter 276) and its registration under the Road Traffic Act (Chapter 276) has not been cancelled at the time of the accident, loss or damage.

Limitations As To Use

Use only for social, domestic and pleasure purpose and for the Insured's business. The Policy does not cover use for hire or reward, racing, pace-making, speed testing, reliability trial, the carriage of goods other than samples in connection with any trade or business or use for any purposes in connection with the Motor Trade.

ExcelDrive Workshops and Accident Reporting


It is a condition precedent to liability that the Insured shall call at the Company's Accident Reporting Center with the Motor Car within 24 hours of the accident or by the next working day thereafter.

All accident repairs to the Motor Car must be carried out at ExcelDrive Workshops, otherwise the claim is not payable under the Policy. For ExcelDrive Prestige Plan, accident repairs to the Motor Car can be carried out at any workshop other than ExcelDrive Workshops.

For the list of Accident Reporting Centres and ExcelDrive Workshops, please visit our website at www.sompo.com.sg or call our Emergency Hotline: (65) 6226 3323.

WE HEREBY CERTIFY that the policy to which this Certificate relates is issued in accordance with (1) the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia), and (2) the Policy terms, conditions and exclusions of the Private Car Policy ref MTP 27

Sompo Insurance Singapore Pte. Ltd.



Authorised Signatory

Date/Time of Issue : 17 APRIL 2019 16:11

IMPORTANT NOTICE

1. Keep this Certificate in your Motor Car.
2. Under the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189), it shall be unlawful for any person to use or cause to permit any other person to use a motor vehicle without a valid policy of insurance under the Act.
3. On the sale of the Motor Car or if for any reason the Insurance is terminated during its currency, the Insured must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a statutory declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189).
4. This Policy will cease to be valid once the Motor Car has been sold to another person. The Policy is not transferable to the new owner of the Motor Car.

Intermediary Code & Name : 11504405 & SIME DARBY INSURANCE BROKERS (S) PTE LTD **CI Code** : 22A-3H000L04B25B6EA

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X
Toll-Free Number (1800-2258269)

103, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kembangan Road
East Coast Centre
Singapore 438188
Fax: 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64756601 (AfterSales)
64756624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

05 NOV 2019

ESTIMATE

Estimate No. : b1 53326
Date Estimated : 05/11/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -
Sim Kin Song
341 Upper Bukit Timah Road
#06-05

Singapore 588195

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKN1871S	WBA5A32000D334505	21/05/2014	5201A	0

DESCRIPTION

To replace rear bumper and attachments.

Painting rear bumper.

To check electrical wiring systems and lightings at the rear section for proper function.

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.

Sundries.

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged parts during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

VALUE

850 1,275.00

934 1,038.00

150 177.00

150 177.00

80.00

Total Labour 1: 2,747.00

DESCRIPTION

Set of mount

RR RH MOUNT

REAR BUMPER PRIMED (PDC)

QTY	PRIC	VALUE
1	63.55	63.55
1	193.15	193.15
1	1,571.95	1,571.95

Total Parts : 1,828.65

Claims ID / 3rd Party / Uninsured losses / Direct Settlement

Claim No.

Excess \$

Sign

Authorised Yes / No

Time

REPAIR BY SURVEYOR Yes / No

PML Yes / No

Signature

03 days

Labour 1 : 2,747.00

Parts : 1,828.65

Labour 2 : 0.00

Excess : 0.00

Total GST @ 7% : 320.30

Grand Total : 4,895.95

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

4575.65

Print Received Message

This mail is associated with :

***SKN1871S (MCT19100745)**
[SHC3372X]
TP
SIM KIN SONG
Oct 30 2019 5:00PM
[-]
Performance Motors Limited

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 27/12/2019 10:12 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$4357.47) - SKN1871S - Claim Handler: Sherini Pillai

Approved:4357.47:Please negotiate LOU @ \$100 first.

Print Received Message

This mail is associated with :

*SKN1871S (MCT19100745)
[SHC3372X]
TP
SIM KIN SONG
Oct 30 2019 5:00PM
[-]
Performance Motors Limited

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 20/01/2020 09:38 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$4357.47) - SKN1871S - Claim Handler: Sherini Pillai

Approved:4357.47.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Dec 2019 Edit Reg		20 Nov 2019 00:00 Edit Adj Rpt	S\$3,735.95 Edit Estimates	S\$3,735.95 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R									
Main Claimant: SIM KIN SONG , ID: S0028383E									
Vehicle Reg. No.: SKN1871S		Date of Loss: 30/10/2019 17:00 - :59 [65 Months and 9 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / MCT19100745		Policy/Cover Note No.: MCOM0015							
Vehicle Reg. No. (Insured): SHC3372X		Policy No. (Claimant): D19MTPV01006503							
		Excess:							
Repairer: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174									
Handling Insurer: India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]									
Claimant's Insurer: Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 14/11/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (20/01/2020): Alert - Adj Mandate Approved (S\$4357.47) - SKN1871S - Claim Handler: Sherini Pillai - III_SG (27/12/2019): Alert - Adj Mandate Approved (S\$4357.47) - SKN1871S - Claim Handler: Sherini Pillai - III_SG (07/11/2019): Alert - Adj Mandate Approved (S\$0.00) - SKN1871S - Claim Handler: Sherini Pillai									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKN1871S (MCT19100745)
[SHC3372X]
TP
SIM KIN SONG
Oct 30 2019 5:00PM
[COMFORT TRANSPORTATION PTE LTD]
Performance Motors Limited

[Upload Documents](#) | [Upload Photos](#) | [Compose New Letter](#)

View View in Browser

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	04/12/19 17:55	Odometer Reading		Load JPG	☒
2	04/12/19 17:55	Chassis Number		Load JPG	☒
3	04/12/19 17:55	General View		Load JPG	☒
4	04/12/19 17:55	General View		Load JPG	☒
5	04/12/19 17:55	General View		Load JPG	☒
6	04/12/19 17:55	General View		Load JPG	☒
7	04/12/19 17:55	General View		Load JPG	☒
8	04/12/19 17:55	General View		Load JPG	☒
9	04/12/19 17:55	General View		Load JPG	☒
10	04/12/19 17:55	General View		Load JPG	☒
11	04/12/19 17:55	General View		Load JPG	☒
12	04/12/19 17:55	Replacement Part Photo		Load JPG	☒
13	04/12/19 17:55	Replacement Part Photo		Load JPG	☒
14	04/12/19 17:55	Replacement Part Photo		Load JPG	☒

Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	05/11/19 15:36	TP EST & GIA REPORT		Load PDF	
2	22/11/19 16:33	TP ESTIMATE- MARKED		Load PDF	
3	26/12/19 14:50	WORKSHOP INVOICE		Load PDF	
4	26/12/19 14:50	LOD		Load PDF	
5	07/02/20 12:32	AUTHORISATION TO ACT FORM		Load PDF	
6	07/02/20 12:32	DISCHARGE VOUCHER		Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	06/11/19 08:30	Singapore Accident Statement		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III19019542/T1GS3Q2

Date: 07/02/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant Vehicle No: SKN1871S Insured Vehicle No: SHC3372X
 Date of Loss: 30/10/2019 Nature of Claim: TP Claim No: MCT19100745

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKN1871S
 Make & Model: BMW 520i, 2.0 AT D/AB 2WD 4DR HID NAV (A) Engine No: B5980625N20B20B
 Reg. Date: 21/05/2014 (Man. Year: 2013) Chassis No: WBA5A32000D334505
 Colour: Grey Odometer: 101443 km
 Engine Capacity: 1997 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17 Rear Tyre Size: 225/55 R17
 Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
 Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,908.65	1,651.95	256.70	13.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,667.00	2,084.00	583.00	21.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,575.65	3,735.95	839.70	18.35
+ GST 7.00/7.00% (S\$)	320.30	261.52	58.78	18.35
Nett Amount (S\$)	4,895.95	3,997.47	898.48	18.35
+ Loss of Use (3.0 x S\$120.00/day) (S\$)		360.00		
	Nett Liability (S\$)	4,357.47		

INSPECTION

Date of Assignment: 20/11/2019
 Date Inspected: 20/11/2019 Inspected At: Performance Motors Limited
 (Alexandra)
 303 Alexandra Road, Sime Darby
 Performance Centre
 Singapore 159941
 Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 26 Dec 2019)
Parts: 143	BMW 520I 2.0 AT D/AB 2WD 4DR HID NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKN1871S)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	1		*SET OF MOUNT	Not Necessary	63.55 FS	*- FS
3	1		*RR RH MOUNT	Not Necessary	193.15 FS	*- FS
4	1		*REAR BUMPER PRIMED (PDC)	Deformed	1,571.95 FS	*1,571.95 FS
Total Parts (S\$)					1,908.65	1,651.95

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER AND ATTACHMENTS	New	1,275.00	850.00
2	PAINTING REAR BUMPER	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
4	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (S\$)			2,667.00	2,084.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >