

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

05 NOV 2019

E S T I M A T E

Estimate No. : b1 53326	Page No. : 1 of 4
Date Estimated : 05/11/2019	
Prepared By : Inthiran A/L Thurasamy	

- ESTIMATE REPAIR FOR - Sim Kin Song 341 Upper Bukit Timah Road #06-05 Singapore 588195	- ACCOUNT - 40000 Cash Sales - Service Singapore
--	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKN1871S	WBA5A32000D334505	21/05/2014	520iA	0

DESCRIPTION	VALUE
To replace rear bumper and attachments.	850 1,275.00
Painting rear bumper.	934 1,038.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150 177.00
Sundries.	80.00

Total Labour 1: **2,747.00**

DESCRIPTION	QTY	PRIC	VALUE
Set of mount	1	63.55	63.55
RR RH MOUNT	1	193.15	193.15
REAR BUMPER PRIMED (PDC)	1	1,571.95	1,571.95

Total Parts : **1,828.65**

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. Claim No.

Date & Time 20/11/2019 Excess \$

Surveyor's Name Tan Kim Sign

Surveyor's Tel 92495449 Authorised Yes / No

Authorised Date 11/11/2019 Time

REPAIR PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail tan.kim@performance.com.sg

Labour 1 : **2,747.00**Parts : **1,828.65**Labour 2 : **0.00**Excess : **0.00**Total GST @ 7% : **320.30**Grand Total : **4,895.95**

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **