

INS. CASE OWNER:

Bernard Ler

CC6/AIG19019544/Aha3 *sz*

LKK:

IDAC:

ASSIGNMENT

Surveyor:

ADRIAN

DOI: 04.11.2019

Date / Time: 04.11.2019

Registered in Merimen: 05.11.2019

Pre-assign / CCU / FTE



Insured Vehicle No. : SMH 667E

Claim No. : 8699927465SG

Name of Insured : ANG CHEE TENG

Policy No. :

Insured Tel No. : HP: +65-96210988

Make / Model : MAZDA CX-5-2.0 (A)

Excess Sec II : \$\$ D.O.A : 03.11.2019

Place of Accident : CTE ANG MO KIO NORTH FLYOVER

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. :

(V/L: YES / NO)

Insured Liability : % Final ? Yes / No

SMH 667E

SLQ 4820S

SJL 7580P



INSRS:

WSP:

Tel :

Liability :

RMKS: OI



INSRS:

WSP: SM

Tel : AUTOMOTIVE

Liability :

RMKS: TP



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time	SLQ 4820S - X	SMH 667E - X	STAGE	DATE / PIC
			Non-Reporting ltr (1st):	
			Non-Reporting ltr (2nd):	
			Non-Reporting ltr (Final):	
			Notification ltr (if non-pickup):	
			Call OI:	
			After call ltr to OI:	13/11/19 - JIC
			Documentation Check List:	Handler Typist
			Notification ltr (if non-pickup)	☐
			After call ltr to OI:	☒
			Authorisation To Act:	☒
			Release Voucher:	☒
			Final Repair Bill:	☒
			Car Rental Invoice:	☒
			Towing Invoice:	☒
			LTA / GIA :	☐
			Medical Bill:	☐
			PIR:	☐
			Mandate/Reject Instruction:	☒
			LOD	☒
			Payment Breakdown Form:	☐
			Post-Repair Photos:	☐
			Others:	☐

PRELIMINARY ADVICE Date/Time:		Sent By:		Confirm by:	
FINALIZATION Date/Time:		Confirm with:		Email ☐ Call ☐	
Repair Cost: <i>UG</i>	\$S 15,600.00	(14 days) Reduction: <i>52</i> %			
FINAL SETTLEMENT Date/Time: <i>10/01/20</i>		Confirm with: <i>SMK</i>		Email ☒ Call ☐	
Final Liability:	% <i>100</i> (Agreed / Assessed)	BOLA S/N No. :	<i>28</i>		
Repair Cost:	\$S 15,600.00	If NO or B 28, Ass. Lia: <i>100%</i>			
Loss of Rental (LOR):	\$S — (days)	<i>(3 Veh. C.O.C., 01 Unit)</i>			
Loss of Use (LOU):	\$S 960.00 <i>50</i> x 16 days)				
Loss of Income (LOI):	\$S — (\$ x days)				
LOR only ☒ LOU only ☐	LOR + LOU ☐ LOR + LOI ☐ [Tick only one]				
GIA/LTA Search	\$S —				
Medical:	\$S —	1) Claim status: Normal/Reject/Private Settle			
Disbursement:	\$S — (e.g. Tow/ Independent)	2) Report Format:			
Legal Cost	\$S —	3) Survey fee: <i>4320.00</i>			
Total:	\$S 16,560.00	Global Sum \$S:			
FINAL PAYMENT Date/Time:		Confirm with:		Email ☐ Call ☐	
Payee 1:	\$S 16,560.00	Name 1:	<i>SM AUTOMOTIVE</i>		
Payee 2: (Strike if N.A.)	\$S —	Name 2:	—		
Payee 3: (Strike if N.A.)	\$S —	Name 3:	—		

COPY SENT
14/01/2020

REF:

ASS. REC. BY:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 14 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLQ4820S yr Regn: 2015 oct.Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel c.c. 1496Colour: Black A/O: Insured / Std / NI / NASp. Reading: 95924 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 2411021355Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / SRim / STD A/Rim orTyre Size: F: 215/60R16R: 215/60R16BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mmR/Bal. 06 mmL/Bal. 06 mmL/Bal. 06 mm

D.O.A. _____

D.O.I. 04/11/19Survey held at SMDes. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP ALG.
	46 \$15,600.00 (CRD: \$17,063.05 / 52%)
	MV: 55K
	PV: 39.1K.
	Nett: 15.9K

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + Pk \$1

Folio

Other

TOTAL

Report Format: _____

Lump Sum / L.B.I: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Wash end (\$

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

BASHEER AHAMED BIN ALI

04/11/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPA 16

Vic

Accident date: 03/11/2019

Estimated repair cost for vehicle no: SLQ4820S HONDA VEZEL 1.5X CVT ' 15

S/N	QTY	ITEMS	U/PRICE	AMOUNT
1	1	Front Bumper <i>distorted</i>		\$927.50 <i>880</i>
2	2	Front Bumper Side Retainer <i>new</i>	\$28.50	\$57.00 ✓
3	10	Front Bumper Clips <i>new</i>	\$6.50	\$65.00 <i>30</i>
4	2	Front Bumper Fog Lamp <i>cracked</i>	\$327.70	\$655.40 ✓
5	2	Front Bumper Fog Lamp Cover <i>cracked</i>	\$30.10	\$60.20 ✓
6	1	Front Bumper Center Lower Garnish <i>delid</i>		\$87.50 ✓
7	1	Front Bumper Lower <i>new</i>		\$351.00 +
8	1	Front Bumper Lower Spoiler <i>delid</i>		\$361.00 ✓
9	1	Front Bumper Reinforcement <i>best</i>		\$322.00 ✓
10	2	Front Fender Protector <i>new</i>	\$153.00	\$306.00 +
11	2	Front Head Lamp <i>cracked</i>	\$1,784.50	\$3,569.00 ✓
12	2	Front Head Lamp Lower Bracket <i>cracked</i>	\$65.00	\$130.00 ✓
13	1	Front Grille Top <i>cracked</i>		\$421.80 ✓
14	1	Front Grille Lower <i>new</i>		\$351.80 +
15	1	Front Grille Lower Chrome <i>new</i>		\$95.00 +
16	1	Front Grille Emblem Logo <i>new</i>		\$24.70 ✓
17	1	Front Grille Cover <i>not new</i>		\$85.00 x
18	1	Front Bonnet <i>cracked</i>		\$892.50 ✓
19	2	Front Bonnet Hinge <i>new</i>	\$45.80	\$91.60 +
20	1	Front Bonnet Insulator <i>new</i>		\$122.30 +
21	10	Front Bonnet Insulator Clip <i>new</i>	\$6.50	\$65.00 +
22	1	Front Bonnet Inner Rubber		\$31.20 +
23	1	Front Number Plate <i>best</i>		<i>30</i> \$50.00 <i>50</i>
24	1	Front Radiator <i>new</i>		\$1,250.60 +
25	1	Front Air-Con Condenser <i>best</i>		\$568.10 ✓
26	1	Front Support Panel <i>best</i>		\$576.20 +
27	1	Front Support Panel Top Cover <i>delid</i>		\$40.10 ✓
28	10	Front Support Panel Top Cover Clip <i>new</i>	\$6.50	\$65.00 <i>15</i>

29	1	Front Support Panel Lock	3 xrp		\$87.70	+
30	1	Front Support Panel Lock Cover	1 xrp		\$38.70	+
31	1	Rear Boot Lid	Distorted		\$1,160.90	✓
32	2	Rear Boot Lid Hinge	xen	\$68.10	\$136.20	+
33	2	Rear Boot Lid Shock Absorber	xen	\$180.90	\$361.80	+
34	1	Rear Boot Lid Emblem Logo	xen		\$45.10	✓
35	1	Rear Boot Lid Top Garnish	cracked		\$335.80	✓
36	10	Rear Boot Lid Top Garnish Clips	xen	\$6.50	\$65.00	10
37	1	Rear Boot Lid Camera (Special Nett)	Not xrp Dmgd.		\$680.00	+ 400/s
38	1	Rear Boot Lid Number Plate	xen		\$50.00	+
39	2	Rear Boot Lid Number Plate Lamp	xen	\$38.50	\$77.00	+
40	2	Rear Boot Lid Side Reflector	cracked	\$284.60	\$569.20	✓
41	1	Rear Boot Lid Windscreen Seal	xen		\$151.70	✓
42	1	Rear Boot Lid Inner Lock	Dmgd		\$185.60	✓
43	1	Rear Boot Lid Inner Rubber	cut		\$135.25	✓
44	1	Rear Boot Lid Inner Trim Board	cracked		\$335.75	✓
45	2	Rear Tail Lamp	cracked	\$565.80	\$1,131.60	✓
46	2	Rear Tail Lamp Lower Bracket	xen	\$38.80	\$77.60	+
47	4	Rear Tail Lamp Clips	xen	\$6.50	\$26.00	✓
48	1	Rear Bumper	Distorted		\$863.70	✓
49	2	Rear Bumper Side	Delnd	\$198.70	\$397.40	✓
50	2	Rear Bumper Side Retainer	xen	\$38.00	\$76.00	✓
51	2	Rear Bumper Side Reflector	cracked	\$148.40	\$296.80	✓
52	10	Rear Bumper Clips	xen	\$6.50	\$65.00	30
53	1	Rear Bumper Lock Sensor	cracked		\$95.80	✓
54	1	Rear Bumper Reverse Sensor (Special Nett)	Damaged		\$380.00	- 200/s
55	2	Rear Bumper Side Retainer	xen	\$148.40	\$296.80	68
56	2	Rear Fender Protector	xen	\$250.20	\$500.40	+
57	2	Rear Fender Inner Trim Board	LH Delnd		\$325.25	243
58	1	Rear End Panel	Distorted		\$595.60	✓
59	1	Rear End Panel Top Garnish	Delnd		\$132.30	✓
60	1	Rear Spare Tyre Panel	Buckled		\$1,230.60	✓
61	1	Rear Spare Tyre Panel Top Cover	Delnd		\$306.65	✓
62	1	Rear Spare Tyre Panel Top Sponge	Delnd		\$285.45	✓
63	1	Rear Spare Tyre Panel Under Lower Cover	Delnd		\$190.90	✓
64	8	Rear Spare Tyre Panel Under Lower Cover Clips	xen	\$6.50	\$52.00	30
65	1	Rear Spare Tyre Panel Sealant	xen		\$450.00	+
66	1	Rear Exhaust	Bent		\$828.00	✓
67	1	Rear Centre Exhaust	xen		\$956.00	+
68	1	Rear Exhaust Chrome Pipe	xen		\$135.00	+

17953.40 Subtotal:- \$25,733.05

14362.72 S.N: 600

Labour charges

To remove & refit cushion	\$280.00 180
To remove & refit rear windscreen	\$120.00 ✓
Gum	\$50.00 ✓
To remove & refit front air-con condenser, radiator top fan motor & top up gas	\$450.00 120
To remove & refit rear & centre exhaust	\$380.00 80
To remove & refit reverse sensor	\$120.00 50
To remove & refit rear camera	\$180.00 50
To check wiring	\$100.00 60
Tuff kote	\$150.00 120
Towing fee	\$100.00 X
Panel beating	\$2,800.00 2000
Spray painting	\$2,200.00 1700

Subtotal:- \$6,930.00

Total:- \$32,663.05

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Adrian Lj

24/11/19

14 Days.

total: 19492.72.

w/s: 15.6k.

15.6k

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 565Z

Vehicle Details

Vehicle No.: SLQ4820S

Vehicle to be Exported: No

Intended Deregistration Date: 04 Nov 2019

Vehicle Make: HONDA

Vehicle Model: VEZEL 1.5X CVT

Primary Colour: Black

Manufacturing Year: 2015

Engine No.: L15B3521375

Chassis No.: RU11021355

Maximum Power Output: 96.0 kW (128 bhp)

Open Market Value: \$18,517.00

Original Registration Date: 02 Oct 2015

First Registration Date: 02 Oct 2015

Transfer Count: 1

Actual ARF Paid: \$8,517.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 01 Oct 2025

PARF Rebate Amount: \$6,387.00

Intended COE Rebate Details

COE Expiry Date: 01 Oct 2025

COE Category: A - Car up to 1600cc & 97kW
(130bhp)

COE Period(Years): 10

QP Paid: \$55,399.00

COE Rebate Amount: \$32,731.00

Total Rebate Amount: \$39,118.00

The information contained herein is correct as at 04 Nov 2019

OK



Bidded Car Plate Number for sale

Looking for auspicious numbers?

Browse our list of hottest bidded car plate numbers for sale.

SEARCH

Used Car Comparison

--- Comparing 4 Vehicles ---

Honda Vezel 1.5A X



Clear All

Add all to Shortlist

Back to search result

Add to Shortlist

Honda Vezel 1.5A S



Add to Shortlist

Honda Vezel 1.5A X



Add to Shortlist

Honda Vezel 1.5A X



Add to Shortlist

CAR DETAILS

	Honda Vezel 1.5A X	Honda Vezel 1.5A S	Honda Vezel 1.5A X	Honda Vezel 1.5A X
Price	\$56,800	\$58,800	\$57,800	\$57,800
Instalment	\$667	\$682	\$670	\$670
Registration Date	02-Oct-2015	15-Oct-2015	16-Oct-2015	28-Oct-2015
Manufactured	2015	2015	2015	2015
Mileage	43,418 km	50,000 km	42,000 km	58,459 km
Transmission	Auto	Auto	Auto	Auto
Engine Cap	1,496 cc	1,496 cc	1,496 cc	1,496 cc
Road Tax	\$682 /yr	\$682 /yr	\$682 /yr	\$682 /yr
Power	96.0 kW (128 bhp)	96.0 kW (128 bhp)	96.0 kW (128 bhp)	96.0 kW (128 bhp)
Curb Weight	1,190 kg	1,210 kg	1,190 kg	1,190 kg
Features	1.5L 4 Cylinder Inline DOHC I-VTEC Engine, CVT (A) Transmission, Keyless Entry/Engine Start, Airbags, Auto Headlights, Cruise Control, Brake Hold.	1.5L 4 Cylinders Inline 16 Valves I-VTEC Engine, CVT Automatic Transmission, 128 BHP, Traction Control, ABS, SRS Airbags, CTBA, Knockdown Rear Seats	1.5 I-VTEC Electric Dream Engine, 6 SRS Airbags, ABS, Electric Parking Brake, Auto Retractable Side Mirrors, New Digital Aircon, Fog Lamps, CBTA Mode.	Reliable And Fuel Efficient VTEC Engine, Smooth Auto Transmission, Air Keyless Entry/Start, Br
Accessories	Leather Seats, 16" Sports Rims, Pioneer DVD Player, iRoad Recording Camera, Reverse Camera, Reverse Sensors, Fog Lights, Solar Film,	Sports Rims, Leather Seats, Pioneer DVD Player With Bluetooth, Reverse Camera/Sensors, Solar Film, Retractable Side Mirrors, Fog Lights.	Pioneer DVD Player, USB, Bluetooth, Reverse Sensors, Sports Rims, Auto Headlights/LED, Fog Lamps, Retractable Mirrors.	Sports Rims, Reverse Entry/Start, Retractable Multi-Function Control Lights, Knockdown Re
Description	100% Not A PHV Vehicle. Previous Family Man Owner Upgraded To A New MPV. Proof To Show! Elegance Silver Exterior With Black Interior. If You Are Looking For A Vezel, Surely This Is The Unit You Do Not Want To Miss. Up To 100% Loan Available With Attractive Interest Rate And No Extra Surcharge Can Be Done If You Do Not Wish To Come Out Much Cash Upfront. Hurry, Call Us Now To Arrange To View Now!	1 Owner Best Deal 'S' Model Sports Package With Sport Paddle Shifter.Free Extended Warranty.100% Accident Free.Don't Miss It. Up To 100% Flexible Loan. We Provide Lowest Interest Rate. Flexible Loan And High Trade In Are Available. Package With Unrivaled Warranty Complete With Certificate And Test Report. Trade In Welcome. Meet Our Friendly Consultant For An Non Obligation Advise.	Low Monthly From \$6xx! Low Depreciation! Good For Grab Use! Low Mileage At 42k Only! Well Maintained By 1 Owner! 100% Accident Free! No Repair Needed! Vehicle In Excellent Condition And Clean Interior! Flexible Financing Scheme Available To Your Needs! Free 6 Months Servicing From By Our Reputable Workshop! View To Believe! Call Our Friendly Sales Consultant Now For More Details!	Beautiful Metallic Pear Owner, Ownership Car Accident Free, Still On Genuine Mileage, Insp Flexible Loan Available
COE	\$57,498	\$55,889	\$55,399	\$57,301
OMV	\$18,248	\$20,496	\$18,719	\$19,736
ARF	\$8,248	\$15,695	\$8,719	\$9,736
Depreciation	\$8,910 /yr	\$8,570 /yr	\$8,980 /yr	\$8,850 /yr
No. of Owners	1	1	2	1
Type of Vehicle	SUV	SUV	SUV	SUV
Category	PARF Car, Premium Ad Car	PARF Car	PARF Car, Premium Ad Car	PARF Car, Premium Ad
Availability	Available	Available	Available	Available

SELLER INFORMATION

Print Received Message

This mail is associated with :

***SLQ4820S (8699927465SG)**
[SMH667E]

TP

BASHEER AHAMED BIN ALI

Nov 3 2019 12:00PM

[Ang Chee Teng]

SM Automotive

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 03/01/2020 12:01 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$16560.00) - SLQ4820S - Claim Handler: Ler, Bernard-JQ

Approved:16560.00:Cost of Repair \$15,600.00 As per surveyor finalization Loss of Use \$960.00 16 days @ S\$ 60/day LTA/ GIA Search Fee \$- Total \$16,560.00

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Nov 2019 Edit Reg		04 Nov 2019 00:00 Edit Adj Rpt	S\$15,600.00 Edit Estimates	S\$15,600.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	Ang Chee Teng, Co. Reg. No.: -		
Main Claimant:	BASHEER AHAMED BIN ALI, ID: S1694565Z		
Vehicle Reg. No.:	SLQ4820S	Date of Loss:	03/11/2019 12:00 - :59 [49 Months and 1 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 8699927465SG	Policy/Cover Note No.:	(Comprehensive) Coverage: 09/01/2019 - 08/01/2021
Vehicle Reg. No. (Insured):	SMH667E	Policy No. (Claimant):	5094301028-02
		Excess:	
Repairer:	SM Automotive (HQ) 756 JURONG WEST STREET 74, #12-60, 640756 Kaki Bukit - Tel: 67479241		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 14/11/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG_EXPRESS (03/01/2020): Alert - Adj Mandate Approved (S\$16560.00) - SLQ4820S - Claim Handler: Ler, Berna...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLQ4820S (8699927465SG)
[SMH667E]**

**TP
BASHEER AHAMED BIN ALI
Nov 3 2019 12:00PM
[Ang Chee Teng]
SM Automotive**

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser ▼			
Video																		1 per page ▼		✓	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)														Thumbnail	Print				
1	06/11/19 14:06	OI VIDEO													i	Load MP4					
Letters/Correspondences																		1 per page ▼		✓	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print				
1	(Draft)	Third Party Express Settlement – Payment Breakdown													i	Edit					
Photos/Images																		3 per page ▼		✓	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print				
1	02/12/19 13:42	General View													1	Load JPG	✓				
2	02/12/19 13:42	General View													1	Load JPG	✓				
3	02/12/19 13:42	General View													i	Load JPG	✓				
4	02/12/19 13:42	General View													1	Load JPG	✓				
5	02/12/19 13:42	General View													1	Load JPG	✓				
6	02/12/19 13:42	General View													1	Load JPG	✓				
7	02/12/19 13:42	General View													1	Load JPG	✓				
8	02/12/19 13:42	General View													1	Load JPG	✓				
9	02/12/19 13:42	General View													1	Load JPG	✓				
10	02/12/19 13:42	General View													1	Load JPG	✓				
11	02/12/19 13:42	General View													1	Load JPG	✓				
12	02/12/19 13:42	General View													1	Load JPG	✓				
13	02/12/19 13:42	General View													1	Load JPG	✓				
14	02/12/19 13:42	General View													1	Load JPG	✓				
15	02/12/19 13:42	General View													i	Load JPG	✓				
16	02/12/19 13:42	General View													1	Load JPG	✓				
17	02/12/19 13:42	General View													i	Load JPG	✓				
18	02/12/19 13:42	General View													1	Load JPG	✓				
19	02/12/19 13:42	General View													i	Load JPG	✓				
20	02/12/19 13:42	General View													1	Load JPG	✓				
21	02/12/19 13:42	General View													i	Load JPG	✓				
22	02/12/19 13:42	General View													1	Load JPG	✓				
23	02/12/19 13:42	General View													i	Load JPG	✓				
24	02/12/19 13:42	General View													1	Load JPG	✓				
25	02/12/19 13:42	General View													i	Load JPG	✓				
26	02/12/19 13:42	General View													1	Load JPG	✓				
27	02/12/19 13:42	General View													1	Load JPG	✓				
28	02/12/19 13:42	General View													1	Load JPG	✓				

Video			1 per page ▾	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
29	02/12/19 13:42	General View	 Load JPG	☒
30	02/12/19 13:42	General View	 Load JPG	☒
31	02/12/19 13:42	General View	 Load JPG	☒
32	02/12/19 13:42	General View	 Load JPG	☒
33	02/12/19 13:42	General View	 Load JPG	☒
34	02/12/19 13:42	General View	 Load JPG	☒
35	02/12/19 13:42	General View	 Load JPG	☒
36	02/12/19 13:42	General View	 Load JPG	☒
37	02/12/19 13:42	General View	 Load JPG	☒
38	02/12/19 13:42	General View	 Load JPG	☒
39	02/12/19 13:42	General View	 Load JPG	☒
40	02/12/19 13:42	General View	 Load JPG	☒
41	02/12/19 13:42	General View	 Load JPG	☒
42	02/12/19 13:42	General View	 Load JPG	☒
43	02/12/19 13:42	General View	 Load JPG	☒
44	02/12/19 13:42	General View	 Load JPG	☒
45	02/12/19 13:42	General View	 Load JPG	☒
46	02/12/19 13:42	General View	 Load JPG	☒
47	02/12/19 13:42	General View	 Load JPG	☒
48	02/12/19 13:42	General View	 Load JPG	☒
49	02/12/19 13:42	General View	 Load JPG	☒
50	02/12/19 13:42	General View	 Load JPG	☒
51	02/12/19 13:42	General View	 Load JPG	☒
52	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
53	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
54	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
55	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
56	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
57	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
58	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
59	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
60	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
61	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
62	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
63	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
64	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
65	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
66	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
67	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
68	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
69	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
70	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
71	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
72	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
73	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
74	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
75	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
76	02/12/19 13:43	Reinspection Photo	Load JPG	☒

Video			1 per page ▼	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
77	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
78	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
79	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
80	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
81	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
82	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
83	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
84	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
85	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
86	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
87	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
88	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
89	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
90	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
91	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
92	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
93	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
94	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
95	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
96	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
97	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
98	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
99	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
100	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
101	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
102	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
103	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
104	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
105	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
106	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
107	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
108	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
109	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
110	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
111	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
112	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
113	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
114	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
115	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
116	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
117	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
118	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
119	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
120	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
121	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
122	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
123	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
124	02/12/19 13:43	Reinspection Photo	Load JPG	☒

Video			1 per page ▼	✓
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
125	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
126	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
127	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
128	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
129	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
130	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
131	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
132	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
133	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
134	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
135	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
136	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
137	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
138	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
139	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
140	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
141	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
142	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
143	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
144	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
145	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
146	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
147	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
148	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
149	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
150	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
151	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
152	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
153	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
154	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
155	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
156	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
157	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
158	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
159	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
160	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
161	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
162	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
163	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
164	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
165	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
166	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
167	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
168	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
169	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
170	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
171	02/12/19 13:43	Reinspection Photo	 Load JPG	✓
172	02/12/19 13:43	Reinspection Photo	 Load JPG	✓

Video			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
173	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
174	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
175	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
176	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
177	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
178	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
179	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
180	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
181	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
182	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
183	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
184	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
185	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
186	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
187	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
188	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
189	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
190	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
191	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
192	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
193	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
194	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
195	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
196	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
197	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
198	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
199	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
200	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
201	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
202	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
203	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
204	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
205	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
206	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
207	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
208	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
209	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
210	02/12/19 13:43	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/11/19 15:50	TP GIA REPORT	 Load PDF	
2	13/11/19 14:13	EMAIL TO OI	 Load PDF	
3	13/11/19 14:13	LETTER TO OI	 Load PDF	
4	03/12/19 14:39	TP ESTIMATE - FINALIZED	 Load PDF	
5	13/12/19 11:49	LOD	 Load PDF	
6	10/01/20 16:44	EMAIL FROM TP	 Load PDF	
7	14/01/20 16:50	Release Voucher	 Load PDF	
8	03/02/20 15:59	Authorisation to Act	 Load PDF	
9	03/02/20 15:59	WORKSHOP INVOICE	 Load PDF	

Video				1 per page ▼	✓
No	Finalized On	AIG Asia Pacific Insurance Pte, Ltd. (SG)		Thumbnail	Print
No	Finalized On	AIG Asia Pacific Insurance Pte, Ltd. (SG)		Thumbnail	Print
1	06/11/19 14:05	OI GIA REPORT	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST				Reset	Save	Print
There are no document checklists configured.						

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SMH667E (Insd veh)	Model:	HONDA VEZEL 1.5 X CVT (A)
	SLQ4820S (TP veh)		
Date of Accident:	03/11/2019		

Global Sum Settlement	:	[]	Yes	[X]	No
Repair Estimate	:	\$			32,663.05
Final Repair Cost	:	\$			15,600.00
Loss of Use	:	\$			960.00
					16.00 days at \$60.00 per day
Rental (if any)	:	\$			days
LTA / GIA Search Fee	:	\$			
Others:	:	\$			
	:	\$			
Final Settlement Sum	:	\$			16,560.00

Is Third Party Workshop GIA Registered?	[]	YES	[X]	NO	(Kindly indicate below)
A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)					
B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____					
BOLA Liability: _____ (%) Assessed Liability (*): _____ 100 _____ (%)					
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.					
Remarks _____					

Payment Instruction: Payee's Breakdown			
1)	SM Automotive	:	\$ 16,560.00
2)		:	\$

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

03 Feb

2020

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19019544/AHA3S2
Date: 03/02/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SLQ4820S

Insured Vehicle No : SMH667E

Date of Loss: 03/11/2019

Nature of Claim: TP

Claim No: 8699927465SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLQ4820S

Make & Model: HONDA VEZEL, 1.5 X CVT (A)

Engine No: L15B3521375

Reg. Date: 02/10/2015 (Man. Year: 2015)

Chassis No: RU11021355

Colour: Black

Odometer: 95924 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side: Dunlop 6 mm

Rear Left Side:

Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side:

Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,783.05	14,972.72	10,810.33	41.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,880.00	4,480.00	2,400.00	34.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,663.05	19,452.72	13,210.33	40.44
Approved Total (Overridden) (S\$)		15,600.00		
Nett Amount (S\$)	32,663.05	15,600.00	17,063.05	52.24
+ Loss of Use (16.0 x S\$60.00/day) (S\$)		960.00		
Nett Liability (S\$)		16,560.00		

INSPECTION

Date of Assignment: 04/11/2019

Date Inspected: 04/11/2019 Inspected At:

SM Automotive (HQ)

756 JURONG WEST STREET 74, #12-60

Singapore 640756

Estimated Period of Repair: 14.0 days

Adjuster: ADRIAN LING

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_printpt&caseid=884305&extid=322114&CFID=66452458&C... 1/5

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	927.50 F	*880.00 FL
2	2		*FRONT BUMPER SIDE RETAINER	Necessary	57.00 F	*57.00 FL
3	10		*FRONT BUMPER CLIPS	Necessary	65.00 F	*30.00 FL
4	2		*FRONT BUMPER FOG LAMP	Cracked	655.40 F	*655.40 FL
5	2		*FRONT BUMPER FOG LAMP COVER	Cracked	60.20 F	*60.20 FL
6	1		*FRONT BUMPER CENTER LOWER GARNISH	Deformed	87.50 F	*87.50 FL
7	1		*FRONT BUMPER LOWER	Not Necessary	351.00 F	*- FL
8	1		*FRONT BUMPER LOWER SPOILER	Deformed	361.00 F	*361.00 FL
9	1		*FRONT BUMPER REINFORCEMENT	Bent	322.00 F	*322.00 FL
10	2		*FRONT FENDER PROTECTOR	Not Necessary	306.00 F	*- FL
11	2		*FRONT HEAD LAMP	Cracked	3,569.00 F	*3,569.00 FL
12	2		*FRONT HEAD LAMP LOWER BRACKET	Crumpled	130.00 F	*130.00 FL
13	1		*FRONT GRILLE TOP	Cracked	421.80 F	*421.80 FL
14	1		*FRONT GRILLE LOWER	Not Necessary	351.80 F	*- FL
15	1		*FRONT GRILLE LOWER CHROME	Not Necessary	95.00 F	*- FL
16	1		*FRONT GRILLE EMBLEM LOGO	Necessary	24.70 F	*24.70 FL
17	1		*FRONT GRILLE COVER	Not Necessary	85.00 F	*- FL
18	1		*FRONT BONNET	Buckled	892.50 F	*892.50 FL
19	2		*FRONT BONNET HINGE	Not Necessary	91.60 F	*- FL
20	1		*FRONT BONNET INSULATOR	Not Necessary	122.30 F	*- FL
21	10		*FRONT BONNET INSULATOR CLIP	Not Necessary	65.00 F	*- FL
22	1		*FRONT BONNET INNER RUBBER	Not Necessary	31.20 F	*- FL
23	1		*FRONT NUMBER PLATE	Bent	50.00 F	*30.00 FL
24	1		*FRONT RADIATOR	Not Necessary	1,250.60 F	*- FL
25	1		*FRONT AIR-CON CONDENSER	Bent	568.10 F	*568.10 FL
26	1		*FRONT SUPPORT PANEL	Repair	576.20 F	*- FL
27	1		*FRONT SUPPORT PANEL TOP COVER	Deformed	40.10 F	*40.10 FL
28	10		*FRONT SUPPORT PANEL TOP COVER CLIP	Necessary	65.00 F	*15.00 FL
29	1		*FRONT SUPPORT PANEL LOCK	Not Necessary	87.70 F	*- FL
30	1		*FRONT SUPPORT PANEL LOCK COVER	Not Necessary	38.70 F	*- FL
31	1		*REAR BOOT LID	Distorted	1,160.90 F	*1,160.90 FL
32	2		*REAR BOOT LID HINGE	Not Necessary	136.20 F	*- FL
33	2		*REAR BOOT LID SHOCK ABSORBER	Not Necessary	361.80 F	*- FL
34	1		*REAR BOOT LID EMBLEM LOGO	Necessary	45.10 F	*45.10 FL
35	1		*REAR BOOT LID TOP GARNISH	Cracked	335.80 F	*335.80 FL
36	10		*REAR BOOT LID TOP GARNISH CLIPS	Necessary	65.00 F	*10.00 FL
37	1		*REAR BOOT LID NUMBER PLATE	Not Necessary	50.00 F	*- FL
38	2		*REAR BOOT LID NUMBER PLATE LAMP	Not Necessary	77.00 F	*- FL
39	2		*REAR BOOT LID SIDE REFLECTOR	Cracked	569.20 F	*569.20 FL
40	1		*REAR BOOT LID WINDSCREEN SEAL	Necessary	151.70 F	*151.70 FL
41	1		*REAR BOOT LID INNER LOCK	Damaged	185.60 F	*185.60 FL
42	1		*REAR BOOT LID INNER RUBBER	Cut	135.25 F	*135.25 FL
43	1		*REAR BOOT LID INNER TRIM BOARD	Cracked	335.75 F	*335.75 FL
44	2		*REAR TAIL LAMP	Cracked	1,131.60 F	*1,131.60 FL
45	2		*REAR TAIL LAMP LOWER BRACKET	Not Necessary	77.60 F	*- FL
46	4		*REAR TAIL LAMP CLIPS	Necessary	26.00 F	*26.00 FL
47	1		*REAR BUMPER	Distorted	863.70 F	*863.70 FL
48	2		*REAR BUMPER SIDE	Deformed	397.40 F	*397.40 FL
49	2		*REAR BUMPER SIDE RETAINER	Necessary	76.00 F	*76.00 FL
50	2		*REAR BUMPER SIDE REFLECTOR	Cracked	296.80 F	*296.80 FL
51	10		*REAR BUMPER CLIPS	Necessary	65.00 F	*30.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*REAR BUMPER LOCK SENSOR	Cracked	95.80 F	*95.80 FL
53	2		*REAR BUMPER SIDE RETAINER	Necessary	296.80 F	*68.00 FL
54	2		*REAR FENDER PROTECTOR	Not Necessary	500.40 F	*- FL
55	1		*REAR FENDER INNER TRIM BOARD	N/s Deformed	325.25 F	*245.00 FL
56	1		*REAR END PANEL	Distorted	595.60 F	*595.60 FL
57	1		*REAR END PANEL TOP GARNISH	Deformed	132.30 F	*132.30 FL
58	1		*REAR SPARE TYRE PANEL	Buckled	1,230.60 F	*1,230.60 FL
59	1		*REAR SPARE TYRE PANEL TOP COVER	Deformed	306.65 F	*306.65 FL
60	1		*REAR SPARE TYRE PANEL TOP SPONGE	Deformed	285.45 F	*285.45 FL
61	1		*REAR SPARE TYRE PANEL UNDER LOWER COVER	Deformed	190.90 F	*190.90 FL
62	8		*REAR SPARE TYRE PANEL UNDER LOWER COVER CLIPS	Necessary	52.00 F	*30.00 FL
63	1		*REAR SPARE TYRE PANEL SEALANT	Not Necessary	450.00 F	*- FL
64	1		*REAR EXHAUST	Bent	828.00 F	*828.00 FL
65	1		*REAR CENTRE EXHAUST	Not Necessary	956.00 F	*- FL
66	1		*REAR EXHAUST CHROME PIPE	Not Necessary	135.00 F	*- FL
67	1		*REAR BOOT LID CAMERA	Damaged	680.00 FS	*400.00 FS
68	1		*REAR BUMPER REVERSE SENSOR	Damaged	380.00 FS	*200.00 FS
69	1		*GUM	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	25,783.05	18,553.40
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	3,580.68
Total Parts (\$\$)	25,783.05	14,972.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT CUSHION.	New	280.00	180.00
2	TO REMOVE & REFIT REAR WINDSCREEN.	New	120.00	120.00
3	TO REMOVE & REFIT FRONT AIR-CON CONDENSER, RADIATOR TOP FAN MOTOR & TOP UP GAS.	New	450.00	120.00
4	TO REMOVE & REFIT REAR & CENTRE EXHAUST.	New	380.00	80.00
5	TO REMOVE & REFIT REVERSE SENSOR.	New	120.00	50.00
6	TO REMOVE & REFIT REAR CAMERA.	New	180.00	50.00
7	TO CHECK WIRING.	New	100.00	60.00
8	TUFF KOTE.	New	150.00	120.00
9	TOWING FEE.	New	100.00	0.00
10	PANEL BEATING.	New	2,800.00	2,000.00
11	SPRAY PAINTING.	New	2,200.00	1,700.00
Gross Labour Cost (S\$)			6,880.00	4,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >