

22/05/2019

ASS. REC. BY:

REF:

CS/FCI11019547/T1+ d3 n4

Special Instruction:

Surveyor: Taufik

ASSIGNMENT (Office)

CWS

From (Person): Melina Chia

of

FCI

Date/Time: 8:24am @ 5/11/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLX 411D

Insured:

SHC 0163C

at Workshop m/s

Comfort Delgro

Tel:

6867 6919

of

45 Pandan Road

Policy No:

Claim No:

D19006832 MP34

Sum Insured:

Excess:

Make of Veh:

D.O.A.

25/10/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

(DS)

H.O.D. Endorsement:

Date/Time: 9:40am @ 5/11/19

Person Contacted:

Mr. Wong

Vehicle IN/OUT

Date/Time

Action/Instruction

Fohm/11 ✓

SLX 411D-X

SHC 0163C-CC3/A14170010H/A1/pb352

2019/23/2/2019

13/11/19 @ 11:44am revised to Melina Chia by email.

Confirm \$173.50 Cred: 173.30 (69%)

ASS. REC. BY:

REF:

FC1

ASSIGNMENT

From:

Date:

12.11.2019

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLX 411D

at Workshop m/s

ComfoAdi/gro

of

45 Pandan Road

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

10.000.000

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
X	

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

"M"

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLX 411D

Yr Regn:

2019, Feb

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Vios

C.C.

1496

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

11532

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MR 2B23F3421/63386

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

185/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

mm

Rear

6

mm

R/Bal.

R/Bal.

L/Bal.

6

mm

L/Bal.

D.O.A.

D.O.I.

12/11/19 145

Survey held at

COXIE Pardon

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 10 NOV 2019

Date/Time, File Pass to?



Preli. Report

11/11/19 Typist



Final Report

Date/Time, File Return to?

2)

Rep. Form:

Lump Sum / TP:

TP

773.50

Days Of Repair:

2

Resurvey No. of Trip:

2

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation:

\$ + RS. SI

Photos

Others

TOTAL

110

50

50+50

31

291



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19006832MFSH

Date: 13 November 2019

Our Ref: CS/FCI19019547/T1tD3

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLX 411D

Please be informed that we had conducted the inspection of the abovementioned vehicle on 12/11/2019 at the premises of M/s COMFORTDELGRO ENGINEERING, and have the following to report:-

Workshop Estimate Amount	: S\$ 2,506.80 .
Revised Estimate Amount	: S\$ 773.50 .
"Check" Items Amount	: S\$ 441.65 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

Taufikh
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	29-10-2019	Our Ref No. D19006832MFSH
Accident Date	25-10-2019	Claim Type. Third Party
Insured Vehicle	SHC0163C	Third Party Vehicle. SLX411D
Survey Location	45 PANDAN ROAD	
Contact Person.	WONG CHEE WEI	
Contact No.	68676919/ 0	Fax No. 0
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	COMFORTDELGRO ENGINEERING PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MERINA CHIA SAN SAN	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 13 November 2019 11:44 AM
To: 'CWS Motor Claims'; assignments
Cc: 'Merina Chia'; SUR
Subject: RE: SURVEY ASSESSMENT - D19006832MFSH/1
Attachments: CSFCI19019547T1td3.pdf

Dear Merina,

Enclosed herewith preliminary advice of SLX 411D.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Tuesday, 5 November 2019 11:37 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Merina Chia' <MerinaChia@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19006832MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 5 November 2019 8:24 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Merina Chia <MerinaChia@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19006832MFSH/1

Dear Sir/Mdm,

Denise Tay (LKKAUTO)

From: CDGE Pandan Private Cars Crash Repair Counter <pandan_cr@sparkcarcare.com>
Sent: Friday, 15 November 2019 10:55 AM
To: Taufikh (LKKAUTO)
Subject: Re: SLX411D - Finalization Cost Of Repair

Hi Taufikh ,

Ok Noted ,COR \$773.50 2 Day Repair confirmed .

Thank you.

Wong Chee Wei
Pandan Crash Repair
ComfortDelgro Engineering Pte. Ltd.
DID 68676919



Think Before Printing

From: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Sent: Friday, 15 November 2019 10:47 AM
To: CDGE Pandan Private Cars Crash Repair Counter <pandan_cr@sparkcarcare.com>
Cc: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Subject: RE: SLX411D - Finalization Cost Of Repair

Hi Wong,

COR \$773.50 , 2 days.

Regards
Taufikh
Lkk Auto

From: CDGE Pandan Private Cars Crash Repair Counter [mailto:pandan_cr@sparkcarcare.com]
Sent: Friday, 15 November 2019 10:24 AM
To: Taufikh (taufikh@lkkauto.com)
Subject: SLX411D - Finalization Cost Of Repair

Hi Taufikh ,

With refer to attach our finalization form for you advice and confirm.
and attach before paint and after repair photo.

Thank you.

Wong Chee Wei
Pandan Crash Repair
ComfortDelgro Engineering Pte. Ltd.
DID 68676919

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : ☐ Own Damage
☒ 3rd Party
☐ Windscreen

Vehicle No. : **SLX411D**

Make & Model : **TOYOTA / VIOS 1.5 E**

Year of Manufacture : **2019**

Chassis No. : **MR2B23F3401163386**

Engine No. : **2NR5316493**

Policy No. : _____

Ins Company : **NTUC INCOME**

Excess : _____

Date of Accident : **25/10/2019**

Time of Accident : **17.10 PM**

Suggested Days of Repair : _____

In-house Vehicle Assessor

Repair Estimates

Name : **Wong Chee Wei**

Signature : _____

Contact No : **68676919**

Parts (a) Cost Price Items **\$1,062.40**

Less 25 % **\$(265.60)**

(b) Nett Price Items _____

Less _____ % _____

(c) Special Nett Items **\$200.00**

Total Parts Cost (Appendix A) \$996.80

Labour (Appendix B) \$1,510.00

Total Repair Cost \$2,506.80

The above total will be subjected to 7% G.S.T.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Name of Surveyor : **Tan Jhi 9749549**

Company : **LKK**

Survey conducted on : **12/11/19** at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : **2** day(s)

(c) Resurvey : **Required / Not Required**

(d) Excess : \$ _____

(e) Signature of surveyor : **[Signature]**

Date: **12/11/19**

COMFORTDELGRO ENGINEERING PTE LTD

Appendix A

45 Pandna Road S (609286)

Tel: 68676919 Fax: 62626950

Spare Parts

Vehicle No. : **SLX411D** Submit By : **Wong Chee Wei**
 Make & Model : **TOYOTA VIOS 1.5 E** Year Manufacture : **2019**
 Chassis No. : **MR2B23F3401163386** Engine No. : **2NR5316493**

TP**S/Order** : **_____**

S/No.	Part Description	Qty	Cost Price	Nett Price	List Price	S- Nett Price	Diposition By Surveyor
1	REAR BUMPER	1			\$390.00		de ✓
2	CLIP REAR BUMPER	10			\$28.00		re ✓
3	R/REAR SIDE RETAINER	1			\$156.00		X X
4	L/REAR SIDE RETAINER	1			\$156.00		X ?
5	R/ REAR UPPER BRACKET	1			\$35.60		X X
6	L/REAR UPPER BRACKET	1			\$35.60		X ?
7	R/REAR REFLECTOR	1			\$130.60		X X
8	L/REAR REFLECTOR	1			\$130.60		X ?
9	REVERSE SENSOR SET	1				\$200.00	X ?
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

45 Pandan Road S (609386)
Tel: 68676919 Fax: 62626950,68676903

Tel: 68676919 Fax: 62626950,68676903

Vehicle No. : SLX411D Submit By : : Won
Make & Model : TOYOTA Year of Manufacture : _____

Year of Manufacture : _____

200 ✓
200 ✓
30 ✓
30 ✓

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : ☐ Own Damage
☒ 3rd Party
☐ Windscreen

Vehicle No. : SLX411D

Make & Model : TOYOTA / VIOS 1.5 E

Year of Manufacture : 2019

Chassis No. : MR2B23F3401163386

Engine No. : 2NR5316493

Policy No. : _____

Time of Accident : 17.10 PM

Ins Company : NTUC INCOME

Excess : _____

Date of Accident : 25/10/2019

Suggested Days of Repair : _____

In-house Vehicle Assessor

Name : Wong Chee Wei

Signature : _____

Contact No : 68676919

Repair Estimates

Parts (a) Cost Price Items \$1,062.40

Less 25 % \$(265.60)

(b) Nett Price Items _____

Less _____ % _____

(c) Special Nett Items \$200.00

Total Parts Cost (Appendix A) \$996.80

Labour (Appendix B) \$1,510.00

Total Repair Cost \$2,506.80

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Tan Jiah 9749549

Company : LKK

Survey conducted on : 12/11/19 at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 2 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : [Signature]

Date: 12/11/19

Spare Parts

Vehicle No. : **SLX411D** Submit By : **Wong Chee Wei**
Make & Model : **TOYOTA VIOS 1.5 E** Year Manufacture : **2019**
Chassis No. : **MR2B23F3401163386** Engine No. : **2NR5316493**

TP

S/Order : _____

S/No.	Part Description	Qty	Cost Price	Nett Price	List Price	S- Nett Price	Disposition By Surveyor
1	REAR BUMPER	1			\$390.00		de ✓
2	CLIP REAR BUMPER	10			\$28.00		ng ✓
3	R/REAR SIDE RETAINER	1			\$150.00		X
4	L/REAR SIDE RETAINER	1			\$150.00		?
5	R/ REAR UPPER BRACKET	1			\$35.60		X
6	L/REAR UPPER BRACKET	1			\$35.60		?
7	R/REAR REFLECTOR	1			\$180.00		X
8	L/REAR REFLECTOR	1			\$180.00		?
9	REVERSE SENSOR SET	1				\$200.00	?
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

45 Pandan Road S (609386)
Tel: 68676919 Fax: 62626950, 68676903

Vehicle No. : SLX411D Submit By : : Won
Make & Model : TOYOTA Year of Manufacture :

[illegible]




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19019547/T1td3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 20-11-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 163C	Veh. Inspected	SLX 411D	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19006832MFSH	Excess (\$)	0.00	
Assign From	MERINA CHIA	Assign Date	05/11/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VIOS	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	MR2B23F3401163386	Colour	SILVER	
Odometer	11532	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	YOKOHAMA	6 mm	
L/H Front Tyre	185/60 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/10/2019	Inspection Date	12/11/2019	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 45 PANDAN ROAD SINGAPORE 609286			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 411D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	390.00	390.00
10	CLIP REAR BUMPER	NECESSARY	28.00	28.00
1	R/REAR SIDE RETAINER	NOT NECESSARY	156.00	-
1	L/REAR SIDE RETAINER	NOT NECESSARY	156.00	-
1	R/REAR UPPER BRACKET	NOT NECESSARY	35.60	-
1	L/REAR UPPER BRACKET	NOT NECESSARY	35.60	-
1	R/REAR REFLECTOR	NOT NECESSARY	130.60	-
1	L/REAR REFLECTOR	NOT NECESSARY	130.60	-
	LESS 25% DISCOUNT		-265.60	-104.50
			796.80	313.50
SPECIAL NETT ITEMS				
1	SET REVERSE SENSOR (SN)	NOT NECESSARY	200.00	-
			200.00	-
LABOUR				
	TO REMOVE & REPLACE,STRAIGHTEN,RE-ALIGN:REAR BUMPER,DAMAGED AFFECTED AREA.		800.00	200.00
	TO PUTTY,SPRAY PAINT:REAR BUMPER,DAMAGED AFFECTED AREA.		600.00	200.00
	TO RE-INSTALL NEW REVERSE SENSOR.		80.00	30.00
	TO CHECK WIRING.		30.00	30.00
			1,510.00	460.00
GRAND TOTAL			2,506.80	773.50
RECOMMENDED COST OF REPAIRS				773.50

Report Ref No. CS/FCI19019547/T1td3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.