

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 18004

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1314/2019/NS
Date : 4-Nov-19

Vehicle IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Kimberly - Anne Tan
Address : 6 Nim Crescent
Singapore 807689
Telephone : HP +65 96470982
Type of Claim : Own Damage Claims
Policy No. : 1700037703-02
Vehicle No : **SLR 3061 S**
Model Code : Audi A3 Sedan 1.0 TFSI 8V
Model / Year : Aug-17
Engine No : CHZ 39034
Chassis No : WAUZZZ8V5J1003079
Mileage : 30419
Date In : 3-Nov-19
Estimated By : Johnny Boo / Allan Wu
Accident Date : 3-Nov-19
Place of Accident : Along CTE Between Yio Chu Kang And AMK Ave 5 Exit

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLR 3061 S

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	✓
2	To remove and transfer aircond condenser, radiator and additional radiator. Check electrical fans and control unit. Pressurise cooling system To carry out vacuum and regas.	S/N \$ 1,200.00	X X
3	To dsimantle and renew front bumper, both front fenders, bonnet and both headlights. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$ 6,300.00	Sts. 2500 without back 3750 with back
4	To respray front bumper, both front fenders and bonnet.	\$ 4,000.00	2200
5	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 12,052.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLR 3061 S

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/NETT		
1	FRONT BUMPER <i>Defend</i>	\$	1,830.00	✓ 1464
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$	170.00	x
3	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	2 \$	NEC 70.00	x 55.04
4	FRONT BUMPER GRILLE - CENTRE <i>could</i>	\$	146.00	✓ 116.40
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	\$	488.00	x
6	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>new</i>	2 \$	540.00	+
7	FRONT BUMPER COVER TRIM - LH / RH <i>new</i>	2 \$	296.00	+
8	FRONT BUMPER WHEEL HOUSING LINER ADAPTER - LH / RH <i>new</i>	2 \$	68.00	+
9	RADIATOR GRILLE <i>could</i>	\$	1,301.00	✓ 1040.80
10	RADIATOR GRILLE CLOSING ELEMENT <i>could</i>	\$	174.00	✓ 138.80
11	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>new</i>	2 \$	342.00	✓ 272.80
12	FRONT BUMPER SIDE REINFORCEMENT BEAM <i>Best</i>	\$	660.00	✓ 527.60
13	FRONT BUMPER FOAM FILLER PIECE <i>could</i>	\$	172.00	✓ 137.60
14	FRONT BUMPER FOAM FILLER PIECE COVER <i>Defend</i>	\$	111.00	✓ 88.80
15	SIGNAL HORN - LH HIGH TONE <i>new</i>	\$	182.00	x
16	SIGNAL HORN - RH LOW TONE <i>new</i>	\$	182.00	x
17	EXTERNAL TEMPERATURE SENSOR <i>new</i>	\$	54.00	x
18	EXTERNAL TEMPERATURE SENSOR BRACKET <i>new</i>	\$	17.00	x
19	FRONT FENDER - LH / RH <i>Brake</i>	2 \$	1,556.00	✓ 1244
20	FRONT FENDER ATTACHMENT PARTS <i>new</i>	2 \$	130.00	x
SUB TOTAL SPARE PARTS		:	\$ 8,489.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLR 3061 S

S/N	Parts Description			Damage Parts & Prices	
				S/NETT	Remarks
21	FRONT FENDER BRACKET - LH / RH	2	\$	50.00	+ x
22	FRONT FENDER BRACKET - LH / RH	2	\$	70.00	+ x
23	FRONT FENDER BRACE - LH / RH	2	\$	176.00	+ x
24	FRONT WHEEL HOUSING LINER - LH / RH	2	\$	316.00	+ 126
25	BONNET		\$	2,898.00	2318.40
26	BONNET ATTACHMENT PARTS		\$	149.00	+ x
27	BONNET LID HINGE - LH / RH	2	\$	112.00	+ x
28	BONNET GAS FILLED STRUT		\$	109.00	+ x
29	BONNET SAFETY CATCH		\$	81.00	+ x
30	BONNET STRIKER - LH / RH	2	\$	200.00	+ x
31	BONNET EDGE PROTECTION		\$	25.00	+ x
32	BONNET CATCH HOOK		\$	58.00	+ x
33	BONNET LID LOCK	2	\$	367.00	+ x
34	FLAT CONNECTOR HOUSING		\$	12.00	+ x
35	BONNET BOWDEN CABLE - CENTRE		\$	53.00	+ x
36	AIRCON STICKER	NEC	\$	7.00	✓ 5.12
37	CAUTION SIGN STICKER	NEC	\$	13.00	✓ 9.76
38	LED HEADLIGHT - LH / RH	2	\$	10,058.00	✓ 8046.40
39	LIFT CYLINDER - LH / RH	2	\$	256.00	+ x
40	LIFT CYLINDER HOSE		\$	61.00	+ x
SUB TOTAL SPARE PARTS			:	\$	15,071.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLR 3061 S

S/N	Parts Description			Damage Parts & Prices	
				S/NETT	Remarks
41	RADIATOR AIR GUIDE - LH / RH	7. CRACK	2	\$ 44.00	? 34 24
42	RADIATOR AIR GUIDE - UPPER CENTRE	N/A		\$ 11.00	X
43	AIR INTAKE AIR INLET	N/A		\$ 53.00	X
44	AIR INTAKE AIR GUIDE	N/A		\$ 62.00	X
45	AIR INTAKE INTER COOLER GASKET	N/A		\$ 13.00	X
46	AIR INTAKE AIR GUIDE	N/A		\$ 19.00	X
47	AIR INTAKE WATER DRAINAGE HOSE	N/A		\$ 31.00	+
48	AIR INTAKE AIR FILTER	N/A		\$ 252.00	+
49	LOCK CARRIER	N/A		\$ 663.00	X
50	READY MIX COOLANT	N/A	4	\$ 84.00	X
51	FRONT NO PLATE	Bent	S/N	\$ 40.00	40
52	SUNDRIES	N/A		\$ 400.00	7/104 96
TOTAL SPARE PARTS				\$ 25,232.00	
TOTAL LABOUR CHARGES				\$ 12,052.00	
GRAND TOTAL				\$ 37,284.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Admin
Surveyed Date : 05/11/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : not Authorised, 07 Days without Load Carrier
10 Days with Load Carrier

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No. PA/OD/1314/2019/NS
Date 12-Nov-19
Service Advisor Glory Tan
Pages 1 of 1
Regn No SLR3061S
Model No Audi A3 Sedan 1.0 TFSI 8V

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Headlight hose RHS	\$ 36.00	\$ 28.32
2	Headlight hose LHS	\$ 36.00	\$ 28.32
		\$ 72.00	\$ 56.64
<u>LABORS</u>			
TOTAL		\$ 72.00	\$ 56.64

For Premium Automobiles Pte Ltd

Adrian Ling -
H. S. J.

Authorised Signature