

ASS REC BY:

REF: CS/INC19019562/Dtd302

Special Instruction:

Survey: Bryan

ASSIGNMENT (Office)

From (Person): Hazelysa B Ibrahim

of INC

Date/Time: 5/11/19 @ 10:01 am

Estimated Cost:

Bill to:

OD ☒ TP FWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMG 3831 H

Insured:

SHB 8334R

at Workshop m/s

JWG International

Tel:

6909 8882

of

10 Amk Ind. Park 2A #03-08

Policy No:

Claim No:

MT/1069 802-002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

1/11/2014

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:37pm 5/11/19

Person Contacted:

Kalvin

Vehicle

☒ IN/OUT

Date/Time

Action/Instruction

To inspect

31/12/19

To request OI GVA to check on consistency of damage.

Bryan

ASSIGNMENT

Vehicle No. **SMG 3831H** or Regn **2017 March**

Type: ☒ M.C. / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make **Honda Jazz** CC **1498**

Colour **Blue** A/C: Insured / Std / Nil / NA

Sp/Resoling **46720** E/Radio: Insured / Std / Nil / NA

Eng/Hrs **L16B31190916**

C/Pic: **JHMGK5850HX201268**

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Mod: ☒ Nil / STD A/Rim or

Tyre Size F: **206/50 R16**

R: **— 11 —**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **Bridgestone**

Front Rear

R/Bal. **S** mm R/Bal. **S** mm

L/Bal. **S** mm L/Bal. **S** mm

D.O.A. **04/11/2019** D.O.I. **05/11/2019**

Survey held at **JWG AMIC** **0111PM**

Des. of Damages: ☒ Fnt / Rear / O/S / N/S / UIC / Rooftop or

Rear

The UIC / Chassis frame / Body Structure affected due to collision.

OU: IP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle Hrs:

At Workshop only:

at

Insured: /

Policy No:

Claims No:

Some Insured:


Excess:

(p. Sec'ds / Sec'ds)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value:

IMAC Accident Report Consistent? : Yes or No

Est. / PR Seen Consistent? : Yes or No

Est. Repair: **4** days Res.: Yes or No

Est. Sum: **20** % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Date / Time Action / Instruction

NTUC SHB 8339R

31/01/2020 Jinnu Lp 43001 - with 4 days given (Red 15455.70.7870)

RECEIVED 05 FEB 2020

Final Time, File Path to? ☐ : Prel. Report

512 Typist ☒ : Final Report

Final Time, File Path to?

3

Pop. Form:

Final 0 / 11:15

7P

4300k

Days Of Repair: **4**

Resurvey No. of Trip: **2**

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Meet and (\$

Survey Fee:

Transportation:

3 + 15 = 18

Fuel:

Other:

Total:

250

250

Nivitha (LKK Auto)

From: Hazalya Binte Ibrahim <hazalya.ibrahim@income.com.sg>
Sent: Wednesday, 6 November 2019 9:13 AM
To: Admin-D (LKKAuto); assignments
Cc: Hazalya Binte Ibrahim
Subject: FW: TP CASES FARMED OUT TO LKK ON 05/11/2019

Dear LKK,

RE-send with details.

Thank you.

Warmest Regards

Hazalya Bte Ibrahim
Admin Assistant
Motor Department
www.income.com.sg



At Income, we are 'In with You' on Performance. Growth.
Innovation and Impact. These attributes reflect what we promise
as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 5 November 2019 10:49 AM
To: Hazalya Binte Ibrahim <hazalya.ibrahim@income.com.sg>; assignments <assignments@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: TP CASES FARMED OUT TO LKK ON 05/11/2019

Dear Hazalya,

Thank you for the assignment.

Please be informed that SJN6248X (HUI YANG MOTOR) the vehicle is not in the workshop, repairer will arrange.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hazalya Binte Ibrahim [mailto:hazalya.ibrahim@income.com.sg]

Sent: Tuesday, 5 November 2019 10:01 AM

To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; assignments@lkkauto.com>

Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Hazalya Binte Ibrahim <hazalya.ibrahim@income.com.sg>

Subject: TP CASES FARMED OUT TO LKK ON 05/11/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	David Phua	MT/1069328-002	SMA1928H	AUTOMOTIVE REPAIR CENTRE PTE. LTD.	38. WOODLANDS INDUSTRIAL PARK E1 #05-18 SINGAPORE 757700	Lin Shu Juan / 6468 8834	10:00-16:00	SJK695A	30/10/19	
2	Eric Tang	MT/1069802-002	SMG3831H	JWG INTERNATIONAL PTE. LTD	10 ANG MO KIO INDUSTRIAL PARK 2A #03-08 AMK AUTOPOINT	/ 6909 8882		SHB8339R	04/11/19	

Thank you.

Warmest Regards

Hazalya Bte Ibrahim
Admin Assistant
Motor Department
T +65 6430 7902
www.income.com.sg

income
TRADE ASSOCIATION



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.

Find out more at Income.com.sg/careers

in with you

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL....

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/11/2019 17:33
Date Of Accident	04/11/2019 07:45
Exact Location Of Accident	ECP TWRDS AYE B4 EXIT 7A
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMG3831H
Insured/Policyholder	
Name Of Registered Owner	LEOW CHEW ENG
NRIC No	S1744267H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96713498
Alternative Phone No	OTHERS-96713498

Vehicle Particulars

Manufacturer	HONDA
Model	JAZZ 1.5 VTIR CVT ABS D/AIRBAG 2WD
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5106766684
Cover Note Number	

Driver

Name of Driver	CALVIN LANG YI JUN
NRIC No	S9541116I
Date Of Birth	06/11/1995
Occupation	OUTDOOR
Date Of Driving Pass	19/03/2015
Driving Experience	4 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97213006
Fax Number	
Contact Number	
E Mail Address	NOEMAIL

Address	17 FLORA ROAD #03-06 AVILA GARDENS
Postcode	509735
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED;

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHB8339R
Vehicle Make/Model/Colour	HYUNDAI / I30 GDH 1.6 TCI 5DR DCT
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	CHER CHUNMING
NRIC/Passport Number	S1098334G
Contact Number	96904637
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

VEHICLE NO: SMG 3831 H
INSURER: NTUC Income
DATE & TIME: 04/11/2019 0745 hrs

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorized Driver.
- Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application to interested parties.
- By the signing of this report to the insurers, you hereby consent to the archiving of this report at this centre and to copies of the report being made available aforesaid.
- Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - investigating the accident and/or my claims;
 - carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as the external cover of envelopes/mail packages), and/or
 - complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purpose(s); and
- my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be situated outside of Singapore, for one or more of the above Purpose(s);
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing risk, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - for complying with requirements under any regulatory, laws or court orders.


Policyholder's Signature
Date & Time: _____


Driver's Signature
(If & who is not the policyholder)
Date & Time: _____


IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4 #02-02
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vack@idac.com.sg
Reporting Centre Personnel's Signature
Name: _____
NIC/ID No: _____

Accident Sketch Plan

SKETCH PLAN

Vehicle A: SMG 3831 H
Vehicle B: SHB 8339 R

ICP TWPAS AYE-B4 Exit 7A



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, I, Vehicle A (SMG 3831 H) was travelling along the stated location on the right lane. As the vehicle in front slow down and stop, I followed suit. Suddenly, Vehicle B (SHB 8339 R) collided onto the rear portion of my vehicle causing damages.

Note: Please note that your insurer may have 14 days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

(We declare the foregoing particulars are true in every respect.)

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

☐ Claim Own Policy ☐ Claim Third Party
☐ Claim CCIR or other workshop

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4 #02-02
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vackb@idac.com.sg
Reporting Centre (Accident 24/7)

Name
Who? (Policy)
Reporting Only

Accident

I, Cher Chunming, S1098334 G, hit a vehicle, SMG3831H, at Ecp towards AYE, My head to his rear His car is stationary, my car SHB8339R could not brake in time and hit his rear.

I am sorry and i will bear all consequences and repairs for SMG3831H.


Cher Chunming
S1098334G
96904637

^{Car}
Calvin Lang
S084 1116I
97213006.

Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo





A: SHD 8339R

B: SMG 3834H

ON 04/11/2019 @ 0745HRS, I WAS DRIVING MY TAXI (SHB 8339 R) - TRAVELLING ALONG ECP - TUAS (BEFORE BEDOK ROAD EXIT) WITH A PASSENGER ONBOARD, IN LANE 1.

WHILE MOVING AHEAD, VEHICLE B (SMG 3831 G - HONDA JAZZ) WHICH WAS IN FRONT OF ME, STOPPED.

UPON SEEING IT, I IMMEDIATELY APPLIED MY BRAKES BUT WAS UNABLE TO STOP IN TIME - THUS COLLIDED ONTO THE REAR OF VEHICLE B.

DUE TO THE IMPACT, NO DAMAGES TO MY TAXI & NO VISIBLE DAMAGES TO VEHICLE B.

NO INJURY INVOLVED.

NO PASSENGERS ONBOARD VEHICLE B.

JWG INTERNATIONAL PTE. LTD.

Co. & GST Reg. No.: 201837488H

Blk 10, Ang Mo Kio Ind Park 2A,

#03-08 AMK AutoPoint,

Singapore 568047

H/P: 9069 7882 Fax: 6909 9592

E-Mail: jwg.claims@yahoo.com

DATE : 21/10/19

VEHICLE NO : SMG 3831 H
MODEL : HONDA JAZZ
CHASSIS NO : JHMGK5850GX201121

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR WINDSCREEN MOULDING <i>hlec</i>	1	\$ 223.50	\$ 223.50
2	REAR TAILGATE <i>hjt</i>	1	\$ 1,320.00	\$ 1,320.00
3	REAR TAILGATE STOPPER <i>hhl</i>	1	\$ 14.25	\$ 14.25
4	REAR TAILGATE DAMPER L+R <i>hhl</i>	2	\$ 198.00	\$ 396.00
5	REAR TAILGATE HINGE <i>hhl</i>	2	\$ 75.00	\$ 150.00
6	REAR TAILGATE DETECTOR <i>hhl</i>	1	\$ 87.00	\$ 87.00
7	REAR TAILGATE LAMP L+R <i>hhl</i>	2	\$ 193.50	\$ 387.00
8	REAR TAILGATE CHROME HANDLE <i>hhl</i>	1	\$ 334.50	\$ 334.50
9	REAR TAILGATE CHROME HANDLE NUMBER PL <i>hhl</i>	2	\$ 189.00	\$ 378.00
10	REAR TAILGATE LOGO <i>hlec hhl</i>	1	\$ 48.00	\$ 48.00
11	REAR TAILGATE EMBLEM - RS <i>hlec</i>	1	\$ 34.50	\$ 34.50
12	REAR TAILGATE EMBLEM - JAZZ <i>hlec</i>	1	\$ 58.00	\$ 58.00
13	REAR TAILGATE INNER TRIM <i>mondy cradle</i>	1	\$ 147.00	\$ 147.00
14	REAR TAILGATE LOCK <i>hhl</i>	1	\$ 235.50	\$ 235.50
15	REAR TAILGATE CATCH <i>hhl</i>	1	\$ 36.00	\$ 36.00
16	REAR TAILGATE WEATHER STRIP <i>distorted</i>	1	\$ 138.00	\$ 138.00
17	TAILLAMP L+R <i>hhl</i>	2	\$ 430.50	\$ 861.00
18	TAILLAMP PANEL L+R <i>hhl</i>	2	\$ 112.50	\$ 225.00
19	TAILLAMP CLIPS <i>hhl</i>	2	\$ 10.00	\$ 20.00
20	REAR BUMPER <i>distorted</i>	1	\$ 684.00	\$ 684.00
21	REAR BUMPER SIDE GARNISH L+R <i>hhl</i>	2	\$ 51.00	\$ 102.00
22	REAR BUMPER RETAINER L+R <i>hhl</i>	2	\$ 31.50	\$ 63.00
23	REAR BUMPER BRACKET L+R <i>hhl</i>	2	\$ 98.00	\$ 196.00
24	REAR BUMPER WIREHARNES <i>hhl</i>	1	\$ 1,485.70	\$ 1,485.70
25	REAR FENDER L+R <i>hhl</i>	2	\$ 957.00	\$ 1,914.00
26	REAR FENDER COWLING L+R <i>hhl</i>	2	\$ 124.50	\$ 249.00
27	REAR FENDER INNER TRIM - BTM <i>hhl</i>	2	\$ 279.00	\$ 558.00
28	REAR FENDER INNER SHIELD <i>hhl</i>	2	\$ 239.80	\$ 479.60

✓ 814.20

✓ 492.50

29	REAR END PANEL <i>Destroyed</i>	1	\$ 471.00	\$ 471.00	✓
30	REAR END PANEL TOP GARNISH <i>destroyed</i>	1	\$ 180.00	\$ 180.00	✓
31	FLOOR PANEL <i>NH</i>	1	\$ 1,045.50	\$ 1,045.50	X
32	FLOOR PANEL TOP BOARD <i>NH</i>	1	\$ 297.00	\$ 297.00	X
33	REAR TOOLS TOOLS BOX COVER <i>NH</i>	1	\$ 198.70	\$ 198.70	X
34	REAR TOOLS TOOLS BOX COMPARTMENT <i>form</i>	1	\$ 190.50	\$ 190.50	✓

rear End panel Antennas receiver money crane
281.70

TOTAL PRICE \$ 13,207.25
LESS 20% \$ 2,641.45
SUB TOTAL PRICE \$ 10,565.80

3030-90
2424.72

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REVERSE SENSOR <i>Don</i>	1	\$ 250.00	\$ 250.00	220/-
2	REVERSE CAM <i>NH</i>	1	\$ 400.00	\$ 400.00	X
3	REAR END PANEL SEALANT <i>NH</i>	1	\$ 100.00	\$ 100.00	40/-
4	SPARE WHEEL PANEL SEALANT <i>NH</i>	1	\$ 100.00	\$ 100.00	X
5	SPARE WHEEL INSULATOR <i>NH</i>	1	\$ 400.00	\$ 400.00	X
6	REAR BUMPER CLIPS <i>NH</i>	1	\$ 100.00	\$ 100.00	30/-
7	REAR FENDER COWLING CLIPS <i>NH</i>	1	\$ 100.00	\$ 100.00	X
8	REAR FENDER INNER TRIM CLIPS <i>NH</i>	1	\$ 100.00	\$ 100.00	X 1420.00
9	BOOTLID INNER TRIM CLIPS <i>NH</i>	1	\$ 100.00	\$ 100.00	X
10	REAR END PANEL TOP GARNISH CLIPS <i>NH</i>	1	\$ 100.00	\$ 100.00	X
11	REAR BOOTLID EMBLEM - JFC <i>NH</i>	1	\$ 80.00	\$ 80.00	50/-
12	REAR BOOTLID EMBLEM - JSRACING <i>NH</i>	1	\$ 200.00	\$ 200.00	80/-
13	REAR BUMPER LOWER SPOILER <i>destroyed / money crane</i>	1	\$ 1,800.00	\$ 1,800.00	1000/-
14	REAR BUMPER LOWER SPOILER SEAL <i>NH</i>	1	\$ 250.00	\$ 250.00	X

TOTAL \$ 4,080.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00	600/-
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	600/-
3	TUFF COAT	\$ 250.00	40/-
4	WIRING CHECK	\$ 180.00	NH
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 350.00	120/-
6	CONDUCT WATER LEAKAGE TEST	\$ 100.00	NH
8	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	40/-

11	TO RNR REAR WINDSCREEN TO ASSIST WORK LOAD	\$ 250.00	120/-
12	TO RNR REAR BOOT MECHANISM TO ASSIST WORK LOAD	\$ 200.00	60/-
22	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 300.00	1580 w 1200 NN

TOTAL \$ 5,110.00

5424.72

ESTIMATE REPORT

2/S 4300/-

TOTAL PARTS COST : \$ 14,645.80
TOTAL LABOUR COST : \$ 5,110.00
TOTAL REPAIR COST : \$ 19,755.80

1908/16

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

KELVIN WO

KELVIN WO
HP 9069 7882

05/11/2019 @ 13:00m

N/A Andrew

2/3m 4 days.

[Signature]

2 KK Auto

[Signature]

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19019562/Dtd3e2

73 BRAS BASAH ROAD

Date: 05-02-2020

#05-01 NTUC TRADE UNION HOUSESINGAPORE

189556



ATTN : ERIC TANG

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 8339R	Veh. Inspected	SMG 3831H
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1069802-002	Excess (\$)	0.00
Assign From	HAZALYSA BINTI IBRAHIM	Assign Date	05/11/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA JAZZ	c.c	1498
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JHMGK5850HX201268	Colour	BLUE
Odometer	46720 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/50 R16	BRIDGESTONE	5 mm
L/H Front Tyre	205/50 R16	BRIDGESTONE	5 mm
R/H Rear Tyre	205/50 R16	BRIDGESTONE	5 mm
L/H Rear Tyre	205/50 R16	BRIDGESTONE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	04/11/2019	Inspect Date / Time	05/11/2019 (01:11 PM)
Survey held at	JWG INTERNATIONAL PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A #03-08 AMK AUTOPOINT SINGAPORE 568047		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMG 3831H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR WINDSCREEN MOULDING	NECESSARY	223.50	223.50
1	REAR TAILGATE	BENT	1,320.00	814.20
1	REAR TAILGATE STOPPER	NOT NECESSARY	14.25	-
2	REAR TAILGATE DAMPER L+R @\$198.00	NOT NECESSARY	396.00	-
2	REAR TAILGATE HINGE @\$75.00	NOT NECESSARY	150.00	-
1	REAR TAILGATE DETECTOR	NOT NECESSARY	87.00	-
2	REAR TAILGATE LAMP L+R @\$193.50	NOT NECESSARY	387.00	-
1	REAR TAILGATE CHROME HANDLE	NOT NECESSARY	334.50	-
2	REAR TAILGATE CHROME HANDLE NUMBER PL @\$189.00	NOT NECESSARY	378.00	-
1	REAR TAILGATE LOGO	NOT NECESSARY	48.00	-
1	REAR TAILGATE EMBLEM - RS	NECESSARY	34.50	34.50
1	REAR TAILGATE EMBLEM - JAZZ	NECESSARY	58.00	58.00
1	REAR TAILGATE INNER TRIM	MTG CRACKED	147.00	147.00
1	REAR TAILGATE LOCK	NOT NECESSARY	235.50	-
1	REAR TAILGATE CATCH	NOT NECESSARY	36.00	-
1	REAR TAILGATE WEATHER STRIP	DEFORMED	138.00	138.00
2	TAILLAMP L+R @\$430.50	NOT NECESSARY	861.00	-
2	TAILLAMP PANEL L+R @\$112.50	NOT NECESSARY	225.00	-
2	TAILLAMP CLIPS @\$10.00	NOT NECESSARY	20.00	-
1	REAR BUMPER	DISTORTED	684.00	492.50
2	REAR BUMPER SIDE GARNISH L+R @\$51.00	NOT NECESSARY	102.00	-
2	REAR BUMPER RETAINER L+R @\$31.50	NOT NECESSARY	63.00	-
2	REAR BUMPER BRACKET L+R @\$98.00	NOT NECESSARY	196.00	-
1	REAR BUMPWR WIREHARNES	NOT NECESSARY	1,485.70	-
2	REAR FENDER L+R @\$957.00	NOT NECESSARY	1,914.00	-
2	REAR FENDER COWLING L+R @\$124.50	NOT NECESSARY	249.00	-
2	REAR FENDER INNER TRIM - BTM @\$279.00	NOT NECESSARY	558.00	-
2	REAR FENDER INNER SHIELD @\$239.80	NOT NECESSARY	479.60	-
1	REAR END PANEL	DENTED	471.00	471.00
1	REAR END PANEL TOP GARNISH	DEFORMED	180.00	180.00

Report Ref No. CS/INC19019562/Dtd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FLOOR PANEL	NOT NECESSARY	1,045.50	-
1	FLOOR PANEL TOP BOARD	NOT NECESSARY	297.00	-
1	REAR TOOLS BOX COVER	NOT NECESSARY	198.70	-
1	REAR TOOLS BOX COMPARTMENT	TORN	190.50	190.50
1	REAR END PANEL ANTENNA RECEIVER	MTG CRACKED	281.70	281.70
	LESS 20% DISCOUNT		-2,697.79	-606.18
			10,791.16	2,424.72
	<u>SPECIAL NETT ITEMS</u>			
1	REVERSE SENSOR (SN)	DAMAGED	250.00	220.00
1	REVERSE CAM (SN)	NOT NECESSARY	400.00	-
1	REAR END PANEL SEALANT (SN)	NECESSARY	100.00	40.00
1	SPARE WHEEL PANEL SEALANT (SN)	NOT NECESSARY	100.00	-
1	SPARE WHEEL INSULATOR (SN)	NOT NECESSARY	400.00	-
1	REAR BUMPER CLIPS (SN)	NECESSARY	100.00	30.00
1	REAR FENDER COWLING CLIPS (SN)	NOT NECESSARY	100.00	-
1	REAR FENDER INNER TRIM CLIPS (SN)	NOT NECESSARY	100.00	-
1	BOOTLID INNER TRIM CLIPS (SN)	NOT NECESSARY	100.00	-
1	REAR END PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	100.00	-
1	REAR BOOTLID EMBLEM - JFC (SN)	NECESSARY	80.00	50.00
1	REAR BOOTLID EMBLEM - JSCASING (SN)	NECESSARY	200.00	80.00
1	REAR BUMPER LOWER SPOILER (SN)	DISTORTED / MTG CRACKED	1,800.00	1,000.00
1	REAR BUMPER LOWER SPOILER SEAL (SN)	NOT NECESSARY	250.00	-
			4,080.00	1,420.00
	<u>LABOUR</u>			
	PANEL BEATING, REMOVAL AND REPLACING PARTS.		1,800.00	600.00
	TO SPRAY PAINT AFFECTED AREA.		1,600.00	600.00
	TUFF COAT.		250.00	40.00
	WIRING CHECK.	NOT NECESSARY	180.00	-
	REMOVE AND REFIX CUSHION SEAT / UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR.		350.00	120.00
	CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	100.00	-

Report Ref No. CS/INC19019562/Dtd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		80.00	40.00
	TO RNR REAR WINDSCREEN TO ASSIST WORK LOAD.		250.00	120.00
	TO RNR REAR BOOT MECHANISM TO ASSIST WORK LOAD.		200.00	60.00
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	NOT NECESSARY	300.00	-
			5,110.00	1,580.00
GRAND TOTAL			19,981.16	5,424.72
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				4,300.00

Report Ref No. CS/INC19019562/Dtd3e2

ANG BRYAN TANI

Automotive Assessor / Investigator

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.